



***Federal Railroad Administration  
Office of Railroad Safety  
Accident and Analysis Branch***

***Accident Investigation Report  
HQ-2017-1209***

***Union Pacific Railroad Company (UP)  
Ohlman, IL  
June 14, 2017***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report, including this one, made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

**SYNOPSIS**

On June 14, 2017, at approximately 6:30 p.m., CDT, a Union Pacific Railroad (UP) freight train, MYCAS-14, operating southwest from Villa Grove, Illinois, to St. Louis, Missouri, struck an occupied van on the N 80 Road public highway-rail grade crossing (also known as County Road 1800 East). The U.S. DOT National Highway-Rail Grade Crossing Inventory number is 542135C; the crossing was equipped with yield signs and cross-bucks. The accident occurred in the Township of Rosamond, in Christian County, near Ohlman, Illinois, at Milepost 211.73 on UP's Pana Subdivision of the St. Louis Service Unit. The driver and the four passengers were fatally injured. There were no injuries to the train crew.

The estimated track and signal damage was \$66. The estimated equipment damage was \$500.

At the time of the accident, it was cloudy and the temperature was 73 °F.

FRA determined the probable cause of this accident was cause code M303 – Highway user misjudgment under normal weather and traffic conditions. No contributing cause codes were identified.

**TRAIN SUMMARY**

1. Name of Railroad Operating Train #1 Union Pacific Railroad Company	1a. Alphabetic Code UP	1b. Railroad Accident/Incident No. 0617SL011
--	---------------------------	---

**GENERAL INFORMATION**

1. Name of Railroad or Other Entity Responsible for Track Maintenance Union Pacific Railroad Company	1a. Alphabetic Code UP	1b. Railroad Accident/Incident No. 0617SL011
2. U.S. DOT Grade Crossing Identification Number 542135C	3. Date of Accident/Incident 6/14/2017	4. Time of Accident/Incident 6:30 PM
5. Type of Accident/Incident Hwy-Rail Crossing		
6. Cars Carrying HAZMAT 6	7. HAZMAT Cars Damaged/Derailed 0	8. Cars Releasing HAZMAT 0
	9. People Evacuated 0	10. Subdivision Pana Subdivision
11. Nearest City/Town Ohlman	12. Milepost (to nearest tenth) 211.73	13. State Abbr. IL
		14. County CHRISTIAN
15. Temperature (F) 73 °F	16. Visibility Day	17. Weather Cloudy
		18. Type of Track Main
19. Track Name/Number Single Main Track	20. FRA Track Class Freight Trains-60, Passenger Trains-80	21. Annual Track Density (gross tons in millions) 15.2
		22. Time Table Direction South

**OPERATING TRAIN #1**

1. Type of Equipment Consist: Freight Train					2. Was Equipment Attended? Yes		3. Train Number/Symbol MYCAS-14				
4. Speed (recorded speed, if available) R - Recorded 48.0 MPH E - Estimated		Code E	5. Trailing Tons (gross excluding power units) 5121		6a. Remotely Controlled Locomotive? 0 = Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter					Code 0	
6. Type of Territory Signalization: <u>Signaled</u> Method of Operation/Authority for Movement: <u>Signal Indication</u> Supplemental/Adjunct Codes: <u>Q</u>											
7. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	8. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box			Alcohol		Drugs	
(1) First Involved <i>(derailed, struck, etc.)</i>		UP4790	1	no							
(2) Causing <i>(if mechanical, cause reported)</i>		N/A	0	no	9. Was this consist transporting passengers?					No	
10. Locomotive Units (Exclude EMU, DMU, and Cab Car Locomotives.)	a. Head End	Mid Train		Rear End		11. Cars (Include EMU, DMU, and Cab Car Locomotives.)	Loaded		Empty		e. Caboose
		b. Manual	c. Remote	d. Manual	e. Remote		a. Freight	b. Pass.	c. Freight	d. Pass.	
		(1) Total in Train	2	0	0		0	0	(1) Total in Equipment Consist	28	
(2) Total Derailed	0	0	0	0	0	(2) Total Derailed	0	0	0	0	0
12. Equipment Damage This Consist 500			13. Track, Signal, Way & Structure Damage 66								
14. Primary Cause Code M303 - Highway user misjudgment under normal weather and traffic conditions											
15. Contributing Cause Code											
Number of Crew Members						Length of Time on Duty					
16. Engineers/Operators 1		17. Firemen 0		18. Conductors 1		19. Brakemen 0		20. Engineer/Operator Hrs: 4 Mins: 15		21. Conductor Hrs: 4 Mins: 15	
Casualties to:		22. Railroad Employees		23. Train Passengers		24. Others		25. EOT Device? Yes		26. Was EOT Device Properly Armed? Yes	
Fatal		0		0		5		27. Caboose Occupied by Crew? N/A			
Nonfatal		0		0		0					
28. Latitude 39.360181000				29. Longitude -89.196640000							

**CROSSING INFORMATION**

Highway User Involved		Rail Equipment Involved	
1. Type Van		5. Equipment Train (Units Pulling)	
2. Vehicle Speed ( <i>est. mph at impact</i> ) 5	3. Direction ( <i>geographical</i> ) South	6. Position of Car Unit in Train 1	
4. Position of Involved Highway User Moved over Crossing		7. Circumstance Rail Equipment Struck Highway User	
8a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? Rail Equipment		8b. Was there a hazardous materials release by Neither	
8c. State here the name and quantity of the hazardous material released, if any. N/A			
9. Type of Crossing  1. Gates      4. Wig wags      7. Crossbucks      10. Flagged by crew 2. Cantilever FLS      5. Hwy. traffic signals      8. Stop signs      11. Other ( <i>spec. in narr.</i> ) 3. Standard FLS      6. Audible      9. Watchman      12. None  7, 11		10. Signaled Crossing Warning	11. Roadway Conditions Wet
12. Location of Warning Both Sides		13. Crossing Warning Interconnected with Highway Signals N/A	14. Crossing Illuminated by Street Lights or Special Lights No
15. Highway User's Age 79	16. Highway User's Gender Male	17. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train No	18. Highway User Did not stop
19. Driver Passed Standing Highway Vehicle No		20. View of Track Obscured by ( <i>primary obstruction</i> ) Not Obstructed	
Casualties to:	Killed	Injured	21. Driver was Killed 22. Was Driver in the Vehicle? Yes
23. Highway-Rail Crossing Users	5	0	24. Highway Vehicle Property Damage ( <i>est. dollar damage</i> )      5000 25. Total Number of Vehicle Occupants ( <i>including driver</i> )      5
26. Locomotive Auxiliary Lights? Yes		27. Locomotive Auxiliary Lights Operational? Yes	
28. Locomotive Headlight Illuminated? Yes		29. Locomotive Audible Warning Sounded? Yes	


**10. Signaled Crossing Warning**

**Explanation Code**

- |  |  |
|--|--|
| 1 - Provided minimum 20-second warning             | A - Insulated rail vehicle   |
| 2 - Alleged warning time greater than 60 seconds   | B - Storm/lightning damage   |
| 3 - Alleged warning time less than 20 seconds      | C - Vandalism  |
| 4 - Alleged no warning                             | D - No power/batteries dead  |
| 5 - Confirmed warning time greater than 60 seconds | E - Devices down for repair  |
| 6 - Confirmed warning time less than 20 seconds    | F - Devices out of service   |
| 7 - Confirmed no warning                           | G - Warning time greater than 60 seconds attributed to accident-involved train stopping short of the crossing, but within track circuit limits, while warning devices remain continuously active with no other in-motion train present |
| N/A - N/A  | H - Warning time greater than 60 seconds attributed to track circuit failure (e.g., insulated rail joint or rail bonding failure, track or ballast fouled)   |
|  | J - Warning time greater than 60 seconds attributed to other train/equipment within track circuit limits   |
|  | K - Warning time less than 20 seconds attributed to signals timing out before train's arrival at the crossing/island circuit   |
|  | L - Warning time less than 20 seconds attributed to train operating counter to track circuit design direction  |
|  | M - Warning time less than 20 seconds attributed to train speed in excess of track circuit's design speed  |
|  | N - Warning time less than 20 seconds attributed to signal system's failure to detect train approach   |
|  | O - Warning time less than 20 seconds attributed to violation of special train operating instructions  |
|  | P - No warning attributed to signal systems failure to detect the train  |
|  | R - Other cause(s). Explain in Narrative Description   |

**SKETCHES**

Accident Sketch (Derived From IL State Police Sketch)




SKETCHES

Pana, IL FRA Sight Distance Sketch




NOT TO SCALE





NOT TO SCALE

### Clearing Sight Distance Triangle – UP Pana Subdivision N County Road 1800 E (DOT #542135C, MP 211.73)



**N 80 Rd (N 1800 East Rd)  
(DOT #542135C, MP 211.73)**

- Distance from outside rail to Cone C - 15 ft
- Distance from Cone C to Cone D - 593 ft
- Case B: Departure from Stop
- Table 32, AASHTO Green Book p 734, 2004

N 80 Rd  
(N1800 East Rd)  
(paved)  
12'ft Wide



## NARRATIVE

**Circumstances Prior to the Accident**

The crew of Union Pacific Railroad (UP) freight Train MYCAS-14 (striking train) consisted of a locomotive engineer and conductor. The crew reported for duty at 2:14 p.m., CDT, on June 14, 2017, at UP's Villa Grove Yard, located in Villa Grove, Illinois. This was the home terminal for both crew members. Both crew members received the statutory rest period prior to reporting for duty. The crew was scheduled to operate their train from Villa Grove to Alton Southern (ALS) Yard, in St. Louis, Missouri. The crew added nine cars to the train at Villa Grove Yard and had no other scheduled pick-ups or set-outs between Villa Grove and ALS.

The striking train consisted of 2 locomotives, 28 loaded cars, and 56 empty cars of mixed freight. The total length of the train was 5,704 feet and the train weighed 5,521 tons. The train received a Class I air brake test conducted by mechanical employees at UP's Yard Center, in Dolton, Illinois. The crew at Villa Grove performed an air brake test on the nine cars they added prior to departing at 4:25 p.m. The crew tested the locomotive bell and headlights at Villa Grove Yard prior to departing and no exceptions were noted. The locomotive horn was sounded at the first grade crossing with no exceptions noted. All locomotive safety devices were working as intended.

The accident occurred in the township of Rosamond, Illinois on UP's Pana Subdivision of the St. Louis Service Unit. In the area where the accident occurred, the track is a single main track with a timetable maximum speed limit of 60 mph. DOT Crossing 542135C (the crossing) is a public highway-rail grade crossing at milepost (MP) 211.73, and is equipped with passive warning devices (yield sign and crossbucks). The striking train was traveling geographically southwest on the St. Louis Service Unit's Pana Subdivision. The timetable direction is south (timetable direction will be used throughout this report).

As the striking train approached the accident area, the Locomotive Engineer was seated at the controls on the right (west) side of the cab facing forward. The Conductor was seated in the conductor's seat on the left (east) side of the locomotive cab, also facing forward.

**The Accident****The Striking Train**

The train was being operated at a recorded speed of 48 mph as it approached the crossing. The maximum authorized speed for this train was 60 mph. The Engineer and Conductor observed a van that appeared to be slowing to a stop as it approached the crossing. The crew then observed the brake lights go off, and the van proceeded into the crossing. At that time, the Engineer initiated an emergency application of the brakes and the locomotive collided with the van as it entered the crossing.

Once the train came to a stop, the Locomotive Engineer contacted the Dispatcher via the radio to report the accident. The crew conducted a job briefing and the Conductor walked back to separate the rail cars at the crossing so emergency personnel could access the injured passengers from the IL-16 roadway. The Conductor observed three of the passengers from the vehicle, lying on the ground, that appeared to be deceased. The Train Dispatcher contacted local authorities and two fire departments were dispatched to the scene, Witt Volunteer Fire Department and Pana Fire Department. Records indicate that the fire

departments were dispatched at 6:31 p.m. The first fire unit arrived on-scene at 6:46 p.m. The Illinois State Police also responded to the accident scene.

There was no derailment of the train, no hazardous material involved, and this was not a passenger train rout. There was no toxicological testing performed on the train crew. The Federal Railroad Administration (FRA) does not require such testing for this type of accident.

### **Highway Vehicle**

A 2009 Chrysler Town & Country passenger van (struck vehicle) with a driver and four passengers was approaching the crossing from the north. Per statements given by the train crew, the vehicle appeared to be slowing to stop for the train, and then began to accelerate into the crossing, and into the path of the train, and was struck.

From the point of impact, the struck vehicle was thrown airborne and struck the top of the yield and cross-buck sign. The vehicle then overturned and came to rest on the passenger's side facing southwest. The driver and three passengers were ejected from the vehicle. The three passengers were pronounced deceased on the scene. The driver of the vehicle was transported by Pana Ambulance to Pana Community Hospital and then airlifted to St. Louis University Hospital and pronounced deceased at approximately 11:06 p.m. The other occupant of the vehicle was air-lifted to Barnes Jewish Hospital and later succumbed to injuries and pronounced deceased.

The Illinois State Police report stated the 79-year old male driver of the vehicle failed to yield at the crossing, and was struck by the train.

### **Analysis and Conclusions**

Analysis - Toxicological Testing: There were no toxicological reports for the driver, or three of the four passengers. The Office of the Medical Examiner from the City of St. Louis performed toxicological testing on the remains of an 87-year old female passenger and the results were primarily negative. The results were positive for the presence of Etomidate, Ketamine, and Metoprolol. UP did not conduct drug and alcohol testing on the crew members nor was testing required by Federal regulations.

Conclusion: There was no evidence to indicate intoxication was a causal factor of the accident.

Analysis - Highway-Rail Grade Crossing: The highway-rail crossing at grade is equipped with yield signs and cross-buck signs. There is no advance warning sign posted at the crossing. There are no pavement markings within 100 feet of the crossing. A sight distance evaluation was conducted of the crossing in accordance with the method described in the Federal Highway Administration's Railroad-Highway Grade Crossing Handbook (revised Second Edition, 2007). Based on a highway speed limit of 30 mph, with a motor vehicle speed of 5 mph (on impact), and a 15-foot safe zone (Cone C) from the nearest rail, the beginning of the approach zone for this crossing was determined to be 490 feet (Cone A), with a point of nonrecovery beginning at 220 feet (Cone B). For a train speed of 48 mph, the distance along the railroad from crossing was determined to be 593 feet (Cone D). The actual sight visibility triangle was measured from the first point, at which the vehicle operator had an unobstructed line of sight from the vehicle to the front of the train. This point was determined to be 490 feet. There was no vegetation on the northeast side of the grade crossing, the direction from which the train was approaching.

Conclusion: The crossing, decision, approach, and clearing sight distances were clear and visible.

Analysis - Locomotive Safety Devices: The leading locomotive was equipped with a headlight, auxiliary

lights, and the audible warning device (horn and bell) required by Federal regulations. Records indicate these devices were tested prior to departing Villa Grove. The locomotive safety devices functioned as intended. The crew did not note any exceptions with the operation of the locomotive lights, bell, or horn during their trip.

Conclusion: The locomotive safety devices were in full compliance with Federal regulations.

Analysis - Locomotive Engineer Operating Performance: The locomotive was equipped with a speed indicator and an event recorder, as required. The relevant event recorder data was downloaded by UP's Manager of Operating Practices at the accident site. The downloaded data was analyzed by a qualified UP manager. The downloaded data was further analyzed independently by qualified FRA employees. Total duration of the horn sequence was approximately 16 seconds at 50 mph which began at Milepost (MP) 211.52 to MP 211.75, approximately ¼-mile. Documentation indicates that the road crossing where the incident took place was at MP 211.73. From the time the train was placed in emergency until complete stop, a total of 1,992 feet was traversed. The locomotive event recorder indicated the striking train was operating at an estimated speed of 48 mph when it struck the vehicle on the driver side as it entered the grade crossing.

Conclusion: The Locomotive Engineer was in compliance with all applicable railroad operating and train handling requirements.

Fatigue Analysis: FRA obtained fatigue-related information for the 10-day period preceding this accident/incident, including the 10-day work history (on-duty/off-duty cycles) for the Locomotive Engineer and Conductor.

Conclusion: Upon analysis of that information, FRA concluded fatigue was not probable for any of the employees nor was it a causal factor in the accident.

### **Overall Conclusion**

The railroad was in full compliance with its own operating rules and all applicable Federal regulations. The train crewmembers were the only witnesses to the accident, and they had no information that could be used to determine why the automobile failed to yield to the train at the crossing.

### **Probable Cause and Contributing Factors**

FRA determined the probable cause of this accident was cause code M303 – Highway user misjudgment under normal weather and traffic conditions. No contributing cause codes were identified.