U.S. DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION Washington, D.C. 20590

Locomotive Engineer Review Board

Decision Concerning Union Pacific Railroad's Revocation of Mr. J.A. Barrera's Locomotive Engineer Certification

FRA Docket Number EQAL 2011-18

Decision

The Locomotive Engineer Review Board (Board) of the Federal Railroad Administration (FRA) has reviewed the decision of Union Pacific Railroad (UP) to revoke Mr. J.A. Barrera's (Petitioner) locomotive engineer certification (certification) in accordance with the provisions of Title 49, Part 240 of the Code of Federal Regulations (49 C.F.R. Part 240). The Board hereby grants the petition for the reasons stated below.

Background

On February 22, 2011, at approximately 4:10 p.m., while operating Train APXEGR-21, Petitioner allegedly failed to reduce his train speed to 30 MPH to comply with the speed restriction in place when the wayside hot box and dragging equipment detector (hot box) located at MP 374 on the Del Rio Subdivision failed to communicate an exit message to the crew. Pet. Ex. A.

UP charged Petitioner with a violation of 49 C.F.R. § 240.117(e)(2), "Failure to adhere to limitations concerning train speed when the speed at which the train was operated exceeds the maximum authorized limit by at least 10 MPH." An investigation and hearing was held on March 8, 2011, and UP notified Petitioner of the revocation of his certification by a letter dated March 18, 2011. Pet. at 1. See also Pet. Ex. A.

Petitioner's Assertions

By petition received on June 22, 2011, Petitioner requested FRA to review UP's decision to revoke his certification. The petition asserts that the revocation was improper because:

(1) The basis for the determination to revoke the Petitioner's certificate was a direct result of his alleged failure to "immediately" reduce train speed to 30 MPH when there was a detector failure. Unlike signal rules, there is no requirement in the UP System Special Instructions (SSI) stating a train must immediately reduce speed and the Petitioner believes he complied with the instruction. Pet. at 2; and (2) The Petitioner was qualified to operate on the territory. However, due to infrequent operation over the territory, Petitioner had to reference the UP SSI to determine appropriate action after the hot box failed to issue an exit message. The instructions were complicated, consisting of nine pages and required the cross referencing of two separate tables. On one table, UP assigns characters #, (#), &, (&), %, @ to connote specific wayside detector types. The wayside detector at MP 374 was a (#) that equates to Hot Box (Hot Wheel) and Dragging Equipment. The Petitioner then had to reference a second table in order to determine appropriate crew action. The instruction required Train APXEGR-21 to immediately contact the train dispatcher and reduce train speed to 30 MPH. Pet. at 4.

UP's Response

Pursuant to 49 C.F.R. § 240.405(b) and (c), a copy of the petition was sent to UP on July 20, 2011, and the railroad was afforded an opportunity to comment. UP submitted a timely response to Petitioner's assertions by letter dated September 14, 2011, as follows:

- (1) The Petitioner testified that there was no exit message and increased his speed from 39 to 50 MPH, resulting in a failure to adhere to speed restriction in place because the crew did not receive an exit message. The crew testified that they attempted to contact the dispatcher and understood that that was a necessary action to be taken. The Petitioner took no action to reduce the train speed, but rather increased it, despite not receiving an exit message. Actions to reduce the train speed only occurred when the train reached a distance of more than four miles after clearing the detector. Resp. at 3; and
- (2) There was no evidence presented that the Petitioner was required to be off his turn in unfamiliar territory. Additionally, no evidence was presented that the Petitioner notified Crew Management (CMS) or a Manager of Operating Practices (MOP) for re-familiarization over the territory. Resp. at 3-4.

Locomotive Engineer Review Board's Determination

Based on its review of the record, the Board has determined that:

- (1) On February 22, 2011, at approximately 4:10 p.m., Petitioner served as a locomotive engineer of Train APXEGR-21 with a total length of 5,763 feet (1.1 miles). Pet. at 1. See also, Tr. at 61.
- (2) At the same time and date, two UP Managers of Road Operations (MRO) were performing a Field Training Exercise (FTX) at a wayside hot box and dragging equipment detector located at MP 374 on the Del Rio Subdivision. The purpose of the test was to observe operating rule compliance when the automatic radio

transmitted exit message was not communicated to the crew (detector failure). Resp. at 1. See also, Pet. at 1. See also, Tr. at 33-34, 110.

- (3) The crew received an entry message from the hot box as the train entered the wayside detector at MP 374 at a speed of approximately 39 MPH. Tr. at 60. At this same time, the head-end was entering a segment of main track between MP 373.9 and 373.2 under form B authority where Maintenance of Way was working. The crew received permission to proceed at maximum authorized speed and accelerated to a speed of 50 MPH. Tr. at 60. The maximum authorized speed on the main track was 70 MPH. Pet. at 1. See also, Tr. at 177-182, 241.
- (4) In the vicinity of Laughlin Base Crossing (MP 372), the crew realized they heard no transmitted response from the hot box, and immediately attempted to contact the train dispatcher and held a "rolling job safety briefing" as the conductor referred to railroad issued materials in their possession to determine the appropriate action. Tr. at 184.
- (5) Approximately, three minutes later the conductor discovered Item 13 of the UP SSI, which required slowing the train to 30 MPH and the Petitioner applied the train brake to reduce train speed. Considering safe train handling and according to event recorder data, this action occurred at MP 368.9 and took one minute and thirty-one seconds over a distance of 1.2 miles to achieve. At MP 367.7 train APXEGR-21 was proceeding at the prescribed SSI speed. Tr. at 183-186.
- (6) The train was stopped at Amanda, approximately 12 miles from the location of the wayside equipment detector, and the crew was removed from service by the MROs. Tr. at 52.
- (7) UP charged Petitioner with a violation of 49 C.F.R. § 240.117(e)(2), "Failure to adhere to limitations concerning train speed when the speed at which the train was operated exceeds the maximum authorized limit by at least 10 MPH." An investigation and hearing was held on March 8, 2011, and UP notified Petitioner of the revocation of his certification by a letter dated March 18, 2011. Pet. at 1. See also, Pet. Ex. A.

Analysis of the Petition

In reviewing petitions of revocation decisions, the Board considers whether substantial evidence exists to support the railroad's factual findings in its decision for revocation under FRA's regulations. See 49 C.F.R. § 240.405(f). See also, 58 Fed. Reg. 18982, 19001 (April 9, 1993). Based on the Petitioner's first assertion, the Board does not find that UP had substantial evidence to revoke Petitioner's certification. The alleged violation occurred during a controlled FTX test and the Petitioner does not refute the fact Train APXEGR-21 did not receive an exit message to the hot box and dragging equipment detector at MP 374. Pet. at 1. According to event recorder data, the train accelerated to 50 MPH and traveled 4 miles and 15 feet (approximately 6 minutes)

after the rear end passed the wayside detector before action was taken to reduce train speed. Tr. at 172. However, the Action Table for UP SSI 13.7.2., Item 4, requires no immediate action and instead states: "proceed not exceeding 30 MPH," which Petitioner did at MP 367.7. Pet. Ex. 2. See also, Tr. at 127-128, 183-186. Nevertheless, even if the term "immediate" did apply to Item 4, "immediate" is too vague and ambiguous a term regarding exactly where the speed restriction should have begun. Because the rule is ambiguous on this issue, the Board cannot determine objectively whether Petitioner violated the SSI, and thus violated any speed restriction. Consequently, the Board has decided that, as a matter of law, UP has failed to present substantial evidence that this incident met the requirements for a revocable event.

Petitioner's second assertion involves an intervening cause. In determining whether revocation was proper under FRA's regulations, the Board considers whether "an intervening cause prevented or materially impaired the locomotive engineer's ability to comply with the railroad operating rule or practice which constitutes a violation under §§ 240.117(e)(1) through (e)(5) of this part." 49 C.F.R. § 240.307(i)(1). Petitioner argues that he should not be held responsible for the alleged violation because the nine-page SSI is excessively complicated to access. The Board finds this assertion is without merit. Table symbols and cross-referencing is a common practice when a railroad has different types or models of fixed or rolling equipment that require different restrictions or special actions. This is evidenced by the quickness (about 2-3 minutes) the conductor demonstrated in accessing the information and reducing speed. Tr. at 183. The written format of the nine-page SSI does not mitigate the alleged violation.

Conclusion

Based on the findings noted above, the Board hereby grants Engineer Barrera's petition for review in accordance with the provisions of 49 C.F.R. Part 240.

Issued in Chicago, IL on ______.

of McC

Richard M. McCord Chairman, Locomotive Engineer Review Board

SERVICE LIST EQAL 2011-18

A copy of the Locomotive Engineer Review Board decision in this matter has been sent by certified mail and return receipt requested to each person shown below.

SENT CERTIFIED MAIL RETURN RECEIPT REQUESTED

Mr. J.A. Barrera P.O. Box 421788 Del Rio, TX 78842-1788

Mr. Warren Dent General Chairman BLET Union Pacific, Southern Region 607 W. Harwood Rd. Hurst, TX 76054

Mr. Lawrence Brennan, Jr. Manager, Engineering Certification & Licensing Union Pacific Railroad Company 1400 Douglas St., Mailstop 1010 Omaha, NE 68179

Ms. Christine Hampton Director, Training and Quality Assurance Union Pacific Railroad Company 1400 Douglas St., Mailstop 1030 Omaha, NE 68179

Diane Filipowicz

Administrative Assistant

enc: Post LERB Memo cc: FRA DOCKET EQAL 2011-18 FEB 0 7 2012

Date

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.	A. Signature
 Print your name and address on the reverse 	X Agent
so that we can return the card to you. Attach this card to the back of the mailpiece,	B. Received by (Printed Name) C. Date of Delivery
or on the front if space permits.	D. Is delivery address different from Item 1?
1. Article Addressed to:	If YES, enter delivery address below:
Mr. J.A. Barrera	
P.O. Box 421788	
Del Rio, TX 78842-1788	3. Service Type
	Certified Mail Express Mail
	Registered Insured Mail C.O.D.
EQNL 2011-18	4. Restricted Delivery? (Extra Fee)
2. Article Number 2008 3230) 002 3925 8136
	etum Receipt 102595-02-M-1540
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
Complete items 1, 2, and 3. Also complete	A. Signature
item 4 if Restricted Delivery is desired.	X Agent
Print your name and address on the reverse so that we can return the card to you.	
Attach this card to the back of the mailpiece, or on the front if space permits.	B. Received by (PrInted Name) C. Date of Delivery
Article Addressed to:	D. Is delivery address different from Item 1? Yes
1. PILIOD PLATESSOU IO.	If YES, enter delivery address below: No
Mr. Warren Dent	
General Chairman, BLET	
Union Pacific, Southern Region	
607 W. Harwood Rd.	3. Service Type
Hurst, TX 76054	Certified Mail Express Mail Registered Return Receipt for Merchandise
EQUAL 2011-18	4. Restricted Delivery? (Extra Fee)
2 Article Mumber	0002 3925 8129
PS Form 3811, February 2004 Domestic R	eturn Receipt 102595-02-M-1540
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
	A. Signature
Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.	
Print your name and address on the reverse	X Addressee
so that we can return the card to you. Attach this card to the back of the mailpiece, 	B. Received by (Printed Name) C. Date of Delivery
or on the front if space permits.	D. Is delivery address different from item 1? Yes
1. Article Addresseù ru.	IT delivery address below: Solar No
Mr. Lawrence Brennan, Jr.	Licensing
Manager, Engineering Certification &	Lifensing H
Desite Desited (Company	
Union Pacific Railroad Company	2. Service Type
1400 Douglas St., Mailstop 1010	3. Service Type
1400 Douglas St., Mailstop 1010 Omaha, NE 68179	Certified Mail Express Mail
1400 Douglas St., Mailstop 1010	Certified Mail Express Mail
1400 Douglas St., Mailstop 1010 Omaha, NE 68179	Certified Mail Express Mail
1400 Douglas St., Mailstop 1010 Omaha, NE 68179 EQAL 2011 - 18	Certified Mail Express Mail Registered Insured Mail C.O.D. Yes
1400 Douglas St., Mailstop 1010 Omaha, NE 68179 EQAL 2011 - 18	Certified Mail Express Mail Registered Insured Mail C.O.D. Yes

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse 	A. Signature X QAGENT
 so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 	
1. Article Addressed to:	D. Is delivery address different from item 1? Ses
the Objective Hermiters	
Ms. Christine Hampton Director, Training and Quality As Union Pacific Railroad Company	
Director, Training and Quality As	
Director, Training and Quality As Union Pacific Railroad Company 1400 Douglas St., Mailstop 1030	3. Service Type Certified Mail Express Mail Registered Return Receipt for Merchandise
Director, Training and Quality As Union Pacific Railroad Company 1400 Douglas St., Mailstop 1030 Omaha, NE 68179	3. Service Type Certified Mail Express Mail Registered X Return Receipt for Merchandise

,

•

.