



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2010-11***

***Montreal, Maine and Atlantic Railway, Ltd. (MMA)
Brownville Junction, ME
February 26, 2010***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Montreal, Maine and Atlantic Rwy, Ltd. [MMA]		1a. Alphabetic Code MMA		1b. Railroad Accident/Incident No. 10022601		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Montreal, Maine and Atlantic Rwy, Ltd. [MMA]		4a. Alphabetic Code MMA		4b. Railroad Accident/Incident No. 10022601		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 02 Day 26 Year 2010		7. Time of Accident/Incident 03:45:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative) Code 04		
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		
				12. People Evacuated 0		
				13. Division SYSTEM		
14. Nearest City/Town Brownville Jct		15. Milepost (to nearest tenth) 0		16. State Abbr Code ME 23		
				17. County PISCATAQUIS		
18. Temperature (F) (specify if minus) 30 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 5		
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2		
22. Track Name/Number BACK LEAD		23. FRA Track Code Class (1-9, X) 1		24. Annual Track Density (gross tons in millions) N/A		
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 3		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		
2. Passenger train		5. Single car		7. Yard/switching		
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code		
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1 2		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 12 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) N/A		n N/A N/A N/A N/A				
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) MMA8553		b. Position in Train 1		
(2) Causing (if mechanical cause reported)		0		c. Loaded (yes/no) no N/A		
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0		
				34. Was this consist transporting passengers? (Y/N) N		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		3		0 0		
(2) Total Derailed		2		0 0		
				36. Cars		
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
				(1) Total in Equipment Consist 0 0 0 0 0		
				(2) Total Derailed 0 0 0 0 0		
37. Equipment Damage		38. Track, Signal, Way, & Structure Damage		39. Primary Cause Code H017		
This Consist \$100,000.00		\$0.00		40. Contributing Cause Code H999		
Number of Crew Members				Length of Time on Duty		
41. Engineer/Operators 0		42. Firemen 0		43. Conductors 0		
				44. Brakemen 0		
				45. Engineer/Operator Hrs 0 Mi 0		
				46. Conductor Hrs 0 Mi 0		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		49. Other 0		
Nonfatal		0		0		
				50. EOT Device? 1. Yes 2. No N/A		
				51. Was EOT Device Properly Armed? 1. Yes 2. No N/A		
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		
2. Passenger train		5. Single car		7. Yard/switching		
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code		
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No 1 1		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	
					55. Train Number/Symbol 203	

57. Trailing Tons (gross tonnage, excluding power units) 3707	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) 1 N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
--	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) MMA8578	a. Initial and Number 1	b. Position in Train 1	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 2	0	0	0	(1) Total in Equipment Consist 31	0	2	0
(2) Total Derailed 0	0	0	0	(2) Total Derailed 0	0	0	0

64. Equipment Damage This Consist \$60,000.00	65. Track, Signal, Way, & Structure Damage \$3,500.00	66. Primary Cause Code H017	67. Contributing Cause Code H999
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 1	69. Firemen 0	70. Conductors 1	71. Brakemen 0	72. Engineer/Operator Hrs 8 Mi 45	73. Conductor Hrs 8 Mi 45
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No 2	78. Was EOT Device Properly Armed? 1. Yes 2. No 2
Fatal	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	1	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) N/A				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0	0	(1) Total in Equipment Consist 0	0	0	0
(2) Total Derailed 0	0	0	0	(2) Total Derailed 0	0	0	0


91. Equipment Damage This Consist \$0.00	92. Track, Signal, Way, & Structure Damage \$0.00	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West	Code N/A		112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On 2/26/2010, at Brownville Junction, Maine, 3 Montreal, Maine & Atlantic (MMA) locomotives (MMA 8553-MMA 5017 and MMA 758) were set off at the west end of the back lead in Brownville Junction Yard. None of the hand brakes on the 3 locomotives were applied nor were the independent or automatic brake systems cut in on the 3 locomotives. The air trapped in the brake cylinders bled off and the brakes released. The locomotives rolled east uncontrolled down a 1% grade through Brownville Junction Yard for 3/4 of a mile resulting in a side collision with train #203's locomotives, (MMA 2001 and MMA 8578) which were on the Brownville Junction Running track (CP Main). The crew of train #203 were on the locomotives when they realized that a collision was imminent and jumped off just prior to impact.

One crew member sustained a sprained knee due to the jump. There was considerable damage to the locomotives and 2 locomotives were derailed. The cause of the accident was determined to be "failure to properly secure engines—railroad employees" H017, and a contributing cause "Other train operations/human factors H999". FRA's investigation determined that even though there was a job briefing conducted, there was no specific discussion of which of the three crew members would be tasked with securing the light locomotives when they were finally set off. At the time of the accident, it was dark, windy and sleeting and the temperature was hovering at 30 degrees.

138. NARRATIVE

Circumstances Prior to the Accident

Train #420, a single engineer job, reported for duty at the Derby Shops at 7:30 P.M. and after preparing and inspecting his unit he departed and operated his train to Brownville Junction, ME. Upon arrival at Brownville Jct Yard, train #420 performed various switching operations in preparation for train #202's arrival from Northern Maine Jct and train #001's arrival from Millinocket. Train #202 arrived shortly after train #420 had completed his first set of switching duties. After the arrival of #202 the two crews worked together switching out #202 and beginning to build #203 for a return trip to Northern Maine Jct.

Train #203 began making up their train on the east end of the CP Main, and the single engineer assignment the crew of #420 continued switching on the west end of the Yard. Train #001, arriving from Millinocket, called for permission to enter Brownville Jct Yard. The #420 was working on the west end of the yard, instructed #001 to hold at Van Horn Street Crossing until he was in the clear and ready for them to enter the yard limits. Once he was cleared up, the #420 engineer instructed the #001 to proceed into the west end of the yard, where the two crews met and held a job briefing.

After the job briefing concluded, several switching moves were performed by the crews of train #001 and train #420 as they set off cars from train #001. After setting cars on the back lead, the cars were picked up and taken by Train #203 down to the east end of the yard and placed into the consist they had built for their return to Northern Maine Junction. Train #001 then set out 3 light locomotives (MMA 8553, MMA 5017, and MMA 758) on the back lead. The crews of train #001 and train #420, then picked up 2 different locomotives and doubled their trains together. When train #001 was made up, it departed the yard heading west to Canada.

The Accident

As soon as train #001 departed the yard the single engineer on train #420 noticed that the 3 light locomotives were no longer on the back lead where they had been set out. Upon noticing that the locomotives had

apparently moved he attempted to radio the crew on train #203 who were still working on the other end of the yard, in an attempt to warn them that the light locomotives might be moving towards them. Receiving no response from the crew on train #203, the lone engineer proceeded to get his remote control locomotive in order to go to the other end of the yard to check on the crew of train #203.

Before he was able to get his locomotive set up to move the lone engineer overheard the Rail Traffic Controller (RTC) call the conductor on train #001 and ask him if he had set a hand brake on the 3 locomotives that they had set off at Brownville Jct. The conductor of train #001 replied that he thought the lone engineer of train #420 had secured the locomotives. The RTC said that all 3 locomotives had rolled through the yard uncontrolled and collided with the side of train #203's power. The results of the collision were that locomotive 8553 was completely derailed and listing with considerable side damage, including a punctured fuel tank with a release of approximately 300 gallons of diesel fuel. Locomotive 5017 had one truck completely derailed and significant side damage. The locomotives on train #203 weren't derailed, but they both had considerable side damage. The track damage was minor due to the fact that the derailed equipment did not move far after it derailed.

Analysis and Conclusions

Analysis

Discussions with MMA mechanical and operations personnel revealed that the three light locomotives that were set off by train #001 were found after the accident with no hand brakes applied and the brake valves were all cut out. This was confirmed by interviewing the crew members of train #001 and the single engineer of Train #420. The crew members, all three of whom were qualified locomotive engineers, had each thought the other crew member secured the air brakes and applied the hand brakes on the light locomotives.

Conclusion

The 3 locomotives were not secured properly in accordance with the MMA operating rules. Not being secured in the proper fashion allowed the brakes to bleed off after the locomotives were set off on the back lead. Additionally, not having any hand brakes applied allowed the light locomotives to roll free for 3/4 of a mile and collide with Train #203's locomotives which were at the east end of Brownville Jct Yard.

Analysis

Interviews with the crews of trains #001 and #420 disclosed that the job briefing did not include specific discussion as to who would be responsible for properly securing the 3 locomotives and applying the hand brakes once they were set off. MMA's Air Brake and Train Handling Rules place the responsibility for locomotives on the engineer of the consist.

Conclusion

A more thorough job briefing would have included a discussion of which crew member would be responsible for ensuring that the 3 locomotives were properly secured prior to their departure.

Analysis

Federal Railroad Administration (FRA) mechanical personnel performed testing on the 3 locomotives that had rolled uncontrolled through Brownville Jct Yard. FRA's testing disclosed that there was leakage on the brake cylinders of the light locomotives that allowed the independent brakes to release after just 27 minutes as shown on the event recorder read outs after the accident.

Conclusion

Leakage of the air brake system on the 3 locomotives which were set off by train #001 allowed the independent brakes to release.

Fatigue Analysis

FRA obtained fatigue-related information for the 10-day work history preceding the accident for the engineer

and conductor of train #001 and engineer of train #420.

Conclusion

Upon analysis of that information, FRA concluded fatigue was not a factor in this accident.

Analysis-Toxicological-Testing

The carrier performed FRA required testing on the engineer and conductor of train #001 and the engineer of train #420.

Conclusion

The results indicated that Intoxication was not a factor in this accident.

Probable Cause & Contributing Factors

The probable cause of the accident was the failure of the crews on train #001 and/or #420 to secure the 3 locomotives according to Federal regulation, 49 CFR 232.103(n) and railroad operating rules. An incomplete job briefing may have also contributed to the cause.