

Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2010-18

Dakota, Missouri Valley & Western Railroad, Inc. Washburn, ND March 25, 2010

FEDERAL RAILE					FRAFA	ACTUA	L RAII	LROAD	AC	CIDI	ENT I	REPOR	Т	I	FRA F	ile#	HQ-201	0-18	
1.Name of Railroad (1a. Alphabetic Code					1b.	b. Railroad Accident/Incident No.											
Dakota, Missouri V		DMVW						DE0325518											
2.Name of Railroad C N/A								N/A						b. Railroad Accident/Incident No. N/A					
3.Name of Railroad O N/A		3a. Alphabetic Code N/A						b. Railroad Accident/Incident No. N/A											
4.Name of Railroad F Dakota, Missouri V		4a. Alphabetic Code DMVW					4b. 1	b. Railroad Accident/Incident No. DE0325518											
5. U.S. DOT_AAR G								6. Date of Accident/Incident					7. 1	7. Time of Accident/Incident					
							Month 03			Day 25 Year 2010			١	11:30: 🗸 AM			F	PM	
1 77						ollision	'					Explosion		/ 1 .1				С	ode
(single entry in cod	de box)				`	g collision		RR grad Obstruc		ossing	-			ure	narra		п	1 (01
3. Rear end collision 6. Brown 9. Cars Carrying 10. HAZMAT Cars						n Train co	llision Cars Relea		поп	1	12. 12. Peo _l	Other imp	acts		13. Div	vision	1		
HAZMAT	11	Damaged			0		ZMAT	0			Evacuat			0			System		
14. Nearest City/Tow	n					15. Mile	-	-4 <i>I</i> -1	16		Abbr	Code	17	. County					
	W	ashburn				<u> </u>		8.5			N/A ND			MCLI			AN		
18. Temperature (F)	,	19. Visib	ility Dawn	(sing	le entry)	Code		Veather (single e . Clear 3. Rain			lloot	Code		1		of Track		C	Code
(specify if minus) 25	F		Day	4.D		2		Clear 3. Cloudy 4.	5.Sleet 6.Snow 2			2	1. Main 3. Sio 2. Yard 4. Inc					1	
22. Track Name/Nu	mber				_	23. FRA Clas	Track s (1-9, X)	Code			24. Annual Track Density (gross tons in			25. Time Table 1. North				C	Code
		Sii	ngle Ma	in Tr	ack		ODED 4	1 millions)			8.	7		2. Sout	h 4.	West		1	
26 77 677 1		T		4 337	1			ATING TR			G 1	27. Was	Fanis			lao i	T	1 (6	
26. Type of Equipme Consist (single er		Freight tra Passenger				Yard/swi Light loc		A. Spec. N	loW	Equip.	Code	1	equip nded?	oment (Code	28.	Train Nur	nber/S	symbol
Consist (single cr		_			of cars 9.	_		1 1.			Yes	es 2. No 1 DMN			DMVV	V #136	5		
29. Speed (recorded					Method(s)			nter code(:	s) th	at app	oly)	1		31a. Rem	otely C	ontro	olled Loco	motiv	re?
R - Recorded a. ATCS								g. Automatic block m.Special instructions n. Other than main track						0 = Not a remotely controlled					
E - Estimated 13 MPH R b. Auto train control h.								ent of traffic table/train orders o. Positive train control						1 = Remo		•			
30. Trailing Tons		onnage,		d.	Auto trair Cab	j.Track warrant control p. Other (Specify in narrat					ıtive)								
excluding power units) e. Traffic 2380 f. Interlocking							k. Direct traffic control 1. Yard limits Code(s						remote control transmitter						
22 Principal Car/Uni		a. Initial a	and Nur			on in Train			1	1	N/A N								0
32. Principal Car/Unit (1) First involved	ι	a. Illiuai a	ana Nui	noer	b. Positio	on in Train	C. LC	oaded(yes/no	"					ed for drug positive in		ol use	Alcohol	⊥ D	rugs
(derailed, struck, e	etc)	DMV	W00950	04		1		N/A		the appropriate box.				•			0	1	0
(2) Causing (if med	chanicai	!	0			0		N/A	N/A 34. Was this con			consist tra	nsport	ing passen	gers? (Y/N)			N
35. Locomotive Units a. Head Mid Tr.				rain c. Remote		ar End	36. C	36. Cars			a F		aded b. Pass.	c Fre	Emp	oty d. Pass.	e Ca	aboose	
(1) Total in Train	1	End 5	b. Man		0	0	0		al in	Equip	ment C		31	0		3	0	0. 0.	0
(2) Total Deraile	d	3	0	,	0	0	0	(2) Tot	al D	erailed			0	0	()	0		0
37. Equipment Dama	ige			_	ck, Signal, V		1	39. Pri	mor	, Conc.									
This Consist	8	6250,000.00	· I		cture Dama		250,000.0	Code	mar	y Cause T002				40. Contributing Cause Code T001					
		Number										Len	gth of	h of Time on Duty					
41. Engineer/	42. Fir	emen	4	13. Co	nductors	44. Bra	kemen	45. En	45. Engineer/Operator					46. Conductor				20	
Operators 1		0 1					1		I	Irs	6	Mi 30)	Hrs 6 Mi 30				30	
Casualties to:	ies to: 47. Railroad Employees 48. Train Passengers						Other		50. EOT Device?					51. Was EOT Device Properly Armed?					
Fatal		1 0					0	1. Yes 2. No 1					1. Yes 2. No 1						
Nonfatal 0 0							52. Caboose Occupied by Crew? 1. Yes 2					2. No	No N/A						
						OI	PERATI	ING TRA	IN #	2									
53. Type of Equipme	111	Freight tra				Yard/swit	-	A. Spec. M	oW	Equip.	Code	54. Was		ment C	ode	55. 7	Гrain Nun	nber/S	ymbol
Consist (single en	u y j	Passenger Commuter		•	_	Light loce				1	NT/A		nded?	1 37/4			/A		
56. Speed (recorded					of cars 9. Method(s)	Maint./ins	•	r N/A 1. Y (enter code(s) that apply)					Yes	2. No N/A N/A Sa. Remotely Controlled Locomotive?					
R - Recorded	speed, if	uvanable)	Code	1	ATCS	•	on (<i>e</i>) . Automat				<i>ny)</i> al instru	ctions		0 = Not a	-			,,,,ouv	· .
E - Estimated	0	MPH	N/A	1	Auto train	ū				•		ain track		1 = Rem					

Form FRA F 6180.39 (11/2006) Page 1 of 7

FEDERAL RAILR					FRAFA	ACTUAI	RAILR	OAD AC	CIDENT REP	ORT	F	RA File #	HQ-201	<u>0-18</u>	
57. Trailing Tons (groest) excluding power	d. e.	Auto train Cab Traffic Interlocking	j.T k.	Γime table/tr rack warran Direct traffic ard limits	nt control p	o. Positive train control. Other (Specify in Code(s) N/A N/A N/A N/A	narrative)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A							
59. Principal Car/Uni	it	a. Initial	and N	Vumber	b. Posit	ion in Train	c. Load	led(yes/no)	60. If railroad emp	oloyee(s) tes	ted for dru	g/alcohol ι	ıse,		
(1) First involved (derailed, struck, etc) 0					0		N/A	enter the numb		were positive in Alcohol Drugs N/A N/A					
(2) Causing (if mechanical cause reported) 0					0	1	N/A	61. Was this cons	ist transport	ing passen	N/A				
<u> </u>		a. Head End	b. M	Mid T			Rear End d. Manual c. Remote			a. Freight	aded Er		npty d. Pass.	e. Caboose	
(1) Total in Train		0		0	0	0	0 0		Equipment Consist	0	0	0	0	0	
(2) Total Derailed		0		0	0	0	0	(2) Total D	erailed	0	0	0	0	0	
64. Equipment Dama	ige		П	65. Tra	ck, Signal,	Way,		66. Primar	y Cause			ributing Ca	use		
This Consist		\$0.00			tructure Dar	nage	\$0.00	Code		N/A	Code			N/A	
50 P (to)	CO 15:		r of C	70 Co	mbers	71. Bral	Faman	70 Engine	/0	Length of		-			
68. Engineer/ Operators 0	69. Fir	emen 0		/U. CU	0	/1. Diai	0	_	eer/Operator Hrs 0 M	i 0	73. Conductor Hrs		0	Mi 0	
Casualties to:	74. Railr	oad Emplo	yees	75. Trai	in Passenge	rs 76. Oth	er	77. EOT Device?					ce Properly	Armed?	
Fatal		0			0		0		es 2. No	N/A	1.	Yes	2. No	N/A	
Nonfatal		0	\dashv		0		0	79. Caboo	se Occupied by Crev					NT/A	
NOmatan		Ü			U	0		G TRAIN	1. Yes	2. No				N/A	
80. Type of Equipmen	nt 1.	Freight tra	in	4. Wor	rk train 7.	Yard/switc				Was Equipn	nent Co	ode 82.	Train Num	nber/Symbol	
Consist (single en	try) 2.	Passenger Commuter	train	5. Sing	gle car 8.	Light loco((s).	Attended? N/A 1. Yes 2. No N/A N/A							
83. Speed (recorded)						of Operation		r code(s) th	at apply)		85a. Remo	otely Contr	olled Loco	motive?	
R - Recorded				a	ATCS		Automatic b	nock	n.Special instructions . Other than main tra			remotely c			
E - Estimated	N/A	MPH	0		Auto train		Current of to	rame	. Other than main tra o. Positive train contr			ote control te control t	•		
=	gross ton	nage,	_		Auto train Cab		rack warran		o. Other (Specify in			te control	Owei		
excluding power	r units)	27/1			Traffic		Direct traffic		Code(s)			ter - more ontrol tran			
		N/A		f.	Interlocking	g l.Y	ard limits		N/A N/A N/A	N/A N/A	remote c	Ontroi uan	smitter	N/A	
86. Principal Car/Uni	it	a. Initial	and N	lumber	b. Positi	ion in Train	c. Load	led(yes/no)	87. If railroad empl	•	_	•			
(1) First involved (derailed, struck,	etc)		0			0		N/A	enter the numb the appropriate		positive i	n	Alcohol N/A	Drugs N/A	
(2) Causing (if mechanical 0					†	0	1	N/A			ting passengers? (Y/N) N/A				
89. Locomotive Unit		a. Head		Mid T	rain		r End	90. Cars			aded		npty		
(1) Total in Train	_	End 0	b. M	Ianual 0	c. Remote	d. Manual	c. Remote		Equipment Consist	a. Freight	b. Pass.	c. Freight	d. Pass.	e. Caboose	
	+		_			0			• •				<u> </u>		
(2) Total Deraile	ı	0	Ь.,	0	0	0	0	(2) Total D		0	0	0	0	0	
91. Equipment Dama This Consist	ige I	\$0.00			ck, Signal, ' ructure Dan		\$0.00	93. Primary	y Cause Code	N/A	94. Contr Code	ributing Ca	use	N/A	
III. 00			r of C	Crew Me		lage	Ψ0.00	 		Length of		uty		IV/A	
95. Engineer/	96. Fire				97. Conductors 98. Brake			99. Engine	eer/Operator		100. Cor				
Operators 0		0			0		0		Hrs 0 M	ii 0	Hrs 0 Mi 0				
Casualties to:	101. Rai	lroad Emp	loyees	s 102.	Гrain	103. Otl	her	104. EOT	2 N-		105. Was	-			
Fatal		0			0		0	1. Y	es 2. No ose Occupied by Cro	N/A ew?	1. Yes 2. No N/A				
Nonfatal 0 0								1. Yes 2. No N/A							
		Highwa	ay Us	ser Invo	olved			Γ		Equipmen	t Involved	1			
107. C. Truck-T	railer.	F Rus		I Other	Motor Veh	icle	Code	111. Equip		(standing)	6.Light	Loco(s) (n	noving)	Code	
A. Auto D. Pick-Up	Truck (G. School l	Bus]	K. Pedes	strian		NT/A	1.Train(units pulling) 4.Car(s) (moving) 7.Light(s) (standing)							
B. Truck E. Van 108. Vehicle Speed	J		ycle 1 109.	M. Othe	er (spec. in i		N/A Code	2.Train(units pushing) 5.Car(s)(standing) 8.Other (specify in narrative) N/A 112. Position of Car Unit in							
(est MPH at in	mact)	N/A		rth 2 Sc	geographi outh 3 East		N/A	112. Positio	on of Car Unit in		0				


Form FRA F 6180.39 (11/2006) Page 2 of 7

	ENT OF TRAN			FRAF	ACTU	AL RAILR	OAD AC	CCII	DENT F	REPC	RT	F	RA File # <u>HQ-2010</u>	-18
110. Position						Code	113. Circu	ımstaı	nce					Code
	1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User													N/A
	highway user at					Code	114b. W	as the	ere a hazar	dous m	aterials releas	ie		Code
in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither 1. N/A 1. Highway User 2. Rail Equipment 3. Both 4. Neither												N/A		
1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A 1. Highway User 2. Rail Equipment 3. Both 4. Neither 114c. State here the name and quantity of the hazardous materials released, if any.												IN/A		
114c. State he	ere the name and	quantity	y of the haza	ardous materia	ıls release	d, if any. N/A								
115. Type	115. Type 1.Gates 4.Wig Wags 7.Crossbucks 10.Flagged by crew 116. Signaled Crossing Code 117. Whistle Ban											117. Whistle Ban	Code	
Crossing 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs 11.Other (spec. in narr.) (See instructions for codes) 1. Yes Warning 3.Standard FLS 6.Audible 9.Watchman 12.None 2. No														
Code(s)	N/A N	N/A	N/A	N/A	N/A	N/A	N/A	1	N/A 3. Unknown					N/A
	118. Location of Warning 1. Both Sides Code with Highway Signals Code U20. Crossing Illuminated by Street Lights or Special Lights											Code		
2. Side of	Vehicle Approac		1. Yes	1. Yes										
3. Opposite	e Side of Vehicle	ach		2. No 3. Unknown		N/A			2. No 3. Unknow	n		N/A		
121.	122. Driver's G	ender	Code 123		e Behind or in Front of Co			de 124. Driver 1. Drove around or thru the Gate 4. Stopped on Crossin						Code
Age	1. Male 2. Female			1. Yes	r was Suu 2. No	3. Unknowi					then Proceede		5. Other (specify in	
0	2. Pelliale		N/A	1. 103	2.110	3. Challowi	N/A	A	3. Did no	ot Stop			narrative)	N/A
125. Driver Pa		Code				y (primary ob								Code
Highway V		N/A		Permanent Str			ng Train 5.	_			Other (spec		narrative)	N/A
1. Yes 2. No	3. Unknown	19/2	2. 3	standing Railr	oad Equip	ment 4. Topo	graphy 6.	High					** 1 . 1 . 2	Code
Casualties to: Killed Injured						ed 2.Injured 3.	,					2. No	N/A	
129. Highway-	Rail Crossing Us	0	1	ghway Vehicle t. dollar damaş		roperty Damage 0 131. Total Number of Highway-Rai (include driver)					Highway-Rail Crossin 0	g Users		
132. Locomoti	ive Auxiliary Lig	ghts?		•		Code	133. Locomotive Auxiliary Lights Operational?				Code			
1. Y	es	No			1.	1. Yes 2. No								
134. Locomotive Headlight Illuminated? Code 135. Locomotive Audible Warning Sounded?												Code		
1. Yes 2. No N/A 1. Yes 2. No											N/A			

Form FRA F 6180.39 (11/2006) Page 3 of 7

FRA File # <u>HQ-2010-18</u>

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



Form FRA F 6180.39 (11/2006) Page 4 of 7

137. SYNOPSIS OF THE ACCIDENT

A northward Dakota, Missouri Valley & Western Railroad (DMVW) Freight Train #136 derailed on March 25, 2010, at 11:30 a.m., CDT. The accident occurred near Washburn, North Dakota (approximately 42 miles north of Bismarck) on single main track, at milepost 518.5, of the Missouri Valley Subdivision.

The train consisted of five locomotives, 31 loaded and 13 empty freight cars. The first three locomotives derailed as train #136 was operating on a 0.271 percent descending grade and entering a 1 degree 40 minute left-hand curve. The train traveled approximately 355 feet after the engineer induced an emergency application of the train air brakes.

The two leading locomotives derailed and rolled down an embankment as the track's sub-grade suddenly collapsed (slipped out) from beneath the locomotives. The third locomotive derailed upright and was hovering over approximately 20 feet of skeleton track with its lead truck derailed. The two leading locomotives landed on the bank of Turtle Creek and began leaking approximately 2,000 gallons of diesel fuel; however the diesel fuel was contained before it entered Turtle Creek.

The conductor was fatally injured and the engineer received non-life threatening injuries as a result of this accident. The brakeman who was shadowing the train's movements in a motor vehicle was not injured. The railroad reported total monetary damages of \$500,000; with track damages of \$250,000 and equipment damages of \$250,000.

At the time of the derailment it was daylight with cloudy skies and a temperature of 25 degrees Fahrenheit.

A contributing factor to this accident was the failure of the track's drainage facilities, due to obstruction of its key components. At the point-of-derailment (POD), at milepost 518.5 the drainage ditch was obstructed by debris, vegetation, and silting which prevented run-off water from draining to the culverts located at mileposts 518.43, 518.42, 518.41, 518.40, and 518.39. The outlets of the five culverts were also obstructed by silting and vegetation. The combined obstructions of the drainage ditch and culverts caused the drainage and water-carrying facilities to deteriorate to the point that it allowed the track's sub-grade to become saturated. (FRA Accident/Incident code T001)

The probable cause of the accident was roadbed saturation. (FRA Accident/Incident code T002)

138. NARRATIVE

Circumstances Prior to the Accident:

The crew of DMVW Freight Train #136 consisted of a locomotive engineer, a conductor, and a brakeman. They first went on duty at 5 a.m., CST, on March 25, 2010, at Bismarck, North Dakota. This was the home terminal for this crew. Each of the crewmembers had received the required statutory off-duty period prior to reporting for duty.

The assigned freight train consisted of five locomotives, 5 loaded cars and 5 empty cars (10 total cars), 800 trailing tons, and was 600 feet in length. It was a freight train scheduled to travel from Bismarck to Max, North Dakota, a distance of approximately 99.3 miles.

The Class I (initial terminal) air brake test was performed at Bismarck at 6:30 a.m. The train departed Bismarck at approximately 6:40 a.m.

The crew had a work order to pick up 8 empty cars at Arnold, North Dakota. They arrived at Arnold at 7:40 a.m., and added the 8 empty cars to their consist. Upon completion of the work and their Class I air brake test, they departed Arnold at 7:55 a.m. The crew also had a work order to pick up 26 loaded cars at Wilton, North Dakota. They performed the work at Wilton, made a Class I air brake test, and departed Wilton at 10:40 a.m. Departing Wilton, their train consisted of five locomotives, 31 loaded cars and 13 empty cars (44 total cars), 4,420 trailing tons, and was 2,420 feet in length.

As the train approached the derailment area, the locomotive engineer was seated at the controls on the right (east) side of the leading locomotive. The conductor was seated on the left (west) side of the cab of the

Form FRA F 6180.39 (11/2006) Page 5 of 7

leading locomotive.

Interviews conducted by the Federal Railroad Administration (FRA) determined the trip was uneventful prior to the derailment.

Approaching the derailment site from the south, traversing northward, there is tangent track from milepost 519.5 to milepost 518.56, followed by a 1 degree 40 minute curve to the left on single main track. The derailment occurred in the 1 degree 40 minute curve to the left. The track has a 0.15 percent descending grade from milepost 519.5 to milepost 519.25, a 0.8 percent descending grade from milepost 519.25 to milepost 518.93, and a 0.271 percent descending grade from milepost 518.93 to milepost 518.12. There is one public road crossing located at milepost 519.6.

The method of operations on the DMVW's Missouri Valley Subdivision is by General Code Of Operating Rules (GCOR) Rule 6.14 (Restricted Limits). The train was traveling timetable and geographical north on single main track at a recorded speed of 13 mph while approaching the POD. The speed was recorded by the event recorder of the controlling locomotive. The maximum authorized speed for this segment of track on the Missouri Valley Subdivision is 10 mph, as designated by the current DMVW Timetable No. 107 Effective: February 12:01 a.m., Sunday, February 17, 2008.

The Accident:

The train was traveling northward at 13 mph when the engineer observed two railroad crossties hanging near a clump of grass or debris which was next to the track. The engineer initiated an emergency application of the train air brakes approximately 263 feet ahead of the two hanging crossties and a total of 350 feet ahead of milepost 518.5 which was the POD. The leading locomotive rolled to the west and slid down the bank. The second locomotive derailed and rolled on top of the lead locomotive. The third locomotive was hovering over approximately 20 feet of skeleton track with its lead truck derailed. The conductor, just prior to the derailment, went out the back door on the engineers side of the locomotive to jump. The engineer was going to follow the conductor out the back door but did not make it and was thrown to the conductor's side of the locomotive. The engineer ended up on the control stand at the bottom of the embankment when the track collapsed beneath the locomotive.

Emergency Response:

The North Dakota Highway patrol was at the scene first arriving at 12:38 p.m and was the lead state agency in-charge of the accident site. The Washburn Fire Department, Wilton Fire Department, and McLean County Sheriff's Department responded and aided in conducting the rescue operations. The conductor was fatally injured and the engineer was transported to St. Alexius hospital in Bismarck by ambulance where he was treated and released with non-life threatening injuries. The brakeman who was shadowing the train's movements in a motor vehicle along the highway, was not injured. The two locomotives that rolled and slid down the embankment landed next to Turtle Creek which drains into the near-by Missouri River. The two locomotives leaked approximately 2,000 gallons of diesel fuel; however the diesel fuel was contained and did not enter Turtle Creek. There was no evacuation ordered and no release of hazardous materials.

Post-Accident Investigation:

On March 25, 2010 the FRA began an investigation of this accident. FRA's Region 8 management assigned a Track Safety Inspector as Investigator/Inspector-in-Charge (IIC) of this investigation. The IIC was assisted by an Operating Practices Supervisory Railroad Safety Specialist, a Rail Integrity Safety Specialist, and a Operating Practices Safety Inspector. FRA has completed its investigation and the following analysis and conclusions as well as any possible contributing factors and the probable cause represent the findings of the FRA's investigation.

Analysis and Conclusions:

Analysis-Point-of-Derailment (POD): FRA conducted an on-site investigation to determine the exact point-of-derailment.

Conclusion: FRA's investigation of the derailment site determined that the initial POD was at milepost 518.5, on a descending grade track. The maximum authorized speed for this segment of track on the Missouri

Form FRA F 6180.39 (11/2006) Page 6 of 5

FRA File # HQ-2010-18

Valley Subdivision is 10 mph, as designated by the current DMVW Timetable NO. 107 Effective: 12:01 a.m., Sunday, February 17, 2008. The train traveled approximately 355 feet after the engineer induced an emergency train air brake application.

Analysis-Locomotive event recorder from DMVW train 136: The event recorder from the leading (controlling) locomotive of DMVW Train #136 was downloaded and analyzed.

Conclusion: An inspection of the data printout from the lead locomotive event recorder indicated that the train was being operated at 13 mph at the location of the POD. The maximum authorized track speed at this location is 10 mph. DMVW train 136 was operating 3 mph over maximum authorized track speed at this location. The event recorder also indicated no unusual events related to train handling.

Analysis-Fatigue: FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

Conclusion: Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

Analysis-FRA Post-Accident Toxicology Testing

This accident met the criteria for FRA Post Toxicology Testing, as required under Title 49 CFR, Part 219, Subpart C. The crew provided blood and urine samples at an Occupational Health Services Collection Facility.

Conclusion: Tests were negative for all three employees tested.

Possible Contributing Factors:

A contributing factor to this accident was the failure of the track's drainage facilities, due to obstruction of its key components. At the point-of-derailment (milepost 518.5) the drainage ditch was obstructed by debris, vegetation, and silting which prevented run-off water from draining to the culverts located at mileposts 518.43, 518.42, 518.41, 518.40, and 518.39. The five culverts were also obstructed by silting and vegetation. The combined obstructions of the drainage ditch and culverts caused the drainage and water-carrying facilities to deteriorate to the point that it allowed the track's sub-grade to become saturated. (FRA Accident/Incident code T001)

Probable Cause:

The probable cause of this accident was roadbed saturation (FRA Accident/Incident code T002).

Form FRA F 6180.39 (11/2006) Page 7 of 7