



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2009-06***

***Long Island Railroad (LIRR)  
Syosset, NY  
February 13, 2009***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Long Island Rail Road [LI ]			1a. Alphabetic Code LI			1b. Railroad Accident/Incident No. GR20090201					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident No. N/A					
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A			3b. Railroad Accident/Incident No. N/A					
4. Name of Railroad Responsible for Track Maintenance: Long Island Rail Road [LI ]			4a. Alphabetic Code LI			4b. Railroad Accident/Incident No. GR20090201					
5. U.S. DOT_AAR Grade Crossing Identification Number 338308F			6. Date of Accident/Incident Month 02 Day 13 Year 2009			7. Time of Accident/Incident 08:59:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM					
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision					
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts					
			13. Other (describe in narrative)			Code 07					
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		12. People Evacuated 0		13. Division SYSTEM			
14. Nearest City/Town Syosset			15. Milepost (to nearest tenth) 27.08		16. State Abbr Code N/A NY		17. County NASSAU				
18. Temperature (F) (specify if minus) 32 F		19. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		Code 2		20. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		Code 1			
21. Type of Track 1. Main 3. Siding 2. Yard 4. Industry			Code N/A								
22. Track Name/Number Port Jefferson #2			23. FRA Track Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) N/A		25. Time Table Direction 1. North 3. East 2. South 4. West				
			Code 3								
OPERATING TRAIN #1											
26. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 2		27. Was Equipment Attended? Code 1. Yes 2. No   1			
28. Train Number/Symbol 1612											
29. Speed (recorded speed, if available) R - Recorded E - Estimated 69 MPH   R			Code R			31. Method(s) of Operation (enter code(s) that apply)					
30. Trailing Tons (gross tonnage, excluding power units) N/A			Code N/A			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
			Code 0								
32. Principal Car/Unit			a. Initial and Number LI7764		b. Position in Train 1		c. Loaded (yes/no) yes				
(1) First involved (derailed, struck, etc)							33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol   Drugs N/A   N/A				
(2) Causing (if mechanical cause reported)			0		0		N/A				
						34. Was this consist transporting passengers? (Y/N) Y					
35. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		36. Cars			
								a. Freight b. Pass. c. Freight d. Pass. e. Caboose			
(1) Total in Train		1		0 0		0 0		(1) Total in Equipment Consist 0 9 0 0 0			
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed 0 0 0 0 0			
37. Equipment Damage This Consist \$46,122.00			38. Track, Signal, Way, & Structure Damage \$12,380.00			39. Primary Cause Code M303			40. Contributing Cause Code N/A		
Number of Crew Members					Length of Time on Duty						
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 1		45. Engineer/Operator Hrs 4 Mi 25		46. Conductor Hrs 4 Mi 25	
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other		50. EOT Device? 1. Yes 2. No   N/A		51. Was EOT Device Properly Armed? 1. Yes 2. No   N/A	
Fatal		0		0		1					
Nonfatal		0		0		0		52. Caboose Occupied by Crew? 1. Yes 2. No   N/A			
OPERATING TRAIN #2											
53. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		54. Was Equipment Attended? Code 1. Yes 2. No   N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) R - Recorded E - Estimated 0 MPH   N/A			Code N/A			58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		
			a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track								

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No N/A	79. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
E - Estimated	N/A MPH 0	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
84. Trailing Tons (gross tonnage, excluding power units)	N/A	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A
		N/A N/A N/A N/A N/A	

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0


91. Equipment Damage This Consist	\$0.00	92. Track, Signal, Way, & Structure Damage	\$0.00	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No N/A	105. Was EOT Device Properly	1. Yes 2. No N/A	106. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code	111. Equipment	3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)	Code			
	A			1			
108. Vehicle Speed (est. MPH at impact)	22	109. geographical	Code	112. Position of Car Unit in			
		1. North 2. South 3. East 4. West	2	0			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code 3				113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code 1											
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code 4				114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A											
114c. State here the name and quantity of the hazardous materials released, if any. N/A																							
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code 01 03 06 07 N/A N/A N/A				116. Signaled Crossing (See instructions for codes)				Code 01											
												117. Whistle Ban 1. Yes 2. No 3. Unknown				Code 2							
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code 1				119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code 2				120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown				Code N/A			
121. Age 86		122. Driver's Gender 1. Male 2. Female		Code 1		123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code 2		124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop				Code 3							
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code 2				126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code 8							
Casualties to:				Killed		Injured		127. Driver 1. Killed 2. Injured 3. Uninjured				Code 1		128. Was Driver in the Vehicle? 1. Yes 2. No				Code 1					
129. Highway-Rail Crossing Users				1		0		130. Highway Vehicle Property Damage (est. dollar damage) 25000				131. Total Number of Highway-Rail Crossing Users (include driver) 1											
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code 1				133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code 1											
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code 1				135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code 1											

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



## 137. SYNOPSIS OF THE ACCIDENT

On February 13, 2009, at approximately 8:59 a.m. EST, eastbound Long Island Rail Road (LIRR) passenger train #1612 struck a single person occupied automobile at the Robbins Lane grade crossing in Syosset, NY. The automobile was traveling southbound on Robbins Lane. The automobile was being driven by an 86 year old male. The driver of the vehicle failed to stop at the lowered crossing gates and was struck by Long Island Rail Road train # 1612. The train was traveling at a recorded speed of 69 mph. The automobile was traveling at 22 mph and there were no indication of the auto trying to slow or stop for the crossing. The occupant of the automobile was killed. There were no other injuries to the crew or passengers. Robbins Lane is located at milepost 27.1 on the Port Jefferson Branch of the Long Island Rail Road. The DOT number is 338 308 F.

The weather was clear and 32 degrees F.

The probable cause of the collision was the failure of the operator of the vehicle to yield the right of way to the oncoming LIRR Passenger Train.

## 138. NARRATIVE

## CIRCUMSTANCES PRIOR TO THE ACCIDENT

LIRR Train #1612, carrying 285 passengers, departed Penn Station, N.Y. at 8:01 a.m. The eastbound passenger train was due at Huntington at 9:10 a.m. The crew consisted of one engineer, one brakeman, and one conductor. The locomotive engineer reported no unusual occurrences during the trip from Penn Station to the site of the accident. The locomotive event recorder substantiated the engineer's rendition. As Train #1612 approached Robbins Lane, it activated the grade crossing warning system, consisting of flashing lights and gates. This activation caused the gates to lower. The locomotive event recorder indicated that the engineer properly sounded the train horn as it approached the Robbins Lane crossing. The recorded train speed was 69 mph.

The automobile, driven by an 86 year old male, was a 2007 Lincoln Town Car. The automobile was being driven southbound on Robbins Lane. Robbins Lane is a four lane highway in a north/south direction. The speed limit on Robbins Lane is 35 mph.

The affected area is a 2 track territory in an east/west direction. Track # 1 is the north track and is closest to the entering gate of the automobile. Track # 1 is normally westbound. Track # 2 is normally eastbound and was the track that LIRR Train 1612 was traveling on the day of the accident. The Robbins Lane crossing is tangent track with clear visibility from the west.

The vantage point of the crew of the LIRR Train and the driver of the vehicle was unobstructed. Each had a clear view.

The weather was sunny and cold with the temperature 32° F. It was windy with gusts to 30 mph.

## THE ACCIDENT

The accident occurred at 8:59 a.m. The automobile entered the grade crossing under the horizontal gate (north #1), crossed track # 1, and drove in the path of oncoming LIRR Train #1612 on track # 2. The automobile was struck on the front passenger side and shoved approximately 1400 feet from point of impact. The driver was killed instantly. LIRR Passenger Train #1612 was operating normally with no unusual occurrences. The crew of LIRR Train # 1612 initiated an emergency brake application upon observing the automobile enter the crossing.

## ANALYSIS AND CONCLUSION

### ANALYSIS

The locomotive event recorder was downloaded and provided the following information. LIRR Passenger Train #1612 was traveling at 69 mph with an MAS cab signal. The MAS cab signal allows for a speed up to 80 mph. Upon approach to the Robbins Lane crossing, the engineer sounded 2 short and 1 long horn bursts. It took LIRR Train #1612 approximately 24 seconds to decelerate from a speed of 69 mph to full stop, after the crew initiated the emergency brake application.

The signal event recorder at Robbins Lane was downloaded and provided the following information. The recorded times and actual times are four minutes apart. The recorded times indicate four minutes later than actual time. At 9:00:15 a.m., the Robbins Lane crossing was activated with the approach of LIRR Train #1612. At 9:00:29 a.m., the 1GRP relay (indicates the position of the # 1 north gate) picked up. At 9:00:31 a.m., the 2GRP relay (indicates the position of the # 2 south gate) picked up. When these gate position pick up relays indicate that the gates are within 5 degrees of fully horizontal they are energized. This indicated that the warning system flashing lights were functioning and the gates were horizontal with the approach of LIRR Train #1612. At 9:00:50, gate # 1 relay 1GRP drops, indicating that the gate has raised more than 5 degrees from fully horizontal. The 2GRP relay remains up, indicating that the south # 2 gate remains fully horizontal. Five seconds later, at 9:00:55 a.m., the 1 GRP again picked up, indicating that the north gate was fully horizontal. It is at this time that the automobile was struck by LIRR Train #1612. At 9:01:05 a.m., the 1GRP relay dropped and at 9:01:06 a.m., the 2GRP dropped. This indicates that LIRR Train #1612 has passed the crossing and deactivated the warning system. The north and south gates were now vertical.

An attempt to determine the reason that north gate #1 rose for 5 seconds before again becoming fully horizontal was made. It should be noted that the relay that controls the motors for the gates operate both gates. Therefore, if there had been a relay failure, both gates would have raised. The fact that the # 2 gate remained horizontal eliminates the possibility of a relay failure. Crossing gates are motor driven up and gravity driven down. It takes a minimum amount of effort to manually lift a crossing gate from a fully horizontal position.

The Lincoln Town Car has a hood height of 38 inches. The hood height is lower than a horizontal crossing gate. On February 20, 2009 a re-enactment was made utilizing a Ford Crown Victoria, which has the same hood height as the Lincoln Town Car. The re-enactment consisted of driving the Crown Victoria under the horizontal gates at various speeds to determine if the five seconds in question was caused by the Lincoln Town Car on the day of the accident. At 18 mph the crossing gate lifted from the fully horizontal position for four seconds, allowed the car to continue entering the crossing, and returned to a fully horizontal position. The windshield shattered at 18 mph so for safety reasons further testing was discontinued. It is estimated that to obtain the five second discrepancy the automobile would have to be traveling approximately 22 mph as it entered the crossing.

Further FRA analysis reveals that 22 mph is the approximate speed that the automobile would have to be traveling in order to be positioned in front of LIRR Passenger Train #1612. The automobile had 2 seconds from the time the gate indicated not fully horizontal to travel the 70 feet from the warning gate to the center of track 2. Mathematical computation puts the vehicle speed at approximately 22 mph.

The Long Island Rail Road also downloaded the event recorder at the crossing for the dates of February 14, 15, and 16, 2009. There were no exceptions taken to the functioning of the crossing system.

### CONCLUSIONS



Based on the information provided by the event recorders, the re-enactment, and a time/distance computation, FRA determined that the automobile passed through the warning gate at approximately 22 mph. The vehicle hit the gate, forcing it up for 5 seconds as the car drove through the crossing and into the path of oncoming LIRR Train #1612.

The probable cause of the collision was the failure of the operator of the vehicle to yield the right of way to the oncoming LIRR Passenger Train.