

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2009-12

Southwestern Railroad (SWRR) Rosswell, NM March 30, 2009

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT ( FEDERAL RAILR	OF TRA OAD A	ANSPORT DMINIST	TATIC TRATI	ON ON	FRA FA	ACTUA	LRA	ILRO	DAD AG	CCIE	ENT	REPO	ORT		FRA Fi	le #	<u>HQ-200</u>	<u>)9-12</u>
1.Name of Railroad Operating Train #1									1a. Alphabetic Code					1b. Railroad Accident/Incident No.				
2.Name of Railroad Operating Train #2 N/A									Alphabetic	2b.	2b. Railroad Accident/Incident No. N/A							
3.Name of Railroad O N/A	3a. Alphabetic Code N/A					3b.	b. Railroad Accident/Incident No. N/A											
4.Name of Railroad R Southwestern RR C	4a. Alphabetic Code SW					4b.	b. Railroad Accident/Incident No.											
5. U.S. DOT_AAR Grade Crossing Identification Number 019918J									ate of Acc th 03	ident/Iı   Day	ncident 30	Year 2	009 7.	Time of A 05:4	ccident/ 47:	Incid	ent AM	V PM
8. Type of Accident/In	4. Side c	ollision		7. I	Hwy-rail c	rossing	; 10	0. Explo	sion-deto	I-detonation 13. Other				Code				
(single entry in cod	5. Rakin	g collision	I	8. F	RR grade c	crossing	g 1	1. Fire/v	/violent rupture (dei nar			ribe i tive)	n	07				
9. Cars Carrying		3. Rear e	nd colli	ision 'ars	6. Broke	n Train co	llision	9. ( leasing	Obstruction	n	12. Other impact			ts 13 Div				07
HAZMAT	AT Damaged/Derailed					HAZ	ZMAT	leasing	N/A		Evacuated			0			System	
14. Nearest City/Towr	<u> </u>					15. Milepost			1		te		. 1	7. County	1			
	-	Dexter				(to n	iearest te 1	<i>enth)</i> 117.1	<i>th</i> ) 7.1		Abbr Coo		ie M		CHAVES		ES	
18. Temperature (F)		19. Visit	oility	(sing	gle entry)	Code	20. W	Veather	r (single	entry)	entry)		ode	21. Type of Tra				Code
(specify if minus) 61	F	1. 2.	Dawn Day	3.D 4.I	usk Dark	2	2	2. Cloudy 4. Fog		in 5 g 6	n 5.Sleet		1	1. N 2. Y	lain 3. ard 4.	Indu	ng stry	1
22. Track Name/Nur	nber					23. FRA	Track	C	Code 2		nual Tr	ack Den	sity	25. Tin	ne Table	Direction		Code
		S	ingle m	ain tr	ack	Class (1-9, 2			4 (gross tons in millions)			ıs in	5.6		1. North 3. East		. East West	3
							OPER	ATIN	NG TRA	IN #1					2. 504			
26. Type of Equipment	nt 1.	. Freight tra	ain	4. Wo	ork train 7	. Yard/swi	itching	A. 5	Spec. MoV	V Equi	p. Cod	le   27. V	Was Equi	pment	Code	28.7	Train Nu	nber/Symbol
Consist (single en	<i>try</i> ) 2.	. Passenger	train	5. Sir	ngle car 8	. Light loc	o(s).		Atte					ed?				TT 120 1
20. 6	3. Commuter train 6. Cut of cars 9. Maint./inspect.car												1. Yes	s 2. No 1 CREBN1429A				
29. Speed (recorded speed, if available) Code 31. Method(s) of Operation (enter code(s) that apply) 31a. Remotely Controlled Locomotive												motive?						
E - Estimated 38 MPH   R   h Auto train control h. Curret								nt of tra	affic	n. Othe	er than r	nain trac	k	1 = Remote control portable				
30 Trailing Tons (gross tonnage c. Auto train stop i. Tin								able/tra	ain orders	o. Posi n. Oth	tive tra	in contro	1	2 = Remote control tower 3 = Remote control				
excluding power units) d. Cab e. Traffic							. I rack w	traffic	control	p. oui	Cod	le(s)	arrative)	transm	itter - m	ore th	nan one	
11368 f. Interlocking								nits	[	j	N/A	N/A N	A N/A	remote	control	trans	mitter	0
32. Principal Car/Unit		a. Initial	and Nu	mber	b. Positio	on in Trair	1 c. I	Loadec	d(yes/no)	33. If	railroa	d employ	/ee(s) tes	ted for dru	g/alcoho	ol use	,	I
(1) First involved BNSE 7571						1		N	/A	6	enter the	e numbe	that wer	e positive	in	F	Alcohol	Drugs
(derailed, struck, etc)							_			1	ne appr	opriate t	oox.				N/A	N/A
(2) Causing (if mec cause reported)	hanica		0			0		N/	N/A 54. was this const			IS CONSIS	transpor	ting passer	Emptr			N
35. Locomotive Units	s	a. Head End	b. Mai	Mid T nual	rain c. Remote	e d. Manual c.		mote	36. Cars	"S		L a. Freigh	oaded t b. Pass.	c. Fre	Emp ight	oty d. Pass.	e. Caboose	
(1) Total in Train		3		0	0	0	0		(1) Total i	in Equi	pment (	Consist	84	0		)	0	0
(2) Total Derailed	1	0		0	0	0	0		(2) Total l	Deraile	d		0	0	(	)	0	0
37. Equipment Dama	ge		3	8. Tra	ck, Signal, V	Way,			39. Prima	rv Cau	se			40 Con	tributing	r Cau	se	
This Consist		\$2,500.00		& Stru	icture Dama	ge	\$0.00		Code M302 Code					N	//304			
41 5	40 E	Numbe	r of Cre	$\frac{12}{42}$	mbers	1 11 Pr	komon		Len			Length of	th of Time on Duty					
Operators 1	41. Engineer/ 42. Firemen 43. Conduction					Conductors 44. Brakemen			45. Engineer/Operator			20	40. COI	Hunctor H	ſrs	5	Mi 20	
Casualties to:						40 (	U Débou		50 EOT Device?			20	51 Was FOT De			Properly	Armed?	
	+7. Ram		,yees 4.	o. 11a		\$ 49.0			1. Yes 2. No 1 1				1	1. Yes 2. No   1				
Fatai		0 0					0		52. Caboose Occupied by Crew?				?					
Nonfatal         0         0         0         1. Yes									2. No					2				
						0	PERAT	ГING	TRAIN	#2								
53. Type of Equipmen	nt 1.	Freight tra	in traia	4. Wo	ork train $\frac{7}{2}$	Yard/swi	tching	A. S	Spec. MoW	V Equip	o. Cod	e 54. V	Vas Equij	pment (	Code	55. T	Frain Nur	nber/Symbol
Consist (single ent	try) 2. 3.	Commute	train r train	5. Sin 6. Cui	gie car 8. t of cars 9	Maint /in	u(s). spect.car	r			N/A	, A	1 Yes	Yes 2 No N/A			N/A	
56. Speed (recorded s	speed, if	available)	Code	58.	Method(s)	of Operati	on (	enter	code(s) t	hat ar	ply		1. 103	58a. Ren	notely C	ontro	olled Loco	omotive?
R - Recorded	_ , ,	1		a.	ATCS	g	. Autom	natic bl	ock	m.Spec	cial inst	ructions		0 = Not a remotely controlled				
E - Estimated 0 MPH N/A b. Auto train control h. Current of traffic n. Other than main track $1 =$ Remote control portable																		

DEPARTMENT FEDERAL RAILF	OF TRA	NSPORT	TATIO TRATI	ON ON	FRA FA	CTUAL	RAILR	OAD AC	CIDENT REP	ORT	F	RA File	# <u>HQ-200</u>	9-12		
57. Trailing Tons (gross tonnage, excluding power units)					c. Auto train stop i. Time table/tr d. Cab j.Track warran e. Traffic k. Direct traffi				ain orders o. Positive train control t control p. Other (Specify in narrative) c control				2 = Remote control tower 3 = Remote control transmitter - more than one			
		N/A		f.	f. Interlocking 1. Yard limits				N/A N/A N/A	N/A N/A	remote c	N/A				
59. Principal Car/Unit a. Initial and Nut			umber	b. Positio	on in Train	c. Load	ed(yes/no)	60. If railroad emp	loyee(s) tes	ted for drug/alcohol use,						
(1) First involved (derailed, struck, etc) 0				0		1	J/A	the appropriate	e box.			Alcohol N/A	Drugs N/A			
(2) Causing ( <i>if mechanical</i>					0		N/A		61. Was this cons	ting passengers? (Y/N)			10/1			
cause reported)				Pag	Rear End			L Lo	oaded Empty			N/A				
62. Locomotive Units		a. Head End	b. Ma	Mid T nual	rain c. Remote	Remote d. Manual		63. Cars		a. Freight	b. Pass. c. Freig		ht d. Pass.	e. Caboose		
(1) Total in Train 0		0		0	0	0	0	(1) Total in Equipment Consis		0	0	0	0	0		
(2) Total Deraile	d	0		) 0		0	0 0		Derailed	0	0	0	0	0		
64. Equipment Dama This Consist	age	\$0.00	1	65. Tra	. Track, Signal, Way,			66. Prima Code	NI/A	67. Contr Code	ributing (	Cause	NI/A			
		Numbe	r of Cr	ew Me	& Structure Damage  V Members					Length of	Time on D	uty		IN/A		
68. Engineer/	69. Fire	men		70. Co	0. Conductors 71. Brakemen			72. Engin	eer/Operator		73. Con	ductor				
Operators 0		0			0		0		Hrs 0 M	i 0	Hrs		s 0	Mi 0		
Casualties to:	74. Railr	oad Emplo	oyees 7	75. Trai	n Passengers	5 76. Othe	76. Other		Device?	NT/ A	78. Was	EOT Dev	vice Properly	Armed?		
Fatal		0			0		0		79 Caboose Occupied by Crew?			1. Yes 2.				
Nonfatal		0			0		0		1. Yes 2. No							
						OI	PERATIN	G TRAIN	[#3							
80. Type of Equipment       1. Freight train       4. Work train       7. Yard/switching       A.         Consist (single entry)       2. Passenger train       5. Single car       8. Light loco(s).         3. Computer train       6. Get train       6. Ot train								Spec. MoW Equip. Code 81. Was Equipment Code 82. Train Number/Symbol Attended? N/A 1. Yes 2. No N/A N/A								
83. Speed (recorded	speed, if a	vailable)	Code	85.	Method(s) of	f Operation	(ente	r code(s) th	nat apply)		85a. Remo	otely Cor	ntrolled Loco	motive?		
R - Recorded	NI/A		0	a.	ATCS	g. /	Automatic b	olock n	<ul> <li>Special instructions</li> <li>Other than main tra</li> </ul>	s ck	0 = Not a	remotely	controlled			
E - Estimated	N/A	MPH	0	b. c.	Auto train c Auto train	ontrol h. ( stop i. T	Current of the Curren	affic ain orders	). Positive train contr	ol	1 = Remo 2 = Remo	te contro	ol portable			
84. Trailing Tons ( excluding powe	84. Trailing Tons (gross tonnage, arcluding power units) d. Cab j.Track warran							t control 1	b. Other (Specify in r	uarrative)	3 = Remo	ote contro	ol ra than ana			
N/A					I raffic Interlocking	к. 1 1.Y	ard limits	c control	N/A N/A N/A	N/A N/A	remote c	control tra	ansmitter	N/A		
86. Principal Car/Un	and N	umber	b. Positio	on in Train	c. Load	ed(ves/no)	87. If railroad empl	ovee(s) test	ed for drug	z/alcohol	use.					
(1) First involved				0				enter the numb	er that were	e positive i	n	Alcohol	Drugs			
(derailed, struck, etc)		,							the appropriate	e box.		0.01	N/A	N/A		
(2) Causing (17 mechanical 0 cause reported)						)	]	N/A	88. was this cons	ist transport	ing passen	gers? (Y	/N)	N/A		
89. Locomotive Uni	ts	a. Head End	b. Ma	Mid Train nual 1 c. Remoted		Rear d. Manual	Rear End . Manual   c. Remote			Lo a. Freight	aded b. Pass.	E c. Freig	Empty ht   d. Pass.	e. Caboose		
(1) Total in Train	n	0		0	0	0	0	(1) Total in	Equipment Consist	0	0	0	0	0		
(2) Total Deraile	d	0		0	0	0	0	(2) Total E	Derailed	0	0	0	0	0		
91. Equipment Dama	age		-	92. Tra	ck, Signal, V	Vay,		93. Primar	y Cause Code		94. Contr	ributing (	Cause	1		
This Consist	r of Cr	& St	ructure Dam	age	\$0.00	Length of Time on Duty										
95. Engineer/	96. Fire	men		97. C	97. Conductors 98. Brakemen				eer/Operator	Lengui or	1 100. Conductor					
Operators 0		0	57.0		0	0 0			Hrs 0 M	i 0	Hrs 0 Mi 0					
Casualties to:	101. Rail	road Emp	loyees	102.	Train	103. Oth	103. Other		104. EOT 105. Was EOT Device Properly							
Fatal		0			0		0		1. Yes         2. No         N/A         1. Yes         2. No           106         Caboose Occupied by Craw?							
Nonfatal 0					0		0	1. Yes 2. No						N/A		
Highway User Involved								Rail Equipment Involved								
107. C. Truck-1	107. C Truck Trailer, p. p								111. Equipment							
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian							1.Train(units pulling) 4.Car(s)(moving) 7.Light(s) (standing) 2.Train(units pulling) 5.Car(s)(moving) 7.Light(s) (standing)									
B. Truck E. van H. Motorcycle M 108. Vehicle Speed 109.					geographic	arranve) al)	Code	112. Position of Car Unit in								
(est. MPH at impact) N/A 1.North 2.South 3.East 4.West 4								1								

DEPARTMENT OF TRANSPORTATION       FRA FACTUAL RAILROAD ACCIDENT REPORT       FRA File # HQ-2009-12         FEDERAL RAILROAD ADMINISTRATION       FRA FACTUAL RAILROAD ACCIDENT REPORT       FRA File # HQ-2009-12												<u>·12</u>		
110. Position	110. PositionCode113. Circumstance													Code
1.Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Crossing       1. Rail Equipment Struck Highway User         2. Rail Equipment Struck by Highway User												1		
114a. Was the	114a. Was the highway user and/or rail equipment involved Code 114b. Was there a hazardous materials release												Code	
in the impact transporting hazardous materials?											4			
1. Highway User 2. Kail Equipment 3. Both 4. Neither														
114c. State nere the name and quantity of the hazardous materials released, if any. N/A														
115. Type 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 116. Signaled Crossing Code 117. Whistle Ban												Code		
Crossing       2.Cantilever FLS       5.Hwy. traffic signals       8.Stop signs       11.Other (spec. in narr.)       (See instructions for codes)       1. Yes         Warning       3.Standard FLS       6.Audible       9.Watchman       12.None       2. No														
Code(s)	01	03	(	)6	07	N/A	N/A	A N/A 01 3. Unknown						2
118. Location of Warning     Code     119. Crossing Warning     Code     120. Crossing Illuminated by Street       1. Both Sides     with Highway Signals     Lights or Special Lights											by Street hts	Code		
2. Side of Vehicle Approach 1. Yes								1. Yes 1. Yes						
<ol><li>Opposit</li></ol>	e Side of Vehic	le Appro	ach		1		2. No 3. Unknown		2		2. No 3. Unknown			2
121.	122. Driver's	Gender	Code	123.	Driver Drov	e Behind o	hind or in Front of Code 124. Driver						Code	
Age	1. Male				and Struck o	r was Struc	k by Second	Frain	1. Dro	ve arc	ound or thru th	e Gate	4. Stopped on Crossing	
68	68     2. Female     1. Yes     2. No     3. Unknown     2. Stopped and then Proceeded     5. Other (specify in narrative)       68     2     3. Did not Stop     narrative)									5. Other (specify in narrative)	2			
125. Driver Pa	ssed	Cod	e 12	6. Vie	w of Track C	bscured by	(primary ob	struction)						Code
Highway V	ehicle			1. P	ermanent Str	ucture	<ol><li>Passi</li></ol>	ng Train 5.	Vegetation		7. Other (s	pecify in r	uarrative)	
1. Yes 2. No	3. Unknown	2		2. S	tanding Railı	oad Equipr	ment 4. Topo	graphy 6.	Highway Vel	nicle	8. Not obstru	icted		8
Casualties to: Killed Injured 127							d 2 Injured 3	Uninjurad	Code		128. Was D	Driver in th	e Vehicle?	
129. Highway-Rail Crossing Users 0 3						130. Higi	130. Highway Vehicle Property Damage     26000       (art dollar damage)     26000					f Highway-Rail Crossin	g Users	
132. Locomotive Auxiliary Lights? Code 133. Locomotive Auxiliary Lights Operational?											12	Code		
1. Yes 2. No							1 1. Yes 2. No					1		
134. Locomotive Headlight Illuminated? Code 135. Locomotive Audible Warning Sounded?												Code		
1. Y				1	1.	1. Yes 2. No					1			

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



#### 137. SYNOPSIS OF THE ACCIDENT

On March 30, 2009 at 5:47 p.m. MDT an eastbound South Western Railroad (SW) Freight Train CRLBNT4-29A collided with a school bus at a highway-rail grade crossing near Dexter, New Mexico. The accident occurred near SW railroad mile post 117.1 and the intersection of Darby road FRA DOT # 019 918 J. The Dexter Independent School District bus was transporting twelve passengers including the operator at the time of the collision. As a result of the collision three of the bus passengers suffered minor injuries. The school bus received moderate damage. There were no injuries reported to the train crew. The leading locomotive sustained minor damage of about \$2,500, and there was no derailment.

At the time of the accident it was daylight and clear, with a west wind of about 24 mph gusting to 33 mph. The temperature was 61° F.

The accident was caused by failure of the school bus operator to yield to the oncoming train. According to the New Mexico State Police, the bus operator was cited for failure of the bus driver to cross the train tracks at a time it was safe to do so.

#### 138. NARRATIVE

### CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of eastward SW Freight Train CRLBNT4-29A included a locomotive engineer and a conductor. They went on duty at 12:30 p.m. MDT on March 30, 2009, at the Southwestern Rail Yard in Carlsbad, New Mexico. This is the away from home terminal for these crew members, and both had received more than the required statutory off-duty rest period prior to reporting for duty.

The assigned freight train consisted of the lead locomotive, the BNSF 7571, two other locomotives and 84 loaded potash hopper cars. It was 5,264 feet long, and weighed 11,368 tons. The train was scheduled to travel from Carlsbad, New Mexico en route to Beaumont, Texas with an interchange to the Burlington Northern Santa Fe railroad at Clovis, New Mexico. The train received an initial terminal train air brake test, and departed Carlsbad at 2:00 p.m.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the east side of the leading locomotive and the conductor was seated opposite in the conductor's seat on the west side.

The Dexter Independent School District bus was about half way through its route as it approached the Southwestern railroad highway rail grade crossing at Darby Road. The bus has a capacity for 72 passengers and is a 38 foot 2006 Bluebird model school bus. The bus driver was seated in the driver's seat and ten students and a transportation aid were occupying the first 5 rows of seats on the bus. As the bus approached the crossing it moved to the center of Darby Road to pass by an area of construction on the north shoulder of the road. The bus then stopped about twenty feet from the tracks, paused, then proceeded. At the same time the bus preceded the highway rail grade crossing warning system activated. The bus continued westbound across the tracks with the north crossing gate striking and dragging along the roof of the bus. Because the bus was still traveling close to the center of the road, the south crossing gate also struck and drug along the driver's side roof of the bus.

In this area of the Southwestern Railroad, the tracks are tangent and level as they approach the Darby Road highway rail grade crossing. New Mexico State Route 2 parallels the SW tracks. Darby Road is a gravel road that crosses the tracks at a ninety degree angle then requires a stop about 40 feet further as it then intersects with NM State Route 2.

The railroad timetable direction of the train is east. The geographic direction is north. Geographic directions are used throughout this report.

THE ACCIDENT

EASTWARD SW TRAIN CRLBNT4-29A:

Eastward SW Freight Train CRLBNT-29A was being operated at 41 mph approaching the Darby Road crossing. With a clear view of the crossing the engineer observed the school bus slow to a stop before crossing the tracks. The bus then proceeded, occupying the crossing after the crossing warning lights began flashing. As the engineer observed the bus preceding, he sounded and continued to sound the locomotive horn. The bus then stopped with about one third of the rear end of the bus still on the crossing. At about 500 feet from the crossing, the engineer placed the train in emergency braking. The bus pulled ahead but again stopped, leaving about two feet still fouling the tracks. The train speed recorded on the lead locomotive was about 40 mph when it collided with the school bus. The maximum authorized speed for the train was 49 mph as designated in the Southwestern Railroad timetable.

# **HIGHWAY VEHICLE:**

The school bus was traveling west on Darby Road as it approached the railroad intersection. According to the bus driver she made the required stop, opened the bus door, and looked both directions. Seeing no trains and observing that the crossing warning devices were not activated, she then proceeded towards the crossing. As the bus occupied the crossing, the driver observed the approaching train but continued forward. Traveling a few feet further she stopped at the intersection of State Route 2 assuming the rear of the bus was clear of the tracks. When the bus stopped the passengers began yelling for her to go because they saw the oncoming train. She pulled the bus ahead but had to stop because of an oncoming north bound motor vehicle on State Route 2. Darby Road is a two lane gravel road with a speed limit of 35 mph. Thirty nine feet after crossing the tracks it requires a stop as it intersects with State Route 2.

The train collided with the bus lifting it and knocking the rear end ninety degrees to land parallel to the tracks. The bus now facing south rolled back several feet before stopping north of the crossing between State Route 2 and the railroad tracks. The train came to a stop about 1,580 feet north of the crossing.

After stopping the engineer stayed on the locomotive and made contact with another train crew in the area and requested they make contact with emergency personnel. The conductor went back to the crossing to assess the situation and offer assistance if needed.

Returning from an earlier call in the area, the Dexter Fire Department was on the scene almost immediately, followed by the emergency medical services and the New Mexico State Police. After assessing the situation, they determined that only minor injuries had occurred to three of the bus passengers. Neither of the train crew members was injured.

The Southwestern Railroad Manager of Operations arrived at the site at about 6:45 p.m. He determined that only minor damage occurred to the lead locomotive with no damage occurring to the track and remaining consist of the train. The train crew members were released at about 8 p.m. and transported by motor vehicle to their home terminal in Clovis, New Mexico, after they reversed the train to clear the road crossing for vehicular traffic. At about 12:00 p.m. a second crew arrived and proceeded to Clovis, New Mexico, on train SW CRLBNT4-29A. Clovis is located about 117 miles north of the accident site.

The three bus passengers were transported by Dexter Ambulance Service to Eastern New Mexico Medical center in Roswell, New Mexico where they were treated for minor injuries and released.

ANALYSIS AND CONCLUSIONS:

# ANALYSIS- TOXICOLOGICAL TESTING:

The driver of the Dexter Independent School District bus was not tested on the day of the collision. There were no toxicological tests performed on the train crew. FRA does not require such testing for this type of accident.

CONCLUSION:

Intoxication was not a casual factor.

ANALYSIS- HIGHWAY-RAIL GRADE CROSSING:

The highway-rail grade crossing is equipped with a single bell, warning flashing lights and gates for both directions of highway traffic. There is an advanced warning sign posted 398 feet east of the crossing. Darby road is a loose gravel road without pavement markings and is maintained by Chaves County Highway Department.

The railroad has a whistle post in place about 1,410 feet south of the crossing. Both crew members stated the engineer began sounding the horn right after passing the whistle post. This was confirmed by analysis of the locomotive event recorder and the lead locomotive on board video recording.

Following the accident the active warning devices were tested by the SW signal maintainer and were determined to be working as intended. These tests were performed again on April 13, 2009, in the presence of an FRA Signal and Train Control (S&TC) Inspector and the State of New Mexico Public Regulatory Commission, Crossing Safety Inspector. The Darby road active warning system is controlled by a General Electric Transportation System HXP-3 predictor. A review of the data log of the HXP-3 recorded the train traveling at 41 mph at the crossing and giving a warning time of 30 seconds.

Proceeding west after crossing the SW Railroad tracks, Darby Road intersects with State Route 2. The distance from the gage of the nearest rail to the shoulder is about 39 feet with an additional 5 feet to the edge of the traveled lane. During interviews, statements were made that about three years ago State Route 2 was widened to include a left turn lane. This narrowed the distance between State Route 2 and the SW Railroad tracks.

On April 16, 2009, a sight distance survey at the Darby Road grade crossing was performed by an FRA Region 5 Grade Crossing Manager with assistance from a New Mexico Public Regulatory Commission Crossing Safety Inspector. The sight distance at this crossing was based on the Federal Highway Administration's (FHWA) "Sight Distance Combinations of Highway Vehicle and Train Speeds" contained in Table 32 of the FHWA Railroad-Highway Grade Crossing Handbook - Revised Second Edition 2007. The Darby Road grade crossing is equipped with gates and flashing lights designed to warn highway-users of the approach of a train. Since active warning devices are in place at this crossing and the school bus driver was required to make a full stop at the crossing to determine if it was safe to cross the tracks, a vehicle speed of "Zero" was used. A photograph was taken from the westbound lane of Darby Road at a distance of 20 feet from the tracks (it includes 15 feet from the tracks and an additional five feet for the front of the bus). This is about where the driver would have been seated while making a required stop. Using the FHWA formula for a vehicle stopped at the tracks, the FHWA Table 32 indicates that at the maximum authorized train speed of 49 miles per hour (50 miles per hour is the actual speed used by FHWA) the distance down the tracks should be 1201 feet in order for a stopped vehicle to safely complete a crossing of the tracks before the train enters the crossing. As determined by the sight distance survey, a northbound train approaching, should be able to be seen at a distance of 1.201 feet or more from the Darby Road crossing (southeast guadrant of the crossing). The track is basically level and straight, the signal bungalow is not blocking the view of the tracks from a highway-users stopped position, nor is any other obstruction on the railroad-right-of-way that would act as an obstruction at this grade crossing (see Photo #9).

# CONCLUSION:

The crossing is in good operational condition with more than adequate site distance and the warning devices were operating as intended. The distance between SW Railroad tracks and Stated Route 2 is not of sufficient distance to alleviate the hazard of longer vehicles from fouling both State Route 2 and the tracks while

obeying the stop sign.

ANALYSIS - LOCOMOTIVE SAFETY DEVICES:

The leading locomotive was equipped with a headlight, auxiliary lights, and an audible warning device as required by Federal regulations. These devices were tested prior to departure from the initial terminal. The auxiliary lights were seen to be operating in photographs taken at the scene. The audible warning device was recorded sounding on the locomotive video camera for seventeen seconds prior to the collision. This was confirmed on the locomotive data record. This equipment was tested at the scene prior the train being released to continue on to its destination.

# CONCLUSION:

The locomotive safety devices were in full compliance with federal requirements.

### ANALYSIS - LOCOMOTIVE ENGINEER OPERATING PERFORMANCE:

The locomotive was equipped with a speed recorder and an event recorder as required. Because the lead locomotive was one of the BNSF fleet the relevant event recorder data was downloaded by the BNSF Road Foreman when the locomotive arrived in Clovis, New Mexico. The information was processed and was made available to the SW Railroad Staff. All three BNSF locomotives were equipped with on board video cameras that captured the accident.

### CONCLUSION:

The locomotive engineer was in compliance with all applicable railroad operating and train handling requirements.

# ANALYSIS - FATIGUE:

FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis, which is equivalent to blood alcohol content (BAC) of 0.05. At or above this baseline, we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information, FRA uses the default software settings. FRA obtained fatigue related information, including a 10-day work history, for the two crew members involved in the accident.

# CONCLUSION:

FRA concluded fatigue was not probable for any of the rail employees.

### OVERALL CONCLUSIONS:

The railroad was in full compliance with their rules and all applicable Federal Standards. The train crew members as well as the adult occupants of the school bus were interviewed during this investigation. The driver of the school bus approached the crossing and stopped consistent with State and Federal Regulations. The driver continued to proceed after seeing the oncoming train and observing the crossing warning system devices were operating.

# PROBABLE CAUSE & CONTRIBUTING FACTORS:

The accident occurred because the school bus driver failed to cross and clear the tracks at a time when safe to do so. The short distance did not allow the proper clearance of the bus at a point between the Southwestern Railroad tracks and State Route 2 was a contributing factor.