



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-05***

***Kansas City Southern Railway Company (KCS)
Grandview, MO
January 10, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Kansas City Southern Rwy Co. [KCS]		1a. Alphabetic Code KCS		1b. Railroad Accident/Incident No. 08011002	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Kansas City Southern Rwy Co. [KCS]		4a. Alphabetic Code KCS		4b. Railroad Accident/Incident No. 08011002	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 01 Day 10 Year 2008		7. Time of Accident/Incident 09:50: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative) Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
				12. People Evacuated 0	
				13. Division Mid West	
14. Nearest City/Town Grandview		15. Milepost (to nearest tenth) 30.7		16. State Abbr Code N/A MO	
				17. County CASS	
18. Temperature (F) (specify if minus) 40 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 3	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Single Main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 52.3	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 1	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 43 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) 2642					
32. Principal Car/Unit		a. Initial and Number UP7135		b. Position in Train 1	
(1) First involved (derailed, struck, etc)				c. Loaded (yes/no) N/A	
(2) Causing (if mechanical cause reported)		0		0 N/A	
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs 0 0	
				34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End		Mid Train	
		b. Manual		c. Remote	
		d. Manual		c. Remote	
(1) Total in Train		2		0 0	
(2) Total Derailed		2		0 0	
				36. Cars	
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
				0 0 126 0 0	
				0 0 28 0 0	
37. Equipment Damage		38. Track, Signal, Way, & Structure Damage		39. Primary Cause Code	
This Consist \$1,804,559.00		\$152,090.00		T215	
				40. Contributing Cause Code N/A	
				41. Engineer/Operators 1	
				42. Firemen 0	
				43. Conductors 1	
				44. Brakemen 0	
				45. Engineer/Operator Hrs 5 Mi 25	
				46. Conductor Hrs 5 Mi 25	
Casualties to:		47. Railroad Employees		48. Train Passengers	
Fatal		0		0	
Nonfatal		0		0	
				49. Other 0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded E - Estimated	N/A MPH N/A	a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
84. Trailing Tons (gross tonnage, excluding power units)	N/A	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	
		N/A N/A N/A N/A N/A	

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code	111. Equipment	Code	3. Train (standing)	6. Light Loco(s) (moving)	Code	
	N/A	1. Train(units pulling)	N/A	4. Car(s)(moving)	7. Light(s) (standing)		
		2. Train(units pushing)		5. Car(s)(standing)	8. Other (specify in narrative)	N/A	
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code	112. Position of Car Unit in	N/A		
		1. North 2. South 3. East 4. West	N/A				

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A							
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A							
114c. State here the name and quantity of the hazardous materials released, if any. N/A																
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A				
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A							
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A			
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A	4. Stopped on Crossing 5. Other (specify in narrative)		Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A			
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A			
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			N/A			
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A							
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A							

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Northbound Kansas City Southern (KCS) empty coal Train Symboled CWEKC-08 derailed the two lead locomotives and 28 head empty coal cars on January 10, 2008, at 9:50 a.m. The accident occurred near Grandview, Missouri, at KCS Milepost 30.7, on the KCS Pittsburg Subdivision.

At the time of the accident, it was daylight with a light rain and moderate wind. The temperature was 40 degree Fahrenheit.

The equipment damage was estimated at \$1,804,559. Track damage was estimated at \$152,090. There was no signal damage reported.

The probable cause of the accident was of a pair of center broken 136-lb. non-insulated rail joint bars.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of KCS Train CWEKC-08 north included a locomotive engineer and a conductor. The crew went on duty at 4:25 a.m. CST, on January 10, 2008, at the Pittsburg Rail Yard in the city of Pittsburg, Kansas. This is the home terminal for both crew members and each had the required statutory off-duty rest period prior to reporting for duty.

The assigned freight train consisted of two locomotives on the head-end, 126 empty coal cars, and two Distributive Power (DP) locomotives on the rear of the train. Locomotive No. KCS 4592 was the rear locomotive and was functioning as the end-of-train device (EOTD). The train was 6,995 feet in length and the weight was listed at 2,642 tons. The train was scheduled to travel to Kansas City, Missouri, and transfer to the Union Pacific Railroad Company. The train received an initial terminal air brake test by mechanical personnel at Welsh, Texas. After arriving at Pittsburg, Kansas at 3:20 a.m. no additional tests were required and the train departed Pittsburg at 4:29 a.m.

As the train approached the accident area, the locomotive engineer was seated at the controls on the east side of the lead locomotive. The conductor was seated on the west side of the lead locomotive. The railroad timetable direction of the train was north, and the geographical direction was north. Timetable directions are used throughout this report.

The train was exiting a right-hand 2-degree curve at MP 30.8 onto 3,000 feet of tangent track and approaching 183rd Street public highway/rail grade crossing at MP 30.45. The grade at this location is .30 percent descending. The track is constructed with 136-lb. continuous-weld rail (CWR) on wood cross-ties, and the spike pattern is two spikes on the gage side and one spike on the field side of the rail. Two anchor spikes are located in the 14 inch tie plates. The rail anchor pattern consists of a spring type anchor on each side of every other tie (boxed anchored). Both crew members stated the trip was uneventful up to the time the train derailed; until this point the crew did not see or feel anything unusual.

THE ACCIDENT

The train was being operated at a recorded speed of 43 mph approaching the accident area. The speed is recorded by the event recorder on the first and second locomotives, as well as the rear locomotive acting as the EOTD. The maximum authorized speed of this track is 50 mph, as indicated in KCS Timetable No. 7, dated July 1, 2006. The engineer and conductor both stated that at MP 30.7 they experienced a loud clang and bang under the locomotive; the train then started bouncing, shaking, and moving sideways. When the locomotive came to a stop, they looked back at their train and could see numerous cars sideways on the right-of-way.

ANALYSIS AND CONCLUSION

ANALYSIS: - FATIGUE

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded fatigue was not probable for any of the KCS employees.

ANALYSIS: - DRUG:

The two crewmembers of KCS Train CWEKC-08 were mandatory post-accident toxicologically tested. The test results were negative.

CONCLUSION:

Drugs and alcohol were not factors in this accident.

ANALYSIS: - TRACK:

The last ultrasonic rail detection test through this area was performed on December 14, 2007, with the Sperry rail car No. SRS 124 of Sperry Rail Corporation. There were no rail defects noted in the immediate area of MP 30.7. The last geometry car survey was in September by the FRA Geometry Test Car T-217. There were no exceptions noted in the area of the derailment.

Track inspection records revealed that the track was last inspected on January 7, 2008, with no exceptions noted in the area of the derailment. It was later confirmed that the KCS Roadmaster had made another inspection on January 9, 2008 but did not complete an FRA track inspection report. No exceptions were taken to the area around the accident scene.

A pair of center-broke 36-inch, 136-lb. joint bars were discovered at the point of derailment. The south end was still in place and the north piece was out in the right-of-way still attached to rail. There was an internal defect at the base or bottom of the gage side joint bar approximately 15 percent in size. The field side joint bar was also broken, but there was no internal defect identified. It was impossible to ascertain whether the joint bars broke under the rear of the proceeding train, or when the first set of wheels of the accident locomotive made contact.

CONCLUSION:

The KCS railroad was in compliance with their own and all applicable FRA standards. The train crewmembers were the only witnesses to the derailment.

The broken joint bars found at the point-of-derailment (POD) with both ends still attached to rail ends, indicates that an internal defect existed at the time of derailment. The 136-lb. joint bars broke under the weight of the train due to a small fracture at the base of the gage side rail joint bar.

PROBABLE CAUSE AND CONTRIBUTING FACTORS

The probable cause of the derailment is the broken non-insulated rail joint bars - Cause Code T215-Joint bar broken (noninsulated)