



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2008-21***

***Union Pacific (UP)  
Alpine, TX  
February 27, 2008***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0208SA024	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0208SA024	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 02 Day 26 Year 2008		7. Time of Accident/Incident 11:50: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative) Code 01	
9. Cars Carrying HAZMAT 12		10. HAZMAT Cars Damaged/Derailed 02		11. Cars Releasing HAZMAT N/A	
				12. People Evacuated 6	
				13. Division San Antonio	
14. Nearest City/Town Alpine		15. Milepost (to nearest tenth) 609.3		16. State Abbr Code N/A TX	
				17. County BREWSTER	
18. Temperature (F) (specify if minus) 19 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Single main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 27.18	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 4	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 30 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) 7632					
32. Principal Car/Unit		a. Initial and Number SPA 513408		b. Position in Train 5	
(1) First involved (derailed, struck, etc)				c. Loaded (yes/no) yes	
(2) Causing (if mechanical cause reported)		0		0 N/A	
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A	
				34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End		Mid Train	
		b. Manual		c. Remote	
		d. Manual		c. Remote	
(1) Total in Train		4		0 0 0 0	
(2) Total Derailed		0		0 0 0 0	
				36. Cars a. Freight b. Pass. c. Freight d. Pass. e. Caboose 124 0 0 0 0 (2) Total Derailed 25 0 0 0 0	
37. Equipment Damage This Consist \$666,367.00		38. Track, Signal, Way, & Structure Damage \$54,680.00		39. Primary Cause Code T207	
				40. Contributing Cause Code N/A	
				41. Engineer/Operators 1	
		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 0 Mi 35	
				46. Conductor Hrs 0 Mi 35	
Casualties to:		47. Railroad Employees		48. Train Passengers	
Fatal		0		0 0	
Nonfatal		0		0 0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

**OPERATING TRAIN #3**

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code	81. Was Equipment Attended?	82. Train Number/Symbol
				N/A	1. Yes 2. No N/A	N/A

83. Speed (recorded speed, if available)	R - Recorded E - Estimated	Code N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
84. Trailing Tons (gross tonnage, excluding power units)	N/A		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
			m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A
			N/A N/A N/A N/A N/A	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck 108. Vehicle Speed (est. MPH at impact)	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
109. geographical 1. North 2. South 3. East 4. West			Code N/A	112. Position of Car Unit in	N/A		

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



## 137. SYNOPSIS OF THE ACCIDENT

On February 26, 2008, at 11:50 p.m. CST westbound Union Pacific (UP) Freight Train, # IAVLBX-25 derailed at UP Milepost 609.30 on the UP Sanderson Subdivision of the San Antonio Service Unit. This is a rural area located immediately west of Alpine, TX. Twenty-five cars of the 124 car train derailed. Two hazardous cars were included in the derailed cars however there was no release of product. There was a precautionary evacuation ordered by fire officials affecting six people. There were no injuries reported. The 64th thru the 88th loaded head cars behind the four locomotives derailed.

At the time of the accident it was dark and clear. The temperature was 19 degrees F.

The damages were listed at \$ 721,047 (\$ 666,367 to equipment and \$ 54,680 to track)

## PROBABLE CAUSE

The cause of the derailment was due to a broken rail – a detail fracture from shelling or head check, FRA cause code T207.

## 138. NARRATIVE

## CIRCUMSTANCES PRIOR TO THE ACCIDENT:

The crew of UP Freight Train # IAVLBX-25 included a locomotive engineer and a conductor. The crew went on duty at 11:15 p.m. CST on February 26, 2008 at Alpine Texas. The train was scheduled to travel from Alpine to El Paso. El Paso is the home terminal for both crew members. Both crew members had received more than the required statutory off duty rest period prior to reporting for duty.

The train consisted of four locomotives, 124 platform cars. It was 7,632 gross tons and 7,636 feet long and was scheduled to travel from Avondale, LA to Long Beach, CA. The train received a Train Air Brake test at Avondale, LA at 8:20 p.m. on February 24, 2008 by qualified mechanical inspectors. No exceptions were noted as a result of the inspection. The train's End of Train Device (EOTD identified as Number UPRQ 061 808) was also inspected at Avondale at 6:45 p.m. on February 24, 2008.

As the Westbound train approached the accident area, the locomotive engineer was seated at the controls on the north side of the leading locomotive. The conductor was seated on the south side of the leading locomotive.

The grade of the railroad at the point of derailment is a 1.00 percent ascending grade as you approach this area from the east. The track is in a 3-degree 37- minute curve to the left.

The railroad time table direction of the train was west. The geographic direction of the train was southwest. The Timetable directions will be used throughout the report.

As indicated by Union Pacific RR Co. San Antonio Area Timetable No.3, the method of operation at milepost 609.3 of the Sanderson Subdivision was Centralized Traffic Control (CTC).

The weather was reported as dark and clear. The temperature was 19 degrees F.

## THE ACCIDENT:

The crew proceeded westward from the crew change point in Alpine, Texas and gradually increased the speed of the train to 30 mph. The speed was recorded by the event recorder of the lead locomotive. The maximum authorized speed for this segment of track is 50 mph governed by the Sanderson Subdivision General Order No. 2. There were no temporary slow orders in effect for this segment of track.

The engineer commented that the train handled smoothly, having worked the throttle to position eight, when he felt a tug on the train. The engineer then went to throttle position five and the train went into an emergency brake application. When the air would not build up on the rear of the train, the conductor began to walk back to inspect the train. He discovered the derailed cars. He continued to walk back toward the rear of the train and found 25 additional cars derailed, lines 64 through 88 of the train consist list.

**ANALYSIS:**

The train was equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded and analyzed by the UP Manager Road Operations at the accident site. The train crew was administered a Post Accident Toxicology Test. A broken rail was found at the site which was determined to be the result of a detail fracture. The rail which was manufactured in 1986 had originally been laid on the high side of the curve at milepost 609.3. In 2004 that rail was transposed to the low side of the same curve. The rail, which had previously been surface ground in July of 2007, showed considerable evidence of head wear and shelling on the rail surface. On February 12, 2008 the rail in the area of the derailment had been tested by an ultra-sonic rail detector car with no internal defects noted.

**ANALYSIS:**

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

**CONCLUSION:**

Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

**CONCLUSIONS:**

Toxicology Tests for both crew members revealed negative test results. Track geometry measurements were within FRA Standards. The locomotive engineer was in compliance with all applicable railroad operating and train handling requirements, which was confirmed by the relevant event recorder data. Rail flaw detector reports showed three internal defects had been found in the low rail of this curve in 2007. The service failure report shows three broken rails occurring in this same curve, also in the low rail, on November 5, 2007, December 16, 2007, and February 10, 2008. Based on the rail found at the point of derailment and the defect history of the rail in this curve, the cause of the derailment was determined to be a broken rail - detail fracture.

**PROBABLE CAUSE:**

The cause of the derailment was due to a broken rail—detail fracture from shelling or head check, FRA cause code T207.