

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2008-25

Burlington Northern Santa Fe (BNSF) Cottage Crove, MN March 5, 2008

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

r																		
DEPARTMENT OF FEDERAL RAILR					FRA FA	ACTUA	AL RA	ILR	OAD A	CCII	DENT R	EPORT	_	Η	FRA Fi	le #	HQ-200	18-25
1.Name of Railroad Operating Train #1									Alphabetic				1b. Railroad Accident/Incident No.					
BNSF Rwy Co. [BNSF] 2.Name of Railroad Operating Train #2									1					XXXXXXXX 2b. Railroad Accident/Incident No.				
N/A 3.Name of Railroad C	3a.	Alphabetic	N/A Code			3b. I	N/A 3b. Railroad Accident/Incident No.											
N/A									•	N/A				N/A				
4.Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]									4a. Alphabetic Code BNSF					Ib. Railroad Accident/Incident No. XXXXXXXX				
5. U.S. DOT_AAR Grade Crossing Identification Number									Date of Acconth 03	ident/I		ar 2008	7. T	ime of Ac 03:33		Incide	nt AM	V PM
8. Type of Accident/In	ndicent	1. Derail	ment		4. Side c	ollision			Hwy-rail c			Explosion-c	leton		Other			Code
(single entry in code box) 2. Head on collision 5. Raking collision 3. Rear end collision 6. Broken Train collision								8. RR grade crossing 11. Fire/violent					1	apture (describe in narrative)				
9. Cars Carrying		3. Rear e	6. Broke	Cars Releasing			'n	12. Other impacts 12. People				13. Div	vision		11			
HAZMAT	9	Damageo	1		ZMAT	leusin	1		Evacuated			0		CHICAGO		0		
14. Nearest City/Town	n				15. Milepost				16. State Abbr Co		Code	17. County						
	COTT	AGE GRO	VE			(to	(to nearest ter 40				N/A	MN			WAS	HING	TON	
18. Temperature (F)		19. Visit			gle entry)				Weather (single) 1. Clear 3. Rai		,,			21. Type of Track				Code
(specify if minus) 19	F		Dawn Day)usk Dark	2					6.Snow	1		1. Main 3. 2. Yard 4.				1
22. Track Name/Nur	mber					23. FRA			Code		4. Annual Track Density			25. Time Table				Code
		SIN	GLE M	IAIN	LINE	Cla	ss (1-9, X	^{x)}	2		(gross tons in millions) 41.9			1. North 3. East 2. South 4. West			3	
							OPER	ATI	NG TRA	IN #1								·
26. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 27. Was Equipment Code 28. Train Numb Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s). A. Spec. MoW Equip. Code Attended? 28. Train Numb											nber/Symbol							
Consist (single en		. Passenger			0	. Light loo . Maint./ii		ır			1			s 2. No 2 HNTWGALI05				GALI05
29. Speed (recorded speed, if available) Code 31. Method(s) of Operation (enter code(s) that apply) 31a. Remotely Controlled Locomotive												motive?						
R - Recorded a. ATCS g. Auton										•	cial instruc er than mai			0 = Not a remotely controlled 1 = Remote control portable				
									rain orders	o. Pos	itive train o	control		2 = Remo	ote cont	rol to		
excluding power	-	onnage,			. Cab . Traffic				nt control c control	p. Oth	er (Specify Code(s		ve)	3 = Rem transmi			an one	
11477 f. Interlocking l.Yard l									e control	e	т т`	A N/A M	J/A	remote o				0
32. Principal Car/Unit		a. Initial	and Nu	mber	b. Positi	on in Trai	n c.	Loade	ed(yes/no)		f railroad e					ol use,		
(1) First involved (derailed, struck, etc) OWIX15055						75			yes		enter the nu the appropri		were	positive in	n		Alcohol N/A	Drugs N/A
(2) Causing (if med	hanical	l ow	X1505	5		75		,	yes		Was this c		sporti	ng passen	gers? (Y/N)	N/A	
35. Locomotive Unit	cause reported)						ear End		36. Cars	:				aded		Emp	ty	
(1) Tatal in Tasia		End	b. Mai								ipment Cor			b. Pass.		-	1. Pass.	e. Caboose
(1) Total in Train		4		0	0	0	0)	. ,	1		1515t 7	1	0	64	4	0	0
(2) Total Derailed37. Equipment Dama		0	<u> </u>	0	0	0	0)	(2) Total	Deraile	ed		0	0	C)	0	0
This Consist	ige I	\$3,999.00			ick, Signal, V ucture Dama	-	\$0.00		39. Prima Code	ary Cau	ise	Eand		40. Cont	ributing	g Caus		NT / A
	I	Numbe	•						Code E29C Code N/A Length of Time on Duty					N/A				
41. Engineer/ Operators 1	42. Fir	emen		43. Co	onductors	44. Br	akemen		45. Engi		perator			46. Conductor			Mi 25	
1		0			1		0		Hrs 5 Mi 35									
	47. Railr	0	oyees 4	8. Tra	in Passenger	s 49.	Other		50. EOT Device? 1. Yes 2. No 1 1				51. Was EOT Device Properly Armed? 1. Yes 2. No 1					
Fatal		0			0 0				1. Yes 2. No 1 52. Caboose Occupied by Crew?				1.100 2.110 1					
Nonfatal		0			0		0		1. Yes 2. No				No					2
								ΓINC	G TRAIN	#2								
53. Type of Equipmen	in	Freight tra Passenger				Yard/swi	0	A.	Spec. MoV	V Equi	p. Code	54. Was E Attend		nent C	ode	55. T	rain Nun	nber/Symbol
Consist (single en	u yj	Commute			0	Maint./ir		r			N/A	1. Y		2. No 1	N/A		N/	/A
56. Speed (recorded)	speed, if	available)	Code		Method(s)	•	,		nter code(s) that apply)					58a. Remotely Controlled Locomotive?				
R - Recorded a. ATCS g. Automatic block m.Special instructions E - Estimated N/A MPH N/A b. Auto train control h. Current of traffic n. Other than main tract											0 = Not a remotely controlled 1 = Remote control portable							

DEPARTMENT FEDERAL RAILR					FRA FA	CTUAI	RAILR	OAD AC	CIDENT REP	ORT	F	RA File	# <u>HQ-200</u>	08-25	
57. Trailing Tons (gross tonnage, excluding power units)					c. Auto train stop i. Time table/tr d. Cab j.Track warrant e. Traffic k. Direct traffic				p. Other (Specify in Code(s)	3 = Remo transmit	te control ote control ter - more	than one			
N/A					f. Interlocking l.Yard limit				N/A N/A N/A	N/A N/A	remote c	N/A			
59. Principal Car/Un	it	a. Initial	and N	lumber	b. Positio	n in Train	c. Load	led(yes/no)	60. If railroad emp			Drugs			
(1) First involved (derailed, struck, etc) N/A				N/2	A	1	N/A	enter the number that we the appropriate box.			Alcohol N/A				
(2) Causing (if me	,	,							61. Was this consist transpor			I			
cause reported) N/A				N/2	4]	N/A			N/A					
62. Locomotive Units a. Head End b. Mar			Mid T anual	rain c. Remote		r End	63. Cars L a. Freight			b. Pass.		mpty It d. Pass.	e. Caboose		
(1) Total in Train		N/A	N/A		N/A	N/A N/A		(1) Total in	n Equipment Consist	N/A	N/A	N/A	N/A	N/A	
(2) Total Deraile	ed	N/A	N	I/A	N/A	N/A	N/A	(2) Total Derailed N/A			N/A	N/A	N/A	N/A	
64. Equipment Dama This Consist	age	N 7(4			ck, Signal, W	N/A	66. Primary Cause Code			67. Contributing Cause Code N/A					
		N/A Numbe	r of Ci		tructure Dam	age	N/A	coue		N/A Length of		utv		N/A	
68. Engineer/	69. Fire				0. Conductors 71. Brake			72. Engin	eer/Operator		73. Con				
Operators N/]	N/A			N/A		N/A		Hrs N/A Mi N/A			Hrs _{N/A} Mi _N			
Casualties to:	74. Railro	oad Emplo	oyees	75. Tra	in Passengers	76. Oth	er	77. EOT I 1. Y		NT/ A		Armed?			
Fatal		N/A			N/A		N/A			N/A	1.	N/A			
Nonfatal		N/A			N/A		N/A	79. Caboo	ose Occupied by Crev 1. Yes	w? 2. No				N/A	
						0		G TRAIN	G TRAIN #3						
80. Type of Equipme Consist (single en		Freight tra Passenger				rard/swite Light loco	0	Spec. MoW		Was Equipr Attended?				nber/Symbol	
		Commuter				Maint./insj			N/A	1. Yes	2. NO	I/A	N/A		
83. Speed (recorded) R - Recorded									hat apply) n.Special instruction	s			rolled Loco controlled	omotive?	
E - Estimated	a. ATCS g. Hatomatic							nock	a. Other than main tra			ote control			
84. Trailing Tons (c. Auto train stop i. Time table/t								p. Other (Specify in		2 = Remo 3 = Remo	te control			
excluding powe	r units)				Cab Traffic		Track warran Direct traffi		Code(s)	ununve)	transmit	ter - more	than one		
	N/A		f.	Interlocking	1. Y	ard limits		N/A N/A N/A	N/A N/A	remote control transmitter N/A					
86. Principal Car/Unit a. Initial and Nu					b. Positio	n in Train	c. Load	led(yes/no)	87. If railroad emp	oyee(s) test	ed for drug	g/alcohol u	ise,		
(1) First involved			N/A		N	/A		N/A	enter the num the appropriate		e positive i	n	Alcohol		
(derailed, struck, etc)						_	N/A 88. Was this consist transporting passenge					N/A N)	N/A		
cause reported			N/A		N/			N/A		1	01	N/A			
89. Locomotive Uni	its	a. Head End	h M	Mid T anual 1			r End c. Remote	90. Cars		Lo a. Freight	aded b. Pass.		mpty it d. Pass.	e. Caboose	
(1) Total in Train	n	N/A		J/A	N/A	N/A	N/A	(1) Total in	n Equipment Consist		N/A	N/A	N/A	N/A	
(2) Total Deraile	ed	N/A	N	[/A	N/A	N/A	N/A	(2) Total E	Derailed	N/A	N/A	N/A	N/A	N/A	
91. Equipment Dama	age				ck, Signal, W			93. Primary Cause Code 9				94. Contributing Cause			
This Consist		N/A Numbe	r of Ci		ructure Dama	ige	N/A	N/A Code N/A Length of Time on Duty							
95. Engineer/	96. Fire		1 01 0.		Conductors	98. Bra	kemen	99. Engineer/Operator 100. Conductor							
Operators N/A		N/A			N/A				Hrs N/A Mi N/A Hrs N/A						
Casualties to:	101. Rail	road Emp	loyees	102.	Train	103. Ot	103. Other				105. Was	s EOT De	vice Proper	ly	
Fatal		N/A			N/A N/			1. Yes 2. No N/A 106. Caboose Occupied by Crew?			1.	Yes	2. No	N/A	
Nonfatal N/A					N/A		N/A							N/A	
	Highway User Involved									Equipmen	t Involve	d		1	
107. C. Truck-7	Frailer r	Pug		[Other	Motor Vehic	10	Code	111. Equij		(at an June)	6 Light	Loco(s)		Code	
A. Auto D. Pick-Uj	p Truck (. Bus 3. School	J Bus J	K. Pede	strian	le		1.Train(units pulling) 4.Car(s)(moving) 7.Light(s) (standing)							
B. Truck E. Van	ł			M. Othe	er (spec. in no	,	N/A Code	2.Train(units pushing) 5.Car(s)(standing) 8.Other (specify in narrative) N/A							
108. Vehicle Speed 109. geographical) Code (est. MPH at impact) N/A 1.North 2.South 3.East 4.West N/A								112. Position of Car Unit in N/A							

DEPARTMENT OF TRANSPORTATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # <u>HQ-2008-25</u> FEDERAL RAILROAD ADMINISTRATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # <u>HQ-2008-25</u>												-25		
110. Position													Code	
1.Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Crossing 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User												N/A		
	e highway user		-	•			Code	114b. Wa	s there a haza	rdous materia	ls release		Code	
in the impact transporting hazardous materials?											N/A			
1. rigiway User 2. Kan Equipment 5. Bour 4. Neuner												1		
114c. State here the name and quantity of the hazardous materials released, if any. N/A														
115. Type 1.Gates 4.Wig Wags 7.Crossbucks 10.Flagged by crew 116. Signaled Crossing Code 117. Whistle Ban												Code		
Crossing 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs 10.thef (spec. in narr.) (See instructions for codes) 1. Yes Warning 3.Standard FLS 6.Audible 9.Watchman 12.None 2.No														
Code(s)	N/A	N/A	N	/A	N/A	N/A	N/A N/A N/A 3. Unknown						N/A	
118. Location of Warning Code 119. Crossing Warning Code 120. Crossing Illuminated by Street 1. Both Sides with Highway Signals Lights or Special Lights											Code			
2. Side of					1. Yes				Yes					
3. Opposite Side of Vehicle Approach N/A							2. No 3. Unknown			N/A 2. No 3. Unknown				
121.	122. Driver's	Gender	Code	123.	Driver Drov	ve Behind o	or in Front of	Code					Code	
Age	1. Male						k by Second			e around or th		4. Stopped on Crossing		
N/A	N/A 2. Female 1. Yes 2. No 3. Unknown 2. Stopped and then Proceeded 5. Other (specify in narrative) N/A N/A N/A 3. Did not Stop narrative)										N/A			
125. Driver Pa	ssed	Cod	e 12	6. Viev	w of Track C	bscured by	(primary ob	struction)	-				Code	
Highway V					ermanent Str			ng Train 5. '	0	7. Other	(1 55	narrative)	1	
1. Yes 2. No	3. Unknown	N/.	A	2. St	tanding Railı			graphy 6. l	Highway Veh		bstructed		N/A	
Casualties	to:		Kill	ed	Injured	127. Driv		11			as Driver in t		Code	
							d 2.Injured 3.	5			1. Yes 2. No 131. Total Number of Highway-Rail Cross			
129. Highway-Rail Crossing Users N/A N/A							130. Highway Vehicle Property Damage 131. Total Number of Highway (est. dollar damage) N/A						g Users	
132. Locomotive Auxiliary Lights? Code 133. Locomotive Auxiliary Lights Operational?											Code			
1. Yes 2. No						N/A 1. Yes 2. No				N/A				
134. Locomot	ive Headlight I	lluminat	ed?				Code	135. Locor	notive Audibl	e Warning So	unded?		Code	
1. Y	es	2.	No				N/A	1.	Yes	2. No)		N/A	

HQ-2008-25 Between 24th &25th car in train & where air hose St Croix River Bridge North came apart Hi way 10 TC OWIX 15055, 75^{th} car in train & the car that broke 0 Prescott WI Point car stopped Mile post 408.6 Mississippi river car in135 car mixed freight train with ETD TC CHVX 100105 last Cottage Grove MN Single main track

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

137. SYNOPSIS OF THE ACCIDENT

On March 5, 2008, at 3:33 p.m., CST, eastbound BNSF Railway (BNSF) Train HNTWGALI-05 operating on BNSF's Chicago Division, St. Croix Subdivision's single main track, experienced an undesired emergency brake application. The air hoses between the 24th and 25th cars separated. The accident occurred on the Minnesota side of the St. Croix River. Prescott, Wisconsin is approximately one half mile east of the accident site and on the east side of the St. Croix River.

During the emergency train brake application, tank car OWIX 15055, containing Ethylene Glycol (UN 3282) broke in two. As a result of the broken tank, product was released into the St. Croix River. The St. Croix River flows into the Mississippi River a short distance from this location. The release occurred at milepost 408.6 on the single main track.

There was no derailment, fire, or evacuation, however 20,000 gallons of Ethylene Glycol was released. U.S. Route 10, which is directly north of the BNSF at this location, was closed as a precaution for approximately four and one half hours. The tank car was a total loss and BNSF reported the tank car damage as \$3999.29.

The temperature was 19 °F, the weather was clear. There were no injuries to the train crew or the public. BNSF elected not to require the crew to submit to toxicological testing.

The probable cause of the incident was the complete failure of the tank car. The failure occurred due to the presence of two pre-existing fatigue cracks, which were located at the inboard terminations of the welds joining the extended stub sill cradle pad to the tank. These cracks propagated in a brittle manner completely around the tank causing it to fracture into two seperate halves. This was a result of the dynamic forces imposed by the trailing cars as they ran toward the head end cars, which had been slowed by the air hose separation at the 24th and 25th cars in the train.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The train crew of BNSF HNT-05 consisted of a locomotive engineer and a conductor. They reported for duty at 11 a.m., on March 5, 2008, at BNSF's Northtown Yard in Minneapolis, Minnesota. Both crew members had more than 12 hours off duty prior to reporting for duty.

The assigned freight train consisted of four locomotives, 71 loads and 64 empties. BNSF Train HNT-05 was 7,982 feet long and weighed 11,477 tons. Per BNSF rules, two of the locomotives were cut out, and the other two were de-rated to 95% of their nominal rating. The train was scheduled to travel to La Crosse, Wisconsin.

BNSF Train HNT-05 received the required Class 1 initial terminal air brake test, and departed Northtown Yard at 1:40 p.m. The crew stated the trip was uneventful prior to the incident. The St. Croix Subdivision has one main track at the location of the release. The single main track extends from CP Prescott, milepost 407.6, to CP Burns, milepost 407.8. East of CP Prescott and west of CP Burns there are two main tracks. The timetable direction of BNSF Train HNT-05 was east. Geographically the train was going virtually east. Timetable directions are used thru-out this report.

The single main track crosses the St. Croix River on the Prescott Bridge. BNSF has classified the single main track in the area of the incident as FRA Class 2. BNSF has designated a 25 mph permanent speed restriction from milepost 407.4 to 408.1.

THE ACCIDENT:

BNSF Train HNT-05 was operating at 17 mph at the time of the accident. The speed was recorded by the event recorder of the controlling locomotive. BNSF Train HNT-05 experienced an undesired emergency application of the train air brake system when the air hoses between the 24th and 25th cars separated.

Tank car OWIX was the 75th head car of the 136 car consist of BNSF Train HNT-05. Tank car OWIX broke

in two shortly after BBNSF Train HNT-05 stopped. Tank car OWIX then released its product into the St. Croix River.

The conductor left the locomotive and began to walk towards the west to find the cause of the air brake application and subsequent train separation. The conductor received a phone call from a BNSF Road-master, who was in the area, and was told to return to the locomotive and be prepared to give the BNSF Train Hazardous Material Emergency Information to first responders.

The United States Environmental Protection Agency (EPA) responded to the accident. Their report states that all the material discharged onto the ground along the tracks and flowed directly into the St. Croix River. It was determined that the material would eventually dissipate in the river water. The EPA may have additional activity at the site concerning soil sampling, runoff sampling, and bank restoration.

Also responding to the incident were the Hastings, Minnesota, Fire Department, Minnesota Pollution Control Agency, Minnesota Department of Transportation, and the U. S. Coast Guard. The U. S. Army Corps of Engineers will be consulted concerning the damages to the river bank and its restoration. The Hastings Fire Department's Assistant Chief made the decision to close U. S. Route 10.

An EPA responder said there were no water intakes downstream for the next 100 miles. No drinking water related emergency was declared. Hulcher Inc. responded to the incident and used absorbent pads to collect about 100 gallons of the material.

ANALYSIS AND CONCLUSIONS:

ANALYSIS - FATIGUE:

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that data information FRA concluded that fatigue was not probable for any of the crew members.

ANALYSIS - TRACK:

BNSF required FRA track inspection records, BNSF geometry car data, and BNSF internal rail flaw records were reviewed by FRA. No exceptions were taken.

CONCLUSION:

Track was not a causal factor to the incident.

ANALYSIS - TRAIN HANDLING:

FRA reviewed the data from the event recorder of the lead locomotive and took no exception to the performance of the locomotive engineer.

CONCLUSION:

Train handling was not a causal factor.

LONGITUDINAL FORCES STATEMENT:

BNSF requested an analysis of in-train forces for BNSF Train HNT-05 from Rail Sciences Inc. (RSI). RSI used two locations in the train where the undesired emergency application may have occurred, the 76th car, the tank car that broke in two, and the 22nd car, close to where a hose separation occurred. In the 22nd car scenario the maximum draft force exceeded 350,000 lbs. (350 kip). In a 76th car scenario the draft forces on the 76th car would have been more than 400,000 lbs. (400 kips).

TANK CAR OWIX STATEMENT

The tank car failure originated at two fatigue cracks at the inboard terminations of the welds on the A-end of the tank car at the extended stub sill cradle pad. Rust indicated a pre-existing condition in the form of the cracks in the parent metal of the inner tank. This condition indicates the cracks had existed sometime prior to the emergency brake application of BNSF Train HNT-05.

Tank car OWIX had been repaired in 1999. Cracks at the inboard terminations of the welds joining the original stub sill cradle pad were repaired and the stub sill cradle pads were extended at both ends of the car. A head pad extension and head brace also were installed to both ends of the car. The drawings for these repairs are in the attachments.

The two tank car tank halves of car OWIX were shipped to Kansas City, Missouri, for metallurgical tests at Bodycote Testing Group. The test protocols are in the attachments.

The findings of Bodycote are as follows:

"In the opinion of Bodycote Testing Group Inc., two separate high cyclic fatigue cracks originated at the termination toe of the fillet welds joining the cradle pad to the tank. Corrosion on the fatigue fracture surface is consistent with arrestment of the fatigue cracks at their present size long enough to corrode. Determination of the time of formation of the initial fatigue cracks is not possible from this material evidence. Brittle fractures initiated (from an over stress event) at the edge of both arrested fatigue cracks and propagated around the tank causing the tank to separate. Multiple brittle fracture initiation sites are consistent with an impact force incident."

PROBABLE CAUSE AND CONTRIBUTING FACTORS:

The probable cause of the incident was the complete failure of OWIX's tank car tank. This occurred due to the presence of two pre-existing fatigue cracks, which were located at the inboard terminations of the welds joining the extended stub sill cradle pad to the tank. These cracks propagated in a brittle manner completely around the tank causing it to fracture into two halves. This was a result of the dynamic forces imposed by the trailing cars as they ran toward the head end cars, which had been slowed by the air hose separation at the 24th and 25th cars in the train.