



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2008-42***

***Union Pacific (UP)  
Glamis, CA  
April 12, 2008***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 0408LA013					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident No. N/A					
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A			3b. Railroad Accident/Incident No. N/A					
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]			4a. Alphabetic Code UP			4b. Railroad Accident/Incident No. 0408LA013					
5. U.S. DOT_AAR Grade Crossing Identification Number			6. Date of Accident/Incident Month 04 Day 12 Year 2008			7. Time of Accident/Incident 04:00: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM					
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision					
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts					
			13. Other (describe in narrative)			Code 01					
9. Cars Carrying HAZMAT 5		10. HAZMAT Cars Damaged/Derailed 5		11. Cars Releasing HAZMAT 0		12. People Evacuated 0		13. Division Los Angeles			
14. Nearest City/Town Glamis			15. Milepost (to nearest tenth) 699.6		16. State Abbr Code N/A CA		17. County IMPERIAL				
18. Temperature (F) (specify if minus) 87 F		19. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		Code 2		20. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		Code 1			
21. Type of Track 1. Main 3. Siding 2. Yard 4. Industry			Code 1								
22. Track Name/Number Single Main Track			23. FRA Track Code Class (1-9, X) 5		24. Annual Track Density (gross tons in millions) 39.82		25. Time Table Direction 1. North 3. East 2. South 4. West				
						Code 4					
OPERATING TRAIN #1											
26. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		27. Was Equipment Attended? Code 1. Yes 2. No   1			
28. Train Number/Symbol KATLB-09											
29. Speed (recorded speed, if available) R - Recorded E - Estimated 50 MPH   R			Code R			31. Method(s) of Operation (enter code(s) that apply)					
30. Trailing Tons (gross tonnage, excluding power units) 7033			Code 7033			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
						Code(s) e N/A N/A N/A N/A					
32. Principal Car/Unit			a. Initial and Number DDTB724138		b. Position in Train 76		c. Loaded (yes/no) yes				
(1) First involved (derailed, struck, etc)							33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A				
(2) Causing (if mechanical cause reported)			0		0		N/A				
						34. Was this consist transporting passengers? (Y/N) N					
35. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		36. Cars			
								a. Freight b. Pass. c. Freight d. Pass. e. Caboose			
(1) Total in Train		4		0 0		0 0		(1) Total in Equipment Consist 111 0 1 0 0			
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed 32 0 0 0 0			
37. Equipment Damage This Consist \$886,808.00			38. Track, Signal, Way, & Structure Damage \$151,273.00			39. Primary Cause Code T215			40. Contributing Cause Code N/A		
Number of Crew Members					Length of Time on Duty						
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0		45. Engineer/Operator Hrs 4 Mi 30		46. Conductor Hrs 4 Mi 30	
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other		50. EOT Device? 1. Yes 2. No   1		51. Was EOT Device Properly Armed? 1. Yes 2. No   1	
Fatal		0		0		0					
Nonfatal		0		0		0		52. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
OPERATING TRAIN #2											
53. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		54. Was Equipment Attended? Code 1. Yes 2. No   N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH   N/A			Code N/A			58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		
			a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track								

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded E - Estimated	N/A MPH N/A	a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
84. Trailing Tons (gross tonnage, excluding power units)	N/A	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	
		N/A N/A N/A N/A N/A	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment	3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code N/A	112. Position of Car Unit in	N/A		
		1. North 2. South 3. East 4. West					

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A			
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code N/A	114b. Was there a hazardous materials release				Code N/A			
1. Highway User 2. Rail Equipment 3. Both 4. Neither					1. Highway User 2. Rail Equipment 3. Both 4. Neither							
114c. State here the name and quantity of the hazardous materials released, if any. N/A												
115. Type Crossing Warning				Code	116. Signaled Crossing (See instructions for codes)				Code			
1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None												
Code(s)				N/A	N/A				N/A			
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A			
120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown												
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A			
124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop					124. Driver 4. Stopped on Crossing 5. Other (specify in narrative)				Code N/A			
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A			
Casualties to:		Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	Code N/A		
129. Highway-Rail Crossing Users		N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			
132. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A				133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A				135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



## 137. SYNOPSIS OF THE ACCIDENT

On April 12, 2008, at approximately 4:00 p.m. PDT westbound Union Pacific (UP) Railroad Freight Train KATLB-09 consisting of four locomotives and 111 loads and one empty rail car traveling at an estimated speed of 56 mph derailed 32 loaded intermodal well cars on single main track near Glamis, California.

The derailment occurred at milepost 699.65 on the UP Los Angeles Service Unit, Yuma Subdivision. Movements on this part of the railroad are governed by Centralized Traffic Control (CTC) by a dispatcher located in San Bernardino, California. Authorized speed for passenger trains is 79 mph and 70 mph for freight trains designated as FRA Class 5 track regulated by the Los Angeles Area Timetable #3, effective June 18, 2006.

There were no injuries resulting from the accident and no hazardous materials involved.

The weather was clear and the temperature 87° F.

Estimated equipment damage is \$ 866,808. Track and signal damages estimated at \$ 151,273.

Post-accident drug testing was conducted on the engineer and conductor. The results of the test were negative.

The probable cause of the derailment was broken rail joint bars, FRA Code T215.

## 138. NARRATIVE

## CIRCUMSTANCES PRIOR TO THE ACCIDENT

On April 12, 2008 after completing the required statutory off duty rest period a crew consisting of an engineer and conductor reported for duty at their away from home terminal in Yuma, Arizona at 11:30 am PDT. The crew was assigned to operate a westbound UP Intermodal Train KATLB-09 en route from Yuma, Arizona to West Colton, California.

The train consisted of four locomotives, 111 loads and one empty with 7,033 trailing tons and was 7,724 feet in length. The crew departed Yuma at 1:44 p.m. PDT heading geographically and timetable direction west. Timetable directions will be used throughout this report.

The engineer was seated at the controls on the north side of the leading locomotive and the conductor was seated on the south side of the leading locomotive. UP Train KATLB-09 took the siding at Dunes waiting for four freight trains to pass and then proceeded west passing another freight train on the siding at Cactus. The engineer stated he was following UP fuel conservation rules which require an engineer not to operate above run 5 if the timetable speed is over 50 mph.

Approaching the derailment site from the east traversing west there is tangent track from milepost 701.0 to the point of derailment (POD) at mile post 699.65 with a 0.25 percent descending grade. The train passed a hot box detector (HBD) at mile post 700.38.

## THE ACCIDENT

The engineer was operating UP Train KATLB-09 at a recorded speed of 57 mph in run 5 approaching the point of derailment (POD). The maximum authorized speed for this train was 70 mph identified in the UP Los Angeles Area Timetable #3. According to the train crew, they did not observe or feel anything unusual prior to the derailment. The train had slowed to 50 mph when the derailment occurred. Speeds were recorded by the event recorder of the leading locomotive.

Approaching Highway 78 at mile post 698.40 the train experienced an emergency brake application; the engineer attempted to recover the air. The engineer and conductor looked back towards the rear of the train and observed a dust cloud. The conductor left the locomotive and walked towards the rear of the train and observed 32 intermodal bays derailed, identified as lines 76 through 107 on the consist. The engineer remained on the locomotive to establish an emergency radio distress call to the dispatcher. The train was blocking Highway 78, the only route in this remote area, and traffic began backing up on both sides of the crossing. The California Highway Patrol, Imperial County Sheriff's office, and the Brawley City Fire Department responded to the scene.

#### POST-ACCIDENT INVESTIGATION

A post accident investigation conducted by UP engineering forces and a California Public Utilities Commission (CPUC) track inspector discovered a pair of 100 percent center broken joint bars at the POD. The gage side joint bar was broken through the first bolt hole closest to the rail end. The field side bar was center broken. The bars were sent by UP Officials to Rail Sciences for analysis.

FRA reviewed the UP inspection reports for the period of March 31 through April 10, 2008 with special notice to the area of the POD. No defects were noted by the UP inspector and FRA took no exceptions to the reports. The UP inspection report for April 10, 2008 reflects the joint at the POD location was inspected and no defects were noted. UP rail detector inspection car reports for February 27, 2008 reflect no rail defects discovered in the area of the POD.

The FRA DOTX Geometry Car survey of the Yuma subdivision of March 10, 2008 did not reveal any conditions that would have contributed to the broken joint bars but did document tight gage in the vicinity of the POD, measured at 55.87". The FRA minimum track standard for FRA class 5 track is 56".

#### ANALYSIS AND CONCLUSIONS

The UP Rail Cut-Ins and Cut-Outs report revealed the joint at the POD was installed on January, 23, 2008. UP Track Inspection reports discovered the joint was inspected on April 10, 2008 and no defects were noted by the track inspector.

Rail Sciences conducted an analysis of the broken joint bars found at the derailment site. The report concluded, "UP Train KATLB-09 derailed due to a pair of broken joint bars that failed due to fatigue cracks which initiated from the joint in the rail flexing."

The two crew members of UP Train KATLB-09 were subjected to FRA mandatory post-accident toxicology tested; both crew members had negative test results.

The event recorder for the controlling locomotive did not reveal abnormal train handling at or prior to the derailment. The FRA and UP signal inspectors reviewed the detailed train report generated from the hot box detector (HBD) at mile post 700.38 and found no defects recorded from the train.

#### CONCLUSION

The railroad was in compliance with its own Rules and all applicable FRA Standards. There were no witnesses to the accident. The train crew on UP Train KATLB-09 stated they never felt anything unusual traversing over the POD. The data reviewed from the event recorder rules out train handling as a contributing cause and the HBD findings did not reveal any equipment conditions that would have contributed to the derailment.

#### PROBABLE CAUSE AND CONTRIBUTING FACTORS

FRA has concluded that the probable cause of the derailment was the broken joint bars, FRA cause code T215.