



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-45***

***Kansas City Southern (KCS)
Saginaw, KS
April 20, 2008***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Kansas City Southern Rwy Co. [KCS]		1a. Alphabetic Code KCS		1b. Railroad Accident/Incident No. 08042001	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Kansas City Southern Rwy Co. [KCS]		4a. Alphabetic Code KCS		4b. Railroad Accident/Incident No. 08042001	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 04 Day 20 Year 2008		7. Time of Accident/Incident 03:27: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative) Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
				12. People Evacuated 0	
				13. Division Midwest	
14. Nearest City/Town Saginaw		15. Milepost (to nearest tenth) 160.1		16. State Abbr Code N/A MO	
17. County NEWTON					
18. Temperature (F) (specify if minus) 70 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
22. Track Name/Number Single Main Track		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 40.56	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 1	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1	
28. Train Number/Symbol GSLKCS15					
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 43 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 2479		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits k N/A N/A N/A N/A	
				31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) KCS4048		b. Position in Train 6	
(2) Causing (if mechanical cause reported)		0		c. Loaded (yes/no) N/A	
		0		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
				34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End		Mid Train	
		b. Manual		c. Remote	
		d. Manual		c. Remote	
(1) Total in Train		6		0 0 0 0	
(2) Total Derailed		1		0 0 0 0	
				36. Cars a. Freight b. Pass. c. Freight d. Pass. e. Caboose (1) Total in Equipment Consist 0 0 80 0 0 (2) Total Derailed N/A 0 33 0 0	
37. Equipment Damage This Consist \$214,106.00		38. Track, Signal, Way, & Structure Damage \$863,569.00		39. Primary Cause Code T111	
				40. Contributing Cause Code T099	
				41. Engineer/Operators 1	
				42. Firemen 0	
				43. Conductors 1	
				44. Brakemen 0	
				45. Engineer/Operator Hrs 7 Mi 27	
				46. Conductor Hrs 7 Mi 27	
Casualties to:		47. Railroad Employees		48. Train Passengers	
Fatal		0		0	
Nonfatal		1		0	
				49. Other 0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
55. Train Number/Symbol N/A					
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (<i>gross tonnage, excluding power units</i>)		N/A		c. Auto train stop	i. Time table/train orders	o. Positive train control					2 = Remote control tower				
				d. Cab	j. Track warrant control	p. Other (<i>Specify in narrative</i>)					3 = Remote control transmitter - more than one remote control transmitter				
				e. Traffic	k. Direct traffic control	Code(s)									
				f. Interlocking	l. Yard limits	N/A	N/A	N/A	N/A	N/A	N/A				
59. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		60. If railroad employee(s) tested for drug/alcohol use,							
(1) First involved (<i>derailed, struck, etc</i>)		0		0		N/A		enter the number that were positive in the appropriate box.							
								Alcohol		Drugs					
								N/A		N/A					
(2) Causing (<i>if mechanical cause reported</i>)		0		0		N/A		61. Was this consist transporting passengers? (Y/N)							
								N/A							
62. Locomotive Units		a. Head End		Mid Train		Rear End		63. Cars		Loaded		Empty		e. Caboose	
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight	
										d. Pass.					
(1) Total in Train		0		0		0		(1) Total in Equipment Consist		0		0		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0		0	
64. Equipment Damage This Consist		\$0.00		65. Track, Signal, Way, & Structure Damage		\$0.00		66. Primary Cause Code		N/A		67. Contributing Cause Code		N/A	
68. Engineer/Operators		69. Firemen		70. Conductors		71. Brakemen		72. Engineer/Operator		73. Conductor					
0		0		0		0		Hrs 0 Mi 0		Hrs 0 Mi 0					
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other		77. EOT Device?		78. Was EOT Device Properly Armed?					
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A					
Nonfatal		0		0		0		79. Caboose Occupied by Crew?		1. Yes 2. No				N/A	
OPERATING TRAIN #3															
80. Type of Equipment Consist (<i>single entry</i>)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip.		Code		81. Was Equipment Attended?		82. Train Number/Symbol	
		2. Passenger train		5. Single car		8. Light loco(s).				N/A		1. Yes 2. No N/A		N/A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car									
83. Speed (<i>recorded speed, if available</i>)		Code		85. Method(s) of Operation (<i>enter code(s) that apply</i>)				85a. Remotely Controlled Locomotive?							
R - Recorded		N/A		a. ATCS		g. Automatic block		m. Special instructions							
E - Estimated		MPH		b. Auto train control		h. Current of traffic		n. Other than main track							
N/A		N/A		c. Auto train stop		i. Time table/train orders		o. Positive train control							
84. Trailing Tons (<i>gross tonnage, excluding power units</i>)		N/A		d. Cab		j. Track warrant control		p. Other (<i>Specify in narrative</i>)							
				e. Traffic		k. Direct traffic control		Code(s)							
				f. Interlocking		l. Yard limits		N/A		N/A		N/A		N/A	
86. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		87. If railroad employee(s) tested for drug/alcohol use,							
(1) First involved (<i>derailed, struck, etc</i>)		N/A		N/A		N/A		enter the number that were positive in the appropriate box.							
								Alcohol		Drugs					
								N/A		N/A					
(2) Causing (<i>if mechanical cause reported</i>)		N/A		N/A		N/A		88. Was this consist transporting passengers? (Y/N)							
								N/A							
89. Locomotive Units		a. Head End		Mid Train		Rear End		90. Cars		Loaded		Empty		e. Caboose	
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight	
										d. Pass.					
(1) Total in Train		N/A		N/A		N/A		(1) Total in Equipment Consist		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A		(2) Total Derailed		N/A		N/A		N/A	
91. Equipment Damage This Consist		N/A		92. Track, Signal, Way, & Structure Damage		N/A		93. Primary Cause Code		N/A		94. Contributing Cause Code		N/A	
95. Engineer/Operators		96. Firemen		97. Conductors		98. Brakemen		99. Engineer/Operator		100. Conductor					
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A					
Casualties to:		101. Railroad Employees		102. Train		103. Other		104. EOT		105. Was EOT Device Properly					
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A					
Nonfatal		N/A		N/A		N/A		106. Caboose Occupied by Crew?		1. Yes 2. No				N/A	
Highway User Involved								Rail Equipment Involved							
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code								111. Equipment		3. Train (<i>standing</i>)		6. Light Loco(s) (<i>moving</i>)		Code	
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian								1. Train(<i>units pulling</i>)		4. Car(s) (<i>moving</i>)		7. Light(s) (<i>standing</i>)		N/A	
B. Truck E. Van H. Motorcycle M. Other (<i>spec. in narrative</i>) N/A								2. Train(<i>units pushing</i>)		5. Car(s) (<i>standing</i>)		8. Other (<i>specify in narrative</i>)			
108. Vehicle Speed (<i>est. MPH at impact</i>)		N/A		109. geographical Code		N/A		112. Position of Car Unit in		N/A					
				1. North 2. South 3. East 4. West											

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative)	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Northbound Kansas City Southern (KCS) empty grain Train # GSLKCS-15 derailed the sixth locomotive and 33 empty grain cars on April 20, 2008 at 3:25 p.m. CST. The accident occurred near Saginaw, Missouri at KCS Milepost (MP) 160.1 on the KCS Heavener Subdivision.

At the time of the accident it was daylight and clear. The temperature was an estimated 70 F.

The equipment damage was estimated at \$ 214,106. Track damage was estimated at \$ 863,569. There was no signal damage. The KCS Locomotive # 4048 turned over and spilled an estimated 400 gallons of diesel fuel. The local fire department contained the spill.

Following the accident the engineer reported he hit his back on the seat of the locomotive and requested medical assistance.

The probable cause of the accident is FRA Cause Code T-111; wide gage due fasteners not sufficient enough to hold gage from vertical impact. The contributing cause is FRA Cause Code T-099; fouled and insufficient ballast.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of northward KCS Unit Grain Train # GSLKCS-15 included a locomotive engineer and a conductor. They first went on duty at 8:00 a.m. CST on April 20, 2008 at Heavener Yard in the city of Heavener, Oklahoma. This is the away-from-home terminal for both crewmembers and each had the required statutory off-duty rest period prior to reporting for duty.

The assigned freight train consisted of six locomotives on the head-end. The lead, the second and the fifth locomotives were online; the third, fourth and the sixth locomotives were isolated. There were 80 empty grain hopper cars and an end-of-train device (EOTD) # UPRQ 34423. The train was 5,250 feet in length, and the weight was listed at 2,479 tons. The train was scheduled to travel to Kansas City, Missouri. The train received an initial terminal train air brake test at Laredo, Texas by the mechanical personnel and had arrived at Heavener at 3:20 a.m. No other test was required. The train departed Heavener at 9:05 a.m. CST.

As the train approached the accident area, the locomotive engineer was seated at the controls on the east side of the lead locomotive. The conductor was seated on the west side of the lead locomotive. The railroad timetable direction of the train was north, and the geographic direction was north. Timetable directions are used throughout this report.

The train was coming out of a right-hand 2-degree curve at MP 160.4 onto 3,000 feet of tangent track and approaching the south Saginaw switch at MP 160.2. The grade at this location is 0.50-percent ascending. The track was constructed with 136 lb. Continuous-Weld Rail (CWR) on wood cross ties and the spike pattern is two spikes on the gage side, one spike on the field side, and two anchor spikes. The anchor pattern was every other tie boxed anchored.

THE ACCIDENT

The train was being operated at 45 mph approaching the accident area. At the time the accident occurred the

train was being operated at 43 mph. Both speeds were recorded by the event recorder on Locomotive # KCS 4577. The maximum authorized track speed is 50 mph as indicated in KCS Timetable # 7 dated July 1, 2006.

The engineer stated that as the train passed the South Switch at Saginaw they hit a mud hole in the track and bounced the locomotive. He stated he looked back to see if other units made it over and saw Locomotive # KCS 4048 (# 6) was derailed. At the same time the train had experienced an undesired emergency train air brake application. The rear locomotive had separated from the rest of the locomotive consist.

When the train stopped the crew did a job briefing and the conductor dismounted to inspect the damages. The engineer grabbed a fire extinguisher and went back to put out a small fire on locomotive KCS 4048. The Ragan Mill Fire Department arrived and helped extinguish the fire.

ANALYSIS AND CONCLUSION:

ANALYSIS TOXICOLOGICAL TESTING:

The two crewmembers of BNSF Train GSLKCS-15 were mandatory post-accident toxicologically tested. The test results were negative.

CONCLUSION:

Drugs and alcohol were not factors in this accident.

ANALYSIS:

FRA obtained fatigue related information for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

ANALYSIS-LOCOMOTIVE ENGINEER OPERATING PERFORMANCE:

The locomotive was equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded by the manager of operating practices at the accident site and analyzed at the KCS Pittsburg Yard Office in Pittsburg, Kansas.

CONCLUSION:

The locomotive engineer was in compliance with all applicable railroad operating and train handling requirements.

ANALYSIS-TRACK:

The last ultrasonic rail detection test through this area was on December 14, 2007 by Sperry Rail Car # SRS 124. There were no rail defects noted in the immediate area of MP 159 to 161. The last geometry car survey was in February by Holland Track Test Car # 480. There were not any exceptions taken in the area of the derailment. Track inspection records revealed that the track was last inspected on April 17, 2008 with a foul ballast condition 103.02 exception noted in the area of the derailment.

During the investigation it was revealed that a surfacing gang had gone to the area of the derailment on April 18, 2008. The surfacing gang had surfaced two locations between the south and north switches at Saginaw. They left the west side of this area open for drainage. The road-master told FRA that the area had a small rain shower sometime prior to the derailment. This, along with the pumping action of several trains, caused the dirt and the rock to work its way out from under the crossties allowing a 2 1/4 inch profile to work its way into the track surface.

CONCLUSION:

This geometric profile condition created an increased vertical impact by rail equipment which caused the track gage to be widened to 58 1/4 inches at the point of derailment. This condition allowed the rear trucks of Locomotive # KCS 4048, the 6th locomotive, to fall between the gage of the rails resulting in the derailment.

The railroad was not in compliance with its own standards or applicable FRA Track Standards. The train crewmembers were the only witnesses to the derailment.

OVERALL CONCLUSION:

The investigation revealed there was no mechanical, fatigue, or operating factors that contributed to the derailment. Noncompliant track conditions were found to be the primary and contributing causes.

PROBABLE CAUSE, CONTRIBUTING FACTORS, AND CONCLUSION:

The probable cause was FRA Code T-111 - wide gage due to fasteners that were not sufficient to hold gage from high vertical impact. The contributing cause was FRA Code T-099 - foul and insufficient ballast.