



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-46***

***Burlington Northern Santa Fe (BNSF)
Lafayette, LA
May 17, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. GC0508110		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. GC0508110		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 05 Day 17 Year 2008		7. Time of Accident/Incident 01:35: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative)		
Code 01						
9. Cars Carrying HAZMAT 6		10. HAZMAT Cars Damaged/Derailed 4		11. Cars Releasing HAZMAT 1		
				12. People Evacuated 3005		
				13. Division Gulf		
14. Nearest City/Town Lafayette		15. Milepost (to nearest tenth) 147.7		16. State Abbr Code N/A LA		
				17. County LAFAYETTE		
18. Temperature (F) (specify if minus) 75 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2		
22. Track Name/Number 103		23. FRA Track Code Class (1-9, X) 1		24. Annual Track Density (gross tons in millions) N/A		
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 4		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1		
				28. Train Number/Symbol GFC3111-17		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 7 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 1377			31. Method(s) of Operation (enter code(s) that apply)	
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		
(1) First involved (derailed, struck, etc)		GATX 64605		12		
(2) Causing (if mechanical cause reported)		N/A		0		
				c. Loaded (yes/no) yes		
				N/A		
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		
				Alcohol 0		
				Drugs 0		
				34. Was this consist transporting passengers? (Y/N) N		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		2		0 0		
(2) Total Derailed		0		0 0		
				36. Cars		
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
				7 0 16 0 0		
				7 0 0 0 0		
37. Equipment Damage		38. Track, Signal, Way, & Structure Damage		39. Primary Cause Code		
This Consist \$110,900.00		\$140,000.00		M507		
				40. Contributing Cause Code N/A		
Number of Crew Members			Length of Time on Duty			
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		
				44. Brakemen 1		
				45. Engineer/Operator Hrs 2 Mi 5		
				46. Conductor Hrs 2 Mi 5		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0		
Nonfatal		0		0		
				49. Other 0		
				50. EOT Device? 1. Yes 2. No 1		
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A		
				55. Train Number/Symbol N/A		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive?	
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
------------------------	---	-------------	---	----------------	---	--------------	---	-----------------------	------------	---------------	------------

Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No N/A
Fatal	0	0	0	79. Caboose Occupied by Crew?	1. Yes 2. No		N/A
Nonfatal	0	0	0				

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded E - Estimated	N/A MPH 0	a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
84. Trailing Tons (gross tonnage, excluding power units)	N/A	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	
		N/A N/A N/A N/A N/A	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

91. Equipment Damage This Consist	\$0.00	92. Track, Signal, Way, & Structure Damage	\$0.00	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			


95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
------------------------	---	-------------	---	----------------	---	--------------	---	-----------------------	------------	----------------	------------

Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No N/A	105. Was EOT Device Properly	1. Yes 2. No N/A
Fatal	0	0	0	106. Caboose Occupied by Crew?	1. Yes 2. No		N/A
Nonfatal	0	0	0				

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code	111. Equipment	Code	3. Train (standing)	6. Light Loco(s) (moving)	Code	
	N/A	1. Train(units pulling)	N/A	4. Car(s) (moving)	7. Light(s) (standing)		
		2. Train(units pushing)		5. Car(s) (standing)	8. Other (specify in narrative)		N/A
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code	112. Position of Car Unit in			
		1. North 2. South 3. East 4. West	N/A		0		

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On May 17, 2008, westbound Burlington Northern Santa Fe (BNSF) Train R-GFC3111-17 derailed while departing the BNSF Lafayette Yard in Lafayette, LA. The derailment occurred about 1:35 a.m. in Track No. 103 near milepost 147.7 on the Lafayette Subdivision. The train consisted of two locomotives and 23 rail cars. The 10th thru 16th cars behind the locomotives derailed. The BNSF has listed the cost of the derailment as \$250,900 (\$110,900 for equipment and \$140,000 for track damage).

At the time of the derailment, it was dark and the weather was clear and the temperature was 75 degrees F.

During the derailment a loaded tank car impacted a nearby highway overpass causing the car to release a large amount of Hydrochloric Acid. As a result of this release an area within one mile of the derailment site was evacuated, effecting about 3000 nearby residents and businesses.

The cause of the derailment has been determined to be T110- Wide gage due to defective cross ties.

FRA's initial inspection of the equipment revealed no obvious defects. The train's event recorders showed no adverse conditions that would have caused the derailment. FRA's Track Inspector inspected the derailment site after it was cleared by heavy equipment and found nothing definitive that would have caused the derailment. The FRA 6180.54 report that BNSF has submitted shows the cause as M505 (Cause under active investigation by the reporting railroad).

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT:

The crew of Burlington Northern Santa Fe (BNSF) Train R-GFC3111-17 consisted of a locomotive engineer, a conductor, and a brakeman. They went on duty at 11:30 p.m. CST, on May 16, 2008, at the BNSF Lafayette yard. The train was scheduled to go from Lafayette, LA en route to Beaumont, TX and return. All crew members had received more than the required statutory off duty rest period prior to reporting for duty.

The BNSF Train R-GFC3111-17 consisted of two locomotives, seven loaded rail cars, and sixteen empty rail cars. The train was 1,391 feet long and had 1,377 trailing tons. The crew completed the required train air brake test and locomotive inspection before departing Lafayette yard. No exceptions were noted.

The westbound BNSF train departed Lafayette Yard on Track # 153 and then diverted on to Track #103. The engineer was seated at the controls on the north side of the lead locomotive. The conductor was seated in the first seat on the south side of the lead locomotive and the brakeman was sitting in the brakeman's seat.

The area near the Point of Derailment (POD) is flat with a curve leading up to a #10 right hand turnout which connects Track # 103 to Track # 102. Both tracks are designated as FRA Class 1 and the timetable speed is 10 mph. The weather was clear, the temperature was 75° F, and it was dark.

THE ACCIDENT:

As westward BNSF Train R-GFC3111-17 proceeded at a recorded speed of 7 mph, on Track # 103, the crew reported that they felt a slight "tug". The train crew then experienced an emergency brake application of the train air brake system. The speed recorded by the event recorder at this time was 7 mph. After the train stopped the brakeman and conductor began walking east to inspect the rear of the train. They immediately noticed a "cloud" coming from the rear of the train and notified the yardmaster that the train had derailed. They cut one car and the locomotives away from the train and took them to the west end of the yard.

A total of seven cars were derailed on the west end of Track # 103 just east of the switch to Track # 102. As a result of the derailment tank car # GATX 72822 struck a support of the Ambassador Caffery overpass. About 10,000 gallons of hydrochloric acid was released after a valve on the car was damaged by the impact. Louisiana State Police evacuated the area within a one mile radius of the derailment as a precaution for approximately 52 hours.

ANALYSIS:

The accident met the criteria for 49 CFR Part 219 Subpart C Post Accident Toxicological Testing of the crew. The test results were negative.

ANALYSIS:

FRA obtained fatigue related information for the 10-day period preceding the incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

The BNSF Freight Train R-GEC3111-17 event recorder was downloaded by BNSF personnel and no excessive speed or adverse train handling was noted in the data prior to the derailment. On May 19, 2008, FRA and BNSF personnel inspected the derailment site. BNSF Officials took track measurements and FRA observed the results. It should be noted that the derailed equipment had been removed and the site had been disturbed by heavy equipment involved in the clearing process. Due to this fact several of the track measurements taken were not accurate. FRA observed nothing definitive at the site to determine a cause. As part of the investigation FRA inspected BNSF track inspection records for the BNSF Lafayette Yard. The BNSF track inspector recorded no defects for the five months prior to May 17, 2008. Recent track inspections performed by FRA inspectors resulted in numerous defective conditions noted in Lafayette Yard, but none in the immediate area surrounding the derailment. FRA investigators inspected the equipment involved on May 21, 2008, and noted no obvious defects.

CONCLUSION:

The train was being operated in accordance with FRA Regulations and BNSF Rules as indicated by event recorder data. The results of toxicology tests on all crew members test results were negative. FRA has concluded that fatigue was not a probable cause of the accident. The BNSF obtained the services of a derailment investigation firm in an effort to further determine the cause of this accident and the BNSF using data from that investigation concluded that the probable cause of the derailment was wide gage. However, due to fact that FRA was not able to view the derailment site until after heavy equipment significantly altered the site they were not able to determine the cause with reasonable certainty.