



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-48***

***Canadian National-North America (CN)
Crystal Springs, MS
May 27, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Amtrak [ATK]		1a. Alphabetic Code ATK		1b. Railroad Accident/Incident No. 108129	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Canadian National - North America [CN]		4a. Alphabetic Code CN		4b. Railroad Accident/Incident No. 596181	
5. U.S. DOT_AAR Grade Crossing Identification Number 299824D		6. Date of Accident/Incident Month 05 Day 27 Year 2008		7. Time of Accident/Incident 01:00: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative) Code 07	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
				12. People Evacuated 0	
				13. Division Central	
14. Nearest City/Town Crystal Springs		15. Milepost (to nearest tenth) 751.2		16. State Abbr Code N/A MS	
				17. County COPIAH	
18. Temperature (F) (specify if minus) 90 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number single main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 23	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 2	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)					
1. Freight train		4. Work train		7. Yard/switching	
2. Passenger train		5. Single car		8. Light loco(s).	
3. Commuter train		6. Cut of cars		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code 2	
				27. Was Equipment Attended? Code 1. Yes 2. No 1	
				28. Train Number/Symbol P05991-26	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 79 MPH R		31. Method(s) of Operation (enter code(s) that apply)			31a. Remotely Controlled Locomotive?
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
30. Trailing Tons (gross tonnage, excluding power units) N/A		e		N/A N/A N/A N/A	
32. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
(1) First involved (derailed, struck, etc)		ATK 7	1	N/A	Alcohol N/A
(2) Causing (if mechanical cause reported)		0	0	N/A	Drugs N/A
				34. Was this consist transporting passengers? (Y/N) Y	
35. Locomotive Units		a. Head End	Mid Train		Rear End
		b. Manual	c. Remote	d. Manual	c. Remote
(1) Total in Train		1	0	0	0
(2) Total Derailed		1	0	0	0
				36. Cars	Loaded
				a. Freight	b. Pass.
				c. Freight	d. Pass.
				e. Caboose	
				0	6
				0	0
				0	0
37. Equipment Damage		38. Track, Signal, Way, & Structure Damage		39. Primary Cause Code	
This Consist \$1,200,000.00		\$65,928.00		M302	
				40. Contributing Cause Code N/A	
Number of Crew Members			Length of Time on Duty		
41. Engineer/Operators 2		42. Firemen 0		43. Conductors 2	
				44. Brakemen 0	
				45. Engineer/Operator Hrs 2 Mi 10	
				46. Conductor Hrs 4 Mi 30	
Casualties to:		47. Railroad Employees	48. Train Passengers	49. Other	
Fatal		0	0	0	
Nonfatal		8	16	2	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No 2	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)					
1. Freight train		4. Work train		7. Yard/switching	
2. Passenger train		5. Single car		8. Light loco(s).	
3. Commuter train		6. Cut of cars		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code N/A	
				54. Was Equipment Attended? Code 1. Yes 2. No N/A	
				55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive?
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			0 = Not a remotely controlled 1 = Remote control portable

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded E - Estimated	N/A MPH N/A	a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
84. Trailing Tons (gross tonnage, excluding power units)	N/A	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	
		N/A N/A N/A N/A N/A	

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code B			111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
				1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)	
				2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)	1
108. Vehicle Speed (est. MPH at impact)	5	109. geographical	Code 4	112. Position of Car Unit in	1		
		1. North 2. South 3. East 4. West					

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code 3	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code 1				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code 4	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code 4				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code 2	
Code(s)				07	08	N/A	N/A	N/A	N/A	N/A			
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code 1	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code 2
121. Age 44		122. Driver's Gender 1. Male 2. Female		Code 1	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code 2	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code 3
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code 2	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code 8				
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code 2	128. Was Driver in the Vehicle? 1. Yes 2. No			Code 1
129. Highway-Rail Crossing Users			0	2	130. Highway Vehicle Property Damage (est. dollar damage) 70000					131. Total Number of Highway-Rail Crossing Users (include driver) 2			
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code 1	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code 1				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code 1	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code 1				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On May 27, 2008, at 1:00 p.m., CDT, southbound Amtrak (ATK) Train P05991-26 struck a westbound Waste Management garbage truck at Hartley Lane/County Line Road, a non-signalized highway-rail grade crossing. The accident occurred in Crystal Springs, Copiah County, Mississippi (MS). The crossing is located at mile post (MP) 751.20 on the Canadian National (CN) Central Division of the McComb Subdivision. The crossing DOT/AAR No. is 299 824 D. The method of operation for the single Main Track is signal indication of a Traffic Control Signal System (TCS). The maximum authorized speed is 79 miles per hour (mph).

The male Waste Management truck driver was injured and admitted in the Intensive Care Unit under life support. The driver's male assistant was also injured and spent two weeks in the hospital, however he was sent home in stable but serious condition. Amtrak reported sixteen injuries to rail passengers. The injuries consisted of bruises and sprains. The passengers were treated at a medical facility and released. There were eight injuries sustained by six Amtrak employees on the train. The engineer, age 57, sustained a broken ankle. The conductor, age 53, and the assistant conductor sustained nose injuries. Two train attendants, ages 45 and 61, sustained shoulder injuries and one had a bruise to the head. An off duty train attendant, age 42, sustained a bruised knee and a lower back sprain.

The lead end of the lead locomotive derailed, along with the lead end of the last passenger coach car in the train. Emergency responders extinguished a fire on the lead locomotive. Total damages reported are \$1,200,000 for rail equipment and \$65,928 for signal and track structure. The Waste Management truck valued at \$75,000 was completely destroyed.

The accident occurred during daylight hours, the weather was clear, and sight distance was unlimited. The temperature at the time was 90 °F.

The probable cause of the accident was driver inattentiveness and the failure of the Waste Management garbage truck to yield the right of way to the approaching Amtrak passenger train.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

On May 27, 2008, Amtrak Train P05991-26 (ATK 59) originated in Chicago, Illinois (IL). The train consisted of one locomotive, Number ATK 7, with one baggage car, one view-liner, one diner car, one lounge car, and two passenger coach cars for a total of six cars. At Chicago, IL, a Class 1 train air brake test was performed at 3:00 p.m. on May 26, 2008. ATK 59 departed Chicago en route to Jackson, MS, a crew change point and station stop. The new Amtrak crew boarded ATK 59, at Jackson, MS and consisted of a locomotive engineer, a manager of engines, a conductor, and an assistant conductor, with their home terminal being New Orleans, Louisiana (LA). The locomotive engineer reported for duty at Jackson, MS at 10:50 a.m. after receiving 17 hours and 13 minutes rest. The conductor reported for duty at Jackson, MS at 8:30 a.m. after receiving 12 hours and 38 minutes rest. The assistant conductor reported for duty at Jackson, MS at 8:30 a.m. after receiving 12 hours and 22 minutes rest. All the hours of service employees involved had received the required statutory off duty rest period.

Amtrak P05991-26 was traveling at 79 mph as it reached Hartley Lane highway-rail grade crossing on the single Main Track. The engineer was at the controls of the lead locomotive and the manager of engines was seated in the conductor seat of the lead locomotive. The conductor was in the diner car and the assistant conductor was in the view-liner car performing their normal duties.

The single Main Track is tangent with a 0.21 percent ascending grade approaching Hartley Lane. Hartley Lane highway-rail grade crossing is equipped with passive warning devices consisting of cross-bucks and stop signs located on both sides of the tracks. Mississippi Department of Transportation (MDOT) does not have a survey of highway user traffic information for this highway-rail grade crossing.

The CN timetable and the geographic direction for the train are south. Timetable directions are used in this report.

THE ACCIDENT**AMTRAK PASSENGER TYRAIN P05991-26:**

The engineer stated that he was at the controls of Locomotive ATK 7 on passenger Train P05991-26, traveling southbound on the CN Main Track approaching Hartley Lane at 1:00 pm. The train was traveling 79 mph, as recorded by the onboard event recorder of the lead locomotive (ATK 7). The maximum authorized speed for this line segment is 79 mph, as designated in the current CN Central Division Time Table. The engineer stated that he laid on the horn as he saw the Waste Management garbage truck pull in-front of the train. The engineer put the train in emergency, and he and the manager ducked their heads and braced for the collision. Amtrak Train P05991-26 was traveling southward toward the crossing; the garbage truck was traveling in an east to west direction across the crossing prior to impact.

WASTE MANAGEMENT GARBAGE TRUCK:

The Waste Management garbage truck was traveling westward across the crossing when ATK 7 struck the truck square in the large waste container. The force of the impact caused the truck to rotate clockwise 360 degrees and break into three pieces. The truck destroyed the stop signs, the cross-buck signs, and damaged an intermediate signal location device. The full waste container was separated from the truck and came to a rest on the east side of the tracks approximately 86 feet from point of impact. The lead locomotive stopped 2,200 feet south of the point of impact.

After the train stopped, the engineer made an emergency radio transmission and notified the CN Dispatcher of the accident. The CN Dispatcher contacted the local Police and Emergency Service personnel. The engineer, manager of engines, and the conductor were injured, so the assistant conductor remained aboard the train and attended to passenger needs. According to Copiah County Sheriff's Department, the two occupants of the truck were ejected. Copiah County Fire and Rescue responded and rendered emergency aid to the train employees and the passengers. A Copiah County Sheriff's Department Officer was notified at 1:02 p.m. and arrived at the scene at 1:12 p.m. Copiah County Fire and Rescue was notified at 1:00 p.m. and arrived at the scene at 1:13 p.m.

The six Amtrak employees were transported by emergency vehicles to a hospital in Jackson, MS. Sixteen passengers were transported to a nearby medical facility in Crystal Springs by ambulance, and the two Waste Management employees were transported by Life Flight to University Medical Center in Jackson, MS.

ANALYSIS AND CONCLUSION:

The garbage truck involved was a 2003 Mack MR-6 Rear-end-loader configured in order to transport residential waste. The container was almost full at the time of the accident. The operator is a male, age 44. The male passenger/helper riding in the truck passenger's seat was age 57. They were the only vehicle occupants.

No toxicological tests were performed on the highway users or the train crew members.

After the accident, Amtrak Mechanical personnel responded from the New Orleans Shop Facility at New Orleans, LA. The mechanical personnel made emergency repairs to allow Amtrak Passenger Train ATK 59 to be moved to Brookhaven, MS.

Hartley Lane is a two lane asphalt road 20 ft wide and runs in an east/west direction. The street has a posted speed limit of 15 mph and enters into a residential housing area with no other access. The highway-rail grade crossing is equipped with two stop signs and two cross-buck signs. The whistle posts are located on the railroad right-of-way 1,500 feet north and south of the crossing. There are no pavement stop bars. There are two crossing warning signs with one placed twenty-one feet east of the crossing and one placed 150 ft west of the crossing. A vehicle operator's sight distance at Hartley Lane grade crossing for east to west movement is 5,000 feet in either direction.

A Federal Railroad Administration (FRA) inspection of the highway-rail grade crossing did not reveal any conditions that would have contributed to the accident.

The lead locomotive was equipped with a headlight, auxiliary lights, and audible warning device as required by Federal Regulations. These devices were tested and found to be functioning properly at Chicago, IL, prior

to departure. The lead locomotive was equipped with a speed indicator and an event recorder as required. The event recorder data was downloaded in New Orleans, LA, by Amtrak Mechanical personnel. The analysis disclosed that the engineer was in compliance with all railroad operating and train handling requirements.

ANALYSIS: - FATIGUE:

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded that fatigue was not probable for any of the employees.

PROBABLE CAUSE

FRA determined the probable cause of the accident was driver inattentiveness and the failure of the Waste Management garbage truck operator to yield the right of way to the oncoming Amtrak passenger train.