

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2008-54

Burlington Northern Santa Fe (BNSF) Melrose, IA June 12, 2008

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

r																			
DEPARTMENT FEDERAL RAILF	OF TRA ROAD A	ANSPORT DMINIST	ATIC RATI	ON ON	FRA FA	ACTU.	AL RA	ILR	OAD A	CCII	DENT R	EPORT		F	FRA Fi	le #	<u>HQ-200</u>	8-54	
1.Name of Railroad C	1a.	1a. Alphabetic Code					1b. Railroad Accident/Incident No.												
2.Name of Railroad C	BINSF 2a. Alphabetic Code					2h F	NE0608105												
BNSF Rwy Co. [B]	BNSF						NE0608105												
3.Name of Railroad (N/A	3a. Alphabetic Code N/A					3b. I	3b. Railroad Accident/Incident No. N/A												
4.Name of Railroad H	4a.	4a. Alphabetic Code					4b. Railroad Accident/Incident No.												
BNSF Rwy Co. [BI	NSF] Trade Cro	ssing Ident	ificatio	n Nur	nber			6	Date of Acc	BNSF	Incident		7. T	NE0608105 7. Time of Accident/Incident					
5. 0.5. 001_11110	fiude cro		meano	ii i tui	liber			Mo	Ionth 06 Day 12 Year 2008					04:1	0:		AM	🗸 PM	
8. Type of Accident/I	ndicent	1. Deraili	nent		4. Side c	ollision		7. Hwy-rail crossing 10. Explosion-d						tonation 13. Other Code					
(single entry in code box) 2. Head on collision 5. Raking collision 3. Pear and collision 6. Prokon Twin collision									RR grade o	crossin	g 11. I	Fire/violen	t rupti	narrative) 03					
9. Cars Carrying		3. Rear en	$M \Delta T C$	sion	6. Broke	n Train c	Ollision	9. Ieasin	Obstructio	n	12. Other impac				13 Div	ision			
HAZMAT	0	Damaged	ed	N/A	HA	ZMAT	icasin	N/A		Evacuate	d	0			131011	Nebraska	1		
14 Nearest City/Tow	n l				10/1	15. Milepost			16.5		ate		17 County						
in nearest city row		(to	nearest t	<i>enth)</i> 321.1			Abbr Code				MONROE								
18. Temperature (F)		19. Visib	ility	(sing	le entry)	Code	20. V	Veath	eather (single e			Code	21 Type o		e of Tra	of Track		Code	
(specify if minus))	1.1	Dawn	3.D	usk		1	. Cle	ar 3. Ra	in 5	1 5.Sleet			1. Main 3. Sid			ding		
76	5 F	2	Day	4.L	Dark	2	2	2. Clo	udy 4. Fo	g (6.Snow 2			2. Yard 4. 1			stry	1	
22. Track Name/Nu	mber					23. FR	A Track	X).	Code 24. Annual Track Density (gross tons in				25. Time Table Direction 1 North 3 East			Code			
	0 2			-/	4	m	illions)	57.9	6		2. Sout	h 4.	West	3					
							OPER	RATI	ING TRA	IN #1									
26. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 27. Was Equipment Code 28. Train Number/Symbol																			
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s).												Δ							
29 Speed (recorded	3. Commuter train 6. Cut of cars 9. Maint./inspect.car A 1. Yes 2. No 1 N/A																		
R - Recorded R -												induve.							
E - Estimated 30 MPH E b. Auto train control b. Current of traffic n. Other than main track $1 =$											1 = Remote control portable								
20. Trailing Tops (gross topping) i. Time table/train orders o. Positive train control 2 = Remote control tower																			
excluding powe	varrar traffi	ic control	p. ou	Code(s	y in narrat)	ive)	transmi	tter - m	ore th	an one									
N/A f. Interlocking 1.Yard limits σ i N/A N/A N/A remote control transmitter												nitter	0						
32. Principal Car/Uni	t	a. Initial	and Nu	mber	b. Positie	on in Tra	in c.	Load	ed(ves/no)	33. I	f railroad e	mplovee(s) teste	d for drug	/alcoho	l use.			
(1) First involved	1		,	NT/A		enter the n	umber that	were	positive in	1		Alcohol	Drugs						
(derailed, struck, e	etc)	DINC	F 9802	.0		1		1	N/A		the approp	riate box.					0	0	
(2) Causing (if med cause reported	chanical	l	0			0			N/A	34.	Was this c	onsist tran	sporti	ng passen	gers? (Y	Y/N)		N/A	
35. Locomotive Uni	ts	a. Head		Mid T	`rain	R	ear End		36. Cars			_	Lo	aded		Emp	ty		
(1) Total in Trait		End	b. Mai	nual	c. Remote	d. Manu	al c. Re	mote	(1) Total	in Fau	inment Co	a. Fr	eight	b. Pass.	c. Frei	ght (d. Pass.	e. Caboose	
		0		5	0	0	0	,	(1) Total	m Equ			2	0	0	'	0	0	
(2) Total Deraile	d	0	(0	0	0	0)	(2) Total	Deraile	ed		1	0	0		0	0	
This Consist	ck, Signal, V	Way,	\$0.00		39. Primary Cause					40. Contributing Cause									
This Consist	4	Number	of Cre	& Stru	tcture Dama	ge	<i>Q</i> 0.00		Code			H607	th of '	Code	hity.			N/A	
41. Engineer/	42. Fir	emen		43. Co	onductors	44. B	rakemen		45. Engir	neer/O	perator	Leng	uror	46. Conductor					
Operators 2 0					0		0		Hrs 9 Mi 10			Mi 10		Hrs 0 Mi 0			Mi 0		
Casualties to:	Ities to: 47. Railroad Employees 48				in Passenger	·s 49.	49. Other		50. EOT Device?				51. Was EOT Device			evice	Properly	Armed?	
Fatal	0				0		0		- 1. Yes 2. No N/A				1. Yes 2. No N/A						
							0		52. Caboose Occupied by Crew?			Crew?							
Nonfatal 2 0							0		1. Yes 2. No N								N/A		
						C	PERA	TIN	G TRAIN	#2									
53. Type of Equipme	nt 1.	Freight tra	in	4. Wo	rk train 7.	Yard/sw	itching	A.	Spec. MoW	V Equi	p. Code	54. Was I	Equip	ment C	ode	55. T	'rain Nun	nber/Symbol	
Consist (single en	<i>try</i>) 2.	Passenger	train train	5. Sin	gie car 8.	Light lo	co(s).	r	Attend					d? CNAMCXE029				CXE029	
56. Speed (recorded	sneed if	available	Code	5. Cut	Method(s)	of Opera	ion /	ı (ente	r code(s)	that a	$\frac{1}{nnlv}$	1. 1		2. 1NO 58a, Rem	• otelv C	ontro	lled Loco	motive?	
R - Recorded	эрсен, ц	avanable)	Coue	a.	ATCS	opera	g. Auton	natic l	block	m.Spe	cial instruc	tions		0 = Not a remotely controlled					
E - Estimated	0	MPH	R	b.	. Auto train	control	h. Currer	nt of t	raffic	n. Oth	er than mai	n track		1 = Rem	ote con	trol po	ortable		

DEPARTMENT FEDERAL RAILF	OF TRA ROAD AI	NSPOR DMINIST	FATI(FRATI	ON ION	FRA FA	CTUAL	RAILR	OAD AC	CID	ENT	REPO	ORT	F	RA Fil	e # <u>HQ-2</u>	008-	-54
57. Trailing Tons (gross tonnage, excluding power units)					c. Auto train stop i. Time table/tr d. Cab j.Track warran e. Traffic k. Direct traffic				ain orders o. Positive train control t control p. Other (<i>Specify in narrative</i>) c control Code(s)					te contr ote contr ter - mo	ol tower ol re than one	e	
		15966		f.	f. Interlocking l.Yard li			[g	j	N/A 1	N/A N/A	remote control transmitter				0
59. Principal Car/Unit a. Initial and Nu				umber	mber b. Position in Train c			led(yes/no) 60. If railroad employee(s) t				loyee(s) tes	sted for drug/alcohol use,				
(1) First involved (derailed struck etc) CEFX67299			99	11-	4		yes		enter the	e numb opriate	er that were box.	e positive i	n	Alcol	nol	Drugs	
(2) Causing (<i>if mechanical</i> cause reported) 0			0		0		N		61. Was this consist transpo			st transport	ting passengers? (Y/N)				N/A
62. Locomotive Units a. Head End b. M			b. Ma	Mid T anual 1	rain c. Remote	Rea 1. Manual	r End c. Remote	63. Cars				Lo a. Freight	aded b. Pass.	c. Frei	Empty ght d. Pas	s.	e. Caboose
(1) Total in Train		2		0	0	0	0 0		(1) Total in Equipment Consist			112	0	0	0		0
(2) Total Derailed		0		0	0	0	0	(2) Total E	eraile	d		0	0	0	0		0
64. Equipment Dama This Consist	age	72 928 00		65. Tra	5. Track, Signal, Way,			66. Primary Cause			1607	67. Contributing Cause				J/A	
	φ	Numbe	r of Ci	ew Me	mbers	age					1.	Length of	Time on D	uty		1	V/A
68. Engineer/	69. Fire	emen		70. Co	nductors	71. Brak	emen	72. Engin	eer/Op	erator			73. Conductor				
Operators 1		0			1		0		Hrs	4	Mi	i 25	Hrs			M	li 25
Casualties to:	74. Railr	oad Empl	oyees ′	75. Trai	in Passengers	76. Othe	er	77. EOT Device?				1	78. Was EOT Dev			ice Properly Armed	
Fatal		0			0		0	79 Caboose Occupied by Crew?									
Nonfatal		0		0			0		1. Y	'es		2. No					N/A
						OI	PERATIN	G TRAIN	#3								
80. Type of Equipme Consist <i>(single en</i>	80. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s).									. Spec. MoW Equip. Code 81. Was Equipment Code 82. Train Number/Symbol Attended? 82. Train Number/Symbol N/A 1 Yes 2 No N/A N/A							
83. Speed (recorded speed, if available) Code 85. Method(s) of Operation (ente								r code(s) th	at ap	l ply)			85a. Remo	otely Co	ntrolled Lo	ocom	otive?
R - Recorded	R - Recorded a. ATCS g. Automatic								1.Spec	ial instr r than n	uctions ain tra	ck	0 = Not a	remotel	y controlle	d	
E - Estimated N/A MPH N/A b. Auto train control h. Current of the cont								arne orders	. Posit	tive trai	n contre	ol	1 = Remo 2 = Remo	te contr	ol tower	,	
84. Trailing Tons (gross tonnage, excluding power units)									. Othe	r (Spec	ify in n	arrative)	3 = Remo	ote conti	ol re than on		
	I	N/A		f.	Interlocking	к. 1 1.Y	ard limits		N/A	N/A	N/A 1	N/A N/A	remote c	ontrol ti	ransmitter		N/A
86. Principal Car/Unit a. Initial and Nu					b. Positio	n in Train	c. Load	led(yes/no) 87. If railroad employee(s) tes					ed for drug	g/alcoho	l use,		
(1) First involved			N/A		N	/A		N/A enter the number that wer					e positive i	n	Alcol	ıol	Drugs
(derailed, struck, etc)								88. Was this consist transpor						N/2	4	N/A	
cause reported) N/A					N/	A							anded Empty				
89. Locomotive Uni	its	a. Head Mie End b. Manua		Mid T anual ₁	rain c. Remote	i. Manual	c. Remote	90. Cars			a. Freight	b. Pass.	c. Frei	Empty ght d. Pas	s. 6	e. Caboose	
(1) Total in Train	n	N/A	N/A		N/A	N/A	N/A	(1) Total in	in Equipment Consist			N/A	N/A	N/A	N/A		N/A
(2) Total Deraile	ed	N/A	N	/A	N/A	N/A	N/A	(2) Total E	eraile	d		N/A	N/A	N/A	N/A		N/A
91. Equipment Dama	age	NT/A		92. Tra	2. Track, Signal, Way,			93. Primary Cause Code					94. Contributing Cause				
		N/A Numbe	r of Ci	& Sti ew Me	& Structure Damage N/A w Members				Length of Time on Duty								N/A
95. Engineer/	96. Fire	emen		97. C	onductors	emen	99. Engin	erator			100. Conductor						
Operators N/A		N/A			N/A N/A				Hrs	N/A	M	i N/A	Hrs N/A M				li N/A
Casualties to:	101. Rail	lroad Emp	loyees	102. Train 103.			103. Other		104. EOT 105. Was EOT Device Properly								
Fatal	N/A				N/A	N	N/A		I. Yes 2. No N/A I. Yes 2. No N/. 106. Caboose Occupied by Crew?								N/A
Nonfatal N/A					N/A	N/A	1. Yes 2. No N/A									N/A	
Highway User Involved									Rail Equipment Involved								
107. C. Truck-7	Frailer. F	7. Bus	J	. Other	Motor Vehic	le	Code	111. Equipment 3.Train (standing) 6.Light Loco(s) (moving) Code									
A. Auto D. Pick-Up B. Truck E. Van	p Truck (G. School	Bus H ycle M	K. Pede M. Othe	strian	urrative)	N/A	1.Train(units pulling) 4.Car(s)(moving) 7.Light(s) (standing) 2.Train(units pushing) 5.Car(s)(standing) 8.Other (secific in neuronical) N/A							N/A		
108. Vehicle Speed	1	N	109.		geographic	al)	112. Position of Car Unit in							1			
(est. MPH at in	N/A																

DEPARTMENT OF TRANSPORTATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2008-54 FEDERAL RAILROAD ADMINISTRATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2008-54												<u>54</u>			
110. Position	110. Position Code 113. Circumstance														
1.Stalled o 4. Trapped	1. Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Crossing 1. Rail Equipment Struck Highway User 4. Trapped N/A														
114a. Was the	114a. Was the highway user and/or rail equipment involved Code 114b. Was there a hazardous materials release														
in the impact transporting hazardous materials? 1 Highway User 2 Rail Equipment 3 Both 4 Neither N/A 1. Highway User 2. Rail Equipment 3. Both 4. Neither												4. Neither	N/A		
1. Highway User 2. Kall Equipment 5. Both 4. Neither 1997 1997 1997 1997 1997 1997 1997 199												<u> </u>			
114c. State nere the name and quantity of the hazardous materials released, if any. N/A															
115. Type 1.Gates 4.Wig Wags 7.Crossbucks 10.Flagged by crew 116. Signaled Crossing Code 117. Whistle Ban													Code		
Crossing 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs 11.Other (spec. in narr.) (See instructions for codes) 1. Yes Warning 3.Standard FLS 6.Audible 9.Watchman 12.None 2. No															
Code(s)	e(s) N/A N/A N/A N/A N/A N/A N/A 3. Unknown								3. Unknown	N/A					
118. Location of Warning Code 119. Crossing Warning Code 120. Crossing Illuminated by Street												Code			
1. Both Sides with Highway Signals											or Special Lig	ghts			
2. Side of					1. Yes			1. Yes 2. No							
Opposit	ach		N/A		2. No 3. Unknown		N/A	N/A 3. Unknown							
121.	122. Driver's	Gender	Code	123.	Driver Drov	ve Behind o	l or in Front of Code 124. Driver						Code		
Age	1. Male				and Struck o	r was Struc	k by Second	Frain	1. Drov	e around or thr	u the Gate	4. Stopped on Crossing			
N/A	2. Female	; 	N/A		1. Yes	2. No	3. Unknowi		2. Stop	ot Stop	oceeded	5. Other (specify in narrative)	N/A		
125 Duivon Do			12	6 Via	w. of Treals C	hearing d has		107		F					
Highway V	ehicle	Cod	e 12	1 P	ermanent Str	ucture	(primary ob 3 Passi	struction)	Vegetation	7 Other	(specify in	narrative)	Code		
1. Yes 2. No	3. Unknown	N/.	4	2. S	tanding Rail	oad Equipr	nent 4. Topo	graphy 6.1	Highway Vehi	cle 8. Not ob	structed		N/A		
Casualties	to:		Kill	ed	Injured	127. Driv	/er		Cod	e 128. Wa	as Driver in t	he Vehicle?	Code		
Casualties to: Killed Injured 1. Ki						1. Kille	d 2.Injured 3.	Uninjured	N/2	A 1	1. Yes 2. No				
129. Highway-Rail Crossing Users N/A N/A 130. H							hway Vehicle dollar damag	Property Da	mage N/A	131. To (in	131. Total Number of Highway-Rail Crossing (include driver) N/A				
132. Locomot	ive Auxiliary L	ights?					Code	133. Locor	notive Auxilia	ry Lights Oper	ational?		Code		
1. Yes 2. No N/A 1. Yes 2. No											N/A				
134. Locomot	ive Headlight Il	luminate	ed?				Code	135. Locor	notive Audibl	e Warning Sou	nded?		Code		
1. Yes 2. No N/A 1. Yes 2. No											N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On Thursday, June 12, 2008, at 4:10 p.m., CST, an eastbound Burlington Northern Santa Fe Railway Company (BNSF) Brandt Roadrailer, Unit No. 98020, pulling one loaded car of ballast, hopper Car No. BN 958481, collided into the rear car of stopped eastbound BNSF loaded coal Train C NAMCXE0-29. The collision occurred 2.5 miles west of the town of Melrose, Iowa, at BNSF Milepost (MP) 321.1, on Main Track No. 2 of the Nebraska Division, Ottumwa Subdivision, in Monroe County. The crew of BNSF Train C NAMCXE0-29 reported an undesired emergency brake application while they were sitting still with the headend of the train located at MP 320. Inspection of the train revealed that the Brandt Roadrailer had collided with the rear car of the train. Both crewmembers of the Brandt Roadrailer were injured. No hazardous materials were involved.

Damage estimates to equipment total \$274,428. No damages were reported to track or signal equipment.

At the time the collision occurred, the weather conditions were daylight and cloudy, a temperature of 76 °F, and rain had temporarily stopped in the area.

The cause of the collision was determined to be cause code H607, failure to comply with restricted speed or its equivalent not in connection with a block or interlocking signal.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of the Brandt Roadrailer consisted of an operator and a ground man. Both were qualified BNSF group 2 machine operators. The crew went on duty at 7 a.m., CST, on June 12, 2008, at Ottumwa, Iowa, which was the crew's away terminal. Both crewmembers were fully rested and had been off duty for approximately 14 hours prior to reporting for duty.

Their assignment consisted of driving the Brandt Roadrailer from Ottumwa to Chariton, Iowa, by the highway and unloading two cars of ties in the Chariton Yard. When this was completed, they were to pull a loaded car of ballast, Car BN 958481, by rail from Chariton eastward to the east passing siding at Maxon, Iowa, a distance of approximately 33.5 miles by rail.

With the ties unloaded, the crew proceeded to attach the Brandt Roadrailer to the car of ballast and ready the car for movement. Information provided by BNSF estimates the total weight of the car between 97 and 112 tons. An air test was performed on the car and the air brakes were determined to be working properly. The passenger/ground man of the Brandt Roadrailer obtained Track Warrant 992, which gave them authority to proceed eastward from MP 335 to CP Halpin on Main Track # 2, not to foul limits ahead of BNSF 9838 east or BNSF 8837 east. BNSF 8837 east was Train C NAMCXEO 29. The warrant was joint with another maintenance-of-way (MOW) employee who would be operating an additional piece of rail equipment eastward behind them. Track Warrant 992 was Okayed at 3:43 p.m. The maximum authorized speed for the Brandt Roadrailer is 20 mph as outlined in the Engineering Instructions for Roadway Equipment 14.12.5 (2). The crew had observed both eastbound trains go by prior to proceeding eastward.

Approaching the collision site, the operator of the Brandt Roadrailer was seated on the north side of the east facing cab and the passenger/ground man was seated on the south side of the cab. The timetable and geographic direction for the Brandt Roadrailer's movement was east. Timetable directions are used throughout this report.

The crew of BNSF Train C NAMCXEO 29 consisted of an engineer and conductor. The crew went on duty at 11:45 a.m., on June 12, at Creston, Iowa, which was the crew's away terminal. Both crewmembers received more than the required off-duty time prior to reporting for duty.

Their assigned train consisted of 2 locomotives, both at the head-end, coupled to 112 loaded hopper cars of coal. The train was 6,094 feet in length with 15,986 gross trailing tons, excluding power units. The train was scheduled to travel from Creston to Galesburg, Illinois, with no pick-ups or setouts while en route. The initial terminal air brake test and inspection had been performed on this train at Donkey Creek Station in Wyoming, on June 9, as BNSF empty coal Train E CXENAM0254. BNSF loaded coal Train C NAMCXEO 29 received a 1,000-mile inspection at Lincoln, Nebraska, on June 11, 2008. The locomotives had a current daily inspection so an inspection was not performed by the crew prior to departing Creston. They held a valid track warrant, Warrant 986, to proceed eastward from MP 339 to CP Halpin on Main Track # 2. Their warrant was Okayed at 3:07 p.m., on June 12, by dispatcher RAL. BNSF Train C NAMCXEO 29 departed Creston at 12:35 p.m., on June 12, en route to Galesburg. The maximum authorized speed for this train is 50 mph as outlined in the Nebraska Division Timetable # 6, effective December 13, 2006.

BNSF Train C NAMCXEO 29 had proceeded east until required to stop, with the head-end of the train at MP 320, to wait for a clear of wayside block signal to proceed.

Main Track # 2 in the area the collision occurred, MP 321.1, is 136-pound welded rail attached to wood ties. The track at the collision site is tangent for approximately 700 feet to the west and then a 1-degree 0-minute, left-hand curve and then tangent for approximately 340 feet and followed by a 3-degree 23-minute, right-hand curve immediately followed by a 2-degree 59-minute, left-hand curve. The grade to the west is ascending at varying rates of 0.22- percent at MP 321.1 to 0.88-percent at MP 322. The track east of the collision site is tangent for approximately 2,450 feet and then a 2-degree 32-minute, left-hand curve immediately followed by a 1-degree 11-minute, right-hand curve and then tangent again for approximately 5,985 feet. The grade to the east is descending at varying rates from 0.22-percent at the collision site to 0.04-percent at MP 320.

THE ACCIDENT

The crew of eastbound BNSF loaded coal train C NAMCXEO 29 had stopped their train on Main Track # 2 and was waiting on a clear block signal to proceed. They had stopped at 3:47:07 p.m., on June 12, as verified by the event recorder data in lead Locomotive BNSF 8837. The head-end of the train was at MP 320. Maximum authorized speed for this train is 50 mph as outlined in the Nebraska Division Timetable No. 6, effective December 13, 2006.

The BNSF Brandt Roadrailer # 98020 and the carload of ballast it was pulling were traveling eastward on Main Track # 2. Approaching the collision site, they had just gone through a 2-degree 59-minute, left-hand curve followed by a 3-degree 23-minute, right-hand curve, and were going through a 1-degree 0-minute, left-hand curve when they saw the rear car of BNSF Train C NAMCXEO 29. Prior to seeing the rear car of the train, their view around the curve had been obstructed by trees and vegetation along the railroad right-of-way. The operator of the Brandt Roadrailer applied the truck brakes and the passenger/ground man in the Brandt Roadrailer set an emergency brake application on Car # BN 958481 that they were pulling. The crew reported that they could not get stopped due to poor rail conditions. The crew reported that the rail was wet from the rain that had been falling and was greasy from the rail lubricators in the curves. Both crewmembers reported that their speed at the time they saw the rear car of the train was approximately 25 mph. The maximum authorized speed for the Brandt Roadrailer when pulling cars is 20 mph as outlined in Engineering Instructions for Roadway Equipment 14.12.5(2). They collided with the rear of Car CEFX 67299, which caused an undesired emergency brake application to BNSF Train C NAMCXEO 29 at 4:10:25 p.m., as verified by the event recorder in lead Locomotive BNSF 8837.

The train crew of BNSF Train C NAMCXEO 29 notified the dispatcher that they experienced an undesired emergency application of the train air brakes while sitting still at MP 320. As the conductor was walking back inspecting the train, emergency vehicles passed by on the road heading in the direction of the rear of the train. The conductor flagged down an emergency responder and found out that someone had run into the back of the train. When the conductor arrived at the rear of the train, he discovered that the Brandt Roadrailer had collided with the train and the wreckage was blocking Main Tracks # 1 and # 2. Both crewmembers in the Brandt Roadrailer were trapped in the cab of the truck that had ended up on top of the last car of the train. The dispatcher was notified of the situation.

The passenger/ground man in the Brandt Roadrailer had called 911 to get medical help with his personal cell phone. The passenger/ground man was taken to a near-by hospital and treated for abrasions to the right wrist and hand, left hand, right foot and ankle, and then released. The operator was taken by Life Flight to a Des Moines, Iowa, hospital for treatment of a compound fracture to the right tibia and fibula, and a large wound to the right calf muscle.

A call to the Monroe County Sheriff's Office by FRA verified that the 911 call was made at 4:14 p.m., on June 12, 2008, by the ground man of the Brandt Roadrailer. Agencies dispatched to the scene include the Monroe County Sheriff, Monroe County Ambulance, Melrose Fire Department, Albia Fire Department, Lucas County Ambulance, Russell Fire Department, and Life Flight out of Des Moines.

ANALYSIS AND CONCLUSIONS:

ANALYSIS - TOXICOLOGICAL TESTING:

The operator of the Brandt Roadrailer received post-accident toxicological testing under railroad authority. The passenger/ground man was held at the railroad office in Ottumwa, after he was released from the hospital, for post-accident toxicological testing; however, the collector could not reach them due to bad weather and flooding that was occurring. The passenger/ground man was not tested. The crew of BNSF Train NAMCXEO 29 was not tested.

CONCLUSION:

The results were negative for the operator. Intoxication was not a factor.

ANALYSIS: - FATIGUE

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

ANALYSIS - QUALIFICATIONS:

Qualifications for operating the Brandt Roadrailer on BNSF include a valid CDL, DOT qualified through BNSF Vehicle Services Group, current book of rules qualifications, and Brandt Roadrailer Training at the BNSF Technical Training Center.

Documents produced during the interview process verified that the operator and ground man had a valid class "B" CDL operator's license and were DOT qualified through the BNSF Vehicle Services Group. Training records for both employees provided by BNSF show that they had completed the 2008 operating rules qualification in March 2008. The operator had completed the Brandt Roadrailer training in January 2006 and the ground man had completed the Brandt Roadrailer training in February 2007.

CONCLUSION:

Both crewmembers of the Brandt Roadrailer were qualified operators.

ANALYSIS -VOICE DATA RECORDINGS/WARRANT:

Voice data recordings supplied by BNSF of the dispatcher talking to the ground man of the Brandt Roadrailer verify that the track warrant was issued and that it had been copied correctly.

CONCLUSION:

The Brandt Roadrailer had a valid track warrant to occupy Main Track No. 2 from MP 335 to CP Halpin that

was Okayed at 3:43 p.m., on June 12, 2008, by dispatcher RAL.

ANALYSIS - TRACK WARRANT:

Documents provided by BNSF for Train Symbol C NAMCXEO 29 show that the Train had a track warrant to occupy Main Track No. 2 from MP 339 to CP Halpin that was Okayed at 3:07 p.m., on June 12, 2008, by dispatcher RAL.

CONCLUSION:

Train Symbol C NAMCXEO 29 had a valid track warrant for the same section of track as the Brandt Roadrailer.

ANALYSIS - VOICE DATA RECORDINGS/SPEED:

Voice data recordings revealed the dispatcher asking the Brandt Roadrailer passenger/ground man what track speed they would be traveling at prior to giving them a track warrant and he replied 30 mph.

CONCLUSION:

The passenger/ground man is unaware of the maximum authorized speed allowed when pulling a railcar with the Brandt Roadrailer.

ANALYSIS - REPORTS OF INTERVIEW/SPEED:

During the interview process, both the operator and passenger/ground man of the Brandt Roadrailer were asked what the maximum authorized speed was with the Brandt Roadrailer. Both employees responded saying their maximum authorized speed is 60 mph. The operator of the Brandt Roadrailer commented that they would never try to travel 60 mph with the Roadrailer. When both employees were asked what speed they normally traveled with the Brandt Roadrailer, they both replied saying 25 to 30 mph.

CONCLUSION:

Both crewmembers of the Brandt Roadrailer have represented that they are unaware of the maximum authorized speed for the Brandt Roadrailer or the fact that it varies from 30 mph when it is operated by itself to 20 mph when pulling cars as outlined in Engineering Instruction (EI) 14.12.5 and MOW Operating Rules (MWOR) 6.50.1.

ANALYSIS - EVENT RECORDER DATA:

Lead Locomotive BNSF 8837 of BNSF Train C NAMCXEO 29 was equipped with an event recorder as required. The event recorder data was downloaded by the BNSF road foreman at the collision site. The event recorder data shows that BNSF Train C NAMCXEO 29 had stopped at 3:47:07 p.m., on June 12, at MP 320 for 23 minutes 18 seconds, prior to experiencing the emergency train air brake application at 4:10:25 p.m.

CONCLUSION:

The collision between Brandt Roadrailer BNSF 98020 and the rear of Car CEFX 67299 of BNSF Train C NAMCXEO 29 occurred at 4:10:25 p.m., on June 12.

ANALYSIS - SPEED:

The Brandt Roadrailer is not equipped with any type of recording device so exact speed that they were traveling is unknown. Track Warrant 992 which authorized their movement from MP 335 (at Chariton) to CP Halpin was Okayed at 3:43 p.m. Both crewmembers of the Brandt Roadrailer stated that they never left MP 335 prior to getting the warrant. The collision at MP 321.1 occurred at 4:10:25 p.m., as verified by the event recorder data. This means that they traveled 13.9 miles in 27 minutes. This calculates to an average speed of 30.6 mph. This also does not take into consideration the time it took to pull out of the yard track, line the switch for movement to Main Track # 2, pull out onto Main Track # 2, and to line the switch back and lock it before proceeding east.

CONCLUSION:

The crew failed to comply with restricted speed or its equivalent as outlined in El 14.12.5 and MWOR 6.50.1.

ANALYSIS - SIGHT DISTANCE:

Photographs taken by FRA show the trees and vegetation along the south side of Main Track # 2 in the 1degree 0-minute in a left-hand curve west of the collision site which prohibited the operator of the Brandt Roadrailer from seeing the rear car of the train at MP 321.1 until they were almost out of the curve. Sight distance as measured by the BNSF Nebraska division engineer for the operator of the Brandt Roadrailer to the rear car of BNSF Train C NAMCXEO 29 was approximately 736 feet.

CONCLUSION:

Sight distance was very minimal.

ANALYSIS - MWOR 6.50 - MOVEMENT OF ON-TRACK EQUIPMENT:

This rule in part states: On-track equipment must move at a speed that will allow stopping within half the range of vision short of: train, engine, railroad car, etc.

CONCLUSION:

The operator of the Brandt Roadrailer failed to operate the equipment in compliance with rule MWOR 6.50.

ANALYSIS - MWOR 6.50.1 - MAXIMUM AUTHORIZED SPEED:

This rule in part states: When determining the proper speed, take into consideration the following: track conditions, such as grade, curvature and rail condition, load, sight distance, visibility, other conditions that might adversely affect the safe operation of on-track equipment.

During the interview process, both crewmembers of the Brandt Roadrailer stated that rail conditions were poor and that they could not see around the curve because of the trees and vegetation. The track charts provided by BNSF of the area show that they were on a descending grade and had gone through a series of curves prior to the collision.

CONCLUSION:

The operator of the Brandt Roadrailer failed to yield to the conditions and adjust his manner of operation accordingly.

ANALYSIS - MWOR 6.51 MAINTAINING A SAFE BRAKING DISTANCE:

This rule in part states: On-track equipment operators are responsible for maintaining a safe braking distance between their on-track equipment and other on-track equipment, trains and engines.

CONCLUSION:

The operator failed to comply with this rule.

ANALYSIS - AIR BRAKES:

Both crewmembers of the Brandt Roadrailer stated that an air brake test was performed on Car BN 958481 prior to leaving MP 335, and that the air brakes were operational. FRA contacted the BNSF car-men from Fort Madison, Iowa, that made the repairs to Car BN 958481 after the collision occurred. The car-men stated that they made repairs to the air brake train line and combination dirt collector, and cut-out cock but that the remainder of the air brake system was not damaged in the collision.

A copy of the BNSF car repair bill verifies the repairs made. The car-men also stated that a single car air

brake test was performed on Car BN 958481 and that it passed.

CONCLUSION:

It is highly probable that the air brakes on Car BN 958481 were functioning properly on the day the collision occurred.

ANALYSIS - BRANDT ROADRAILLER BRAKES:

Both crewmembers of the Brandt Roadrailer stated that they were unaware of any problems with the brakes on the Brandt Roadrailer and that they were working fine. Tests could not be performed because the equipment was destroyed in the collision.

CONCLUSION:

It is highly probable that the brakes on the Brandt Roadrailer were functioning properly on the day the collision occurred.

OVERALL CONCLUSIONS:

The operator of the Brandt Roadrailer was not in compliance with the railroads operating rules. The crew of the Brandt Roadrailer was the only witnesses to the collision. The crew operated the Brandt Roadrailer at a speed that exceeded the maximum authorized limit which hindered their ability to stop within one-half their range of vision short of BNSF Train C NAMCXEO 29. No equipment deficiencies were identified during the investigation that could have contributed to the cause. Based on the analysis, fatigue was not a factor.

The railroad and the FRA investigator agree that the cause of the collision be listed as cause code H607, failure to comply with restricted speed or its equivalent not in connection with a block or interlocking signal.

PROBABLE CAUSE & CONTRIBUTING FACTORS

Probable cause of the collision was failure to comply with restricted speed or its equivalent. Both crewmembers of the Brandt Roadrailer were aware that they were following behind a train, and were aware of the poor track conditions and short sight distance prior to the collision occurring. Failure of the operator to properly react to these conditions was a significant contributing factor identified during this investigation.