



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-59***

***Union Pacific (UP)
Portland, OR
June 26, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0608PD014	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0608PD014	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 06 Day 26 Year 2008		7. Time of Accident/Incident 06:35: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative) Code 01	
9. Cars Carrying HAZMAT 2		10. HAZMAT Cars Damaged/Derailed 1		11. Cars Releasing HAZMAT 0	
				12. People Evacuated 0	
				13. Division Portland Serv Unit	
14. Nearest City/Town Portland		15. Milepost (to nearest tenth) 6.9		16. State Abbr Code N/A OR	
				17. County MULTNOMAH	
18. Temperature (F) (specify if minus) 58 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Single Main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 31.1	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 3	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1	
				28. Train Number/Symbol APDNP-26	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 39 MPH R		31. Method(s) of Operation (enter code(s) that apply)			31a. Remotely Controlled Locomotive?
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
30. Trailing Tons (gross tonnage, excluding power units) 6784					
32. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
(1) First involved (derailed, struck, etc)		CNW520003	44	yes	Alcohol Drugs N/A N/A
(2) Causing (if mechanical cause reported)		CNW520003	44	yes	34. Was this consist transporting passengers? (Y/N) N
35. Locomotive Units		a. Head End	Mid Train	Rear End	36. Cars
		b. Manual	c. Remote	d. Manual c. Remote	a. Freight b. Pass. c. Freight d. Pass. e. Caboose
(1) Total in Train		3	0	0 2	(1) Total in Equipment Consist 51 0 29 0 0
(2) Total Derailed		0	0	0 2	(2) Total Derailed 22 0 14 0 0
37. Equipment Damage This Consist \$380,000.00		38. Track, Signal, Way, & Structure Damage \$374,600.00		39. Primary Cause Code E61C	
				40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators 2		42. Firemen 1		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 3 Mi 5	
				46. Conductor Hrs 3 Mi 5	
Casualties to:		47. Railroad Employees	48. Train Passengers	49. Other	50. EOT Device? 1. Yes 2. No 2
Fatal		0	0	0	51. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Nonfatal		0	0	0	52. Caboose Occupied by Crew? 1. Yes 2. No N/A
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive?
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			0 = Not a remotely controlled 1 = Remote control portable

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No	N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No	N/A		
Fatal	0	0	0	79. Caboose Occupied by Crew?	1. Yes 2. No	N/A					
Nonfatal	0	0	0								

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	R - Recorded E - Estimated	N/A MPH	N/A	85. Method(s) of Operation (enter code(s) that apply)	a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
84. Trailing Tons (gross tonnage, excluding power units)	N/A							N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	N/A	96. Firemen	N/A	97. Conductors	N/A	98. Brakemen	N/A	99. Engineer/Operator	Hrs N/A Mi N/A	100. Conductor	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No	N/A	105. Was EOT Device Properly	1. Yes 2. No	N/A		
Fatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	1. Yes 2. No	N/A					
Nonfatal	N/A	N/A	N/A								

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code N/A			111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code N/A	1. Train(units pulling)	4. Car(s)(moving)	7. Light(s) (standing)	N/A
		1. North 2. South 3. East 4. West		2. Train(units pushing)	5. Car(s)(standing)	8. Other (specify in narrative)	
				112. Position of Car Unit in	N/A		

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A							
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A							
114c. State here the name and quantity of the hazardous materials released, if any. N/A																
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wigs 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A				
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A			
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A	4. Stopped on Crossing 5. Other (specify in narrative)		Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A			
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A			
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			N/A			
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A							
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A							

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On June 26, 2008 at approximately 6:35 a.m. PDT eastbound Union Pacific Railroad Company (UP) freight train APDNP-26 derailed. The accident occurred on the UP Portland Service Unit, Portland Subdivision, of the Graham Line, on a single Main Track at milepost 6.9 located approximately seven miles east of Portland, Oregon. Two Distributive Power Unit (DPU) locomotives and the rear 36 railcars of the 80 car train derailed.

There was no release of hazardous material and no injuries to the train crew employees.

As a result of the accident the connecting ramp from Interstate 205 to Interstate 84 was closed during the Portland rush hour creating major delays and extensive media coverage.

Reported total estimated damage was \$702,520 (track damage of \$374,600, and equipment damage of \$327,920).

The weather was mostly clear with a temperature of 58° F.

The probable cause of the derailment was a broken wheel rim FRA Code E61C on the R-2 wheel of the 44th car in the train. - CNW 520003.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew assigned to operate eastbound UP freight train # APDNP-26 included a locomotive engineer, a conductor, a student engineer, and a pilot. The crew went on duty at their home terminal at 3:30 a.m. PDT on June 26, 2008 at the UP Albina Rail Yard in Portland, Oregon. Prior to reporting for duty all crew members received the required statutory off duty rest period.

The train consisted of three locomotives attached to the head end of the train, 51 loaded and 29 empty mixed freight rail cars, and two Distributed Power Unit (DPU) locomotives attached to the rear of the train. The train was 6,710 feet in length and weighed 6,782 tons. The train originated in Portland and was traveling east en route to North Platte, Nebraska, a distance of approximately 1,300 miles.

The train received a Class One Air Brake Test at 1:20 a.m. on June 26, 2008 in Portland prior to departure. After conducting a job briefing and being delaying by other train movements, the train departed Albina at 5:57 a.m.

As the train approached the accident site at a recorded speed of 39 mph the student engineer was seated at the controls located on the right (south) side of the locomotive. The engineer was sitting in a jump seat located behind and to the left of the student engineer. The conductor was seated at the conductors table on the left (north) side of the locomotive. The pilot was sitting in a seat behind the conductor. The conductor was performing paper work and monitoring the radio. The engineer was instructing the student engineer and the pilot was an instructor in the use of DPU locomotives.

Approaching the accident site from west to east the track is tangent 1,000 feet to milepost 6.7, a 2-degree curve to the left to the point of derailment (POD) at milepost 6.9, and 2,944 feet beyond. The track grade in the accident area is 0.17 percent ascending. The train came to a stop approximately 3,976 feet east of the POD.

In the accident area trains operate on a single main track under the authority of a Traffic Control System (TCS). The UP Portland Area Timetable # 3, effective June 26, 2005, authorizes a maximum freight train speed of 50 mph on FRA Class 4 track. The timetable and geographic direction that the train was traveling at the time of the derailment was east. Time Table direction will be used throughout this report.

THE ACCIDENT

The student engineer and the conductor stated as they approached the accident site that the trip had been uneventful. The train was being operated at a recorded speed of 39 mph when, according to the train crew, they felt a tug on the train as if the brakes had begun to apply. The student engineer increased the throttle from the Run 2 position to the Run 4 position. The train continued the tugging sensation and began slowing down. The student engineer reduced the throttle and a train line induced emergency air brake application occurred. The train then slowed to a stop.

As soon as the train stopped the crew determined there were no injuries and the conductor walked back and inspected the train. He discovered the two DPU locomotives and 36 railcars had derailed in a straight line with thirty cars remaining upright and six lumber cars on their sides.

ANALYSIS AND CONCLUSIONS:

The first car to derail was the 44th head car. The derailed cars were the rear 36 cars of the 80 car train.

The accident did not meet the requirement for FRA Post Accident Toxicology Testing, as required under Title 49 CFR, Part 219. The crew was not tested.

ANALYSIS: - FATIGUE

FRA obtained fatigue related information for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that data information FRA concluded fatigue was not probable for any of the train crew employees.

Inspection of the data printout from the locomotive event recorder revealed no unusual events related to train handling. The times shown on the event recorder printout were off by 13 minutes and the corrected time of the derailment was 6:35 a.m.

Inspection of the track indicates that the derailment occurred at milepost 6.9 and the train traveled 3,976 feet east before coming to a stop subsequent to the incident. The track is constructed of wooden railroad cross ties that were installed in 2003, and 133 lb rail relayed in 1992. No exceptions to the track structure were noted.

Prior to departure the train received all required equipment tests including a Class One Air Brake Test on June 26, 2008 in Portland. In addition to the airbrake test performed, railcar CNW 520003, the first car to derail, had been inspected on June 23, June 24 and June 25 during movements from Brooklyn Yard to Albina Yard and prior to its release on UP freight train APDNP-26.

Inspection of the derailed equipment indicated a defective condition on the 44th car, number CNW 520003. The rim on the R-2 wheel of CNW 520003 had broken. The wheel is a 36 inch heat treated curved plate Type CH36, serial number 506276, and was built in October, 1997. The wheel was sent to a laboratory for further analysis. The laboratory concluded that the wheel broke under traffic resulting in the derailment.

As a result of the accident the connecting ramp from Interstate 205 to Interstate 84 was closed during the Portland rush hour creating major delays and extensive media coverage.

PROBABLE CAUSE AND CONTRIBUTING FACTORS:

The probable cause of the derailment was a broken wheel rim FRA Code E61C on the R-2 wheel of the 44th

car in the train, - CNW 520003 - E61C - Broken Rim.