



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-67***

***Norfolk Southern (NS)
Shelby, VA
July 30, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS]		1a. Alphabetic Code NS		1b. Railroad Accident/Incident No. 033706		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS]		4a. Alphabetic Code NS		4b. Railroad Accident/Incident No. 033706		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 07 Day 29 Year 2008		7. Time of Accident/Incident 10:03:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative) Code 01		
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		
				12. People Evacuated 0		
				13. Division VIRGINIA		
14. Nearest City/Town BLACKSBURG		15. Milepost (to nearest tenth) V282.8		16. State Abbr Code N/A VA		
				17. County MONTGOMERY		
18. Temperature (F) (specify if minus) 85 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
22. Track Name/Number SIGNAL MAIN TRACK		23. FRA Track Code Class (1-9, X) 2		24. Annual Track Density (gross tons in millions) 42.1		
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 3		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1		
				28. Train Number/Symbol 824V427		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 7 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) 20590						
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		
(1) First involved (derailed, struck, etc)		NS 041694		46		
(2) Causing (if mechanical cause reported)		NS 041694		46		
				c. Loaded (yes/no) yes		
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A		
				34. Was this consist transporting passengers? (Y/N) N		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		3		0 0		
(2) Total Derailed		0		0 0		
				36. Cars		
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
				(1) Total in Equipment Consist 145 0 0 0 0		
				(2) Total Derailed 22 0 0 0 0		
37. Equipment Damage This Consist \$54,450.00		38. Track, Signal, Way, & Structure Damage \$135,000.00		39. Primary Cause Code E46C		
				40. Contributing Cause Code N/A		
Number of Crew Members				Length of Time on Duty		
41. Engineer/Operators 1		42. Firemen 1		43. Conductors 1		
				44. Brakemen 0		
				45. Engineer/Operator Hrs 4 Mi 43		
				46. Conductor Hrs 4 Mi 43		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0		
Nonfatal		0		0		
				49. Other 0		
				50. EOT Device? 1. Yes 2. No 1		
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A		
				54. Was Equipment Attended? Code 1. Yes 2. No N/A		
				55. Train Number/Symbol N/A		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No N/A	79. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No N/A	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
E - Estimated	N/A MPH 0	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
84. Trailing Tons (gross tonnage, excluding power units)	N/A	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A
		N/A N/A N/A N/A N/A	

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0



91. Equipment Damage This Consist	\$0.00	92. Track, Signal, Way, & Structure Damage	\$0.00	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No N/A	105. Was EOT Device Properly	1. Yes 2. No N/A	106. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

Highway User Involved				Rail Equipment Involved					
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	Code	111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code	1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)	
	N/A	2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)	N/A				
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code	112. Position of Car Unit in					0
		1. North 2. South 3. East 4. West	N/A						

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

	FRA FACTUAL RAILROAD ACCIDENT REPORT	FRA File # HQ-2008-67 Final Report TIC ID# 97150																																																																					
108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.																																																																							
<p>HQ-2008-67 Train No. 824V427 July 29, 2008</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Position</th> <th>Car #</th> <th>Derailed</th> </tr> </thead> <tbody> <tr><td>46</td><td>NS-41694</td><td>Upright</td></tr> <tr><td>47</td><td>NS-26617</td><td>Upright</td></tr> <tr><td>48</td><td>NS-40024</td><td>Upright</td></tr> <tr><td>49</td><td>NS-46824</td><td>Upright</td></tr> <tr><td>50</td><td>NS-42054</td><td>Upright</td></tr> <tr><td>51</td><td>NS-30078</td><td>Upright</td></tr> <tr><td>52</td><td>NS-30801</td><td>Upright</td></tr> <tr><td>53</td><td>NS-42672</td><td>Upright</td></tr> <tr><td>54</td><td>NS-44580</td><td>Upright</td></tr> <tr><td>55</td><td>NS-40350</td><td>Upright</td></tr> <tr><td>56</td><td>NS-22625</td><td>Upright</td></tr> <tr><td>57</td><td>NS-47231</td><td>Upright</td></tr> <tr><td>58</td><td>NS-21848</td><td>Upright</td></tr> <tr><td>59</td><td>NS-42732</td><td>Upright</td></tr> <tr><td>60</td><td>NS-27037</td><td>Upright</td></tr> <tr><td>61</td><td>NS-503427</td><td>Upright</td></tr> <tr><td>62</td><td>NS-40036</td><td>Upright</td></tr> <tr><td>63</td><td>NS-41670</td><td>Upright</td></tr> <tr><td>64</td><td>CR-21019</td><td>Upright</td></tr> <tr><td>65</td><td>NS-41379</td><td>Upright</td></tr> <tr><td>66</td><td>NS-32524</td><td>Upright</td></tr> <tr><td>67</td><td>NS-40929</td><td>Upright</td></tr> </tbody> </table> <div style="text-align: center; margin: 10px 0;">  </div> <p style="text-align: center;">Train # 824V427 Lead Locomotive NS824 / Pusher Locomotive NS9825 Eastbound loaded coal train with 145 cars</p>			Position	Car #	Derailed	46	NS-41694	Upright	47	NS-26617	Upright	48	NS-40024	Upright	49	NS-46824	Upright	50	NS-42054	Upright	51	NS-30078	Upright	52	NS-30801	Upright	53	NS-42672	Upright	54	NS-44580	Upright	55	NS-40350	Upright	56	NS-22625	Upright	57	NS-47231	Upright	58	NS-21848	Upright	59	NS-42732	Upright	60	NS-27037	Upright	61	NS-503427	Upright	62	NS-40036	Upright	63	NS-41670	Upright	64	CR-21019	Upright	65	NS-41379	Upright	66	NS-32524	Upright	67	NS-40929	Upright
Position	Car #	Derailed																																																																					
46	NS-41694	Upright																																																																					
47	NS-26617	Upright																																																																					
48	NS-40024	Upright																																																																					
49	NS-46824	Upright																																																																					
50	NS-42054	Upright																																																																					
51	NS-30078	Upright																																																																					
52	NS-30801	Upright																																																																					
53	NS-42672	Upright																																																																					
54	NS-44580	Upright																																																																					
55	NS-40350	Upright																																																																					
56	NS-22625	Upright																																																																					
57	NS-47231	Upright																																																																					
58	NS-21848	Upright																																																																					
59	NS-42732	Upright																																																																					
60	NS-27037	Upright																																																																					
61	NS-503427	Upright																																																																					
62	NS-40036	Upright																																																																					
63	NS-41670	Upright																																																																					
64	CR-21019	Upright																																																																					
65	NS-41379	Upright																																																																					
66	NS-32524	Upright																																																																					
67	NS-40929	Upright																																																																					

4
6
4
4
7
4
8
4
9
5
0
5
1
5
2
5
3
5
4
5
5
5
5
6
5
7
5
8
5
9
6
0
6
1
6
2
6
3
6
4
6
5
6
6
6
7

137. SYNOPSIS OF THE ACCIDENT

On July 29, 2008 at 10:03 p.m. EST Norfolk Southern Railway Company (NS) Unit Coal Train # 824V4-27 was traveling eastbound on single Main Track and derailed. The accident occurred on the NS Whitethorn District, Virginia Division in Whitethorn, VA at mile post (MP) V 282.2. The accident occurred approximately 10 miles west of the City of Blacksburg, VA in Montgomery County. NS Officials reported that the damages for the accident totaled \$54,450 for equipment; \$135,000 for track structures; for a grand total of \$189,450.

At the time of the accident it was dark and clear. The temperature was 85 F.

The probable cause of the derailment was determined to be the failure of the A-end truck bolster and center plate on gondola rail car # NS 41694. The lack of lubrication on the bolster bowl and center plate prevented the truck from swiveling freely.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of eastward NS Unit Coal Train # 824V4-27 included a locomotive engineer and a conductor. The crew went on duty at Bluefield, WV at 5:20 p.m. The crew was taxied to Narrows, VA to get the train. This is the home terminal for the crew members and all received the required statutory off-duty rest period prior to reporting for duty.

The assigned coal train consisted of two locomotives and 145 loaded coal hopper cars. The train was 7,406 feet long and weighed 2,0571 tons when it departed Narrows, VA.

The Crew stopped at Whitethorn, VA to add two distributive power locomotives (pusher) to the rear of the train. The pusher was operated by one engineer and was designated as NS Train # V52V4-29. The crews performed intermediate train air brake test at both locations prior to proceeding toward Roanoke, VA.

As the eastbound train approached the accident area the locomotive engineer of NS train 824V4-27 was seated at the controls on the south side of the leading locomotive. The conductor was seated on the north side of the leading locomotive and the locomotive engineer of train (pusher) V52V4-29 was seated at the controls on the south side of the pusher locomotive.

The direction of the train was eastward toward Roanoke, VA negotiating through a left hand curve as seen by the train crew. The NS timetable identifies the curve as a right hand 8.6 degree curve. The point of the derailment is a spiral of the leaving end (east) of the curve at MP V282.8.

The railroad timetable direction of the train is east. The geographic direction of the train was east. Timetable directions are used throughout this report.

THE ACCIDENT

NS Train # 824V4-27 along with pusher consist NS V52V4-29 was being operated at 19 mph approaching the accident area. The crews proceeded along the Whitethorn District with no indication of a pending problem. After passing way-side signal 282.2 the engineer of the lead locomotive noticed the train was slowly starting to lose speed. The engineer of the lead locomotive radioed to the engineer of the pusher locomotive to ask him if he had lost power to a locomotive. The pusher engineer responded that he did not know what was going on and the pusher still had normal air pressure. The two engineers began to notch down their locomotives together until the train went into emergency. The maximum authorized speed for the train was 25 mph as designated in the former NS Timetable that was in effect at the time of the accident.

At approximately 10:03 p.m. July 29, 2008, NS Train # 824V4-27 experienced an undesired emergency application of the train air brake system. The train was in the 8th notch running 19 mph when the train began to slow. The Engineer had notched the train throttle down to the 3rd notch at 7 mph, 614 amps when the train went into emergency. Once the train came to a complete stop the conductor dismounted the lead locomotive and began inspecting the train. The conductor discovered the 46th through the 67th loaded coal hopper cars had derailed and were all still in an upright position.

Norfolk Southern Management was dispatched to the scene. The managers concluded that there were no hazardous materials involved and the damages were well below the threshold for mandatory drug testing of the crew. One division of Hulcher Railroad Contractors from Barboursville, WV was dispatched to the scene and arrived at 4:35 am on July 30th. One division of Corman Railroad Construction Co. from Huntington, WV also arrived at 4:35 am on July 30th. Crane-masters Inc. was also dispatched to the scene with one crew arriving from Richmond, VA and another from Toney Town, MD. Both Crane-masters crews arrived at 4:35 am on July 30th. All of the derailed cars were re-railed at 11:00 pm on July 30th. The track was repaired and returned to service at 6:30 am on July 31st. NS Officials reported eleven freight train delays on the Whitethorn district due to this accident.

FRA inspections revealed no exceptions with the track conditions or train handling for this accident.

ANALYSIS AND CONCLUSIONS

ANALYSIS - TOXICOLOGICAL TESTING:

The three employees involved in the accident were not tested due to the accident damage dollar amounts did not meet the threshold for mandatory testing.

CONCLUSION:

Intoxication was not a causal factor in this accident.

ANALYSIS - LOCOMOTIVE SAFETY DEVICES:

The leading locomotive was equipped with a headlight, the auxiliary lights and the audible warning device required by Federal regulations. These devices were retested in the presence of an FRA Motive Power and Equipment Inspector (MP&E). No exceptions were noted.

CONCLUSION:

The locomotive safety devices were in full compliance with Federal requirements.

ANALYSIS - LOCOMOTIVE ENGINEER OPERATING PERFORMANCE:

The locomotive was also equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded by the trainmaster and analyzed. The findings were released to Federal inspectors.

CONCLUSION:

The locomotive engineer was in compliance with all applicable railroad operating and train handling requirements and Federal Standards.

ANALYSIS FATIGUE:

FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis which is equivalent to blood alcohol content (BAC) of 0.05. At or above this baseline we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information FRA uses the default software settings. FRA obtained fatigue related information including a 10-day work history for three employees involved in this accident.

CONCLUSION:

FRA concluded fatigue of the train crew was not a factor in this accident.

ANALYSIS - MECHANICAL:

An inspection in the field of all of the freight cars involved in the accident did not yield any apparent or obvious defects. At the time of the inspection no deficiencies were noted. A more detailed scientific analysis report was submitted that analyzed both the evidence from the track and the lead car in the derailment. This testing was completed by the Norfolk Southern (NS) Tests and research department.

CONCLUSION:

FRA reviewed the report carefully and agrees with its findings that the lack of lubrication on the bolster bowl and center plate prevented the truck from swiveling freely which caused the car to climb the rail resulting in the derailment.

OVERALL CONCLUSIONS:

The download data from the event recorder indicated that the engineer was operating the train in compliance with the NS Timetable and Operating Rules and Federal Standards. No exceptions were noted in the handling of the train.

The FRA conclusion was determined by lab analysis and the discovery of a failed truck on gondola car NS 41694 at the accident site. The car was moved to Shaffers Crossing Car Shop at Roanoke, VA for further inspection. The A-end truck was removed from the car. Further inspection revealed that the truck bolster bowl and center plate were binding due to the absence of lubrication. In accordance with the FRA Guide for Preparing Accident / Incident Reports the primary cause code is FRA E46C. (E46C - truck bolster stiff, improper swiveling).

PROBABLE CAUSE & CONTRIBUTING FACTORS:

The derailment occurred when the center plate and bolster bowl of Gondola Car NS # 41694 experienced excessive binding due to a lack of lubrication which prohibited the truck from traveling with the curvature of the track. No contributing factors were found.