



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-70***

***Burlington Northern Santa Fe (BNSF)
Luther, OK
August 22, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2008-70</u>	
1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TX-0808113		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Stillwater Central RR Co., Inc. [SLWC]			4a. Alphabetic Code SLWC		4b. Railroad Accident/Incident No. D532508		
5. U.S. DOT_AAR Grade Crossing Identification Number			6. Date of Accident/Incident Month 08 Day 22 Year 2008		7. Time of Accident/Incident 02:37:21 ☐ AM ☒ PM		
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative)
							Code 01
9. Cars Carrying HAZMAT 13		10. HAZMAT Cars Damaged/Derailed 8		11. Cars Releasing HAZMAT 8		12. People Evacuated 35	
						13. Division Texas	
14. Nearest City/Town Luther			15. Milepost (to nearest tenth) 512.0		16. State Abbr Code N/A OK		17. County OKLAHOMA
18. Temperature (F) (specify if minus) 92 F		19. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		20. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		21. Type of Track 1. Main 3. Siding 2. Yard 4. Industry	
		Code 2				Code 1	
22. Track Name/Number single main track			23. FRA Track Class (1-9, X) 2		24. Annual Track Density (gross tons in millions) 9.768		25. Time Table Direction 1. North 3. East 2. South 4. West
							Code 4
OPERATING TRAIN #1							
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching A. Spec. MoW Equip. Code 1	
						27. Was Equipment Attended? 1. Yes 2. No 1	
						28. Train Number/Symbol TULTPL9-22	
29. Speed (recorded speed, if available) R - Recorded E - Estimated 19 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 10271		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits j N/A N/A N/A N/A			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		THRX 5945		30		yes	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol 0	
						Drugs 0	
						34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		3		0 0		0 0	
(2) Total Derailed		0		0 0		0 0	
36. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose	
(1) Total in Equipment Consist		77		0		33 0 0	
(2) Total Derailed		14		0		0 0 0	
37. Equipment Damage		This Consist \$542,064.00		38. Track, Signal, Way, & Structure Damage \$210,975.00		39. Primary Cause Code T102	
						40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
41. Engineer/ Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0	
45. Engineer/Operator Hrs 4 Mi 35		46. Conductor Hrs 4 Mi 35					
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
50. EOT Device?		1. Yes 2. No 1		51. Was EOT Device Properly Armed?		1. Yes 2. No 1	
52. Caboose Occupied by Crew?		1. Yes 2. No N/A					
OPERATING TRAIN #2							
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching A. Spec. MoW Equip. Code N/A	
						54. Was Equipment Attended? 1. Yes 2. No N/A	
						55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT										FRA File # <u>HQ-2008-70</u>	
57. Trailing Tons (gross tonnage, excluding power units)		c. Auto train stop		i. Time table/train orders		o. Positive train control		2 = Remote control tower					
N/A		d. Cab		j. Track warrant control		p. Other (Specify in narrative)		3 = Remote control transmitter - more than one remote control transmitter				N/A	
		e. Traffic		k. Direct traffic control		Code(s)							
		f. Interlocking		l. Yard limits		N/A N/A N/A N/A N/A							
59. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		60. If railroad employee(s) tested for drug/alcohol use,					
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A		enter the number that were positive in the appropriate box.					
								Alcohol N/A Drugs N/A					
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		61. Was this consist transporting passengers? (Y/N)					
								N/A					
62. Locomotive Units		a. Head End		Mid Train		Rear End		63. Cars		Loaded		Empty	
		b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass.	
										c. Freight		d. Pass.	
(1) Total in Train		N/A		N/A		N/A		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A		N/A		N/A		N/A	
64. Equipment Damage This Consist		N/A		65. Track, Signal, Way, & Structure Damage		N/A		66. Primary Cause Code		N/A		67. Contributing Cause Code	
												N/A	
68. Engineer/Operators		69. Firemen		70. Conductors		71. Brakemen		72. Engineer/Operator		73. Conductor			
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A			
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other		77. EOT Device?		78. Was EOT Device Properly Armed?			
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		N/A		N/A		N/A		79. Caboose Occupied by Crew?		1. Yes 2. No		N/A	
OPERATING TRAIN #3													
80. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip.		Code		81. Was Equipment Attended?	
		2. Passenger train		5. Single car		8. Light loco(s).				N/A		1. Yes 2. No N/A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car						82. Train Number/Symbol	
												N/A	
83. Speed (recorded speed, if available)		Code		85. Method(s) of Operation (enter code(s) that apply)				85a. Remotely Controlled Locomotive?					
R - Recorded		N/A MPH		a. ATCS		g. Automatic block		0 = Not a remotely controlled					
E - Estimated		N/A		b. Auto train control		h. Current of traffic		1 = Remote control portable					
				c. Auto train stop		i. Time table/train orders		2 = Remote control tower					
84. Trailing Tons (gross tonnage, excluding power units)		N/A		d. Cab		j. Track warrant control		3 = Remote control transmitter - more than one remote control transmitter				N/A	
				e. Traffic		k. Direct traffic control							
				f. Interlocking		l. Yard limits		N/A N/A N/A N/A N/A					
86. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		87. If railroad employee(s) tested for drug/alcohol use,					
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A		enter the number that were positive in the appropriate box.					
								Alcohol N/A Drugs N/A					
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		88. Was this consist transporting passengers? (Y/N)					
								N/A					
89. Locomotive Units		a. Head End		Mid Train		Rear End		90. Cars		Loaded		Empty	
		b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass.	
										c. Freight		d. Pass.	
(1) Total in Train		N/A		N/A		N/A		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A		N/A		N/A		N/A	
91. Equipment Damage This Consist		N/A		92. Track, Signal, Way, & Structure Damage		N/A		93. Primary Cause Code		N/A		94. Contributing Cause Code	
												N/A	
95. Engineer/Operators		96. Firemen		97. Conductors		98. Brakemen		99. Engineer/Operator		100. Conductor			
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A			
Casualties to:		101. Railroad Employees		102. Train		103. Other		104. EOT		105. Was EOT Device Properly			
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		N/A		N/A		N/A		106. Caboose Occupied by Crew?		1. Yes 2. No		N/A	
Highway User Involved													
Rail Equipment Involved													
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code				111. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code			
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A			
108. Vehicle Speed (est. MPH at impact)		N/A		109. geographical Code				112. Position of Car Unit in					
				1. North 2. South 3. East 4. West		N/A							

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2008-70</u>	
110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A			
113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A			
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A			
114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A			
114c. State here the name and quantity of the hazardous materials released, if any. N/A							
115. Type 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Crossing Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				116. Signaled Crossing (See instructions for codes)		117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s) N/A N/A N/A N/A N/A N/A N/A				N/A		N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A		119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown	
				Code N/A		120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A		123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown	
				Code N/A		124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
						Code N/A	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A		126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed	
						Code N/A	
Casualties to:		Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured		Code N/A	
						128. Was Driver in the Vehicle? 1. Yes 2. No	
						Code N/A	
129. Highway-Rail Crossing Users		N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)		131. Total Number of Highway-Rail Crossing Users (include driver)	
				N/A		N/A	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A			
				133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No			
				Code N/A			
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A			
				135. Locomotive Audible Warning Sounded? 1. Yes 2. No			
				Code N/A			

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

Sorry, the report can not display the file.

137. SYNOPSIS OF THE ACCIDENT

On August 22, at 2:37 p.m. CST westbound Burlington Northern Santa Fe Railway (BNSF) freight train H-TULTPL9-22A containing various hazardous materials rail cars and general freight derailed approximately 3 miles northeast of Luther, Oklahoma. The incident occurred on the Sooner Subdivision at Milepost 512.0. There were no reported injuries or fatalities to the train crew or general public. The track is owned by the State of Oklahoma and is managed by the Stillwater Central Railroad Company (SLWC).

At the time of the accident the weather was 92°F and clear.

Fourteen rail cars derailed including eight tank cars containing Petroleum Crude Oil, P. G. III, Class 3, UN # 1267. Of the eight tank cars derailed, three were breached in the side of the tank shell (TILX 193325, UTLX 201925, & TILX 194831). All of the remaining derailed tank cars leaked product through the man-way cover. The spilled product caught fire and caused tank car UTLX 201925 to explode. The resulting fire and explosion caused considerable media attention and a local evacuation was ordered.

The evacuation was ordered by the local Fire Officials at about 3:00 p.m. on August 22nd and 14 families (approximately 35 people) were removed. The evacuees were permitted to return to their residences at about 7:30 p.m. on the same day. Emergency responders elected to allow the fire to burn off. The last small fire burning inside tank car TILX 193325 was extinguished by local fire departments at 11:30 a.m. on Saturday, 23 August.

BNSF reports \$542,064 damage to rail cars. SLWC reports \$210,975 damage to track.

The derailment was caused by irregular cross level of the track. An FRA Track Inspector issued a track defect for cross-level deviation in excess of Federal Standards in the area of the derailment.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT:

BNSF freight train H-TULTPL9-22A originated in Tulsa, OK. The initial terminal train air brake test was successfully conducted. The train departed Tulsa at 3:30 a.m. on August 22. The originating crew reached their maximum allowable hours on duty and stopped the train at Stroud, OK.

The relief Oklahoma City based crew consisted of an Engineer and a Conductor. Both relief crew members came on duty at 10:05 a.m. CST on August 22. Both crew members received the required statutory off duty rest period.

The relief crew picked up the train at Stroud, OK. They received their job brief and were told that the train was running smoothly. They noted the brake pressure, confirmed the track warrant was valid then departed Stroud, OK. The crew reported that the train operated smoothly from Stroud, Oklahoma to the accident site.

As the train approached the accident site the Conductor was sitting on the left (South) side of the lead locomotive and was talking with the SLWC dispatcher about the ambient temperature and the upcoming 10 mph speed restriction starting at Milepost 517. The Engineer was sitting on the right (North) side of the lead locomotive and was running in throttle position number 3. The Engineer had not been using the brake but was allowing the train to gradually slow down from 22 mph. The Engineer reported using very little brake from the pickup point to the accident site.

THE ACCIDENT:

The train crew reported having just completed communications with the SLWC dispatcher when they felt the train surge twice. Before the Engineer could react to apply the brakes the train went into emergency.

After the train stopped the Conductor walk back to the second locomotive and could see smoke. He then uncoupled the train from the locomotives and pulled up to the next available highway/rail grade crossing. The

crew members contacted the SLWC dispatcher and their supervisor to advise them of the accident.

There were no reported injuries or fatalities to the train crew or general public.

The local fire officials ordered an evacuation at about 3:00 p.m. on August 22, and 14 families (approximately 35 people) were removed from their homes. All of the evacuees were permitted to return to their residences at about 7:30 p.m. on the same day.

Emergency responders elected to let the fire burn off. The last small fire burning inside tank car TILX 193325 was extinguished by local fire departments at 11:30 a.m. on Saturday August 23.

Fourteen rail cars of the 110 car BNSF train derailed. The 14 cars were in position 30 through 44 of the BNSF train consist. Of those 14 cars, eight were tank cars containing Petroleum Crude Oil, Class 3, UN 1267, P. G. III. These eight tank cars were the only hazardous materials involved in the accident. All eight tank cars leaked their contents and three of the eight were breached in the side of the tank shell. The resulting fire and explosion gained media attention and caused the evacuations of local residents.

BNSF reported \$542,064 damage to rail cars. SLWC reported \$210,975 damage to track.

ANALYSIS AND CONCLUSIONS:

ANALYSIS: - BNSF ENGINEER AND TRAIN OPERATIONS

The event recorder data reflected that the train gradually slowed from 22 mph down to 19 mph at the time of the accident. The train was in a tangent section coming off of a .89-percent descending grade and entering a .67-percent incline grade. The speed limit on this section of track is 25 mph.

The point of derailment was determined by physical evidence to be at track mile post 512.

CONCLUSION:

The engineer operated the train in compliance with all railroad rules and FRA Standards. The train was in good operating condition and operating properly. The crew was operating the train according to existing operating rules and train handling requirements.

ANALYSIS: - FATIGUE

Fatigue Analysis information was collected from BNSF crew members. "FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis, which is equivalent to blood alcohol content (BAC) of 0.05. At or above this baseline, we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information, FRA uses the default software settings."

CONCLUSION:

FRA concluded that fatigue was not a probable factor for the two crew members.

ANALYSIS: - SLWC TRACK:

FRA and BNSF were both involved in taking track measurements after the derailment. The FRA Track Safety Inspector cited one track defect near the POD where the difference in cross level was 2 7/16 inches. This measured geometry did not conform to FRA Standards.

CONCLUSION:

The track had a documented Federal defect near the point of derailment. The FRA, BNSF and SLWC agree that the derailment was caused by irregular track cross level.

PROBABLE CAUSE AND CONTRIBUTING FACTORS:

The probable cause of the accident was a 2 7/16 inch difference in cross level in the track near the point of derailment.