



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2008-86***

***Burlington Northern Santa Fe (BNSF)  
Gallop, NM  
November 10, 2008***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. SW1108102	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. SW1108102	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 11 Day 10 Year 2008		7. Time of Accident/Incident 06:10: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative)	
Code 01					
9. Cars Carrying HAZMAT 29		10. HAZMAT Cars Damaged/Derailed 15		11. Cars Releasing HAZMAT N/A	
				12. People Evacuated 0	
				13. Division Southwest	
14. Nearest City/Town Gallup		15. Milepost (to nearest tenth) 159.1		16. State Abbr Code N/A NM	
				17. County MCKINLEY	
18. Temperature (F) (specify if minus) 24 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2	
22. Track Name/Number 1601		23. FRA Track Code Class (1-9, X) 1		24. Annual Track Density (gross tons in millions) N/A	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 3	

**OPERATING TRAIN #1**

26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		27. Was Equipment Attended? Code		28. Train Number/Symbol	
		2. Passenger train		5. Single car		8. Light loco(s).				1. Yes 2. No		HBARTUL19A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car				1			
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH E		31. Method(s) of Operation (enter code(s) that apply)						31a. Remotely Controlled Locomotive?					
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits						0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
30. Trailing Tons (gross tonnage, excluding power units) 4818		n		N/A		N/A		N/A		N/A		0	
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.					
(1) First involved (derailed, struck, etc)		TILX635562		59		no				Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0		0		N/A				N/A		N/A	
		34. Was this consist transporting passengers? (Y/N)						N					
35. Locomotive Units		a. Head End		Mid Train		Rear End		36. Cars		Loaded		Empty	
		b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass. c. Freight d. Pass. e. Caboose	
(1) Total in Train		3		0		0		0		(1) Total in Equipment Consist		18 0 68 0 0	
(2) Total Derailed		0		0		0		0		(2) Total Derailed		0 0 20 0 0	
37. Equipment Damage		This Consist		\$70,838.00		38. Track, Signal, Way, & Structure Damage		\$200,000.00		39. Primary Cause Code		H703	
										40. Contributing Cause Code		N/A	
Number of Crew Members						Length of Time on Duty							
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0		45. Engineer/Operator Hrs 3 Mi 40		46. Conductor Hrs 3 Mi 40			
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other		50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1			
Fatal		0		0		0							
Nonfatal		0		0		0		52. Caboose Occupied by Crew? 1. Yes 2. No		N/A			

**OPERATING TRAIN #2**

53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		54. Was Equipment Attended? Code		55. Train Number/Symbol	
		2. Passenger train		5. Single car		8. Light loco(s).				1. Yes 2. No		N/A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car		N/A					
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply)						58a. Remotely Controlled Locomotive?					
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track						0 = Not a remotely controlled 1 = Remote control portable					

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
------------------------	---	-------------	---	----------------	---	--------------	---	-----------------------	------------	---------------	------------

Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No N/A
Fatal	0	0	0	79. Caboose Occupied by Crew?	1. Yes 2. No		N/A
Nonfatal	0	0	0				

**OPERATING TRAIN #3**

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded		a. ATCS g. Automatic block m. Special instructions	0 = Not a remotely controlled
E - Estimated	N/A MPH N/A	b. Auto train control h. Current of traffic n. Other than main track	1 = Remote control portable
84. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop i. Time table/train orders o. Positive train control	2 = Remote control tower
		d. Cab j. Track warrant control p. Other (Specify in narrative)	3 = Remote control transmitter - more than one remote control transmitter
		e. Traffic k. Direct traffic control	
		f. Interlocking l. Yard limits	
			N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			


95. Engineer/Operators	N/A	96. Firemen	N/A	97. Conductors	N/A	98. Brakemen	N/A	99. Engineer/Operator	Hrs N/A Mi N/A	100. Conductor	Hrs N/A Mi N/A
------------------------	-----	-------------	-----	----------------	-----	--------------	-----	-----------------------	----------------	----------------	----------------

Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No N/A	105. Was EOT Device Properly	1. Yes 2. No N/A
Fatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	1. Yes 2. No		N/A
Nonfatal	N/A	N/A	N/A				

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code	A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian	B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	N/A	111. Equipment	3. Train (standing) 6. Light Loco(s) (moving) Code	1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing)	N/A
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical Code	N/A	2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)			
		1. North 2. South 3. East 4. West	N/A	112. Position of Car Unit in	N/A		

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



## 137. SYNOPSIS OF THE ACCIDENT

Eastbound Burlington Northern Santa Fe (BNSF) freight train BNSF 4345 derailed in Gallup, New Mexico on November 11, 2008 at 6:10 a.m. The derailment occurred on the 1601 Switch in Gallup Yard of the Gallup Subdivision at mile post 159.1.

A total of twenty (20) cars derailed including fifteen (15) hazardous material cars. No release of hazardous material was reported and no evacuation was ordered. The total damage to the rail cars and the track structure was \$ 288,838.

The temperature at the time of the derailment was recorded at 24 degrees Fahrenheit. At the time of the derailment it was dark, cold, and a combination of snow and ice was falling.

The cause of the derailment was a switch not latched or locked (H703).

## 138. NARRATIVE

## CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of eastward BNSF Freight Train 4345 included a locomotive engineer and a conductor. Both crew members went on duty at 2:30 a.m. MST November 10, 2008 at the BNSF Winslow Yard in Winslow Arizona. This was the home terminal for both crew members who received more than the required statutory off duty rest period prior to reporting for duty.

A switch herder was also involved in the incident. The switch herder is headquartered at Gallup Yard in Gallup, New Mexico.

The assigned freight train consisted of three locomotives, 18 loaded, and 68 empty rail cars of several varieties of freight. That brings the total amount to 86 cars with total length of 5,451 feet and a weight of 4,818 tons. The three locomotives had a total length of 219 feet. The total length of the train was 5,670 feet. The train had 56 tons per operative brake. A class 3 air brake test was performed before departure at Winslow, Arizona.

The train was scheduled to travel to Belen, New Mexico with cars to be added and removed at Gallup, New Mexico.

As the eastbound train approached the derailment area the locomotive engineer was seated at the controls on the south side of the lead locomotive and the conductor was seated on the north side.

In this area of the railroad are two switching leads approaching the derailment site from Track # 1603. The first lead encountered is Lead Track # 1626. The lead branches off to the north. The second lead is Lead Track # 1601. This lead is approximately 580 feet east of the 1626 lead Track. Lead Track Number 1601 branches off to the south. This track has an ascending grade of .27 degrees.

The railroad timetable direction of the train is east. The geographic direction is also east. Timetable

directions are used throughout this report.

#### THE ACCIDENT

A job briefing was conducted with the crew of BNSF Freight Train 4345, the BNSF Train Dispatcher and the BNSF Gallup Switch Herder. The instructions relayed to the crew were that they would be heading into track 1601 at the west end of Gallup Yard. The switch herder was to line the 1601 switch for movement onto Track 1601. The switch herder informed the crew that the switch was lined for their movement. The train was being operated at an estimated speed of 5 mph while entering Track 1601. The engineer reported that after about half the train was in Track 1601, it began to pull heavy. The engineer stopped the train. The switch header and the conductor went back to the rear of the train to investigate and discovered that cars from fifty-six (56) through seventy-five (75) were derailed. All cars were upright. No hazardous materials commodity released, no evacuations were ordered and no injuries were reported due to the derailment. Damage to the cars totaled \$ 70,838, \$ 200,000 for track structure damage, and \$ 18,000 for cleanup. This brings the total cost of the derailment to \$ 288,838.

#### ANALYSIS AND CONCLUSIONS

The track structure was in full compliance with the FRA Track Safety Standards and the railroads own rules. The railroad was at fault for not properly latching and/or locking the switch.

#### PROBABLE CAUSE AND CONTRIBUTING FACTORS

The investigation revealed that the probable cause for the derailment was Switch 1601 not properly latched and/or locked. It was determined that due to the fact that Switch 1601 was not properly latched / locked. This situation caused the switch to line for Track 1603 under the movement of tank car TILX 635562, the fifty-six (56) car in the train.

A contributing factor was ice in the latch mechanism which caused the handle of the switch not to latch properly. There was also no lock on the switch at the time of the derailment.

#### RECOMMENDATIONS AND COMMENTS

When investigating the derailment, a determination was made that the 1601 Switch had not been properly latched and locked. This allowed the switch handle to throw as the train passed over it from 1601 Track to 1603 Track. Two contributing factors were that a lock was not used to lock the latching mechanism and snow and ice had built up in the latching mechanism causing it not to latch properly.

BNSF was not in compliance with General Code of Operating Rules 8.2 (GCOR). This rule states that "After locking a switch or derail the lock must be tested to ensure it is secure." A lock was not present as indicated in the photographs of the latch mechanism. BNSF has attached four locks to the west switches in Gallup, NM Yard. BNSF has instructed that these switches be locked and tested as per instruction with GCOR 8.2. Alternative handling was issued to the switch herder for disciplinary action. FRA agrees that the remedial action taken by BNSF will stop this type of derailment from occurring in the future.