



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-92***

***Burlington Northern Santa Fe (BNSF)
Page, ND
December 7, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TC1208105	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. TC1208105	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 12 Day 07 Year 2008		7. Time of Accident/Incident 12:45:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
				13. Other (describe in narrative)	
				Code 01	
9. Cars Carrying HAZMAT 24		10. HAZMAT Cars Damaged/Derailed 11		11. Cars Releasing HAZMAT 3	
				12. People Evacuated 0	
				13. Division Twin Cities	
14. Nearest City/Town Page		15. Milepost (to nearest tenth) 24.2X		16. State Abbr Code N/A ND	
				17. County CASS	
18. Temperature (F) (specify if minus) 10 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 66.8	
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 4	
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1	
				28. Train Number/Symbol MNTWMIN106	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 55 MPH R		31. Method(s) of Operation (enter code(s) that apply)			31a. Remotely Controlled Locomotive?
		a. ATCS			0 = Not a remotely controlled
		g. Automatic block			1 = Remote control portable
		h. Current of traffic			2 = Remote control tower
		i. Time table/train orders			3 = Remote control transmitter - more than one remote control transmitter
		j. Track warrant control			0
		k. Direct traffic control			
		l. Yard limits			
		e N/A N/A N/A N/A			
30. Trailing Tons (gross tonnage, excluding power units) 6108					
32. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
(1) First involved (derailed, struck, etc)		BNSF4349	1	N/A	Alcohol 0
(2) Causing (if mechanical cause reported)		0	0	N/A	Drugs 0
					34. Was this consist transporting passengers? (Y/N) N
35. Locomotive Units		a. Head End	Mid Train	Rear End	36. Cars
		b. Manual	c. Remote	d. Manual	a. Freight
		c. Remote	c. Remote	c. Remote	b. Pass.
					c. Freight
					d. Pass.
					e. Caboose
(1) Total in Train		4	0	0	0
(2) Total Derailed		2	0	0	0
37. Equipment Damage		This Consist	\$1,364,486.00	38. Track, Signal, Way, & Structure Damage	\$668,000.00
					39. Primary Cause Code T204
					40. Contributing Cause Code N/A
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators	42. Firemen	43. Conductors	44. Brakemen	45. Engineer/Operator	46. Conductor
1	0	1	0	Hrs 2 Mi 15	Hrs 2 Mi 15
Casualties to:		47. Railroad Employees	48. Train Passengers	49. Other	50. EOT Device?
Fatal		0	0	0	1. Yes 2. No 1
Nonfatal		0	0	0	51. Was EOT Device Properly Armed? 1. Yes 2. No 1
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code	
		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
				55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive?
		a. ATCS			0 = Not a remotely controlled
		g. Automatic block			1 = Remote control portable
		h. Current of traffic			
		i. Time table/train orders			
		j. Track warrant control			
		k. Direct traffic control			
		l. Yard limits			
		e N/A N/A N/A N/A			

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
				N/A	1. Yes 2. No	N/A	N/A

83. Speed (recorded speed, if available)	R - Recorded E - Estimated	Code N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
84. Trailing Tons (gross tonnage, excluding power units)	N/A		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
			m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck 108. Vehicle Speed (est. MPH at impact)	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
109. geographical 1. North 2. South 3. East 4. West			Code N/A	112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative)			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A				
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			N/A
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Westbound Burlington Northern Santa Fe Railway Company (BNSF) freight train derailed on December 7, 2008 at 12:45 p.m. CST. The accident occurred at Nolan (a BNSF rail station) located near Page, North Dakota (approximately 44 miles northwest of Fargo), on a single Main Track located at milepost 24.2X on the Twin Cities Division, KO Subdivision.

The train consisted of four locomotives, 42 loaded cars and 25 empty freight cars. The rear two locomotives and the first 37 head cars behind the locomotives derailed as it was traveling west on an ascending grade in a curve. The locomotives and cars traveled approximately 1,600 feet after the emergency brake application.

Included in the derailment were eleven tank cars containing hazardous materials of which three were breached and spilled product. Methanol from one of the breached tank cars was ignited by sparks from the derailment resulting in a fire. There was no evacuation ordered, however, one individual residing near the accident site departed on his own accord.

The railroad signal damage was \$ 91,000 track damage \$ 577,000 and equipment damage was \$ 1,364,486. Total railroad damage was \$ 2,032,486. There were no injuries as a result of the accident.

At the time of the derailment the temperature was 10 degrees F and cloudy.

The probable cause of the accident was a broken rail in Continuous Welded Rail (CWR) territory - T-204 "broken rail - weld (field)."

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of BNSF Freight Train # M-NTWMIN1-06 consisted of a locomotive engineer and a conductor. They first went on duty at 10:30 a.m. CST December 7, 2008 at Dilworth Yard in Dilworth, Minnesota. This is the home terminal for the conductor and the engineer and both received more than the required statutory off duty rest period prior to reporting for duty.

The assigned freight train consisted of four locomotives, 42 loaded rail cars and 25 empty rail cars. There were 6,108 trailing tons and the train was 4,059 feet in length. It was a freight train scheduled to travel from Dilworth to Minot, North Dakota, a distance of approximately 241 miles.

The train departed Dilworth at approximately 11:15 a.m. CST. The initial terminal train air brake test was performed at Minneapolis, Minnesota on December 6, 2008 at 10:21 p.m. BNSF Train # M-NTWMIN1-06 did not require a pre departure train air brake test at Dilworth because the train was never off air more than four hours and no cars were added to the consist.

As the train approached the derailment area the locomotive engineer was seated at the controls on the right (north) side of the leading locomotive. The conductor was seated on the left (south) side of the cab of the leading locomotive. Interviews conducted by the Federal Railroad Administration (FRA) Investigators revealed the trip was uneventful prior to the derailment.

Approaching the derailment site from the east traversing westward there is tangent track from milepost 23.0X to milepost 24.0X followed by a 3- degree curve to the left on single Main Track from milepost 24.0X to point of derailment (POD). The derailment occurred in a 3-degree curve to the left. The track has a .30 percent descending grade from milepost 23.0X to 23.89X, and a .09 percent ascending grade from milepost 23.89X to POD. There are two public rail grade crossings between milepost 23.0X and milepost 24.2X, one at milepost 24.06X and one at milepost 24.13X.

THE ACCIDENT

As the train was traveling westward it experienced an undesired train induced emergency air brake application. After coming to a stop the conductor notified the train dispatcher of the event via railroad radio. The conductor then walked back to inspect the train and discovered that the two rear locomotives and 1st through the 37th head cars behind the locomotives had derailed.

There were no injuries reported as a result of this accident.

Included in the derailed cars were eleven tank cars containing hazardous materials. Three of these cars were breached and leaking product and a fire ensued. The first breached tank car, UTLX 202192, contained Methanol. It was penetrated in two areas on the A end. The tank car eventually leaked and burned off approximately 6,000 gallons of product. The car continued to burn approximately 29 hours until the fire was extinguished by repositioning the tank car to stop the leaks. The second breached tank car, UTLX 20490, contained Residue Crude Oil. The third tank car, TEAX 3405, contained Residue Liquefied Petroleum Gas. Both of these cars were also on fire. There was no evacuation ordered, however one individual residing near the accident site departed on his own accord.

ANALYSIS AND CONCLUSIONS:

Investigation of the derailment determined that the initial POD was at milepost 24.2X on an ascending grade track. The train was traveling timetable and geographical direction west on single Main Track at a recorded speed of 55 mph as it approached the POD. The speed was recorded by the event recorder of the controlling locomotive. The maximum authorized speed for this segment of track on the KO Subdivision is 55 mph as designated by the current BNSF Timetable # 3, dated Wednesday October 24, 2007.

The Page, North Dakota rural fire department was at the accident scene for fire control. The Cass County Sheriff's department was at the accident scene for security and traffic control.

ANALYSIS - FATIGUE:

FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis, which is equivalent to blood alcohol content (BAC) of 0.05. At or above this baseline, FRA does not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information, FRA uses default settings.

The engineer had a fatigue rating of 82.21 and the conductor had a rating of 96.40.

CONCLUSION:

FRA obtained fatigue related information including a 10-day work history for the members of the train crew. FRA concluded fatigue was not a probable causal factor of the accident.

The railroad concluded that signal damage was \$ 91,000; track damage was \$ 577,000 and equipment damage was \$ 1,364,486. Total railroad damage was estimated at \$ 2,032,486.

ANALYSIS - TOXICOLOGICAL TESTING:

The accident met the criteria for FRA Post Accident Toxicology Testing as required under Title 49 CFR, Part 219- Subpart C. The crew was blood and urine tested at an Occupational Health Services Collection Facility. Test results of these tests were negative for the engineer and conductor.

CONCLUSION:

Toxic impairment of the crew members was not a factor in the accident.

ANALYSIS - OPERATING PRACRISES:

An inspection of the data from the event recorder located on the lead locomotive indicated that the train was

being operated at 55 mph at the time of the accident. The event recorder also indicated no unusual events related to train handling. The locomotives and cars traveled approximately 1,600 feet after the train induced emergency air brake application.

At the time of the derailment the temperature was 10 Degrees F and it was cloudy.

CONCLUSION:

Train handling did not cause the accident.

PROBABLE CAUSE:

The probable cause of the accident was a broken rail in continuous welded rail (9cwr) territory, T-204 "broken rail - weld (field)." The broken rail was sent to BNSF facility at Topeka, Kansas for laboratory analysis.