



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2007-05***

***Burlington Northern Santa Fe (BNSF)  
Columbus, Kansas  
January 30, 2007***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. SF0107129	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. SF0107129	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 01 Day 30 Year 2007		7. Time of Accident/Incident 11:20: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 14		10. HAZMAT Cars Damaged/Derailed 4		11. Cars Releasing HAZMAT 0	
		12. People Evacuated 0		13. Division Springfield	
14. Nearest City/Town Columbus		15. Milepost (to nearest tenth) 146.9		16. State Abbr Code N/A KS	
		17. County CHEROKEE			
18. Temperature (F) (specify if minus) 10 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
22. Track Name/Number Single Main		23. FRA Track Code Class (1-9, X) 2		24. Annual Track Density (gross tons in millions) 16.36	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 1			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		28. Train Number/Symbol HTULKCK130	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 13 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 8404		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits e N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) ATW90055		b. Position in Train 49	
		c. Loaded (yes/no) no		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A	
(2) Causing (if mechanical cause reported)		0		0	
		N/A		34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End (1) Total in Train 3		Mid Train b. Manual c. Remote 0 0	
		Rear End d. Manual c. Remote 0 0		36. Cars (1) Total in Equipment Consist 49	
(2) Total Derailed 0		0 0		(2) Total Derailed 6	
		0 0		0 0	
37. Equipment Damage This Consist 141999		38. Track, Signal, Way, & Structure Damage 263000		39. Primary Cause Code M507	
				40. Contributing Cause Code N/A	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 8 Mi 0	
46. Conductor Hrs 8 Mi 0					
Casualties to:		47. Railroad Employees 0		48. Train Passengers 0	
Fatal		0		49. Other 0	
Nonfatal		0		0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? 1. Yes 2. No N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number N/A	b. Position in Train N/A	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N) N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train N/A	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist N/A	N/A N/A	N/A N/A	N/A
(2) Total Derailed N/A	N/A	N/A N/A	N/A N/A	(2) Total Derailed N/A	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist N/A	65. Track, Signal, Way, & Structure Damage N/A	66. Primary Cause Code N/A	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators N/A	69. Firemen N/A	70. Conductors N/A	71. Brakemen N/A	72. Engineer/Operator Hrs N/A Mi N/A	73. Conductor Hrs N/A Mi N/A
Casualties to: Fatal N/A	74. Railroad Employees N/A	75. Train Passengers N/A	76. Other N/A	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Nonfatal N/A	N/A	N/A	N/A	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) N/A				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number N/A	b. Position in Train N/A	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train N/A	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist N/A	N/A N/A	N/A N/A	N/A
(2) Total Derailed N/A	N/A	N/A N/A	N/A N/A	(2) Total Derailed N/A	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist N/A	92. Track, Signal, Way, & Structure Damage N/A	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators N/A	96. Firemen N/A	97. Conductors N/A	98. Brakemen N/A	99. Engineer/Operator Hrs N/A Mi N/A	100. Conductor Hrs N/A Mi N/A
Casualties to: Fatal N/A	101. Railroad Employees N/A	102. Train N/A	103. Other N/A	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Nonfatal N/A	N/A	N/A	N/A	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van F. Bus G. School Bus H. Motorcycle J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative) Code N/A				111. Equipment 1. Train(units pulling) 2. Train(units pushing) 3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing) 6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative) Code N/A			
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West Code N/A			112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

**On January 30, 2007, at about 11:20 p.m. Central Standard Time (c.s.t.), northbound BNSF Railway Company (BNSF) Train Symbol H-TULKCK1-30A, which originated at Tulsa, Oklahoma, and terminated in Kansas City, Kansas, derailed 24 cars, lines 44 through 67 which included 4 empty hazardous materials tank cars; however, nothing was reported leaking and there were no injuries. The derailment occurred at milepost 146.6 on single main track on the Springfield Division, Afton Subdivision in the town of Columbus, Kansas.**

**The conditions at the time were cloudy and calm with a temperature of 10 degrees Fahrenheit on tangent track with a 0.5 percent ascending grade.**

**Equipment damages were estimated at \$141,999 and track damages were estimated at \$263,000 for a total of \$404,999, with \$48,000 (not reportable) for re-railing costs.**

**After extensive investigations efforts by both the FRA and BNSF, no probable cause could be determined.**

138. NARRATIVE

**Circumstances Prior to the Accident:**

**The crew of Train Symbol H-TULKCK1-30A consisted of a locomotive engineer and a conductor. They went on duty at 3:20 p.m., c.s.t., January 30, 2007, at the BNSF Tulsa, Oklahoma, Yard, which is the home terminal for both of the crew members. The engineer had been off duty since 11:25 a.m., on January 29, 2007, and the conductor had been off duty since 6:15 a.m., on January 27, 2007. Both of the employees had received more than the statutory off-duty period, prior to reporting for duty.**

**Prior to departure, Train Symbol H-TULKCK1-30A, which consisted of mixed freight, received a Class I brake test and inspection at the Tulsa Yard on January 30, which was completed by the carmen at 4:22 p.m. Departing from Tulsa at 4:25 p.m., Train Symbol H-TULKCK1-30A consisted of 3 locomotives and 79 cars; 43 loaded and 36 empty with 6,223 trailing tons, and 4,499 feet in length. This train was scheduled to set out and pick up cars at Columbus en route to Kansas City, Kansas.**

**The railroad timetable direction of the train was north. The main line in Columbus is tangent track with a 0.5 percent ascending grade, and there was a 25 mph speed restriction due to tie conditions.**

**After Train Symbol H-TULKCK1-30A arrived Columbus at 8:54 p.m., on January 30, the crew aboard Locomotive No. BNSF 7664 left 64 cars with the air brakes set on the main line; they then brought the head 15 cars with them to make an 11 car set out, keeping the head 4 cars coupled to the rear locomotive. They then coupled up to 59 cars on Track No. 623. The conductor walked to the rear of the fill cars coupling up the air hoses. He then placed a gauge on the rear of the fill cars, and the engineer made a 20-pound reduction. The conductor then made his air brake test which lasted 17 minutes and 20 seconds, according to the event recorder download.**

**After the brakes were released on the fill cars, the crew made their way back over to the main line, first in a northern direction and traveling over a gated grade crossing, then reversed the movement in a southerly direction returning to where the 64 cars were previously left. The conductor was riding the rear car of the fill in a southerly movement, and stopped movement 86 feet prior to the standing cars on the main line. He then dismounted and instructed the engineer to back up to make the coupling. The conductor stated the car they coupled into the standing cars with, had an end-of-car cushioning unit, and it did not go all the way in at the time of the coupling, which would indicate a smooth coupling, (2 mph according to the download).**

**After the conductor coupled the two remaining air hoses, the air was restored to the train line and the conductor started back to the head-end of his train when he heard a loud "pop." He walked back to where the joint was made, but did not see anything unusual. He then continued his way back to the lead locomotive on the west side of the mainline while the engineer performed a continuity test.**

**The Derailment:**

About 2 minutes and 14 seconds after Train Symbol H-TULKCK1-30A started to pull north and traveled about 1,396 feet at a maximum recorded speed of 13 mph in throttle position 7, the train experienced an undesired emergency air brake application. The speed was recorded to be 11 mph at the time the undesired emergency air brake application occurred; this is also believed to be the point at which the train derailed as indicated by the rise in amperage seen on the event recorder download.

There was a 25 mph speed restriction placed between milepost (MP) 102.6 and 148.5 on May 5, 2005, due to the poor tie conditions, and this was scheduled to be removed on April 6, 2007. The last track inspection was conducted on January 30, 2007, and no defects were noted.

According to a report from the BNSF Network Operations Center (NOC) warm bearing desk in Fort Worth, Texas, at about 12:05 a.m., on January 31, 2007, the crew reported lines 44 through 67 had been derailed, including 4 hazardous material tank cars containing residue; however, nothing was reported to be leaking.

**Analysis and Conclusion:**

**Analysis**

An inspection was performed on the cars which had already been re-railed and were placed in a siding. Car No. ATW 90055 was observed with the center-of-car cushioning unit in a defective condition which would not allow the center sill to return to its normal position. This car was also the first car derailed according to the BNSF officials on the scene shortly after the derailment. However, it was not clear if the cushioning unit was defective prior to the derailment or was a consequence of the derailment. All other cars seemed to have "normal" damage occurring from a derailment of this type and no obvious truck or wheel defects were noted. Therefore, since the main line track is tangent with very little grade, this would point to a track related derailment.

The event recorder download from the lead locomotive did not reveal any unusual train handling that would cause the derailment.

After Train Symbol H-TULKCK1-30A arrived at Argentine Yard in Kansas City, Kansas, on February 2, 2007. FRA conducted an inbound inspection on the cars that had departed Columbus. Of the remaining 103 cars, 13 were found to be defective for a defect ratio of 12.6 percent and all but 3 were air brake related.

All evidence discovered at the derailment including event recorder download, portions of rail, and the center-of-car cushioning unit, was sent to the BNSF lab in Topeka, Kansas, for analysis.

There was no post accident toxicological testing done as a result of this derailment.

**Conclusion**

There was no clear evidence of the probable cause of the derailment discovered at the site. All evidence discovered at the derailment including the event recorder download, portions of rail, and the center-of-car cushioning unit was sent to the BNSF lab in Topeka, for analysis. The event recorder, all portions of rail and the center-of-car cushioning unit were thoroughly analyzed at the site and BNSF lab. Despite these extensive investigative efforts of the FRA and the BNSF lab analysis, no probable cause could be determined.

**Probable Cause & Contributing Factors:**

M-507 Investigation complete, cause could not be determined. Despite extensive investigative efforts of the FRA and the BNSF lab analysis, no probable cause could be determined.