



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-07***

***Norfolk Southern (NS)
Plainfield, New Jersey
February 15, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS]		1a. Alphabetic Code NS		1b. Railroad Accident/Incident No. 028206			
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A			
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A			
4. Name of Railroad Responsible for Track Maintenance: Consolidated Rail Corp. [CRSH]		4a. Alphabetic Code CRSH		4b. Railroad Accident/Incident No. 053746			
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 02 Day 14 Year 2007		7. Time of Accident/Incident 06:40:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM			
8. Type of Accident/Incident (single entry in code box)							
1. Derailment		4. Side collision		7. Hwy-rail crossing			
2. Head on collision		5. Raking collision		10. Explosion-detonation			
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture			
		9. Obstruction		12. Other impacts			
				13. Other (describe in narrative)			
				Code 12			
9. Cars Carrying HAZMAT 75		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A			
				12. People Evacuated 0			
				13. Division North Jersey			
14. Nearest City/Town South Plainfield		15. Milepost (to nearest tenth) 6.92		16. State Abbr Code N/A NJ			
				17. County MIDDLESEX			
18. Temperature (F) (specify if minus) 19 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1			
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 4			
22. Track Name/Number Whittaker Lead		23. FRA Track Code Class (1-9, X) 1		24. Annual Track Density (gross tons in millions) 00			
				25. Time Table Direction Code 1. North 3. East 2. South 4. 3			
OPERATING TRAIN #1							
26. Type of Equipment Consist (single entry)		1. Freight train		4. Work train			
2. Passenger train		5. Single car		7. Yard/switching			
3. Commuter train		6. Cut of cars		A. Spec. MoW Equip. Code			
		9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1			
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 26 MPH R		31. Method(s) of Operation (enter code(s) that apply)			31a. Remotely Controlled Locomotive?		
30. Trailing Tons (gross tonnage, excluding power units) 9686		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		
		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)			0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0		
32. Principal Car/Unit		a. Initial and Number NS9476		b. Position in Train 1			
(1) First involved (derailed, struck, etc)				c. Loaded (yes/no) no			
(2) Causing (if mechanical cause reported)		0		0 N/A			
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
				Alcohol N/A			
				Drugs N/A			
				34. Was this consist transporting passengers? (Y/N) N			
35. Locomotive Units		a. Head End		Mid Train			
		b. Manual		c. Remote			
		d. Manual		c. Remote			
(1) Total in Train		2		0 0 0 0			
(2) Total Derailed		0		0 0 0 0			
				36. Cars			
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose			
				(1) Total in Equipment Consist 75 0 2 0 0			
				(2) Total Derailed 0 0 1 0 0			
37. Equipment Damage This Consist		13200		38. Track, Signal, Way, & Structure Damage 0			
				39. Primary Cause Code H702			
				40. Contributing Cause Code N/A			
Number of Crew Members				Length of Time on Duty			
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0	
				45. Engineer/Operator Hrs 7 Mi 40		46. Conductor Hrs 7 Mi 40	
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
				50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A			
OPERATING TRAIN #2							
53. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching	
2. Passenger train		5. Single car		8. Light loco(s).		A. Spec. MoW Equip. Code	
3. Commuter train		6. Cut of cars		9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive?		
		a. ATCS b. Auto train control			g. Automatic block h. Current of traffic		
		m. Special instructions n. Other than main track			0 = Not a remotely controlled 1 = Remote control portable		
						55. Train Number/Symbol N/A	

57. Trailing Tons (gross tonnage, excluding power units) 0	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0

64. Equipment Damage This Consist 0	65. Track, Signal, Way, & Structure Damage 0	66. Primary Cause Code N/A	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 0	69. Firemen 0	70. Conductors 0	71. Brakemen 0	72. Engineer/Operator Hrs 0 Mi 0	73. Conductor Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Fatal 0	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) 0				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0


91. Equipment Damage This Consist 0	92. Track, Signal, Way, & Structure Damage 0	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal 0	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West	Code N/A		112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A					
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A					
114c. State here the name and quantity of the hazardous materials released, if any. N/A														
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wigs 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A		
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A						
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A	
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A	
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A	
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)				0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A					
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A					

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

A eastbound NS freight train was diverted from the main track by a switch improperly lined, on February 14, 2007, at 6:40 p.m. The train entered an industrial track, struck a brush cutter and proceeded into the industrial building. The accident occurred on a private industrial lead known as the Whittaker Lead in South Plainfield, New Jersey, adjacent to Milepost 6.92, Conrail Shared Assets (CRSH) Port Reading Secondary mainline.

There were no injuries to the train crew. The leading locomotive sustained estimated damage of \$24,000. The trailing locomotive sustained estimated damage of \$ 4,000 and the brush cutter was totaled (due to its age) at \$3,000. Damage to the building was estimated at \$250,000. Both locomotives and one end of a trailing car derailed when they ran out of running rail within the building.

At the time of the accident it was dark and clear. The temperature was 19° F.

The accident was caused by a track foreman who failed to comply with CRSH Timetable Special Instruction 405-1 procedure and the Federal Railroad Administration Emergency Order No. 24 [Docket No. FRA-2005-22796, Notice No. 1].

138. NARRATIVE

Circumstances Prior to the Accident:

A three man Maintenance of Way (M of W) Group consisting of a track foreman, class one machine operator, and a trackman were assigned to cut brush on the Port Reading Secondary main track between Block Station Center and CP Bound Brook. The group had worked normal assignments of 8 hours each day prior to this assignment.

The track foreman had permission at 8:58 AM from the South Jersey Dispatcher to occupy the Port Reading Secondary main track with an on track brush cutter number WC 2060 that was parked on the Whittaker-Clark and Daniels private industrial lead at Mile Post 6.92. The switch for the siding is facing east. The machine operator and the trackman operated the brush cutter east of the siding switch to Mile Post 7.2 to cut brush.

Due to inclement weather, the track supervisor reached the machine operator by cell phone at 11:42 a.m., informing him that he needed to prepare to tie up the brush cutter and report back to South Plainfield yard to remove snow from the switches.

The machine operator moved the brush cutter west of the switch of the private siding and stopped. He stated that he told the trackman to throw the switch, and after the machine goes by, throw it back normal and put the (M of W) lock on it. The trackman stated that the machine operator told him to throw the switch and lock it. The trackman threw the switch, locked the switch with a (M of W) lock without throwing the switch back to the normal position. The track foreman was standing near the switch, to the north of the trackman, but down a slight embankment at his vehicle.

The track foreman stated that he see the trackman throw the switch, when the machine passed, and lock the switch. He stated that he personally should have checked the switch.

There was no Switch Position Awareness Form (SPAF) completed by the track foreman, no Job Briefing at the completion of the work between the track foreman, machine operator and trackman. The track foreman canceled his Form D with the dispatcher at 12:17 p.m. and said the switches are lined and locked normal. The work group left the site.

The crew of train NS 68Q included a locomotive engineer and a conductor. They went on duty at 11:00 a.m., est, February 14, 2007, at the NS Harrisburg yard in Harrisburg, Pennsylvania. This was the home terminal for the train crew and both received more than the statutory off duty period, prior to reporting for duty.

Their assigned freight train consisted of two locomotives, 2 empty box cars and 75 loaded cars of Ethanol. It was 4,710 feet long, and weighed 9,686 tons. The train was scheduled to travel to Sewaren, New Jersey. The train received an initial terminal train air break test, and departed Harrisburg Yard at 12:30 p.m.

As the eastbound train approached the accident area, the engineer was seated at the controls on the south side of the leading locomotive. The conductor was seated on the north side of the leading locomotive.

In this area of the railroad there are, in succession, a 2 degree curve to the right of about 2,000 feet, followed by a tangent of 3,880 feet to the industry switch, a 11degree curve to the left, 285 feet to the point of the accident, and 448 feet beyond into a industrial building.

The railroad timetable direction of the train was east. The geographic direction was southeast. Timetable directions are used throughout this report.

The Accident:

Train NS 68Q East

The train was being operated east, on the Port Reading Secondary, approaching the accident area. Maximum authorized timetable speed for this train was 30 mph. The engineer noticed the switch target was red approximately 100 feet before entering the private track. He then applied an emergency break application to the rear of his train first and upon entering the siding he noticed a CRSH brush cutter and initiated a full emergency break application. The recorded train speed was 26 mph when the collision to the brush cutter occurred on the Whittaker Lead.

The train impacted the brush cutter and pushed it down the track to the industrial building door, where it derailed to the north, taking out two structural support beams of the northeast corner of the building. The train continued into the building striking a concrete barrier, where trackage ended, and continued to a stop at the east wall of the building.

Brush cutter CRSH WC2060

The brush cutter was parked 285 feet east of the main track switch, on the Whittaker Lead and was unattended. The brush cutter had been parked there by a CRSH machine operator.

Analysis and Conclusions:

Analysis:

The track foreman had seven years service with CRSH, and had been a foreman for only five months. He was book of rules qualified and had received instruction on EO-24. His last date of qualification was on March 14, 2006, and he attained a scoring grade of 90.

For four months, he was a foreman working out of the Oak Island yard headquarters, where he did not have the opportunity to take main track out of service. He was transferred to South Plainfield headquarters and had been a foreman there for about a month. He had only taken track out of service 2-3 times.

When he was in Oak Island yard, he did not have to make SPAF forms out when handling yard switches. It did not occur to him, until after being notified that the accident happened, that he should have made out the SPAF form and complied with EO-24. He was unaware that the trackman was not qualified in the book of rules.

The machine operator had 32 years service with CRSH. He was book of rules qualified, and had received instruction on EO-24. His last date of qualification was on March 16, 2006, and he attained a scoring grade of 100. He thought the trackman understood his instructions for handling the switch. He was unaware that the trackman was not qualified in the book of rules.

The trackman had only 8 months service with CRSH and was not book of rules qualified, and had received no instruction on EO-24. He did not know he was not to operate main track switches in non-sigaled territory, without being qualified on the railroad's operating rules relating to their operation.

Conclusions:

The train crew was in full compliance with the operating rules of the railroad. The train crew members were the only witnesses to the accident, and had no information that could be used to determine why the switch was left in the wrong position.

The track foreman felt that he lacked experience in taking form D's and making out SPAF forms. But when he worked as a welder, he said that they used to take track out of service and at the end of the day they would make sure everything was correct.

Had he followed proper procedures that he had been trained on, made out a SPAF form and held a job briefing with his group, the accident would not have happened. His assuming the trackman had lined and locked the switch for the main track, failing to make out a SPAF form and hold a job briefing put the NS train crew in a position for serious injury or death.

The foreman, machine operator and trackman were terminated from service with CRSH.

The railroad concluded that the accident happened because of non-compliance to Timetable Special Instruction 405-1 and Emergency Order No. 24 procedures. I concur with their conclusion.

Probable Cause and Contributing Factors:

The track foreman's failure to complete the SPAF form and hold a job briefing with his work group to discuss the switch position was the primary contributing factor in this accident.

The FRA concluded that the accident occurred because the track foreman did not comply with CRSH Timetable Special Instruction 405-1 procedure and the Federal Railroad Administration Emergency Order No. 24 [Docket No. FRA-2005-22796, Notice No. 1].