



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-10***

***Union Pacific (UP)
Chandler, Texas
March 4, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0307FW002	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0307FW002	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 03 Day 04 Year 2007		7. Time of Accident/Incident 03:57: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 25		10. HAZMAT Cars Damaged/Derailed 4		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division Fort Worth	
14. Nearest City/Town Chandler		15. Milepost (to nearest tenth) 555.9		16. State Abbr Code N/A TX	
17. County HENDERSON		18. Temperature (F) (specify if minus) 55 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2	
		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Single Main Track		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 19.62	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 4			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		Code 1	
		28. Train Number/Symbol MSHEW 04			
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 48 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 8909		31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) ACFX 44069		b. Position in Train 40	
		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A	
		(2) Causing (if mechanical cause reported) ACFX 44069		40 yes	
		34. Was this consist transporting passengers? (Y/N) N			
35. Locomotive Units		a. Head End (1) Total in Train 3		Mid Train b. Manual 0	
		c. Remote 0		Rear End d. Manual 0	
		e. Remote 0		36. Cars (1) Total in Equipment Consist 62	
		(2) Total Derailed 0		a. Freight 12	
				b. Pass. 0	
				c. Freight 53	
				d. Pass. 0	
				e. Caboose 0	
37. Equipment Damage This Consist 659095		38. Track, Signal, Way, & Structure Damage 569327		39. Primary Cause Code E48C	
				40. Contributing Cause Code N/A	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 5 Mi 47	
46. Conductor Hrs 5 Mi 47		Casualties to:		47. Railroad Employees 0	
		48. Train Passengers 0		49. Other 0	
		50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
		52. Caboose Occupied by Crew? 1. Yes 2. No N/A			
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? 1. Yes 2. No N/A		Code N/A	
		55. Train Number/Symbol N/A			
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track Code(s) e N/A N/A N/A N/A		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) 0	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0

64. Equipment Damage This Consist 0	65. Track, Signal, Way, & Structure Damage 0	66. Primary Cause Code N/A	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 0	69. Firemen 0	70. Conductors 0	71. Brakemen 0	72. Engineer/Operator Hrs 0 Mi 0	73. Conductor Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Fatal 0	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) 0				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0


91. Equipment Damage This Consist 0	92. Track, Signal, Way, & Structure Damage 0	93. Primary Cause Code E48C	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal 0	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West	Code N/A		112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew Warning 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in 3. Did not Stop narrative)	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On March 4, 2007 at 3:57 pm, a Westbound Union Pacific Freight Train traveling at a recorded speed of 48 mph derailed twenty eight (28) rail cars. Eight (8) rail cars remained upright, five (5) rail cars landed on their side, and fifteen (15) rail cars piled up. The accident occurred near Chandler, TX at mile post 555.95 on the UP's Southern Region, Fort Worth Service Unit, Corsicana Subdivision.

Four (4) of the derailed cars contained hazardous materials. Three (3) were residue cars, one (1) was loaded with Ammonium Nitrate. There was no release of product from any of the derailed cars containing hazardous materials. There was an initial evacuation ordered by the Chandler Fire Department of an unknown number of people. However, the evacuation was cancelled before anyone was evacuated. There was a fire caused by the derailment which ignited the spillage of 23,000 gallons of lube oil which was allowed to burn to prevent most of it from entering into a nearby waterway. AMTRAK does not operate on this subdivision. There were no casualties to railroad employees or the public.

Total damages were \$1,228,422 (\$659,095 equipment) and (\$569,327 track).

At the time of the accident it was daylight and cloudy. The temperature was 55°F.

The cause of the accident was E48C (Broken, Missing or otherwise Defective Springs) on Covered Hopper ACFX 44069.

138. NARRATIVE

Circumstances Prior to the Accident:

The crew of train MSHEW-04 included a locomotive engineer and a conductor. They first went on duty at 10:10am CST. March 04, 2007 at Eastman Road, Longview, TX. This is a home terminal for both crew members, and both crew members had received more than the statutory off duty period prior to reporting for duty.

Their assigned freight train consisted of three locomotives, 62 loaded and 53 empty cars of several varieties. The train was 7174 feet long and weighed 8909 tons. The train originated on the Union Pacific Railroad, in Shreveport, LA where it received a Class I Brake Test, and was scheduled to travel to Englewood Yard, Houston, TX.

This train after traveling from Longview, TX to Tyler, TX was held at Tyler, TX for 2 hours and 45 minutes while there was a broken rail repaired at Chandler, TX.

As the Westbound train approached the accident area, the locomotive engineer was seated at the controls on the North side of the leading locomotive. The conductor was seated on the South side of the leading locomotive.

Topography:

In this area of the railroad there is a left hand 2 degree curve with a super elevation of 3 ½ inch. At the point of derailment the train is still in the West spiral of the curve with a cross level of 1 3/4 inches and alignment of 7/8 inch. The elevation was descending at 0.390%

The railroad timetable direction of the train is West. The geographic direction of the train is West. Timetable directions are used through out this report.

Method of Operation:

As indicated by timetable, the method of operation is Centralized Traffic Control.

Weather:

The weather was reported as Cloudy and Daylight. The temperature was 55 degrees F.

The Accident:

The train was being operated at 48 mph approaching the accident area. At the time of the accident the train was being operated at 48 mph. Both speeds were recorded by the event recorder of all three locomotives. Maximum authorized timetable speed is 55+ mph.

The engineer stated that he was operating the locomotives in power, number 8 throttle. The engineer noticed that the train

jerked a little and went into emergency.

Once the train stopped the conductor got off of the locomotives and started walking the train on the engineers side (North side) of the train. After walking for about 35 car lengths he discovered the derailed cars and notified the engineer, who in turn notified the dispatcher that they had a derailment. It was discovered that 28 cars were derailed and that 12 were loaded cars and 16 were empty cars. It was also discovered that 4 of the derailed cars were HAZMAT cars. Three were residue cars and 1 was a load of Ammonium Nitrate. There was no HAZMAT release. There was an initial evacuation ordered by the Chandler Fire Department of an unknown number of people. However, the evacuation was cancelled before anyone was evacuated. There were no human casualties.

There was a spillage of 23,000 gallons of lube oil which caught fire, but was allowed to burn to prevent most of it from entering into a nearby waterway. AMTRAK does not operate on this subdivision.

It was discovered that the point of derailment was at the 555.95 mile post but that the cars turning over and the pile-up happened at the 557 mile post The first car derailed traveled for over a mile before becoming catastrophic.

Analysis and Conclusions:

Analysis: Federal Railroad Administration Post-Accident Forensic Toxicology Result Reports indicates that the two crew members tested had negative test results.

During the accident investigation it was discovered that D-3 Springs were applied to all four corners of the Covered Hopper ACFX 44069 and that D-5 Springs were what was standard for the car. It was clearly marked on the car that D-5 Springs were standard.

The D-3 Spring is a stiffer spring and did not allow for proper steering of the truck while coming out of the curve and allowed the leading wheel to mount the top of the rail. The wheel continued on top of the rail for 22 ½ feet before dropping to the ground. The car then traveled for over a mile before turning over and causing the other cars to derail.

The D-3 Springs from this covered hopper car along with other components from this covered hopper car were sent to Rail Sciences for analysis and they also determined that the D-3 Springs were the cause of the derailment in that they did not allow for proper steering of the truck.

Conclusions:

It was determined by the Federal Railroad Administration that The D-3 Springs being a stiffer spring and not standard to the covered hopper car ACFX 44069 allowed the leading wheel (R-4) to mount the right hand (North) rail and drop off to the