



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-15***

***Burlington Northern Santa Fe (BNSF)
Olden, Missouri
April 7, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. SF0407103		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. SF0407103		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 04 Day 07 Year 2007		7. Time of Accident/Incident 02:00:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative) Code 01		
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed 0		11. Cars Releasing HAZMAT 0		
				12. People Evacuated 0		
				13. Division Springfield		
14. Nearest City/Town Olden		15. Milepost (to nearest tenth) 300.8		16. State Abbr Code N/A MO		
				17. County HOWELL		
18. Temperature (F) (specify if minus) 21 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
22. Track Name/Number Single Main		23. FRA Track Code Class (1-9, X) 3		24. Annual Track Density (gross tons in millions) 80.65		
				25. Time Table Direction Code 1. North 3. East 2. South 4. 2		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1		
28. Train Number/Symbol CBKMMHS072						
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 39 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 17131			31. Method(s) of Operation (enter code(s) that apply)	
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number RWSZ6244		b. Position in Train 60		
(1) First involved (derailed, struck, etc)				c. Loaded (yes/no) yes		
(2) Causing (if mechanical cause reported)		0		0 N/A		
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0		
34. Was this consist transporting passengers? (Y/N) N						
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		2		0 0 0 3		
(2) Total Derailed		0		0 0 0 0		
				36. Cars		
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
				(1) Total in Equipment Consist 120 0 0 0 0		
				(2) Total Derailed 35 0 0 0 0		
37. Equipment Damage This Consist 2693684		38. Track, Signal, Way, & Structure Damage 223296		39. Primary Cause Code T299		
				40. Contributing Cause Code N/A		
Number of Crew Members				Length of Time on Duty		
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		
				44. Brakemen 0		
				45. Engineer/Operator Hrs 7 Mi 30		
				46. Conductor Hrs 7 Mi 30		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0 0		
Nonfatal		0		0 0		
				49. Other		
				50. EOT Device? 1. Yes 2. No 1		
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				52. Caboose Occupied by Crew? 1. Yes 2. No 2		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A		
55. Train Number/Symbol N/A						
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply)			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				

57. Trailing Tons (gross tonnage, excluding power units) N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number N/A	b. Position in Train N/A	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N) N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train N/A	N/A	N/A	N/A	(1) Total in Equipment Consist N/A	N/A	N/A	N/A
(2) Total Derailed N/A	N/A	N/A	N/A	(2) Total Derailed N/A	N/A	N/A	N/A

64. Equipment Damage This Consist N/A	65. Track, Signal, Way, & Structure Damage N/A	66. Primary Cause Code N/A	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators N/A	69. Firemen N/A	70. Conductors N/A	71. Brakemen N/A	72. Engineer/Operator Hrs N/A Mi N/A	73. Conductor Hrs N/A Mi N/A
Casualties to: Fatal N/A	74. Railroad Employees N/A	75. Train Passengers N/A	76. Other N/A	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Nonfatal N/A	N/A	N/A	N/A	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) N/A	86. Principal Car/Unit			

86. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number N/A	b. Position in Train N/A	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train N/A	N/A	N/A	N/A	(1) Total in Equipment Consist N/A	N/A	N/A	N/A
(2) Total Derailed N/A	N/A	N/A	N/A	(2) Total Derailed N/A	N/A	N/A	N/A


91. Equipment Damage This Consist N/A	92. Track, Signal, Way, & Structure Damage N/A	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators N/A	96. Firemen N/A	97. Conductors N/A	98. Brakemen N/A	99. Engineer/Operator Hrs N/A Mi N/A	100. Conductor Hrs N/A Mi N/A
Casualties to: Fatal N/A	101. Railroad Employees N/A	102. Train N/A	103. Other N/A	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Nonfatal N/A	N/A	N/A	N/A	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	N/A

107. Highway User Involved C. Truck-Trailer F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A	108. Vehicle Speed (est. MPH at impact) N/A	109. geographical Code 1. North 2. South 3. East 4. West N/A	111. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative) N/A	112. Position of Car Unit in N/A
--	--	--	---	-------------------------------------

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A				
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A				
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			N/A
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Southbound BNSF Railway Company (BNSF) loaded coal Train Symbol C BKMMHS0 72A derailed 35 cars on April 7, 2007, at 2 a.m. CDT. This derailment occurred on the BNSF Springfield Division, Thayer North Subdivision, near Olden, Missouri, at milepost (MP) 300.8. There were no injuries and no hazardous materials released. At the time of the accident it was dark, the temperature was 21 degrees Fahrenheit and the weather was clear. Equipment damages were \$2,693,684; track, signal, and structure damages were \$223,296.

Probable Cause:

The cause of the derailment was a broken rail located on the high side of a left-hand curve at MP 300.8.

138. NARRATIVE

Circumstances Prior to the Accident

The crew of BNSF Train Symbol C-BKMMHS0-72A consisted of a locomotive engineer and conductor. They first went on duty at their home terminal of Springfield, Missouri, at 6:30 p.m. CDT, April 6, 2007, after receiving more than the statutory off-duty period. The engineer had 34-hours 30-minutes off-duty time prior to reporting for duty and the conductor had 36 hours.

Train Symbol C-BKMMHS0-72A is a 1,500-mile extended haul unit coal train and had received a Class I air brake test at Donkey Creek, Wyoming, at 4 p.m., April 2, 2007. After adding 2 additional DPU locomotives to the rear and accomplishing a set and release of the train air brakes, their assigned freight train consisted of 2 lead locomotives, 120 loaded coal cars, and 3 rear DPU locomotives, having a length of 6,385 feet, and a weight of 17,131 tons. They departed the terminal, MP 201, at 7:20 p.m., scheduled to travel to Thayer, Missouri, and operated to the point of derailment without incident.

As the southbound train approached the accident area, the engineer was seated at the controls of leading locomotive, on the west side with the short hood forward, and the conductor was seated on the east side, in the front seat. The last signal observed prior to the derailment was located at MP 299.07 and was displaying a clear indication. A dragging equipment detector (DED) at MP 300.25 reported no exceptions as they passed. Maximum authorized speed at this location, as listed in BNSF Timetable No. 6, in effect January 17, 2007; is 40 mph. The grade is descending at 1 percent, and they were traversing a 4-degree 55-minute left-hand curve.

Nearing the accident site both timetable and geographic direction is south.

The Accident

The train was being operated at 39 mph rounding the curve at MP 300.8 as indicated by the event recorder of the controlling locomotive. The crew reports they encountered no rough track nor any other track condition that would have contributed to this accident. When they heard the train go into emergency, they braced themselves for slack action or run-in to occur. However, the train seemed to come to a normal stop. The conductor then dismounted and walked the train. He discovered that 35 cars of his train had derailed, lines 60 through 94. This count includes the two lead locomotives. He radioed the engineer, who immediately contacted the BNSF dispatcher and advised him of the derailment.

Analysis and Conclusions**Analysis**

Train Symbol C-BKMMHS0-72A was being operated within the limits of the posted maximum authorized speed of 40 mph. It was traversing a 1-percent descending grade and had been for almost one mile. Therefore, the train would have already been bunched and the buff forces would have been adjusted and should not have been a factor in this derailment. The

download of the event recorder from lead Locomotive No. BNSF 5647 indicated they were traveling at 39 mph when an undesired emergency brake application occurred. There were no indications of train handling issues revealed by the download.

Inspection of the cars on the headend of the train revealed a mark on the tread portion of the wheels that indicated a blunt trauma had occurred. These trauma marks would be consistent with a wheel passing over a broken rail.

The last regular track inspection was conducted on April 6, 2007, with no defects noted. The last internal rail test was made March 26, 2007, and the geometry car last operated March 23, 2007. Neither test noted any discrepancies in this area. The track structure here and prior to reaching the derailment site appears to be very strong, and most of it is constructed of 136-lb continuous-welded rail (CWR) on concrete ties. A walking inspection was made starting at MP 299.8 and continued to the point of derailment at MP 300.8, with no defects cited.

Several pieces of 136-lb RE Premium Rail, manufactured in 1999 by Bethlehem Steel, were sent to the BNSF lab in Topeka, Kansas, for testing. The lab determined the rail examined was not the cause of the derailment.

The crew was transported to the Ozark Medical Center at West Plains, Missouri, where drug and alcohol testing was accomplished under FRA authority. The results of the tests were negative for both crew members. The crew was released from duty at 9:15 a.m., April 7, 2007, at Thayer, Missouri, their away-from-home terminal.

Conclusions

The event recorder download did not indicate any unusual train handling that would contribute to this derailment. There was no evidence discovered that there was any mechanical or equipment issues that would have contributed to this derailments. Marks on the wheels ahead of the first car derailed and the sudden catastrophic nature of this derailment indicate a rail broke under the train causing the derailment. Although the rail that caused this derailment was never found, all other causes were ruled out by extensive investigation and analysis of all evidence recovered at the site.

Probable Cause and Contributing Factors

There were no contributing factors identified.

The FRA determined that the probable cause of the accident was a broken rail, cause code T299 (other rail and joint bar defects).