



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-19***

***Union Pacific (UP)
Broadwater, Nebraska
April 8, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0407NP014	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0407NP014	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 04 Day 08 Year 2007		7. Time of Accident/Incident 08:45: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division North Platte	
14. Nearest City/Town Broadwater		15. Milepost (to nearest tenth) 105.2		16. State Abbr Code N/A NE	
		17. County MORRILL			
18. Temperature (F) (specify if minus) 24 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
22. Track Name/Number Main Track No 2		23. FRA Track Code Class (1-9, X) 5		24. Annual Track Density (gross tons in millions) 226	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 3			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		Code CNAAE07	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 40 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
30. Trailing Tons (gross tonnage, excluding power units) 19028		31. Method(s) of Operation (enter code(s) that apply) (continued) m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number CMO288306		b. Position in Train 85	
(1) First involved (derailed, struck, etc)		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
(2) Causing (if mechanical cause reported)		0		34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End 2		Mid Train b. Manual 0 c. Remote 0	
(1) Total in Train		Rear End d. Manual 0 e. Remote 1		36. Cars (1) Total in Equipment Consist 134	
(2) Total Derailed		0		Loaded a. Freight 0 b. Pass. 0	
		0		Empty c. Freight 0 d. Pass. 0	
		0		e. Caboose 0	
37. Equipment Damage This Consist 1691635		38. Track, Signal, Way, & Structure Damage 75608		39. Primary Cause Code T201	
				40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 4 Mi 0	
				46. Conductor Hrs 4 Mi 0	
Casualties to:		47. Railroad Employees 0		48. Train Passengers 0	
Fatal		0		49. Other 0	
Nonfatal		0		0	
				50. EOT Device? 1. Yes 2. No 2	
				51. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? 1. Yes 2. No N/A		Code N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
		58. Method(s) of Operation (enter code(s) that apply) (continued) m. Special instructions n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	0	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	0	65. Track, Signal, Way, & Structure Damage	0	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No	N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No	N/A		
Fatal	0	0	0	79. Caboose Occupied by Crew?	1. Yes 2. No	N/A					
Nonfatal	0	0	0								

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded		a. ATCS	0 = Not a remotely controlled
E - Estimated	N/A MPH 0	b. Auto train control	1 = Remote control portable
84. Trailing Tons (gross tonnage, excluding power units)	0	c. Auto train stop	2 = Remote control tower
		d. Cab	3 = Remote control transmitter - more than one remote control transmitter
		e. Traffic	
		f. Interlocking	
		g. Automatic block	
		h. Current of traffic	
		i. Time table/train orders	
		j. Track warrant control	
		k. Direct traffic control	
		l. Yard limits	
		m. Special instructions	
		n. Other than main track	
		o. Positive train control	
		p. Other (Specify in narrative)	
		Code(s)	
		N/A N/A N/A N/A N/A	

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0


91. Equipment Damage This Consist	0	92. Track, Signal, Way, & Structure Damage	0	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No	N/A	105. Was EOT Device Properly	1. Yes 2. No	N/A		
Fatal	0	0	0	106. Caboose Occupied by Crew?	1. Yes 2. No	N/A					
Nonfatal	0	0	0								

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code	A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian	B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)	N/A	111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical)	Code	1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)	N/A
		1. North 2. South 3. East 4. West	N/A	2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)	
				112. Position of Car Unit in	N/A		

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A
Casualties to:			Killed 0	Injured 0	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

An eastbound Union Pacific Railroad Company (UP) loaded coal train, Train Symbol CNAAE 07, derailed on Sunday, April 8, 2007, at 8:45 a.m., m.d.t. The derailment occurred 4.6 miles west of the town of Broadwater, Nebraska, at UP Milepost (MP) 105.2, on Main Track No. 2 of the North Platte Service Unit, South Morrill Subdivision, in Morrill County. The crew reported an undesired emergency brake application while traveling at a recorded speed of 40 miles per hour. The crew inspected their train and found 29 cars, the 85th through the 113th cars of the train consist, derailed. No injuries were reported. No hazardous materials were involved.

Damage estimates to equipment total \$1,691,634. Damage estimates to track total \$65,608. Damage estimates to signal equipment total \$10,000.

At the time of the derailment, the conditions were daylight and cloudy with a temperature of 24 degrees Fahrenheit and wind SSE at 16 mph.

The cause of the derailment was determined to be a bolt hole fatigue crack which allowed the rail to open and caused the train to derail.

138. NARRATIVE

Circumstances prior to the accident:

The crew of UP Train Symbol CNAAE 07 consisted of an engineer and a conductor. The crew went on duty at 4:45 a.m., m.d.t. on April 8, 2007, at South Morrill, Nebraska, which was the crews away-from-home terminal. Both crew members received the required off-duty time prior to reporting for duty.

Their assigned train consisted of three locomotives, two at the head-end and one at the rear, and 134 loaded cars of coal. The train was 7,458 feet in length with 19,028 gross trailing tons, excluding power units. The initial terminal air brake test and inspection had been performed on this train at North Platte on April 6, 2007, as empty coal Train Symbol CAENA 05. Loaded coal Train Symbol CNAAE 07 departed South Morrill at 5:38 a.m., on April 8, 2007, en route to North Platte. The maximum authorized speed for this train is 50 mph as outlined in the North Platte Area Timetable No. 2, effective October 27, 2002. No pick-ups or set-outs were scheduled for this train while en route.

As the eastbound train approached the location where the derailment occurred, the engineer was seated at the controls on the south side of the leading locomotive. The conductor was seated on the north side of the lead locomotive. The timetable and geographic direction for the train is east.

Main Track No.2 is 133-pound rail attached to concrete ties and was constructed in 1996. The track at the accident site is tangent and level for approximately 1 mile to the west. Prior to that, the track is tangent and descending to the east at a varying rate of 0.24 and 0.14 percent for approximately 2 miles.

The Accident:

UP Train Symbol CNAAE 07 was traveling eastward on Main Track No. 2 with its speed decreasing from 47 mph as they approached the accident area, as recorded by Locomotive No. UP 6999 which was the second locomotive in the consist. Speed at the time the derailment occurred was 40 mph. The maximum authorized speed for this unit coal train was 50 mph, as designated in the current UP Timetable No. 2. The event recorder of the lead locomotive was determined to be defective after the derailment occurred. The engineer had taken the locomotives out of dynamic braking approximately 5 seconds after the head-end of the train passed over the private crossing at MP 105.22. Approximately 48 seconds later, the crew experienced an undesired emergency application of the air brakes; the conductor notified the dispatcher. Upon inspecting the train, the crew discovered 29 cars of their train were derailed at MP 105.22, lines 85 through 113 of the train consist, blocking both Main Track No. 1 and Main Track No. 2.

Analysis and Conclusions:**Analysis**

UP track inspection records indicate that Main Track No. 2 at MP 105.2 received 27 inspections by a qualified track inspector in the previous 31 days, prior to the derailment. No track defects were noted at this location.

On March 22, 2007, 18 days prior to the accident, Detector Car No. 35 made an inspection of this portion of the South Morrill Subdivision, Main Track No. 2, with no defects noted at or near the private crossing at MP 105.22.

A broken rail at a joint was found at the point of derailment (POD); the rail sections and joint bars were sent to the Rail Sciences, Inc. Lab for analysis. The analysis report states that the overall condition of the joint indicates movement had been present in the joint for some time. The fatigue crack which originated from the bolt hole is the cause of the derailment. The location of the joint at the road crossing is consistent with variable track modulus that allows pumping joints to occur.

Both crew members received the required FRA Post-Accident Toxicological Testing. The results were negative for both the engineer and conductor.

Conclusion

The railroad was found to be in compliance with their own and all applicable Federal regulations. The railroad and the FRA agree that the cause of this derailment was a bolt hole fatigue crack that resulted in a broken rail. A broken rail allowed the rail to "open" and caused the train to derail. This defect was likely not detectable during recent internal rail testing or normal track inspections.

Probable Cause and Contributing Factors:

The probable cause of this derailment as determined by an FRA investigation is T201 Broken Rail - Bolt hole crack or break.