



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-22***

***Burlington Northern Santa Fe (BNSF)
Ash, Nebraska
April 24, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. PR0407110	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. PR0407110	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 04 Day 24 Year 2007		7. Time of Accident/Incident 05:40: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division Power River	
14. Nearest City/Town Ashby		15. Milepost (to nearest tenth) 314.5		16. State Abbr Code N/A NE	
		17. County GRANT			
18. Temperature (F) (specify if minus) 43 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 3	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
22. Track Name/Number Main Track No. 1		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 144.11	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 3			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		Code 1	
		28. Train Number/Symbol CNAMPAM110			
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 46 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 17892		31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number JHMX 95288		b. Position in Train 36	
(1) First involved (derailed, struck, etc)		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
(2) Causing (if mechanical cause reported)		0		34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End 2		Mid Train b. Manual 0 c. Remote 0	
		Rear End d. Manual 0 e. Remote 0		36. Cars (1) Total in Train 2	
				Loaded a. Freight 126 b. Pass. 0	
				Empty c. Freight 0 d. Pass. 0	
				e. Caboose 0	
(2) Total Derailed		0		(2) Total Derailed 43	
37. Equipment Damage This Consist 2577628		38. Track, Signal, Way, & Structure Damage 381569		39. Primary Cause Code M507	
				40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 2 Mi 15	
				46. Conductor Hrs 2 Mi 15	
Casualties to:		47. Railroad Employees 0		48. Train Passengers 0	
Fatal		0		49. Other 0	
Nonfatal		0		0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? 1. Yes 2. No N/A		Code N/A	
		55. Train Number/Symbol N/A			
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control g. Automatic block h. Current of traffic m. Special instructions n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	0	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
(1) First involved (derailed, struck, etc)	0	0	N/A	Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)
				N/A

62. Locomotive Units	a. Head End	Mid Train		Rear End		63. Cars	Loaded		Empty		e. Caboose
		b. Manual	c. Remote	d. Manual	c. Remote		a. Freight	b. Pass.	c. Freight	d. Pass.	
(1) Total in Train	0	0	0	0	0	(1) Total in Equipment Consist	0	0	0	0	0
(2) Total Derailed	0	0	0	0	0	(2) Total Derailed	0	0	0	0	0

64. Equipment Damage This Consist	0	65. Track, Signal, Way, & Structure Damage	0	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other		77. EOT Device?		78. Was EOT Device Properly Armed?	
Fatal	0	0	0	0	0	0	0	1. Yes 2. No N/A		1. Yes 2. No N/A	
Nonfatal	0	0	0	0	0	0	0	79. Caboose Occupied by Crew?		1. Yes 2. No N/A	

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No N/A	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available) Code	R - Recorded	E - Estimated	N/A	MPH	0	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
						a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
						g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
						m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	
						N/A N/A N/A N/A N/A	N/A

84. Trailing Tons (gross tonnage, excluding power units)	0	86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
		(1) First involved (derailed, struck, etc)	0	0	N/A	Alcohol N/A Drugs N/A
		(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)
						N/A

89. Locomotive Units	a. Head End	Mid Train		Rear End		90. Cars	Loaded		Empty		e. Caboose
		b. Manual	c. Remote	d. Manual	c. Remote		a. Freight	b. Pass.	c. Freight	d. Pass.	
(1) Total in Train	0	0	0	0	0	(1) Total in Equipment Consist	0	0	0	0	0
(2) Total Derailed	0	0	0	0	0	(2) Total Derailed	0	0	0	0	0


91. Equipment Damage This Consist	0	92. Track, Signal, Way, & Structure Damage	0	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
Casualties to:		101. Railroad Employees		102. Train		103. Other		104. EOT		105. Was EOT Device Properly	
Fatal	0	0	0	0	0	0	0	1. Yes 2. No N/A		1. Yes 2. No N/A	
Nonfatal	0	0	0	0	0	0	0	106. Caboose Occupied by Crew?		1. Yes 2. No N/A	

Highway User Involved				Rail Equipment Involved			
107.	C. Truck-Trailer.	F. Bus	J. Other Motor Vehicle	111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
	A. Auto	D. Pick-Up Truck	G. School Bus		1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)
	B. Truck	E. Van	H. Motorcycle		2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)
			M. Other (spec. in narrative)				N/A
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical)		112. Position of Car Unit in			
		1. North	2. South	3. East	4. West	N/A	

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A				
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A				
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Eastbound coal Train Symbol C NAMPAM1 10 derailed 43 cars on April 24, 2007, at 5:40 a.m., m.d.t. The accident occurred approximately 1 mile east of the town of Ashby, Nebraska, at milepost (MP) 314.5 on the BNSF Railway Company's (BNSF) Sand Hills Subdivision, Powder River Division. The Sand Hills Subdivision is utilized by BNSF to operate 6 manifest and 54 coal trains per day.

There were no injuries or release of hazardous material from the train as a result of the accident. A wayside propane tank was dislodged from its concrete pad and the fuel line used to fuel the switch heater was severed. A minimal amount of propane was released into the atmosphere until the valve was closed at the propane tank. No evacuation occurred as a result of the release other than BNSF employees were not allowed on the scene until the tank had been secured.

As there were no injuries, response was limited to BNSF personnel from various operating and engineering departments and outside contractors consisting of Hulcher Emergency Services, and R. J. Corman Derailment Services.

The weather at the time of the accident was raining and 43 degrees Fahrenheit with a northeast wind gusting at 24 to 29 mph, visibility was minimal.

Reportable estimated damages for rolling equipment are \$2,577,628; track estimated damages \$351,569; and signal equipment estimated damages \$30,000. For a total of \$2,959,197 in estimated damages.

After investigating the evidence available, the primary cause assigned to this derailment is M507 - "Investigation complete, cause could not be determined." Analysis of recovered evidence did not reveal a cause. There was a considerable amount of track and mechanical components that was never recovered.

138. NARRATIVE

Circumstances Prior to the Accident

The crew of Train Symbol C NAMPNM1 10 included a locomotive engineer and a conductor. They went on duty at 3:25 a.m., m.d.t.; on April 24, 2007, at Alliance, Nebraska. This is the home terminal for both the conductor and engineer. The required off-duty time for the conductor and engineer was 8 hours. The conductor was off duty for 40 hours, 15 minutes and the engineer was off duty 47 hours, 5 minutes, prior to reporting for duty on April 24. All crew members received more than the statutory off-duty period, prior to reporting for duty.

The last required testing of Train Symbol C NAMPAM1 10 was a Class 1 air brake test at the railroad location of Donkey Creek in Wyoming, on April 22, 2007.

Their train consisted of 2 head-end locomotives, 1 distributed power locomotive, 126 loaded coal cars, and no empty cars. It was 6,833 feet in length and weighed 17,892 tons. The train departed Alliance and was scheduled to travel to Ravenna, Nebraska. There were no required inspections or air brake tests performed on Train Symbol C NAMPAM1 10 at Alliance. Train Symbol C NAMPAM1 10 departed Alliance at approximately 4:28 a.m., m.d.t.

As the eastbound train approached the accident area, the engineer was operating the train from the engineer's seat at the locomotive control stand of the lead locomotive which was located on the south side of the locomotive. The conductor was positioned in the conductor's seat on the north side of the locomotive.

The railroad timetable direction was east; the geographical direction was east. Timetable directions are used throughout this report

The terrain on which the accident occurred was at the east end of double main track, on Main Track No. 1 which is tangent main line track. The roadbed is slightly elevated due to the roadbed being built on a .49 percent descending grade. The rail is 136-lb continuous-welded rail (CWR). The ties for Main Track No. 1 are concrete and the rail is secured with McKay clips. The switch ties are wood and the rail is secured with lag screws and pandoral clips.

The Accident

The train was traveling at 46 mph recorded speed approaching the derailment site. The maximum authorized speed for coal trains in this area is 50 mph as designated in current BNSF Timetable No. 8. Speeds were recorded by the event recorder of the second locomotive of the consist, Locomotive No. BNSF 6028. The engineer and conductor indicated that at or near the point of derailment, they felt a soft spot in the track and the engineer reports seeing sparks coming from the bottom of their second locomotive. The engineer was in the process of notifying the dispatcher of the soft track condition when the dragging equipment detector located at MP 314.5 sounded an alarm to the train crew of dragging equipment and the train went into an emergency train brake application.

After the train stopped the conductor began walking the train and when she arrived between the 11th and 12th cars, Car Nos. JHMX 97519 and JHMX 99319, she found the air hoses uncoupled. She recoupled the air hoses and tried to recover the train's air brakes, but was unsuccessful. She continued walking her train and when she reached the 34th car, Car No. JHMX 95288, the first car derailed; she observed a gap of approximately 35 car lengths between it and the second derailed car, Car No. JHMX 95394. It was then determined that the 34th car from the trailing locomotive through 76th car had derailed. The conductor immediately notified the engineer, the engineer immediately notified Sand Hills Subdivision train dispatcher of the derailment, and appropriate BNSF personnel were dispatched to the derailment site.

Analysis and Conclusion

Analysis

Toxicological testing was conducted as the federal post-accident criteria was met. Test results were negative for the two crew members.

The Fatigue Avoidance Scheduling Tool (FAST) analysis report indicates fatigue was probable for both crew members involved in this derailment but it is not being considered as a contributing factor in this derailment

During the investigation, data was examined by the BNSF and FRA from the previous hot box detector located approximately 24 miles west of the accident site and the dragging equipment detector located approximately 5.5 miles west of the accident site. There was no information from this data that indicated any mechanical conditions that could have caused the derailment.

The event recorder data from the second locomotive, Locomotive No. BNSF 6028, did not indicate any signs of poor train handling. The data indicated that the train was traveling within the required speeds. It also showed the locomotive was in dynamic braking, throttle position 4; a locomotive operating in this manner would indicate the cars of the train were bunched.)

The division engineer stated that the track was last inspected by hi-rail and geometry car survey on April 23, 2007, with no defective conditions taken in this area. The last ultrasonic rail detection test through this area was on March 30, 2007, with no defective conditions taken in this area.

The FRA investigation revealed that 125 feet of rail, switch components, four freight car wheel sets, two freight car truck side frames, and two freight car bolsters were never found during the investigation; therefore, could not be analyzed.

Conclusion.

Despite spending three days at the site, the BNSF investigation team, consisting of Powder River Division managers and members from the BNSF Technical Research and Development team, and the FRA investigators, could not determine a cause to the Ashby derailment. The derailment area was last tested with the geometry car on April 23, 2007, approximately 16 hours prior to the derailment, with no defective conditions taken. FRA's inspection of all equipment, track components and the download of the event recorder did not reveal a probable cause. There was no evidence discovered that would indicate a mechanical, track, or human factor probable cause of this accident. There is also 125 feet of rail, switch components, four freight car wheel sets, two freight car truck side frames, and two freight car truck bolsters that have not been found. Evidence discovered at the site did not reveal anything that would have contributed to the cause of this accident.

Probable Cause and Contributing Factors

Analysis of recovered evidence did not reveal a cause. There was a considerable amount of track and mechanical components that was never recovered. Therefore, the FRA found the probable cause of the investigation as complete and the cause could not be determined (M507).