



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-28***

***Southeastern Pennsylvania Transportation Authority (SEPA)
Philadelphia, Pennsylvania
May 14, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Southeastern Pennsylvania Transportation Authority		1a. Alphabetic Code SEPA		1b. Railroad Accident/Incident No. 050407R007		
2. Name of Railroad Operating Train #2 Southeastern Pennsylvania Transportation Authority		2a. Alphabetic Code SEPA		2b. Railroad Accident/Incident No. 050407R007		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Southeastern Pennsylvania Transportation Authority		4a. Alphabetic Code SEPA		4b. Railroad Accident/Incident No. 050407R007		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 05 Day 14 Year 2007		7. Time of Accident/Incident 04:52:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative) Code 03		
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		
				12. People Evacuated 0		
				13. Division N/A		
14. Nearest City/Town PHILADELPHIA		15. Milepost (to nearest tenth) 0.06		16. State Abbr Code N/A PA		
17. County PHILADELPHIA						
18. Temperature (F) (specify if minus) 68 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1						
22. Track Name/Number MAIN #2		23. FRA Track Code Class (1-9, X) 1		24. Annual Track Density (gross tons in millions) N/A		
				25. Time Table Direction Code 1. North 3. East 2. South 4. 1		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code 2		
				27. Was Equipment Attended? Code 1. Yes 2. No 1		
				28. Train Number/Symbol 6572		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 6 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 0			31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits d N/A N/A N/A N/A	
					31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) SEPA 286		b. Position in Train 1		
		c. Loaded (yes/no) N/A		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A		
(2) Causing (if mechanical cause reported)		0		0		
		N/A		34. Was this consist transporting passengers? (Y/N) Y		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		5		0 0		
(2) Total Derailed		0		0 0		
		0		0 0		
36. Cars		a. Freight		b. Pass.		
		c. Freight		d. Pass.		
		e. Caboose				
(1) Total in Equipment Consist		0		5 0 0 0		
(2) Total Derailed		0		0 0 0 0		
37. Equipment Damage		This Consist 0		38. Track, Signal, Way, & Structure Damage 0		
				39. Primary Cause Code H222		
				40. Contributing Cause Code H605		
Number of Crew Members				Length of Time on Duty		
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		
				44. Brakemen 2		
				45. Engineer/Operator Hrs 5 Mi 32		
				46. Conductor Hrs 5 Mi 32		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0		
Nonfatal		2		0		
				49. Other 0		
				50. EOT Device? 1. Yes 2. No N/A		
				51. Was EOT Device Properly Armed? 1. Yes 2. No N/A		
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code 2		
				54. Was Equipment Attended? Code 1. Yes 2. No 1		
				55. Train Number/Symbol 4646		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) d N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) SEPA 206	a. Initial and Number 2	b. Position in Train 2	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) Y

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 4	0	0	0	(1) Total in Equipment Consist 0	4	0	0
(2) Total Derailed 0	0	0	0	(2) Total Derailed 0	0	0	0

64. Equipment Damage This Consist 2000	65. Track, Signal, Way, & Structure Damage 0	66. Primary Cause Code H222	67. Contributing Cause Code H605
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 1	69. Firemen 0	70. Conductors 1	71. Brakemen 2	72. Engineer/Operator Hrs 2 Mi 0	73. Conductor Hrs 2 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Fatal	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	2	33	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) N/A				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number N/A	b. Position in Train N/A	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train N/A	N/A	N/A	N/A	(1) Total in Equipment Consist N/A	N/A	N/A	N/A
(2) Total Derailed N/A	N/A	N/A	N/A	(2) Total Derailed N/A	N/A	N/A	N/A


91. Equipment Damage This Consist N/A	92. Track, Signal, Way, & Structure Damage N/A	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators N/A	96. Firemen N/A	97. Conductors N/A	98. Brakemen N/A	99. Engineer/Operator Hrs N/A Mi N/A	100. Conductor Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal	N/A	N/A	N/A	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	N/A	N/A	N/A		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West	Code N/A		112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A				
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)			N/A
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

A northbound Southeast Pennsylvania Transportation Authority, (SEPA), passenger train had a rear end collision with another northbound SEPA train on May 14, 2007 at 4:52 p.m. EST. Neither train derailed. The accident occurred in the Center City Commuter Tunnel, (CCCT), in Philadelphia at Vine Interlocking milepost 0.6.

There was minor equipment damage and no track or signal damage reported. There were 37 minor injuries, including 4 railroad employees and 33 passengers, reported to the Federal Railroad Administration, (FRA).

At the time of the accident it was daylight and clear with a temperature of 68° F.

The accident was caused by failure of the locomotive engineer to comply with restricted speed rules.

Failure of the crew to comply with an Automatic Block Signal or Interlocking Signal displaying other than a stop indication.

A contributing cause was failure of the crew to comply with restricted speed in connection with the restrictive indication of a block or interlocking signal.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of Southeastern Pennsylvania Transportation Authority, (SEPA), train 6572, (operating train #1), included a locomotive engineer, a conductor, and two assistant conductors. They first went on duty at 6:20 a.m. EST on May 14, 2007, at SEPA's Suburban Station in Philadelphia, Pennsylvania. This was the home terminal for the crew members and they received more than the statutory off duty period prior to reporting for duty. On this day both the engineer and the conductor were provided an interim release period of 5 hours at Suburban Station. The release period was from 9:32 a.m. to 2:32 p.m. EST. They were finally released from duty at 8:25 p.m. for a total of 9 hours and 10 minutes on duty.

The crew of SEPA train 4646, (operating train #2), included a locomotive engineer, a conductor, and two assistant conductors. They first went on duty at 2:42 p.m. EST. May 14, 2007, at SEPA's West Trenton terminal. This was the home terminal for all crew members and all received more than the statutory off duty period prior to reporting for duty.

Train 6572 was re-crewed at Suburban Station at about 4:46 p.m. EST. The out-going engineer informed the new engineer that a Class II brake test and a running brake test was done between Powelton Yard and Suburban Station.

Train 6572 consisted of 5 cab cars, (individually powered units). Lead unit 286 followed by 153, 154, 381 and 380. This train was re-crewed at Suburban Station. The previous engineer relayed to the new engineer that everything was OK with the brakes and the mechanical condition of the train.

Train 4646 consisted of 4 cab cars, (individually powered units). Lead unit 255 followed by 203, 9015 and 206.

The engineer on train 6572 was the only person in the cab at the time of the accident. Other crew members were located in cars 286, 154 and 381- first, third and fourth respectively.

The engineer on train 4646 was the only person in the cab when struck by train 6572. Other crew members were located in the rear car, 206.

Both trains, 6572 and 4646 normally operate northward through the Center City Commuter Tunnel, (CCCT), on track number 1. Earlier in the day, train service through the CCCT had been interrupted by an unrelated bomb scare that caused several delays. This caused another northbound train, 6844, to remain on track number 1 at Suburban Station waiting for a re-crew. Due to this, trains 4646 and 6572 were routed to track number 2.

Train 4646 made a routine stop at Market East passenger station, milepost 0.50, at 4:48 p.m. EST which was 8 minutes behind schedule. Upon departure, the engineer radioed the dispatcher at the Regional Rail Operations Center, (RROC), and advised of the necessity to cross back over to track number 1 for their scheduled stop at North Broad Street passenger station, milepost 2.90. The dispatcher complied and began to follow procedures for setting up signals for crossing over to track number 1. This required train 4646 to stop at Vine 4E signal, milepost 0.80, at 4:51 p.m. EST.

At this time the engineer of train 6572 was taking charge of his train at Suburban Station, milepost 0.0.

In the area of this accident the track is on a 10 ½° curve to the left. The grade of the track is level.

The railroad timetable direction is northbound, which is used throughout this report.

THE ACCIDENT

Train 6572 departed Suburban Street passenger station at 4:48:38 p.m. EST in a northbound direction. The following are sequential signal aspects, time received, and train speed:

•	Suburban 4E signal	"clear"	4:48:53	18 mph
•	Juniper signal	"approach"	4:49:09	23 mph
•	Cab signal drops to	"restricting"	4:49:16	22 mph
•	Mark 14E	"restricting"	4:49:58	0 mph
•	Mark 4E	"restricting"	4:52:20	14 mph

After stopping at Market East station between 4:49:58 and 4:52:20 EST, train 6572 gained speed up to 17 mph. At this time he was, unknowingly, about 204 feet from the rear end of train 4646, who was still stopped at Vine 4E signal. Train 6572 then initiated a service brake application. A few seconds later an emergency brake application. Speed dropped to 14 mph just 83 feet behind train 4646. Impact into train 4646 was at 6 mph. The impact caused both trains to move ahead about 9 feet.

The engineer immediately radioed the dispatcher and reported he had just run into a train ahead. He did not initiate an "emergency" call as prescribed by Federal Regulations. The dispatcher asked for a repeat.

The engineer on train 6572 first noticed the train ahead by seeing the rear marker lights reflecting on the tunnel walls about a car length away. This is when he claims he initiated an emergency brake application.

Supervisors were dispatched to the scene within several minutes. There were multiple, minor, injuries on board due to the force of the impact. The two trains were coupled but not derailed. Both trains were thoroughly inspected and found to be safe for movement although they could not be separated at this time. Supervisors on the scene made a decision to transport all injured people, via this train, to Temple University station. They arrived at Temple at about 5:25 p.m. EST. At this point the injured were transported to area hospitals by emergency personnel by 5:45 p.m. EST.

ANALYSIS and CONCLUSIONS

Investigation of the accident included a review of the hours of service performance for all employees involved. All employees were in compliance with the number of hours worked within the 10 days prior to this accident. There were, however, several missing hours of service records.

FRA took no exceptions to an observation of a single car brake test on cab car 286 after the accident.

The weather conditions at the time of the accident were favorable with a temperature of 68°F clear and dry.

A rail greaser is located between Market East and Vine Interlocking. Examination of the rail in this area revealed no conditions that could have contributed to the accident.

Wayside signals and radio communications were inspected. Both systems were found to be working as intended and did not contribute to the accident.

Post accident inspection of train 6572 including cab cars 286, 153, 154, 381 and 380 revealed defective wheel slip tanks in cars 154 and 380. (Supervisor's memo, (attached), refers to cab car #381 with a defective wheel slip tank. However, SEPA's "Vehicle History Report" indicates the two cars with defective wheel slip tanks were 154 and 380). These defects did not contribute to the accident.

Data from the event recorder was used to determine if there were problems with the effects of braking on train 6572. The Rail Equipment Engineering Department concluded that brakes worked as intended and deceleration of train 6572 was normal under the current conditions.

Train 6572 was originally in charge of another engineer. A change of crew took place at Suburban Station at about 4:46 p.m. EST.

The new engineer operated the train from Suburban Station to Market East with no unusual occurrences. After stopping at Market East, he proceeded under a "restricting" signal, meaning the next signal at Vine would be either "Restricting" or "Stop". He reached a top speed of 17 mph, 2 mph over permitted speed in this situation. About this time the engineer stated he saw red reflective lights on the tunnel wall ahead about 267 feet. He initiated a full service brake application but did not seem to slow down, so then he placed the brakes in "emergency". At this point he was about 83 feet from the rear of train 4646 sitting at Vine. The train was being operated in excess of the restricted speed rule.

Restricted speed defined: All movements at restricted speed must be prepared to stop within one half the range of vision. The movement must be controlled in such a manner that permits stopping short of other trains or equipment occupying or fouling the rail envelope, obstructions on the track, improperly lined switches, derails set in derailling position, any signal requiring a stop, looking out for broken rail and not exceeding the speed limitation assigned to the particular track segment (15 mph within interlocking limits, 20 mph outside interlocking limits, or less when lesser civil speeds apply).

Railroad officials acted appropriately in response to the accident by transporting injured passengers and employees as quickly as possible for medical attention.

The engineer was tested under the authority of 49 CFR 219 Subpart C. The tests results were negative.

CONCLUSION

The engineer of train 6572 did not operate within restricted speed rules.

PROBABLE CAUSE & CONTRIBUTING FACTORS

A contributing cause was failure of the crew to comply with restricted speed in connection with the restrictive indication of a block or interlocking signal.

The FRA found that this accident occurred because the engineer failed to comply with provisions of restricted speed.