



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-34***

***Burlington Northern Santa Fe (BNSF)
Tower, North Dakota
June 6, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TC0607103	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. TC0607103	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 06 Day 06 Year 2007		7. Time of Accident/Incident 03:00: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division Twin Cities	
14. Nearest City/Town Tower City		15. Milepost (to nearest tenth) 50.0		16. State Abbr Code N/A ND	
		17. County CASS			
18. Temperature (F) (specify if minus) 73 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
22. Track Name/Number Single Main Track		23. FRA Track Code Class (1-9, X) 3		24. Annual Track Density (gross tons in millions) 60	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 3			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		28. Train Number/Symbol CSCMSUD152	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 50 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 17036		31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) j N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) DET X994371		b. Position in Train 29	
		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
(2) Causing (if mechanical cause reported)		DET X994371		29	
		yes		34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End (1) Total in Train 3		Mid Train b. Manual 0 c. Remote 0	
		Rear End d. Manual 0 e. Remote 0		36. Cars (1) Total in Equipment Consist 122	
(2) Total Derailed 0		0		(2) Total Derailed 29	
37. Equipment Damage This Consist 1509014		38. Track, Signal, Way, & Structure Damage 398000		39. Primary Cause Code E39C	
				40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 8 Mi 45	
46. Conductor				Hrs 8 Mi 45	
Casualties to:		47. Railroad Employees 0		48. Train Passengers 0	
Fatal		0		49. Other 0	
Nonfatal		0		0	
		50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
		52. Caboose Occupied by Crew? 1. Yes 2. No 2			
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? 1. Yes 2. No N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track Code(s)		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) 0	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0

64. Equipment Damage This Consist 0	65. Track, Signal, Way, & Structure Damage 0	66. Primary Cause Code N/A	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 0	69. Firemen 0	70. Conductors 0	71. Brakemen 0	72. Engineer/Operator Hrs 0 Mi 0	73. Conductor Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No N/A	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Fatal 0	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) 0				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0


91. Equipment Damage This Consist 0	92. Track, Signal, Way, & Structure Damage 0	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal 0	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal 0	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck 108. Vehicle Speed (est. MPH at impact) N/A	F. Bus D. Pick-Up Truck E. Van	J. Other Motor Vehicle G. School Bus H. Motorcycle	K. Pedestrian M. Other (spec. in narrative) N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative) N/A	Code N/A
109. geographical 1. North 2. South 3. East 4. West Code N/A				112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On June 6, 2007, at 3:00 p.m. (CDT) a eastbound BNSF Railway Company (BNSF) train, symbol CSCMSUD152 derailed on the Twin Cities Division, Jamestown Subdivision in Tower City, North Dakota at milepost 50.0. The train was traveling on a single main track at a recorded speed of 50 mph. The maximum authorized timetable track speed in the area of the accident is 60 mph.

The train consisted of three locomotives, 122 railcars of coal, with 17,036 trailing tons and 6,476 feet in length. A total of 29 cars, 25th through the 53rd, derailed. There were no injuries reported and no release of hazardous material. The estimated damages was \$1,907,014 (\$150,000 for signal, \$248,000 for track and \$1,509,014 for equipment).

At the time of the derailment it was 73 degrees F and partly cloudy.

The probable cause of the accident was the securement bolts holding the coupler pin retainer plate became either loose or were missing allowing the retainer plate to move, drop, or swing out which allowed the vertical pin to fall out of car (DETX994371). This in turn caused the coupler to fall out, then causing the train to derail (E39C).

138. NARRATIVE

Circumstances Prior to the Accident

On June 6, 2007 after completing more than the statutory off duty time, a crew consisting of an engineer and conductor reported for duty at their home terminal at Mandan, North Dakota at 06:15 a.m.(CDT). The crew was assigned to operate the eastbound BNSF unit coal train from Mandan to Dilworth, Minnesota a distance of about 205 miles.

The train consisted of three locomotives, 122 loaded cars of coal, 17,036 trailing tons, and was 6,476 feet in length. On June 6, 2006, a 1,500 mile air brake test and inspection and daily locomotive inspections were conducted at Mandan prior to departing. The train departed Mandan at approximately 8:40 a.m., on June 6, 2007.

Approaching the derailment site from the west, traveling east, there is tangent track from milepost 51.0 to 50.0. The derailment occurred on tangent track and was on a .14-percent descending grade from milepost 51.0 to 50.8, a .26-percent descending grade from milepost 50.8 to 50.5, and a .12- percent descending grade from milepost 50.5 to 50.

As the train approached the derailment area, the locomotive engineer was seated at the controls on the right (south) side of the leading locomotive. The conductor was seated on the left (north) side of the cab of the leading locomotive.

The interviews revealed the trip was uneventful prior to the derailment.

The Accident

Approaching the accident site, the train was being operated at 50 mph as recorded by the event recorder of the controlling locomotive. In the incident area, trains operate on a single main track under the authority of Track Warrant Control (TWC) and is controlled by a BNSF train dispatcher located in Fort Worth, Texas. The maximum authorized speed for freight trains is 60 mph as designated in the current BNSF Timetable No. 2, dated Wednesday, November 17, 2004.

According to the crew, the train made an undesired train induced emergency application of the train air brakes and the train came to a stop. After coming to a stop; the engineer notified the train dispatcher. The conductor walked back to inspect the train and observed that the 25th through the 53rd cars behind the locomotives had derailed.

Analysis and Conclusions

The accident met the criteria for 49 CFR, Part 219, Subpart C Post Accident Toxicological Testing and the crew was tested. The test results were negative.

FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis, which is equivalent to a blood alcohol content (BAC) of 0.05. At or above this baseline, we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep

information, FRA uses the default software settings.

FRA obtained fatigue related information, including a 10-day work history, for 2 employees involved in this accident, including the locomotive engineer and the conductor assigned to train CSCMSUD152.

FRA concluded fatigue was not probable for the engineer and conductor assigned to train CSCMSUD152

The investigation revealed that the 25th through the 53rd cars behind the locomotives derailed. The leading locomotive traveled approximately 1,600 feet after the emergency air brake application and train separation occurred.

The vertical coupler pin connects to the draft assembly and ultimately the car. The vertical coupler pin is retained in position by a retaining plate secured to the bottom of the car by fasteners. If the retaining plate is not in position, gravity will cause the coupler to fall out. When this happens, the coupler can be easily removed from the car. Freight car wheel tread damage was found on the leading axle from car DETX994371. The damage was caused by wheel tread impact with the coupler that had been released to the ground from the B-end (east end) of car DETX994371, then striking the left side of the leading rail wheels, then derailing the train.

An inspection of the data print out from the lead locomotive event recorder indicated that the train was being operated at 50 mph at the location of the POD. The event recorder also indicated no unusual events related to train handling.

Probable Cause

The probable cause of the accident, as determined by the FRA, was the securement bolts holding the coupler pin retainer plate became either loose or were missing allowing the retainer plate to move, drop, or swing out which allowed the vertical