



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-66***

***Burlington Northern Santa Fe (BNSF)
Ellinor, Kansas
October 29, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. KS1007126		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. KS1007126		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 10 Day 29 Year 2007		7. Time of Accident/Incident 08:34: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
		13. Other (describe in narrative)		Code 01		
9. Cars Carrying HAZMAT 6		10. HAZMAT Cars Damaged/Derailed 0		11. Cars Releasing HAZMAT 0		
		12. People Evacuated 0		13. Division Kansas		
14. Nearest City/Town Ellinor		15. Milepost (to nearest tenth) 127.0		16. State Abbr Code N/A KS		
		17. County CHASE				
18. Temperature (F) (specify if minus) 43 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1				
22. Track Name/Number Single Main Track		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 59.78		
		25. Time Table Direction Code 1. North 3. East 2. South 4. West 3				
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		
		27. Was Equipment Attended? 1. Yes 2. No 1		Code 1		
		28. Train Number/Symbol HBARGAL927				
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 43 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 10727			31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0				
32. Principal Car/Unit		a. Initial and Number BNSF782195		b. Position in Train 33		
(1) First involved (derailed, struck, etc)		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0		
(2) Causing (if mechanical cause reported)		0		34. Was this consist transporting passengers? (Y/N) N		
35. Locomotive Units		a. Head End 2		Mid Train b. Manual 0 c. Remote 3		
(1) Total in Train		Rear End d. Manual 0 e. Remote 0		36. Cars (1) Total in Equipment Consist 83		
(2) Total Derailed		0		a. Freight 25 b. Pass. 0 c. Freight 0 d. Pass. 0 e. Caboose 0		
37. Equipment Damage This Consist \$637,078.00		38. Track, Signal, Way, & Structure Damage \$2,657,808.00		39. Primary Cause Code M507		
		40. Contributing Cause Code N/A				
Number of Crew Members				Length of Time on Duty		
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		
		44. Brakemen 0		45. Engineer/Operator Hrs 4 Mi 34		
46. Conductor Hrs 4 Mi 34						
Casualties to:		47. Railroad Employees 0		48. Train Passengers 0		
Fatal		0		49. Other 0		
Nonfatal		0		0		
		50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
		52. Caboose Occupied by Crew? 1. Yes 2. No		N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A		
		54. Was Equipment Attended? 1. Yes 2. No N/A		Code N/A		
		55. Train Number/Symbol N/A				
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track 0 = Not a remotely controlled 1 = Remote control portable			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
				N/A	1. Yes 2. No	N/A	N/A

83. Speed (recorded speed, if available)	Code R - Recorded E - Estimated	N/A MPH	N/A	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
84. Trailing Tons (gross tonnage, excluding power units)	N/A			a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
				m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)			Code N/A	111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
				1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)	N/A
				2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)	
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical)	Code N/A	112. Position of Car Unit in	0		
		1. North 2. South 3. East 4. West					

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A				
Casualties to:			Killed 0	Injured 0	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On October 29, 2007, at approximately 8:34 a.m.(CDT), an eastbound BNSF Railway Company (BNSF) manifest train, Train Symbol H BARGAL9 27, derailed 25 loaded cars (31st through 55th head cars) at milepost (MP) 126.96 , on single main track. The derailment occurred east of County Road W and west of County Road X.

The weather was clear and the temperature was 43 degrees F. The damage to equipment was \$637,078. The damage to track was \$267,808. There was no signal damage. The total damage was \$904,886. There were no injuries or hazardous materials release.

PROBABLE CAUSE:

Despite exhaustive investigative and analysis efforts of both the FRA and BNSF the cause could not be determined. The investigation is complete.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT:

BNAF Train Symbol H BARGAL9 27 departed Wellington, Kansas, about 4:31 a.m., on October 29, 2007, according to BNSF train documents. There was an initial terminal freight train air brake test performed at Barstow, California, on October 27, 2007, about 3:28 a.m. PDT. No exceptions were taken as a result of the brake test. Train symbol H BARGAL9 27 received a Class IA - 1,000 mile brake test and inspection at Belen, New Mexico, on October 28, 2007. The crew of Train Symbol H BARGAL9 27, consisted of a locomotive engineer and a conductor. The crew went on duty at Wellington, at 4 a.m., October 29, 2007, after receiving the required statutory off-duty rest period. The engineer was seated on the south side of the locomotive operating the train. The conductor was seated on the north side of the locomotive.

The train was operating on tangent track and approaching the next highway/rail grade crossing where they were required to sound the whistle on approach and complied. After passing over the accident scene, the crew stated they felt a soft bump before they experienced a train-line initiated emergency application of the train air brakes.

THE ACCIDENT:

BNSF Train Symbol H BARGAL9 27 had been waiting at Strong City for about 45 minutes while maintenance-of-way (MOW) forces repaired a broken rail. Train Symbol H BARGAL9 27 was being operated in an eastward direction at a speed of 44 mph, as recorded by the locomotive event recorder, on single main track approaching the accident site. The maximum authorized speed was 45 mph. At the accident site, the crew felt a sudden jerk when the train went into emergency; there was no advance warning. After the emergency air brake application, the lead locomotive and trailing unit along with the head 30 cars continued to travel east, on the rail, for another 1,504 feet before coming to a complete stop. The crew initiated an emergency call to the Newton and Emporia dispatchers to report the accident. The 31st through the 54th head cars were discovered derailed; some were on their side and some were upright. All of the cars were loaded.

ANALYSIS AND CONCLUSION:**ANALYSIS**

The crew of Train Symbol H BARGAL9 27 was tested under Federal Railroad Administration (FRA) post accident testing guidelines. The post-accident forensic toxicology result reports indicate the two employees tested had negative test results.

The engineer on Train Symbol H BARGAL9 27 had received 22 operational tests between January 3, 2007 and September 30, 2007. Between June 10, 2007 and September 23, 2007 the conductor received nine operational tests.

Train Symbol H BARGAL9 27 passed a trackside warning detector (TWD) less than 7 miles prior to the accident at milepost 134.0 with no exceptions taken. The locomotive event recorder on the lead locomotive revealed no issues with train handling prior to or at the time of derailment.

BNSF track inspection reports for the 2 week period of October 15, 2007, through October 29, 2007, indicates one defect was found within the 5 miles west of the accident site at milepost 131.6, by hi-rail on October 15, 2007, and was repaired before traffic was allowed to cross over the area. On October 29, a rail defect was found east of the point of derailment (POD) at milepost 128.79 by BNSF at 6:09. The remedial action taken was the repair on the track was made after supervising a train movement over the defect which according to the inspection report was an ordinary break in the rail (Defect code 213.113.10).

An FRA/DOT ATIP car report dated May 22, 2007, indicates no defects found at the derailment location. A BNSF Geometry car report, operated April 10, 2007, and notes one defect which did not exceed FRA parameters and was not noted as a defect.

FRA post accident inspections of the track, signal and event recorded downloads did not reveal any indication of causal factors. FRA discovered what appeared to be a loose wheel on the axle of one of the cars.

An analysis of a loose wheel on Car No. BNSF 782875 conducted by the BNSF Technical Research and Development Team on the right No. 1 location has been ruled out as a possible cause of the accident. The results of this analysis was the loose wheel which was a result of damage from the derailment and did not occur before the accident.

CONCLUSION:

The FRA, BNSF Technical Research and Development team and BNSF Kansas Division Managers could not determine a cause to the Ellinor derailment. The loose wheel was determined to be a result of the derailment and was not a causal factor. The main explanation was that the data necessary was destroyed in the derailment and never recovered.

Despite the extensive investigation of the FRA and BNSF the probable cause could not be determine. Evidence required was never recovered for the derailment site.

PROBABLE CAUSE AND CONTRIBUTING FACTORS:

M507 - The Investigation is complete; The cause could not be determined.