



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-70***

***Canadian Pacific/Iowa Chicago & Eastern Railroad
LaCrescent, MN
November 2, 2007***

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TX1107100		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. TX1107100		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 11 Day 02 Year 2007		7. Time of Accident/Incident 11:50: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
				13. Other (describe in narrative) Code 01		
9. Cars Carrying HAZMAT 10		10. HAZMAT Cars Damaged/Derailed 4		11. Cars Releasing HAZMAT 0		
				12. People Evacuated 0		
				13. Division Texas		
14. Nearest City/Town Fowlkes		15. Milepost (to nearest tenth) 135.2		16. State Abbr Code N/A TX		
				17. County WICHITA		
18. Temperature (F) (specify if minus) 64 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
				21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
22. Track Name/Number Single Main		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 54.29		
				25. Time Table Direction Code 1. North 3. East 2. South 4. West 4		
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		27. Was Equipment Attended? Code 1. Yes 2. No 1		
				28. Train Number/Symbol MALTAMA101		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 7 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 8512			31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits e N/A N/A N/A N/A	
					31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		
(1) First involved (derailed, struck, etc)		BNSF782974		29		
(2) Causing (if mechanical cause reported)		0		0		
				N/A		
				33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A		
				34. Was this consist transporting passengers? (Y/N) N/A		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		3		0 0		
(2) Total Derailed		0		0 0		
				36. Cars		
				a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
				(1) Total in Equipment Consist 58 0 38 0 0		
				(2) Total Derailed 11 0 16 0 0		
37. Equipment Damage		38. Track, Signal, Way, & Structure Damage		39. Primary Cause Code		
This Consist \$97,432.00		\$296,455.00		H503		
				40. Contributing Cause Code T199		
				41. Engineer/Operators 1		
		42. Firemen 0		43. Conductors 1		
		44. Brakemen 1		45. Engineer/Operator Hrs 5 Mi 5		
				46. Conductor Hrs 5 Mi 5		
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0		
Nonfatal		0		0		
				49. Other 0		
				50. EOT Device? 1. Yes 2. No 1		
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		54. Was Equipment Attended? Code 1. Yes 2. No N/A		
				55. Train Number/Symbol N/A		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0

64. Equipment Damage This Consist	\$0.00	65. Track, Signal, Way, & Structure Damage	\$0.00	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	0	69. Firemen	0	70. Conductors	0	71. Brakemen	0	72. Engineer/Operator	Hrs 0 Mi 0	73. Conductor	Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	1. Yes 2. No N/A	78. Was EOT Device Properly Armed?	1. Yes 2. No N/A	79. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train	4. Work train	7. Yard/switching	A. Spec. MoW Equip.	Code	81. Was Equipment Attended?	Code	82. Train Number/Symbol
	2. Passenger train	5. Single car	8. Light loco(s).		N/A	1. Yes 2. No	N/A	N/A
	3. Commuter train	6. Cut of cars	9. Maint./inspect.car					

83. Speed (recorded speed, if available)	Code	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
R - Recorded		a. ATCS	0 = Not a remotely controlled
E - Estimated	N/A MPH 0	b. Auto train control	1 = Remote control portable
84. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop	2 = Remote control tower
		d. Cab	3 = Remote control transmitter - more than one remote control transmitter
		e. Traffic	
		f. Interlocking	
		i. Time table/train orders	
		j. Track warrant control	
		k. Direct traffic control	
		l. Yard limits	
			N/A N/A N/A N/A N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	0	0	N/A			
(2) Causing (if mechanical cause reported)	0	0	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	0	0 0	0 0	(1) Total in Equipment Consist	0 0	0 0	0
(2) Total Derailed	0	0 0	0 0	(2) Total Derailed	0 0	0 0	0


91. Equipment Damage This Consist	\$0.00	92. Track, Signal, Way, & Structure Damage	\$0.00	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	0	96. Firemen	0	97. Conductors	0	98. Brakemen	0	99. Engineer/Operator	Hrs 0 Mi 0	100. Conductor	Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	1. Yes 2. No N/A	105. Was EOT Device Properly	1. Yes 2. No N/A	106. Caboose Occupied by Crew?	1. Yes 2. No N/A		
Fatal	0	0	0								
Nonfatal	0	0	0								

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer	F. Bus	J. Other Motor Vehicle	Code	111. Equipment	3. Train (standing)	6. Light Loco(s) (moving)	Code
A. Auto	D. Pick-Up Truck	G. School Bus	K. Pedestrian	1. Train(units pulling)	4. Car(s) (moving)	7. Light(s) (standing)	
B. Truck	E. Van	H. Motorcycle	M. Other (spec. in narrative)	2. Train(units pushing)	5. Car(s) (standing)	8. Other (specify in narrative)	N/A
			N/A				
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code	112. Position of Car Unit in	0		
		1. North 2. South 3. East 4. West	N/A				

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A	
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	
114c. State here the name and quantity of the hazardous materials released, if any. N/A										
115. Type Crossing Warning 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)			Code N/A	117. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown			Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age 0	122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown			Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative)		
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown			Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed						Code N/A
Casualties to:		Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured			Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No		
129. Highway-Rail Crossing Users		0	0	130. Highway Vehicle Property Damage (est. dollar damage)			0	131. Total Number of Highway-Rail Crossing Users (include driver)		
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A	
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A	

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

A westbound BNSF freight train derailed 27 cars on the main line on November 2, 2007 at 11:50 a.m. The accident occurred near Electra, Texas between switches at Fowlkes Siding, BNSF Milepost 135.2 on the Red River Subdivision.

There were no injuries to the train crew. There was a total of \$97,432 in equipment damage and \$296,455 in track damage.

At the time of the derailment it was daylight and clear, with variable winds. The temperature was 64° F.

The derailment was caused by rapid reduction of throttle followed by rapid increase of dynamic brake while attempting to reduce speed in preparation for stopping. This created a run-in of slack resulting in excessive wheel to rail lateral force (due to car skewing) sufficient to rotate rail head to the field side on tangent track with single gage hold-down spiking and minimal negative rail cant and associated minimal wide gage. This allowed the wheel rim on the opposite end of axle to drop in the gage corner side of opposite rail spreading the gage and derailing it and the trailing cars.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT:

The crew of BNSF Train M-ALTAMA1-01 West included a locomotive engineer, a conductor, and a brakemen. They first went on duty at 6:45 a.m., November 2, 2007, at the BNSF Yard in Wichita Falls, Texas. This is the home terminal for the engineer and brakeman, Amarillo is the home terminal for the conductor. All crew members received more than the required statutory off duty rest period prior to reporting for duty.

The BNSF freight train consisted of three locomotives, 58 loaded rail cars and 38 empty freight rail cars. The train was 5,827 feet long and weighed 8,512 tons. The train was scheduled to travel from Wichita Falls, Texas to Amarillo, Texas with cars added and removed en route. The train received the required Class I Brake Test and pre-departure inspection at Alliance Yard, Ft. Worth, Texas where it originated on November 1, 2007. The train departed Wichita Falls at 9:35 a.m. on November 2, 2007.

As the westbound train approached the accident area, the locomotive engineer was seated at the controls on the north side of the lead locomotive. The conductor and the brakeman was seated on the south side of the lead locomotive.

The derailment occurred on tangent track as the train was operated down a short, steep grade (-1.73%) and transitioning onto a moderate ascending grade (approximately +0.6%%). The territory surrounding the vicinity of the derailment is somewhat undulating.

The railroad timetable and geographic direction is west.

THE ACCIDENT:

The train stopped in between switches on the BNSF Mainline at Fowlkes. The crew was instructed to meet two trains and occupy the mainline, the two eastbound trains had instructions to travel through the siding.

The first of the two trains had already arrived at Fowlkes when BNSF Train M-ALTAMA1-01 came to a stop. The train in the siding departed after this train cleared the east switch at Fowlkes. Directly behind the first train the second eastbound was pulling into the west end of Fowlkes siding. This train began to pull as the second eastbound train arrived and the train went into an emergency air brake application. The brakeman and conductor were both walking back to find the problem when the eastbound train called them on the radio to inform them that their train was derailed.

The crew walked back and discovered 27 cars were derailed. The first car derailed was the 26th car in the train. All cars were in line with the track and all in the upright position.

ANALYSIS:

On November 5, 2007, FRA Inspectors retrieved the event recorder information from the BNSF Officials. On November 06, 2007 FRA inspected the equipment that had been derailed as well as the track structure at the derailment site. All equipment was re-railed and the track had been repaired. FRA took no exceptions with the condition of the equipment or track.

Each of the three crew members that were on the BNSF train were interviewed. All stated it was a normal trip and none of them were aware the train had derailed until they tried to depart Fowlkes. The engineer stated he did notice the train came to a stop faster than usual but he thought nothing of it. The conductor recalled a "surge in the train" as they were stopping but he thought it might have been from a movement in liquid loaded tank cars located near the head end of the train. The engineer and conductor both voiced concerns about the train make-up stating there were loaded cars on the head and rear end of the train with empties in the middle. They stated that the profile was not ideal but it was still in compliance so they departed Wichita Falls without changing the make-up of the train.

FRA reviewed the Event Recorder printout and found no locomotive or train brakes were set at the time of the derailment. The train came to a stop in dynamic braking.

The train profile or make-up was reviewed and it was found to be in compliance. There were concerns of throttle movement shown on the Event Recorder printout but nothing appeared out of the ordinary.

The train speed was approximately 30 mph when it initially derailed. The train was dragged in a derailed state and rolled rail for approximately 4000 feet before coming to rest with the locomotives in Throttle Notch 4 position. There were no locomotive brakes or train brakes applied when the train came to a stop with the lead locomotive near MP 136.4. At this point, the crew did not realize their train was derailed. BNSF employed Rail Science Inc. (RSI) to perform analyzes of the derailment data.

According to RSI, the derailment was caused by rapid reduction of the throttle position followed by rapid increase of dynamic brake when attempting to reduce train speed in preparation for stopping. This created a run-in of slack resulting in wheel to rail lateral force (due to car skewing) sufficient to rotate the head of the rail to the field side on tangent track with single gage hold-down spiking and minimal negative rail cant and associated minimal wide gage. This allowed the wheel rim on the opposite end of the axle to drop inside the gage corner side of the opposite rail which resulted in spreading the gage and derailing the car and the trailing cars. RSI reported that the train handling actually used by the engineer employed a rapid transition from moderately-high throttle (R6-R7) to full (D8) dynamic braking as he approached and progressed through the POD. The run-in slack event predicted by simulating the actual train handling was induced by this rapid throttle transition. Based upon the calculations of RSI, for the derailment data supplied with a -200 kip (-200,000 pound) run-in, on the order of 17,500 pounds lateral force could be generated toward the rail. An empty car would have been the initial car to derail and with this level of lateral force the wheels of one side of the truck struck against one of the rails. Without any significant vertical force, this would have rotated the head of the rail sufficiently to the field side to allow the rim of the opposite wheel to just start to drop inside the gage corner of the rail spreading the gage and derailing it and the trailing cars.

RSI also found track geometry data showed some evidence of rail cant and widening gage near the POD. This was reaffirmed by BNSF track notes taken at the scene of the derailment which showed up to 1/4" gage widening at the POD. There was also some crosslevel deviation (3/4") recorded by the track geometry car. Measurements taken at the scene of the derailment indicate crosslevel was less than this however this was likely an unloaded measurement. While there is some evidence of small track anomalies near the POD, the

track deviations noted were within Class 4 tolerances for the 60 mph authorized freight speeds. RSI additionally found that track geometry was within FRA limits and not a primary factor of this derailment. There is, however, evidence of crosslevel, rail cant and gage widening deviations present at and near the POD which may have contributed to rail roll.

RSI found that alternative train handling could have prevented this run-in and that a more gradual transition from throttle to dynamic braking would have significantly reduced in-train forces. Simulation further showed that the full dynamic braking was not necessary to control the train speed and stop it as intended at the signal near MP 136.5.

Train makeup was not contributory to this derailment despite the fact that the train consist had less than optimum car placement. RSI recommended that more prudent train make-up be utilized if at all possible to minimize the potential for train make-up contributory derailments.

Although track stability was not the primary cause of this derailment, RSI advised to consider double-spiking the gage side of tangent track in undulating territory where slack action is anticipated.

ANALYSIS:

FRA obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that information FRA concluded fatigue was not probable for any of the employees.

CONCLUSION:

The railroad was in compliance with their own, and all Federal standards. No areas of noncompliance were found with the track, train profile, or equipment. A combination of events contributed to the derailment. There was multiple track deviations that were not out of compliance but due to the train handling and track profile at the point of the deviations caused the train to derail. If the train handling would have been performed in a different manner or if these track issues would not have existed, this train would not have derailed.

PROBABLE CAUSE & CONTRIBUTING FACTORS:

The derailment was caused by rapid reduction of the throttle followed by a rapid increase of dynamic braking while attempting to reduce train speed in preparation for stopping. This action created a run-in of slack resulting in excessive wheel to rail lateral force (due to car skewing) sufficient enough to rotate the rail head to the field side on tangent track with single gage hold-down spiking and minimal negative rail cant, and associated minimal wide gage. This allowed the wheel rim on the opposite end of the axle to drop in the gage corner side of the opposite rail, spreading the gage and derailling it and the trailing cars.