



*Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-79*

*Union Pacific
Schuyler, NE
December 10, 2007*

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 1207CB005	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 1207CB005	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 12 Day 10 Year 2007		7. Time of Accident/Incident 07:14:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 01	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division Council Bluffs	
14. Nearest City/Town Schuyler		15. Milepost (to nearest tenth) 68.4		16. State Abbr Code N/A NE	
		17. County COLFAX			
18. Temperature (F) (specify if minus) 10 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2			
22. Track Name/Number Main Track No 2		23. FRA Track Code Class (1-9, X) 5		24. Annual Track Density (gross tons in millions) 152	
		25. Time Table Direction Code 1. North 3. East 2. South 4. West 3			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? Code 1. Yes 2. No 1		28. Train Number/Symbol CBTND908	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 35 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 17750		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits d g h N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) CEFX 40621		b. Position in Train 38	
		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
(2) Causing (if mechanical cause reported)		0		0	
		N/A		34. Was this consist transporting passengers? (Y/N) N	
35. Locomotive Units		a. Head End		Mid Train	
		b. Manual		c. Remote	
		Rear End		d. Manual	
		c. Remote		36. Cars	
(1) Total in Train		2		0	
		0		0	
(2) Total Derailed		0		0	
		0		0	
		0		0	
		0		0	
37. Equipment Damage		This Consist \$152,675.00		38. Track, Signal, Way, & Structure Damage \$144,716.00	
				39. Primary Cause Code T214	
				40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 8 Mi 14	
				46. Conductor Hrs 8 Mi 14	
Casualties to:		47. Railroad Employees		48. Train Passengers	
Fatal		0		0	
Nonfatal		0		0	
				49. Other 0	
				50. EOT Device? 1. Yes 2. No 1	
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
		54. Was Equipment Attended? Code 1. Yes 2. No N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units)	N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
				N/A N/A N/A N/A N/A	N/A

59. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	61. Was this consist transporting passengers? (Y/N)		N/A

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A

64. Equipment Damage This Consist	N/A	65. Track, Signal, Way, & Structure Damage	N/A	66. Primary Cause Code	N/A	67. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

68. Engineer/Operators	69. Firemen	70. Conductors	71. Brakemen	72. Engineer/Operator	73. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device?	78. Was EOT Device Properly Armed?
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	79. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code	81. Was Equipment Attended?	82. Train Number/Symbol
				N/A	1. Yes 2. No N/A	N/A

83. Speed (recorded speed, if available)	R - Recorded E - Estimated	Code N/A MPH N/A	85. Method(s) of Operation (enter code(s) that apply)	85a. Remotely Controlled Locomotive?
84. Trailing Tons (gross tonnage, excluding power units)	N/A		a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter
			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	N/A
			m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)	N/A

86. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded(yes/no)	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	Alcohol N/A	Drugs N/A
(1) First involved (derailed, struck, etc)	N/A	N/A	N/A			
(2) Causing (if mechanical cause reported)	N/A	N/A	N/A	88. Was this consist transporting passengers? (Y/N)		N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train	N/A	N/A N/A	N/A N/A	(1) Total in Equipment Consist	N/A N/A	N/A N/A	N/A
(2) Total Derailed	N/A	N/A N/A	N/A N/A	(2) Total Derailed	N/A N/A	N/A N/A	N/A


91. Equipment Damage This Consist	N/A	92. Track, Signal, Way, & Structure Damage	N/A	93. Primary Cause Code	N/A	94. Contributing Cause Code	N/A
Number of Crew Members				Length of Time on Duty			

95. Engineer/Operators	96. Firemen	97. Conductors	98. Brakemen	99. Engineer/Operator	100. Conductor
N/A	N/A	N/A	N/A	Hrs N/A Mi N/A	Hrs N/A Mi N/A
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT	105. Was EOT Device Properly
Fatal	N/A	N/A	N/A	1. Yes 2. No N/A	1. Yes 2. No N/A
Nonfatal	N/A	N/A	N/A	106. Caboose Occupied by Crew?	
				1. Yes 2. No	N/A

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment	3. Train (standing) 4. Car(s) (moving) 5. Car(s) (standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact)	N/A	109. geographical	Code N/A	112. Position of Car Unit in	N/A		
		1. North 2. South 3. East 4. West					

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A		
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A		
114c. State here the name and quantity of the hazardous materials released, if any. N/A											
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Warning 4. Wig Wags 5. Hwy. traffic signals 6. Audible				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A	N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
121. Age N/A		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed				Code N/A		
Casualties to:			Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No	
129. Highway-Rail Crossing Users			N/A	N/A	130. Highway Vehicle Property Damage (est. dollar damage)				N/A	131. Total Number of Highway-Rail Crossing Users (include driver)	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A		
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

Eastbound Union Pacific Railroad Company (UP) Unit Coal Train CBTND9-08 consisting of two locomotives and 125 loaded coal hopper cars derailed 23 cars on December 10, 2007, at 7:14 a.m. CST. The accident occurred in Schuyler, Nebraska, at milepost (MP) 68.4, on the UP Council Bluffs Service Unit, Columbus Subdivision.

There were no injuries reported and no hazardous material spills reported as a result of the derailment. Total damages reported as a result of the derailment were \$1,297,391.

At the time of the accident, it was dawn and cloudy with a temperature of 10° F.

Probable Cause:"

The probable cause of the derailment is being ruled as T-214 – Joint bar broken (insulated).

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The train crew of UP Train CBTND9-08 consisted of an engineer and conductor. They first went on duty at 11:00 p.m., CST, December 9, 2007, at North Platte, Nebraska. This is the home terminal and both had received more than the required statutory off-duty rest period prior to reporting for duty.

The assigned train consisted of two locomotives on the head-end, 125 loaded coal hopper cars. The train was 7,050 feet long and with 17,750 trailing tons. The crew was scheduled to operate the train to Fremont, Nebraska.

The train had received a Class 1 train air brake test just prior to departing North Platte. The test was performed by UP mechanical personnel in North Platte, on December 9, 2007.

There was no work performed en route after departing, and the trip was uneventful for the 221 miles leading up to the derailment.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the south side of the lead locomotive. The conductor was seated on the north side of the same locomotive.

In this area of the railroad there is little or no grade and is a segment of tangent track that runs 22.5 miles. Approximately 200 feet prior to the point of derailment (POD), there is a No. 10, left hand trailing point switch followed by a grade crossing approximately 30 feet west of the POD.

The track at and leading up to the POD is constructed of 133 lb Continuous Welded Rail (CWR) on wood crossties. It is box anchored on every tie with Unit Channel Anchors leading both into and away from the grade crossing at MP 68.45.

The railroad timetable direction and geographic direction of the train was east.

THE ACCIDENT

The train was being operated at recorded speed of 36 mph approaching the derailment area. According to the train crew, they did not observe or feel anything unusual prior to the derailment. The recorded speed at the time of the derailment was 35 mph. Both speeds (approaching and at the time of derailment) were recorded by the event recorder of the controlling locomotive. The train was traversing a 40 mph track slow order at the time of the accident. Maximum authorized speed for this train was 50 mph as designated in current UP Council Bluffs Area Timetable #3.

Approximately 30 feet after traversing a grade crossing, the train experienced an undesired emergency application of the train air brake system. Immediately following the emergency application, the train crew contacted the UP dispatcher and told him that they were in emergency. The conductor of the derailed train walked back to check the train and discovered the 36th head car derailed, the next 16 were not derailed and then an additional 22 cars were derailed in a pile blocking both main tracks and a siding to the north.

ANALYSIS AND CONCLUSIONS

ANALYSIS: CREW MEMBERS

The two crew members of UP Unit Coal Train CBTND9-08 were Federal Railroad Administration (FRA) mandatory post-accident toxicologically tested because this accident exceeded the \$1 million dollar major accident threshold.

CONCLUSION:

The test results obtained from the FRA Alcohol and Drug Control Program Manager were negative.

The event recorder for the controlling locomotive revealed nothing inconsistent with normal train handling at or prior to the time of the derailment.

ANALYSIS: TRACK

The track was last traversed and inspected by hi-rail vehicle the previous day, with no exceptions taken in the area of the derailment. The last ultra sonic rail detection test through this area was on November 8, 2007, with one exception noted in this area for a bolt-hole crack. According to a UP official, defective rail was replaced in accordance to FRA regulations. The last geometry car survey with the railroads EC-5 car was on September 28, 2007, with no FRA defects noted in the area of POD. The survey revealed some profile deviations that did not meet UP maintenance standards, but were within the parameters of FRA standards.

All on-foot joint bar inspections were performed since January 1, 2007, in accordance to §213.119(g)(6) with the last inspection being made on October 20, 2007.

Track inspection records revealed that this track was inspected well within the required frequency the prior month before the accident, with no exceptions noted in this area.

The track inspector stated he inspected the derailment area the previous day of the accident and took no exceptions. He stated there had been surfacing work performed in this area approximately two months prior to address surface conditions found by their geometry car. He also stated that the 40 mph slow order through this area was because of surface conditions approximately 700 feet prior to the POD. The track inspector further stated there were five total rail joints in the POD area. Two were insulated joints (one on each the north and south rail), and three conventional joints on the south rail. He did not recall any particular problems with these joints other than routine maintenance i.e; loose bolts or an occasional cracked bar.

The UP forwarded six suspect pieces of rail to Rail Sciences Inc., in Omaha, Nebraska for further evaluation. One of these pieces included half of an insulated joint bar with noticeable fatigue cracks initiating in the top of the bars. Unfortunately the other half of this joint was not recovered during clean-up activities.

The pieces of rail revealed they had broken, not because of a defect, but due to an overload rupture caused by the insulated bars breaking. This piece exhibited extreme receiving batter consistent with the markings found on the wheels and one derailed car that passed over this area prior to the catastrophic pile of cars.

The last hotbox/dragging equipment detector at MP 81.03 noted no exceptions.

No suspicious mechanical equipment was found in the wreck or during clean-up activities.

CONCLUSION:

The railroad was in compliance with their own and all applicable FRA standards. There were no witnesses to the accident.

The data reviewed from the event recorder ruled out train handling as a cause. There were no marks found on the rail or ties prior to the pile-up. Also there were no track components, i.e. bridges, grade crossings or culverts at the point of derailment (POD) area that contributed to the cause. The one grade crossing just west of the POD was not damaged by the derailment and did not contribute to this accident. The grade and curvature of the track were not a factor in the derailment.

It was determined that 10 rail cars prior to the first car derailed had definitive marks on the south wheels, consistent with them striking a blunt object. This indicated that the insulated joint most likely broke under the train causing the eventual accident.

PROBABLE CAUSE AND CONTRIBUTING FACTORS:

The evidence discovered on the insulated joint substantiates the cause of the derailment. The probable cause has been determined to be T214 - Broken joint bar (insulated). No contributing cause is suspected.