



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-84***

***Canadian Pacific (CP)
Anamoose, North Dakota
December 23, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Canadian Pacific Rwy Co. [CP]		1a. Alphabetic Code CP		1b. Railroad Accident/Incident No. 204683		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Canadian Pacific Rwy Co. [CP]		4a. Alphabetic Code CP		4b. Railroad Accident/Incident No. 204683		
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 12 Day 23 Year 2007		7. Time of Accident/Incident 03:40:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
		13. Other (describe in narrative)		Code 01		
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT 0		
		12. People Evacuated 0		13. Division St. Paul		
14. Nearest City/Town Anamoose		15. Milepost (to nearest tenth) 413.07		16. State Abbr Code N/A ND		
		17. County MCHENRY				
18. Temperature (F) (specify if minus) 4 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 6		
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1				
22. Track Name/Number Portal Subdivision		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 40		
		25. Time Table Direction Code 1. North 3. East 2. South 4. West 3				
OPERATING TRAIN #1						
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		
		27. Was Equipment Attended? 1. Yes 2. No 1		28. Train Number/Symbol 874-001		
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 45 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 16760			31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) j N/A N/A N/A N/A	
					31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
32. Principal Car/Unit		a. Initial and Number (1) First involved (derailed, struck, etc) NS31749		b. Position in Train 2		
		c. Loaded (yes/no) yes		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0		
(2) Causing (if mechanical cause reported)		0		0		
		N/A		34. Was this consist transporting passengers? (Y/N) N		
35. Locomotive Units		a. Head End		Mid Train		
		b. Manual		c. Remote		
		Rear End		d. Manual		
		c. Remote		36. Cars		
(1) Total in Train		3		0		
		0		0		
(2) Total Derailed		0		0		
		0		0		
		0		0		
		0		0		
37. Equipment Damage		This Consist \$436,026.00		38. Track, Signal, Way, & Structure Damage \$115,000.00		
				39. Primary Cause Code T201		
				40. Contributing Cause Code N/A		
41. Engineer/Operators 1			42. Firemen 0			
43. Conductors 1			44. Brakemen 0			
45. Engineer/Operator Hrs 7 Mi 40			46. Conductor Hrs 7 Mi 40			
Casualties to:		47. Railroad Employees		48. Train Passengers		
Fatal		0		0		
Nonfatal		0		0		
				49. Other 0		
				50. EOT Device? 1. Yes 2. No 1		
				51. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				52. Caboose Occupied by Crew? 1. Yes 2. No 2		
OPERATING TRAIN #2						
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 6		
		54. Was Equipment Attended? 1. Yes 2. No 2		55. Train Number/Symbol N/A		
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH E		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track j N/A N/A N/A N/A			58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) N/A	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) n N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
---	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) NAHX 80045	a. Initial and Number 1	b. Position in Train no	c. Loaded(yes/no) no	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	10 0	0 0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	6 0	0 0

64. Equipment Damage This Consist \$22,901.00	65. Track, Signal, Way, & Structure Damage \$0.00	66. Primary Cause Code T201	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 0	69. Firemen 0	70. Conductors 0	71. Brakemen 0	72. Engineer/Operator Hrs 0 Mi 0	73. Conductor Hrs 0 Mi 0
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No 2	78. Was EOT Device Properly Armed? 1. Yes 2. No 2
Fatal	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No 2	
Nonfatal	0	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) N/A				84. Trailing Tons (gross tonnage, excluding power units) N/A

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number 0	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0 0	0 0	(1) Total in Equipment Consist 0	0 0	0 0	0 0
(2) Total Derailed 0	0	0 0	0 0	(2) Total Derailed 0	0 0	0 0	0 0


91. Equipment Damage This Consist \$0.00	92. Track, Signal, Way, & Structure Damage \$0.00	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West	Code N/A		112. Position of Car Unit in 0			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)				N/A	N/A	N/A	N/A	N/A	N/A				
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A
Casualties to:			Killed 0	Injured 0	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

An eastbound Canadian Pacific Railway (CP) freight train (874-001) derailed on December 23, 2007, at 3:40 a.m. CDT. The accident occurred on the single main track at the west switch in Anamoose, North Dakota. Anamoose is located at milepost 413.07 on the CP Saint Paul Service Area, Portal Subdivision.

The train consisted of three locomotives and 117 loaded coal cars. The 2nd through the 41st cars, behind the locomotives, derailed on tangent track at the west switch into the House Track at Anamoose. The derailed cars struck a standing set of empty cars in the House Track, derailing six more cars. The derailment damaged 900 feet of the single main track. There was no reported damage to the House Track.

There were no injuries to the train crew and no hazardous materials involved.

The railroad estimated equipment damage at \$458,927, track and signal damage at \$115,000. Total railroad damage was estimated at \$573,927.

At the time of the derailment it was 4 degrees F, light snow with 20 mph northwest wind.

The probable cause of the accident was a broken rail in the heel of the switch point. FRA cause code "T201-Broken Rail-Bolt hole crack or break".

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of Train Symbol 874-001 consisted of a locomotive engineer and a conductor. They first went on duty, away from their home terminal, at 7:10 p.m. CDT, on December 22, 2008, at Portal, North Dakota. The crew received more than the statutory off duty period prior to reporting for duty.

The assigned freight train consisted of three locomotives, 117 loaded coal cars, 16,760 trailing tons, and was 6,189 feet in length. The train was scheduled to travel from Fording, BC to Wheelersburg, OH a total distance of about 2,139 miles. The train departed Portal at approximately 11:05 p.m. on December 22, 2008.

As the train approached the derailment area, the locomotive engineer was seated at the controls on the right (south) side of the leading locomotive. The conductor was seated on the left (north) side of the cab of the leading locomotive.

Interviews conducted by the Federal Railroad Administration (FRA) revealed the trip was uneventful prior to the derailment, with no set out or pickups en route.

Approaching the derailment site from the west traversing eastward, there is tangent track from milepost 413.8 to 412.6. The derailment occurred at the west switch at Anamoose, milepost 413.07, on tangent track. The track has a .25 percent ascending grade from milepost 413.3 to 412.8. The train traversed one crossing at milepost 413.5 in the mile preceding the point of derailment.

The west switch at Anamoose is a #10-115 lb. turnout. The switch had a switch package upgrade installed in 2007, which consisted of all new components and a tie replacement program that consisted of 40 new switch ties in the turnout location.

The last track inspection performed at the derailment location was on December 21, 2007.

THE ACCIDENT

Train 874-001, traveling eastward on tangent track, experienced a train induced undesired emergency brake application at the west switch Anamoose, milepost 413.07. The 2nd through the 41st cars of the train derailed and struck a standing set of cars in the House Track. Six of the 10 cars on the House Track were also derailed. The train crew stated they felt a rough spot in the track as the leading locomotive passed over the west switch at Anamoose prior to the derailment. They were going to notify the train dispatcher of the rough location when they experienced the emergency brake application. The derailment damaged 900 feet of main line track.

After coming to a stop, the engineer notified the train dispatcher. The conductor walked back to inspect the train and determined that the 2nd through the 41th car behind the locomotives had derailed.

Further investigation of the derailment determined that the initial POD was at milepost 413.07, on the heel of the switch at the west main line switch at Anamoose.

Train 847-001 was traveling timetable direction east on single main track at a recorded speed of 45 mph while approaching the POD. Geographical direction of the train was southeast. The speed was recorded by the event recorder of the controlling locomotive. The maximum authorized speed for the Portal Subdivision is 49 mph, as designated by the current CP Timetable No. 5, dated Sunday, April 3, 2005.

There were no reported injuries, no hazardous materials involved, and no evacuations were required as a result of the derailment. All cars derailed were transporting coal and no local emergency response personnel were dispatched to the accident scene.

ANALYSIS AND CONCLUSIONS

The two person train crew was drug and alcohol tested in accordance with CP operating rules. The crew was not tested under FRA Part 219. Test results were negative for the engineer and conductor.

An inspection of the data printout from the lead locomotive event recorder indicated that the train was being operated at 45 mph at the location of the POD. The event recorder also indicated no unusual events related to train handling.

Fatigue Analysis

FRA obtained fatigue related information, including a 10-day work history, for two employees involved in this accident, the locomotive engineer, and the conductor assigned to Train 874-001.

Fatigue conclusion:

Even though not a causal factor, fatigue was probable for the engineer and the conductor.

PROBABLE CAUSE

The probable cause of the accident was a broken rail in the heel of the switch point at milepost 413.07. FRA cause code "T201 - Bolt Rail, Bolt Hole Crack or Break."