



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-02***

***Norfolk Southern (NS)
York, Alabama
January 16, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 CSX Transportation [CSX]		1a. Alphabetic Code CSX		1b. Railroad Accident/Incident No. 000019813	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 01 Day: 16 Year: 2006		6. Time of Accident/Incident 12:30: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
				13. Other (describe in narrative) 01	
8. Cars Carrying HAZMAT 22		9. HAZMAT Cars Damaged/Derailed 10		10. Cars Releasing HAZMAT 0	
				11. People Evacuated 0	
				12. Division Alabama	
13. Nearest City/Town Cuba		14. Milepost (to nearest tenth) 276		15. State Abbr Code N/A AL	
				16. County SUMTER	
17. Temperature (F) (specify if minus) 61 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
				20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number single main		22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 43.5	
				24. Time Table Direction Code 1. North 3. East 1	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s).		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code 1	
				26. Was Equipment Attended? 1. Yes 2. No 1	
				27. Train Number/Symbol R60616	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 38 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 9339		30. Method(s) of Operation (enter code(s) that apply) g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	
31. Principal Car/Unit		a. Initial and Number N/A		b. Position in Train 32	
(1) First involved (derailed, struck, etc)				c. Loaded (yes/no) yes	
(2) Causing (if mechanical cause reported)		0		N/A	
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A	
				33. Was this consist transporting passengers? (Y/N) N/A	
34. Locomotive Units		a. Head End		b. Mid Train	
		b. Manual		c. Remote	
		Rear End		d. Manual	
				e. Remote	
(1) Total in Train		5		0	
(2) Total Derailed		0		0	
				35. Cars	
				a. Freight	
				b. Pass.	
				c. Freight	
				d. Pass.	
				e. Caboose	
(1) Total in Train		5		0	
(2) Total Derailed		0		0	
				36. Equipment Damage This Consist 330821	
				37. Track, Signal, Way, & Structure Damage 248322	
				38. Primary Cause Code H503	
				39. Contributing Cause Code N/A	
				Number of Crew Members	
				Length of Time on Duty	
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1	
				43. Brakemen 0	
				44. Engineer/Operator Hrs 2 Mi 55	
				45. Conductor Hrs 2 Mi 55	
Casualties to:		46. Railroad Employees		47. Train Passengers	
Fatal		0		0	
Nonfatal		N/A		0	
				48. Other 0	
				49. EOT Device? 1. Yes 2. No 1	
				50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				51. Caboose Occupied by Crew? 1. Yes 2. No 2	
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s).		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code N/A	
				53. Was Equipment Attended? 1. Yes 2. No N/A	
				54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control		57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	
		g. Automatic block h. Current of traffic		m. Special instructions n. Other than main track	

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A							
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs					
(1) First involved (derailed, struck, etc)		0		N/A		N/A						N/A		N/A					
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)						N/A					
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose					
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.			
(1) Total in Train		0		0		0		(1) Total in Equipment Consist		0		0		0		0			
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0		0		0			
63. Equipment Damage		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A					
Number of Crew Members				Length of Time on Duty															
67. Engineer/Operators		N/A		68. Firemen		N/A		69. Conductors		N/A		70. Brakemen		N/A		71. Engineer/Operator		72. Conductor	
																Hrs 0 Mi 0		Hrs 0 Mi 0	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?				77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No N/A				1. Yes 2. No N/A							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?				N/A							
				1. Yes 2. No															
Highway User Involved								Rail Equipment Involved											
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code							
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A							
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)						2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)									
80. Vehicle Speed		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train											
(est. MPH at impact)				1. North 2. South 3. East 4. West		N/A		N/A											
82. Position				Code		85. Circumstance													
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing				N/A		1. Rail Equipment Struck Highway User													
4. Trapped						2. Rail Equipment Struck by Highway User													
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by													
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither													
						Code													
						N/A													
86c. State here the name and quantity of the hazardous materials released, if any.																			
N/A																			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code			
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes					
3. Standard FLS		6. Audible		9. Watchman		12. None								2. No					
Code(s)		N/A		N/A		N/A		N/A						3. Unknown		N/A			
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides						1. Yes				1. Yes									
2. Side of Vehicle Approach						2. No		N/A		2. No									
3. Opposite Side of Vehicle Approach				N/A		3. Unknown				3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code							
0		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing							
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)							
										3. Did not Stop									
97. Driver Passed Standing Highway Vehicle				Code		98. View of Track Obscured by (primary obstruction)		Code											
1. Yes 2. No 3. Unknown				N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)													
						2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed													
101. Casualties to Highway-Rail Crossing Users				Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
				0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
								102. Highway Vehicle Property Damage (est. dollar damage)		0		103. Total Number of Highway-Rail Crossing Users (include driver)		0					
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes 2. No				N/A		1. Yes 2. No		N/A											
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes 2. No				N/A		1. Yes 2. No		N/A											

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-02-
2006
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On January 16, 2006, about 12:30 p.m. Central Daylight Time (CDT), CSX Transportation (CSX) northbound Train R60616 derailed on Norfolk Southern Corporation's (NS) Alabama Division, Western Region, AGS South District, at milepost (MP) 276. The derailment occurred on the single main track near Cuba, Alabama (AL). It is important to note since October 2005, CSX has been operating six detour trains daily over the NS railroad from New Orleans, Louisiana (LA) to Birmingham, AL.

Train R60616 departed Meridian, Mississippi (MS) at 11:55 a.m. with five locomotives and 105 cars (22 hazardous material cars). Approaching Cuba, Train R60616 was operated in dynamic braking mode. However, before the train slack fully adjusted, the locomotive engineer initiated a brake pipe reduction at a recorded speed of 39 miles per hour (mph). The train slowed to about 10 mph before an undesired emergency application of the train air brakes occurred.

The conductor disembarked and walked back to inspect the train. The conductor discovered the 32nd through 60th cars had derailed. Ten of the 29 cars derailed contained hazardous material. However, nine of the cars containing hazardous material remained upright. There were no leaks or injuries because of the derailment.

At the time of the accident, it was daylight with clear visibility. The temperature was 61 ̊F.

The cause of this derailment is train handling.

110. NARRATIVE

Circumstances Prior to Derailment

On January 16, 2006, following the statutory off duty period (10 consecutive hours or more), a CSX locomotive engineer and conductor went on duty at 8:35 a.m. at Meridian, MS. The crew was to operate CSX detour Train R60616 northward over the NS, AGS South District from Meridian to Birmingham. This was the home terminal for both crew members.

Dynamic brakes on the lead locomotive failed upon arrival at Meridian. The inbound locomotive engineer informed the relieving engineer there were five locomotives in the consist, dynamic brakes were not dependable on the lead locomotive, and the second and third locomotives were not on line. Therefore, the inbound engineer isolated the lead locomotive and set the dynamic brakes to normal position before going off duty.

At 11:55 a.m. CDT, CSX northbound Train R60616 departed Meridian en route to Birmingham. This assigned mixed freight train consisted of locomotives UP 9660 (D-8), UP 2785 (SD-40), FURX 3017 (SD-40), CSXT 8102 (SD-40), and UP 4632 (SD-70), 105 cars (78 loads, 27 empties, 9,339 tons). Twenty-two cars in this train contained hazardous material or residue.

As the train approached the derailment site, the locomotive engineer was seated at the control stand of the lead locomotive, short hood forward. The conductor was seated in the first seat of the lead locomotive, opposite the engineer.

Approaching the derailment site, the track is tangent for one-half mile leading into a 3-degree left-hand curve in the direction of travel. This curve is 1,540 feet long. The point of derailment was in this left-hand curve 20 feet north of MP 276.0. The grade through this same track segment is descending in the direction of travel, beginning at 0.83 descending to the point of derailment area that is 0.73 descending. The grade continues to descend for six tenths of a mile before reaching a gradual ascending grade.

NS timetable direction is northward and the geographic direction is eastward. Timetable directions are used throughout this report.

The Accident

Approaching the derailment site, Train R60616 was being operated at a recorded speed of 39 mph. However, at the time of the derailment the train was operated at 38 mph. Both speeds were recorded by the event recorder on the controlling locomotive. The maximum authorized speed for mixed freight trains is 50 mph, as designated by the current NS timetable No. 15, effective July 2003.

The locomotive engineer was operating the train in dynamic brake mode while attempting to slow the train for a 25 mph temporary speed restriction between MP 274.4 and 274.3. However, the train was not slowing as rapidly as the locomotive engineer had anticipated. Therefore, while operating at 39 mph, the locomotive engineer initiated a 23 pound automatic brake pipe reduction before train slack had fully adjusted. Subsequently, train speed reduced to 10 mph before an undesirable emergency application of the train air brakes occurred.

The conductor disembarked the lead locomotive and walked back to assess the train and discovered the 32nd through 60th cars (29 cars) had derailed. The 32nd through the 44th cars derailed, but remained upright. The 45th (covered hopper containing plastic) and 46th cars (tank car containing acrylic acid) derailed and came to rest on their sides on the west side of the track. The 47th car (loaded auto rack) also came to rest on its side on the west side of the track. The 48th car (loaded auto rack) derailed and overrode the 47th car, also coming to rest on the west side of the track. The 49th through 60th cars derailed, but remained upright. There was no release of hazardous material.

Analysis and Conclusion

The engineer made a 23 pound automatic brake pipe reduction at 39 mph, with the locomotive in dynamic braking mode and before the train's slack had fully adjusted. This created buff forces that turned the west rail over, derailing 29 rail cars.

The engineer and conductor submitted to Federal cause drug testing as outlined in 49 CFR Part 219.301(b)(1). The results were negative.

Probable Cause

Buffing or slack action, excessive train handling.