



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-03***


***CSX Transportation (CSX)
Bieber, California
January 17, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 CSX Transportation [CSX]			1a. Alphabetic Code CSX			1b. Railroad Accident/Incident No. R4019845				
2. Name of Railroad Operating Train #2 CSX Transportation [CSX]			2a. Alphabetic Code CSX			2b. Railroad Accident/Incident R4019845				
3. Name of Railroad Responsible for Track Maintenance: CSX Transportation [CSX]			3a. Alphabetic Code CSX			3b. Railroad Accident/Incident No. R4019845				
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 01 17 2006			6. Time of Accident/Incident 10:20:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM				
7. Type of Accident/Incident (single entry in code box) 1. Derailment 4. Side collision 7. Hwy-rail crossing 10. Explosion-detonation 13. Other (describe in narrative) 2. Head on collision 5. Raking collision 8. RR grade crossing 11. Fire/violent rupture 3. Rear end collision 6. Broken Train collision 9. Obstruction 12. Other impacts										
8. Cars Carrying HAZMAT 15		9. HAZMAT Cars Damaged/Derailed 2		10. Cars Releasing HAZMAT 1		11. People Evacuated 0		12. Division Great Lakes		
13. Nearest City/Town New Castle, PA			14. Milepost (to nearest tenth) 57.2		15. State Abbr Code N/A PA		16. County LAWRENCE			
17. Temperature (F) (specify if minus) 45 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2				
21. Track Name/Number Track 17 Ext / Lead			22. FRA Track Code Class (1-9, X) 1		23. Annual Track Density (gross tons in millions) 0		24. Time Table Direction Code 1. North 3. East 4			
OPERATING TRAIN #1										
25. Type of Equipment Consist (single entry) 1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1			26. Was Equipment Attended? 1. Yes 2. No 1		27. Train Number/Symbol Q 641-16		
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 9 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits					30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
29. Trailing Tons (gross tonnage, excluding power units) 3730		31. Principal Car/Unit a. Initial and Number b. Position in Train c. Loaded (yes/no) (1) First involved (derailed, struck, etc) N/A 41 yes (2) Causing (if mechanical cause reported) 0 0 N/A		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs 0 0					33. Was this consist transporting passengers? (Y/N) N/A	
34. Locomotive Units (1) Total in Train 2 0 0 0 0 (2) Total Derailed 0 0 0 0 0		a. Head End b. Mid Train c. Remote d. Manual e. Rear End		35. Cars (1) Total in Equipment Consist 35 0 6 0 0 (2) Total Derailed 3 0 0 0 0		a. Freight b. Pass. c. Freight d. Pass. e. Caboose				
36. Equipment Damage This Consist 101613		37. Track, Signal, Way, & Structure Damage 18050		38. Primary Cause Code H306		39. Contributing Cause Code N/A				
Number of Crew Members				Length of Time on Duty						
40. Engineer/Operators N/A	41. Firemen 1	42. Conductors 1	43. Brakemen 1	44. Engineer/Operator Hrs 10 Mi 21			45. Conductor Hrs 10 Mi 19			
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No 2		50. Was EOT Device Properly Armed? 1. Yes 2. No 2			
Fatal		0	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No		2			
Nonfatal		N/A	0	0						
OPERATING TRAIN #2										
52. Type of Equipment Consist (single entry) 1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1			53. Was Equipment Attended? 1. Yes 2. No 1		54. Train Number/Symbol Q 352-17		
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 5 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track					57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

56. Trailing Tons (gross tonnage, excluding power units)		12160		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0											
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs									
(1) First involved (derailed, struck, etc)		CSXT4 96786		125		N/A						N/A		N/A									
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A											
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose									
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.							
(1) Total in Train		3		0		0		0		0		(1) Total in Equipment Consist		9		0		9		0		0	
(2) Total Derailed		0		0		0		0		0		(2) Total Derailed		0		0		4		0		0	
63. Equipment Damage This Consist		103248		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		H306		66. Contributing Cause Code		N/A									
Number of Crew Members				Length of Time on Duty																			
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor													
1		0		1		0		Hrs 7 Mi 25		Hrs 7 Mi 25													
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?													
Fatal		0		0		0		1. Yes 2. No 1		1. Yes 2. No 1													
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		79. Was EOT Device Properly Armed?													
								1. Yes 2. No		1. Yes 2. No 2													
Highway User Involved				Rail Equipment Involved																			
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code											
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A											
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A											
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A													
				1. North 2. South 3. East 4. West		N/A																	
82. Position				Code		85. Circumstance		Code															
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A															
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code															
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A															
86c. State here the name and quantity of the hazardous materials released, if any.												N/A											
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code							
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes		Code							
		3. Standard FLS		6. Audible		9. Watchman		12. None						2. No									
Code(s)		N/A		N/A		N/A		N/A						3. Unknown		N/A							
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code											
1. Both Sides						1. Yes				1. Yes													
2. Side of Vehicle Approach						2. No		N/A		2. No													
3. Opposite Side of Vehicle Approach				N/A		3. Unknown				3. Unknown													
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code											
0		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing											
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)											
										3. Did not Stop													
97. Driver Passed Standing Highway Vehicle				Code		98. View of Track Obscured by (primary obstruction)		Code															
1. Yes 2. No 3. Unknown				N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A															
						2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed																	
101. Casualties to Highway-Rail Crossing Users				Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code									
				0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A									
								102. Highway Vehicle Property Damage (est. dollar damage)		0		103. Total Number of Highway-Rail Crossing Users (include driver)		0									
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code															
1. Yes 2. No				N/A		1. Yes 2. No		N/A															
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code															
1. Yes 2. No				N/A		1. Yes 2. No		N/A															

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
 HQ-2006-3.bmp



109. SYNOPSIS OF THE ACCIDENT

An inbound CSX freight train was shoving west into a yard track with the front portion of its train when the rear cars struck the side of a second train moving east on an adjacent yard track at 10:20 a.m. on January 17, 2006. The accident occurred at Mile Post BG 57.2 on the Pittsburgh Subdivision in the CSX Rail Yard at New Castle, Pennsylvania.

There were no injuries but 13,000 gallons of sulfuric acid was lost from a heavily damaged tank car. The first train shoving west had 35 loaded cars and 6 empty cars while the second train (moving east) had 78 loaded cars and 74 empty cars. The first train was shoving 41 cars when the rear 3 cars collided with the 125th through 128th cars of the second train. 4 cars were derailed on the 2nd train. A total of 7 cars derailed. Equipment damage was set \$204,861. Track damage was \$ 18,050.

At the time of the accident it was overcast with a light drizzle. The temperature was 45° F.

The accident was caused by failure to protect the leading end of a shoving movement.

110. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of train Q641-16 East included a locomotive engineer, a qualifying locomotive engineer and a conductor. The crew first went on duty at 12:01 a.m. EST January 17, 2006 at CSX Transportation's Collinwood Yard near Cleveland, Ohio. This was the away from home terminal for the crew members, and all had received more than the statutory off duty period prior to reporting for duty.

Their assigned freight train consisted of 2 locomotives, 86 loaded cars of mixed freight and 30 empty cars. Fourteen of the cars were loaded with hazardous material and there was one residue hazardous car. The train was 11,205 feet in length and weighed 6,507 tons. The lead locomotive was CSXT 337 and the 2nd locomotive was CSXT 7690.

The crew had set-off 12 loaded cars at Lordstown, Ohio while en route. Train Q641-16 arrived at New Castle, Pennsylvania with 74 loaded cars and 30 empty cars. The crew was shoving its 41 lead cars west into the rail yard just prior to the accident.

At the time of the accident the engineer was seated at the controls on the south side of the lead locomotive. The conductor was standing on the rear platform of the second locomotive and the qualifying engineer was in the yard office.

The crew of train Q352-17 East included a locomotive engineer and a conductor. The crew first went on duty at 2:55 AM EST at CSX Transportation's Willard Yard near Willard, Ohio. This was the away from home terminal for the crew members, and all had received more than the statutory off duty period prior to reporting for duty.

Their assigned train consisted of 3 locomotives, 78 loaded cars of mixed freight and 74 empty cars. The train had 2 loaded hazardous material cars and 3 residue hazardous cars. The train was 12,160 feet in length and weighed 9,030 tons. The lead locomotive was CSXT 5227, with two additional locomotives CSXT 4834 and CSXT 2700. The crew did not pick-up or set-off any cars enroute.

At the time of the accident the engineer was seated at the controls on the south side of the lead locomotive. The conductor was seated on the north side, rear seat of the lead locomotive.

The crew of train Q641 and Q352 had been working with the same utility employee in New Castle. The utility employee went on duty at 7:59 AM EST on January 17, 2006 at New Castle Yard. The utility employee had received more than the statutory off duty period prior to reporting for duty. The employee was sitting in a vehicle at the west end of New Castle Yard prior to the accident.

The point of impact was at the west end of New Castle Yard where 17 track extension and 9½ track meet (also called N17 Lead and N95) Approximately MP BG 57.2.

THE ACCIDENT

The first train; Q641, was shoving west at 9 MPH on Yard Track 17 and 17 extension just prior to and at the time of the accident.

The second train, Q352, was moving east on Yard Track 9 ½ at a speed of 10 MPH approaching the accident location decreasing to a speed of 5 MPH at the time of

the accident.

Speed recorded by the event recorder of the controlling locomotive on each train. The maximum allowed speed in this area is 10 MPH. Trains must move at a speed that will "permit stopping within one-half the range of vision, short of a train, a car, an obstruction, a derail or an improperly lined switch."

At 9:39 a.m. Train Q641-16 arrived at New Castle and the crew was instructed, via radio, by the yardmaster to pull into the yard and move to the east end of track 1 & 4 where a utility person would make a cut behind the 41 lead cars and assist in lining the switches so the crew could set the lead 35 loaded cars and 6 empty cars on track 17 and 17 extension. The 41 cars were 2351 feet in length with a weight of 2351 tons. The yardmaster instructed the conductor to stay on the train and get off at the UN Interlocking (east end of the yard) to watch for the signal after the lead 41 cars had pulled by.

The utility employee and crew of Train Q641 communicated via radio as the train approached the east end of track 1 & 4. The utility person made the cut behind the lead 41 cars and told the crew to move east.

The conductor dismounted his lead engine at the westward signal at old UN; the engineer pulled the 41 cars east and the conductor stopped the train after the last car pulled by the signal.

The utility person lined the hand-throw switches from 26 track to 17 extension and 17 track, told the crew the switches were lined and instructed Q641 to back-up.

The utility person told the engineer to have the conductor ride the engines. The engineer relayed this information to the conductor via radio because the conductor could not hear the utility person over his hand held radio. The engineer starting shoving west past the signal into the yard; he stopped to pick up the conductor then continued shoving west with the conductor riding the 2nd (west) engine.

The utility person said no one was going the ride the lead end of the cars because the track was clear and the 41 cars would fit as track 17 would hold approximately 70 cars. The utility person said the Q641 crew was to stop their engines at the east end of 17 extension track.

The conductor said his crew was going to shove their cars into 17 track and he assumed the utility person was going to put air on the cars at the west end of the rail yard. The conductor said he thought the utility person was going to ride the shove. (The Q641 crew also had some discussion via radio concerning the conductor closing the air line valve on the east end of the cars and the utility employee opening the air line valve on the west end of the train.)

The utility person, after instructing train Q641 to back up, said he advised train Q 641 he was "out of here" and drove to the west end of the yard to work with eastbound train Q352.

The conductor of train Q641 said he could barely make out a car count over his radio as Q641 train shoved west but said he did hear: "80 cars, 50, 25 and 12 cars." The conductor of Q641 said he thought the car count was for his train.

Train Q641 crew did not stop at the east end of 17 extension; the Q641 continued to shove the 41 cars west the entire length of 17 track, onto 17 extension west into track 9 1/2 striking the side of the 125th through 128th cars of the second train, Q352, which was moving east.

The crew of train Q641 did not realize they had struck train Q352 until they went into emergency. The conductor of train Q641 said he realized the leaking hazardous material car was Q641's car when he walked to his lead engine and looked at his train profile.

Train Q352 arrived at New Castle behind Train Q641. The yardmaster instructed Train Q352 to pull into yard track 9 1/2 from the west end. The utility person was to stop the train to clear the west switch on 9 1/2 track, he was to remove the end of train device (EOT), go forward, make a cut on the train (pull lead cars from rear train cars) and reinstall the EOT device. A yard crew was going to couple to the west end (rear cars) of Train Q352 and remove those cars from the track.

The crew of Train Q352 and yardmaster held a job briefing via radio and the utility person and Q352 crew performed a job briefing via radio. The utility person was giving eastbound train Q352 car counts. The conductor on Q352 said he first heard: "130 cars, 75, 50 cars and then 25 cars" at which time the train (Q352) went into emergency. Train Q352 was slowing at the east end of the yard to line the east end switch on 9 1/2 track at the time of the collision.

The lead or west car of Q641 (41st car from locomotive train) was a loaded tank car containing sulfuric acid. The car, GATX 6416, contained 13,000 gallons of acid. A large hole was torn on the A end, lower right side of the car with most of the acid leaking onto the railroad right-of-way. Two additional cars from Q641 derailed. The 40th car was GATX 69, also a load of sulfuric acid (no leaks) and the 39th car from the engine was CN 407565 a box car loaded with paper.

The 4 cars that derailed on Q352 were all empties. The cars, positioned 125 through 128 from the engines, were CSXT 496786, UTLX 645051, RGCX 776 and HOKX 75013.

Total car damage was \$204,861. Track damage was \$ 18,050.

The equipment was rerailed by R. J. Corman Company and the environmental clean-up was handled by Specialized Professional Services. 13,000 gallons of contaminated acid and ground water was sent to Dupont Chemical Company with the contaminated soil and stone taken to an Ohio Landfill.

ANALYSIS AND CONCLUSIONS

The crew of train Q641 and utility employee were tested following the accident under carrier "cause testing" guidelines. All tests were negative.

No transcript of radio transmissions is available. Yard radio channels are not recorded at this location.

PROBABLE CAUSE AND CONTRIBUTING FACTORS

Proper and thorough job briefings were not conducted by employees when a utility was assigned and released from a train crew.

Employees failed to follow proper radio procedures in connection with backing movements and did not comply with distance to go requirements of radio rules.

It was found, through an investigation by the Federal Railroad Investigation, that the crew of Q641 and utility employee failed to protect the lead end of a shoving movement.