



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-08***

***Amtrak (ATK)
Sprague, Washington
January 28, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Amtrak [ATK]			1a. Alphabetic Code ATK			1b. Railroad Accident/Incident No. 099682			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: Amtrak [ATK]			3a. Alphabetic Code ATK			3b. Railroad Accident/Incident No. 099682			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 01 28 2006			6. Time of Accident/Incident 01:05: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
			13. Other (describe in narrative)			01			
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Northwest	
13. Nearest City/Town Sprague			14. Milepost (to nearest tenth) 44.3		15. State Abbr Code N/A WA		16. County LINCOLN		
17. Temperature (F) (specify if minus) 32 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
21. Track Name/Number Single Main Track			22. FRA Track Code Class (1-9, X) 3		23. Annual Track Density (gross tons in millions) 79.31		24. Time Table Direction Code 1. North 3. East 3		
OPERATING TRAIN #1									
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 2		26. Was Equipment Attended? 1. Yes 2. No 1	
27. Train Number/Symbol A28127			28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 40 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			
29. Trailing Tons (gross tonnage, excluding power units) N/A			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter			0			
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				
(1) First involved (derailed, struck, etc)		N/A	1	N/A	Alcohol		Drugs		
(2) Causing (if mechanical cause reported)		N/A	N/A	N/A	N/A		N/A		
					33. Was this consist transporting passengers? (Y/N) Y				
34. Locomotive Units		a. Head End	Mid Train		Rear End		35. Cars		
			b. Manual	c. Remote	d. Manual	c. Remote	a. Freight	b. Pass.	
(1) Total in Train		1	0	0	0	0	0	4	
(2) Total Derailed		1	0	0	0	0	0	4	
36. Equipment Damage This Consist		121000		37. Track, Signal, Way, & Structure Damage		112168		38. Primary Cause Code T110	
								39. Contributing Cause Code N/A	
Number of Crew Members					Length of Time on Duty				
40. Engineer/Operators N/A		41. Firemen N/A		42. Conductors 1	43. Brakemen 1	44. Engineer/Operator Hrs 4 Mi 28		45. Conductor Hrs 9 Mi 20	
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other		49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal		0	0	0		51. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
Nonfatal		N/A	0	0					
OPERATING TRAIN #2									
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
54. Train Number/Symbol N/A			55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			
			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			0			

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter	N/A			
58. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.						Alcohol	Drugs		
(1) First involved (derailed, struck, etc)		0	N/A	N/A								N/A	N/A		
(2) Causing (if mechanical cause reported)		0	N/A	N/A		60. Was this consist transporting passengers? (Y/N)						N/A			
61. Locomotive Units		a. Head End	Mid Train		Rear End		62. Cars			Loade		Empty		e. Caboose	
			b. Manual	c. Remote	d. Manual	c. Remote				a. Freight	b. Pass.	c. Freight	d. Pass.		
(1) Total in Train		0	0	0	0	0	(1) Total in Equipment Consist			0	0	0	0	0	
(2) Total Derailed		0	0	0	0	0	(2) Total Derailed			0	0	0	0	0	
63. Equipment Damage This Consist		0	64. Track, Signal, Way, & Structure Damage			0	65. Primary Cause Code			N/A		66. Contributing Cause Code			N/A
Number of Crew Members						Length of Time on Duty									
67. Engineer/Operators		N/A	68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator			72. Conductor			
			N/A		N/A		N/A		Hrs 0 Mi 0			Hrs 0 Mi 0			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?			77. Was EOT Device Properly Armed?				
Fatal		0		0		0		1. Yes 2. No N/A			1. Yes 2. No N/A				
Nonfatal		0		0		0		78. Caboose Occupied by Crew?			N/A				
								1. Yes 2. No							
Highway User Involved						Rail Equipment Involved									
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment			3. Train (standing) 6. Light Loco(s) (moving)			Code			
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian						1. Train(units pulling) 4. Car(s)(moving)			7. Light(s) (standing)						
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		N/A		84. Position of Car Unit in Train			2. Train(units pushing) 5. Car(s)(standing)			8. Other (specify in narrative)			N/A		
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		85. Circumstance			1. Rail Equipment Struck Highway User			Code			
				1. North 2. South 3. East 4. West		N/A			2. Rail Equipment Struck by Highway User			N/A			
82. Position		Code		86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?			Code			86b. Was there a hazardous materials release by			Code		
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither			N/A			1. Highway User 2. Rail Equipment 3. Both 4. Neither			N/A		
86c. State here the name and quantity of the hazardous materials released, if any. N/A															
87. Type of Crossing		1. Gates 4. Wig Wags		7. Crossbucks 10. Flagged by crew		88. Signaled Crossing Warning			Code		89. Whistle Ban		Code		
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)		3. Standard FLS 6. Audible 9. Watchman 12. None		(See instructions for codes)			1. Yes 2. No 3. Unknown		N/A				N/A		
Code(s)		N/A N/A N/A		N/A N/A N/A N/A											
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals			Code		92. Crossing Illuminated by Street Lights or Special Lights			Code			
1. Both Sides				1. Yes 2. No 3. Unknown			N/A		1. Yes 2. No 3. Unknown			N/A			
2. Side of Vehicle Approach															
3. Opposite Side of Vehicle Approach		N/A													
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train			Code		96. Driver			Code	
0		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown			N/A		1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative)			N/A	
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)			Code		99. Driver Was			Code		100. Was Driver in the Vehicle?	
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)			N/A		1. Killed 2. Injured 3. Uninjured			N/A		1. Yes 2. No	
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		102. Highway Vehicle Property Damage (est. dollar damage)			0		103. Total Number of Highway-Rail Crossing Users (include driver)			0	
0		0		0			0		0			0		0	
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?			Code		106. Locomotive Headlight Illuminated?			Code		107. Locomotive Audible Warning Sounded?	
1. Yes 2. No		N/A		1. Yes 2. No			N/A		1. Yes 2. No			N/A		1. Yes 2. No	

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-08-
 2006
 Sketch.
 bmp



109. SYNOPSIS OF THE ACCIDENT

At 1:05 a.m. (PST) on January 28, 2006, an eastbound Amtrak (ATK) passenger train, derailed one locomotive and four cars (all equipment in the train). The derailment occurred at Sprague, WA, approximately 35 miles southwest of Spokane, WA, at milepost 44.3 on the BNSF Railway Company's Northwest Division, Lakeside Subdivision.

A total of 86 people including 79 passengers, an un-ticketed Amtrak deadhead employee, as well as three active on board service employees and the active three person Amtrak train crew were evacuated from the train. The passengers and deadhead employee were transported to a local shelter until buses arrived to take them to Spokane, while the active train crew tended the train before being shuttled to Spokane. Two passengers, the conductor and assistant conductor, were taken to a Spokane hospital and given first aid treatment before being released. Both the conductor and assistant conductor sustained minor injuries that met the criteria for FRA reportable injuries. There were no other injuries reported.

There was no hazardous materials involved in the derailment.

The BNSF Railway Company estimated track damage of \$112,168. Amtrak estimated equipment damage of \$121,000.

At the time of the accident it was dark, the weather was mostly clear, with partial overcast sky and the temperature was 32° F.

Evidence found during the accident investigation indicates the rail on the high side of the curve canted outward under the train, due to rail seat abrasion on concrete crossties, creating wide gage.

The probable cause of the derailment was wide gage (due to defective or missing crossties).

110. NARRATIVE

Circumstances Prior to the Accident

The crew of the Amtrak train (symbol A-28-1-27A) included a locomotive engineer, conductor, and an assistant conductor. The locomotive engineer first went on duty at 8:37 p.m., PST, at Pasco, WA, his away from home terminal. The conductor and assistant conductor first went on duty at 3:45 p.m., (PST), at Portland, OR, their home terminal. Prior to reporting for duty, all crew members received a required statutory off duty period.

The eastbound Amtrak train consisted of one locomotive, four occupied passenger cars, was 409 feet in length and weighed 846,000 pounds. The train was traveling from Portland, OR to Spokane, WA, a distance of 384 miles.

The train received all required equipment tests including a Class One Air Brake Test on January 27, in Portland, OR, prior to departure. The train crew also performed a running brake test prior to departure in Pasco WA.

As the train approached the accident site, the locomotive engineer was seated at the controls located on the right (south) side of the locomotive. The conductor and assistant conductor were seated at the conductors table on the left (north) side of the first coach car behind the locomotive. Both the conductor and assistant conductor were performing paper work and monitoring the radio.

Approaching the accident site from the west, traveling east, there is 1689 feet of tangent track that leads into a 4-degree, 0-minute, right hand curve approximately 633 feet in length. The track speed changes from 50 mph to 40 mph at the beginning of this curve, milepost 44.5. Following this curve there is tangent track approximately 264 feet in length, followed by a 6-degree, 0-minute, left hand curve approximately 739 feet in length. The Point Of Derailment (POD) was approximately in the center of the last mentioned 6-degree, 0-minute, curve. After derailing, the train traveled through the rest of the curve and onto tangent track. The lead locomotive of the train came to a stop approximately 874 feet east of the (POD). The grade at the (POD) is .09-percent ascending grade in the eastward direction of travel.

In the accident area, trains operate on a single main track under the authority of a Traffic Control System (TCS). The BNSF's Northwest Division Timetable No. 2, effective November 5, 2003, authorizes a maximum passenger and freight train speed of 40 mph, FRA Class 3 track. The timetable and geographic direction the train was traveling at the (POD) was east, however, after the train continued through the curve and stopped, it was facing in a northeast geographical direction.

The Accident

The locomotive engineer stated that the trip was uneventful approaching the accident site. He also stated that there were no problems with the operation of the train. While approaching and at the time the accident occurred, the train was being operated at 40 mph. This speed was recorded on the locomotive's event recorder.

According to the train crew the accident occurred at approximately 1:05 a.m., PST, which was also recorded on the locomotive event recorder.

During an FRA interview, the engineer stated he felt the rail roll out on the high side of the curve and after he felt the locomotive drop onto the rolled rail, he initiated an emergency brake application, which is confirmed by the locomotive event recorder. After the rail rolled, the wheels on all the equipment on the engineer's side (south side) of the train rode in the web of the rail on the high side of the curve. The rolled rail basically acted as a trough and held the locomotive and passenger cars on the road bed and stopped them from going over the bank and into Sprague Lake. The derailed equipment all remained coupled and upright.

As soon as the train stopped, the engineer broadcasted over the radio "Emergency, Emergency, Emergency!". The BNSF's Fort Worth, TX, dispatcher responded and after speaking with the engineer, began contacting emergency response personnel. The engineer remained in the locomotive, while the conductor began checking passengers and crew members for injuries. The assistant conductor was shaken, but after having a few minutes to gather composure, she began to assist the conductor in assessing the damages.

Emergency response personnel from the Lincoln County Sheriff's Office as well as the Lincoln County Fire District #1 arrived and began to work with the train crew on a plan to transport the passengers to the local Sprague Public School. Two school buses were used to transport the passengers to the school until charter buses arrived to move the passengers to a hotel in Spokane, WA.

Two passengers and the conductor and assistant conductor were taken to a Spokane hospital where they received first aid treatment before being released. All sustained minor injuries.

Analysis

The accident did not meet the requirement for FRA Post Accident Toxicology Testing, as required under Title 49 CFR, Part 219, Subpart C, at the time of the accident. However, both the conductor and assistant conductor later received medical treatment that caused their injuries to meet the criteria for FRA reportable injuries.

An inspection of the data printout from the locomotive event recorder, indicated no unusual events related to train handling.

A thorough mechanical inspection of the derailed equipment, indicated no mechanical defective conditions on either the locomotive or the four passenger cars.

The track was constructed of concrete ties that were installed in 1998, and 141 lb. continuous welded rail (CWR) that was relayed in 2003.

Evidence found during the accident investigation indicates the rail on the high side of the curve canted outward under the train, causing the gage to be out of compliance with the FRA maximum allowable gage of 57-3/4 inches for FRA Class 3 Track. The rail on the high side of the curve showed 1/2 inch of gage side wear. The concrete ties at the (POD) showed as much as 1-inch of rail seat abrasion on the field side of the rail, allowing the rail to cant outward when loaded.

Field observations of the undamaged portion of the curve prior to the POD showed a static gage measurement of 57-1/2 inches in several places. This measurement, combined with the one inch rail seat abrasion would have caused the gage to be at least 58-1/2 inches at the POD. Investigators all agreed that the probable cause of the derailment was wide gage caused by rail seat abrasion on concrete crossties.

BNSF track inspectors conduct and record track inspections in the area of the derailment at more frequent intervals than required by Title 49 CFR Part 213.33. No FRA noncompliant conditions were recorded by BNSF track inspectors in the area of the derailment, six months prior to the derailment.

The BNSF Geometry Car-80 conducted an inspection of the BNSF Lakeside Subdivision on 10/31/2005, which revealed FRA noncompliant wide gage at milepost 44.27. This condition was reported to be corrected on the same day. Also noted during this inspection were six areas of rail cant and two other incipient gage conditions noted between milepost 44.24 and milepost 44.29. This inspection was a follow-up from the BNSF Geometry Car-80 that was conducted on 09/14/2005. During the inspection on 09/14/2005, four areas of rail cant and five incipient gage conditions were noted between milepost 44.23 and milepost 44.30.

On 09/22/2003, the FRA T-16 Geometry car conducted an inspection in the same area.. During this inspection, FRA noncompliant wide gage was found at milepost 44.27 and milepost 44.3.

Between 09/22/2003 and 10/31/2005 twenty incipient gage and rail cant conditions, including two FRA noncompliant gage conditions, were noted by FRA and BNSF geometry cars within a 370 foot segment of track between milepost 44.23 and milepost 44.3.

Conclusion

Following the Amtrak derailment at Home Valley, WA, on 04/03/2005, BNSF created a list of action items in order to prevent future rail seat abrasion derailments. Some of the items listed in the action plan were: visual inspections of all the concrete curves on BNSF's Northwest Division, reviewing data to raise awareness, using geometry car yellow tag data to determine required walking inspections and augmenting visual and mechanical track inspections.

BNSF was not complying with its own written instructions regarding walking all curves on the Northwest Division constructed with concrete ties, or following up on geometry car red and yellow tag defects. As a result of the Amtrak derailment at Sprague, WA, on 01/28/2006, BNSF issued General Order Number 27, on 02/03/2006, changing the instructions specific to the remediation of rail cant defects on concrete ties. BNSF also issued a newsletter on 02/02/2006 regarding the correction of geometry car red and yellow tag defects.

There has been a task force created to better understand the mechanism of concrete crosstie rail seat abrasion failure, study the effects of computer simulation of F 42 Amtrak locomotives versus other locomotive types, and develop automated means to detect rail seat abrasion.

Probable Cause

Through an inspection by the Federal Railroad Administration, evidence found indicates the rail on the high side of the curve canted outward under the train, due to rail seat abrasion on concrete crossties, creating the wide gage that was determined to be the probable cause of the derailment.