



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-12***


***Amtrak (ATK)/CSX Transportation (CSX)
Boca Raton, Florida
February 22, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 CSX Transportation [CSX]		1a. Alphabetic Code CSX		1b. Railroad Accident/Incident No. 000021190		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A		
3. Name of Railroad Responsible for Track Maintenance: CSX Transportation [CSX]		3a. Alphabetic Code CSX		3b. Railroad Accident/Incident No. N/A		
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 03 Day: 17 Year: 2006		6. Time of Accident/Incident 02:35: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
				13. Other (describe in narrative) 09		
8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed 0	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division Florence		
13. Nearest City/Town Laurens		14. Milepost (to nearest tenth) AK554.9	15. State Abbr Code N/A SC	16. County LAURENS		
17. Temperature (F) (specify if minus) 62 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
21. Track Name/Number single main		22. FRA Track Code Class (1-9, X) 3	23. Annual Track Density (gross tons in millions) 34	24. Time Table Direction Code 1. North 3. East 2		
OPERATING TRAIN #1						
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 8		
				26. Was Equipment Attended? 1. Yes 2. No 1		
				27. Train Number/Symbol F224-17		
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 20 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) N/A		k N/A N/A N/A N/A				
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)		
(1) First involved (derailed, struck, etc)		N/A	1	no		
(2) Causing (if mechanical cause reported)		N/A	N/A	N/A		
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs N/A		
				33. Was this consist transporting passengers? (Y/N) N/A		
34. Locomotive Units		a. Head End	b. Mid Train Manual	c. Rear End Remote	35. Cars	
					a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
(1) Total in Train		1	0	0	(1) Total in Equipment Consist 0 0 0 0 0	
(2) Total Derailed		0	0	0	(2) Total Derailed 0 0 0 0 0	
36. Equipment Damage This Consist 500		37. Track, Signal, Way, & Structure Damage 0		38. Primary Cause Code H405		
				39. Contributing Cause Code N/A		
40. Engineer/Operators N/A			41. Firemen N/A			
42. Conductors 1			43. Brakemen N/A			
44. Engineer/Operator Hrs 8 Mi 35			45. Conductor Hrs 8 Mi 35			
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other		
Fatal		0	0	0		
Nonfatal		N/A	0	0		
				49. EOT Device? 1. Yes 2. No 2		
				50. Was EOT Device Properly Armed? 1. Yes 2. No N/A		
				51. Caboose Occupied by Crew? 1. Yes 2. No 2		
OPERATING TRAIN #2						
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 9		
				53. Was Equipment Attended? 1. Yes 2. No 2		
				54. Train Number/Symbol N/A		
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs	
(1) First involved (derailed, struck, etc)		OTE75281		1		no				N/A		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A	
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loaded		Empty	
		b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass.	
(1) Total in Train		0		0		0		0		(1) Total in Equipment Consist		0	
(2) Total Derailed		0		0		0		0		(2) Total Derailed		0	
63. Equipment Damage		This Consist		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code	
0												N/A	
Number of Crew Members						Length of Time on Duty							
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor			
0		0		0		0		Hrs 0 Mi 0		Hrs 0 Mi 0			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?			
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		0		0		0		78. Caboose Occupied by Crew?				N/A	
								1. Yes 2. No					
Highway User Involved						Rail Equipment Involved							
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code	
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A	
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A	
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A			
				1. North 2. South 3. East 4. West		N/A							
82. Position				Code		85. Circumstance		Code					
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A					
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code					
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A					
86c. State here the name and quantity of the hazardous materials released, if any.													
N/A													
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		89. Whistle Ban	
Code(s)		N/A		N/A		N/A		N/A		N/A		1. Yes	
												2. No	
												3. Unknown	
												N/A	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code			
1. Both Sides				1. Yes		N/A		1. Yes		N/A			
2. Side of Vehicle Approach				2. No				2. No					
3. Opposite Side of Vehicle Approach		N/A		3. Unknown				3. Unknown				N/A	
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code	
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing	
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)	
										3. Did not Stop		N/A	
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code							
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A							
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed									
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code	
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes		2. No	
										103. Total Number of Highway-Rail Crossing Users (include driver)		N/A	
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No		N/A		1. Yes 2. No		N/A							
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No		N/A		1. Yes 2. No		N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-14-
2006
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On March 17, 2006, at 2:35 p.m. Eastern standard Time (EST), CSX Train No. F224-17, operating as a light locomotive in a southward direction on the CSX Spartanburg Subdivision, struck a CSX maintenance-of-way (M/W) hi-rail vehicle and pushed it into a second M/W vehicle at milepost (MP) AK554.9. The accident occurred in Laurens, South Carolina (SC) on a single main track on the approach of a deck plate girder bridge. The accident included one locomotive and two M/W vehicles. None of the equipment derailed. One M/W vehicle was completely destroyed, and the second sustained moderate damage. The locomotive sustained minor damage.

There were no injuries and no evacuation ordered. Equipment damages totaled \$100,500. The weather at the time of the accident was daylight, clear and 62°F.

The cause of this accident is the failure of the engineer and conductor of Train F224-17 to stop at the Irby Block Sign. In addition, the train crew failed to stop at the Form W conditional stop sign placed at MP AK555.07 by the CSX M/W foreman.

110. NARRATIVE

Train F224-17

The crew of CSX F224-17 included a locomotive engineer and a conductor. They went on duty at 6 a.m. March 17, 2006, at the CSX Spartanburg Yard in Spartanburg, SC. This is the home terminal for both crew members who had received more than the required statutory off duty time. They were assigned to operate CSX Locomotive 528, which would be used as helper power for trains operating between Spartanburg and Hunter Junction. Following a job briefing and locomotive inspection, Locomotive 528 coupled to the rear of Train N130-14, a loaded coal train. Train N130-14 completed a terminal train air test and received authority from the train dispatcher to occupy the Arkwright and Roebuck Blocks, and departed Spartanburg Yard at 8:45 a.m.

The train stopped at the south Roebuck Block Sign, six miles south of Spartanburg for opposing traffic. At 11:52 a.m., they received the Tyger Block and proceeded southward toward Hunter Junction. At 12:50 p.m., Train N130-14 stopped at Hunter Junction to allow Locomotive 528 to uncouple and receive authority to operate as Train F224-17 in the Hunter Block, joint with Train N130-14. Train N130-14 continued southward on the Spartanburg Subdivision to the CN&L Subdivision. At 2:18 p.m., F224-17 received an authority for the Hunter and Laurens Blocks to proceed south to MP AK552.2, where the Irby Block begins. This was the last conversation between the dispatcher and Train F224-17 prior to the collision.

As Train F224-17 traveled south, the locomotive engineer was seated at the controls on the east side of the locomotive and the conductor was seated on the west side. The locomotive was being operated with the long end facing southward.

Approaching the accident site from MP AK555.4 there is tangent track for 1,000 ft., leading into a 6-degree, 22-minute left hand curve. This is followed by 240 ft. of tangent track at the north end of a deck plate girder bridge and continues over the bridge. The grade between MP AK555.4 and AK554.9 is a 1.65-percent descending grade. The Irby Block Sign is located at MP AK555.2 on the east side of the track, 105 ft. south of the Flemming Street public road crossing. The sight distance around the curve is obscured by large trees and vegetation growing on both sides of the track. A second public road crossing, Riverside Street, crosses the track at MP AK555.07 and is in the curve.

Maintenance of Way Crews

The M/W crew at Laurens included a foreman, a machine operator, and two trackmen. The welding crew consisted of a welder and a welder helper. They went on duty at 7 a.m., March 17, 2006, at the M/W headquarters in Laurens. The planned work for both crews was to repair internal rail defects identified by the Sperry Rail Service Test Truck No. 952 found on the previous day.

At 7:42 a.m. the foreman of the section crew verified with the dispatcher that their on-track protection, CSX Rule 707, Form W-Conditional Stop was in effect. Their Form W limits were within the Irby Block, between MP AK547.6 and AK555.0. Following a job briefing, the two crews went to MP AK 549.8 to begin repair of the first rail. At 11:47 a.m., the M/W foreman gave permission to CSX Locomotive 420, Train N337-09, to enter the south limits of his Form W, with the understanding that they would not move beyond the north switch of Irby Yard at MP AK 553.9.

