

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2006-14

CSX Transportation (CSX) Laurens, South Carolina March 17, 2006

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TR FEDERAL RAILROAD	ANSPORT	ATION RATIO	N FRAFA	ACTUA	LRA	ILROAD A	ACCIDENT	REPOR'	Г	I	FRA File	e # <u>HQ-20</u>	06-1	4		
1.Name of Railroad Operatin CSX Transportation [CS2	ng Train #1 X ]			1a. Alphabe	1b. 1	. Railroad Accident/Incident No. 000021190										
2.Name of Railroad Operatin	ng Train #2			2a. Alphabet	2b. R	Railroad Accident/Incident										
N/A							N/A									
3.Name of Railroad Respons	ible for Track	c Mainte	enance:		3a. Alphabe	ic Code		3b. 1	Railroad A	ccident/I	ncident No					
CSX Transportation [CS2	X ]				CSX				0000211	90						
4. U.S. DOT_AAR Grade Ci	rossing Identi	fication	Number	5. Date of A	cident/Incident	Veen	6. T	ime of Ac	cident/In	cident						
						Month 03	Day 17	2006 Year		02:35: AM V PM						
7. Type of Accident/Indicent	t 1. Derailn	nent	4. Side c	ollision		7. Hwy-rai	crossing 1	0. Explosion	on-detonation 13. Other							
(single entry in code box)	2. Head or	n collisio	on 5. Raking	g collision	I	8. RR grad	e crossing 1	1. Fire/viole	ent rupture (describe in narrative)							
	3. Rear en	nd collisi	on 6. Broke	n Train co	ollision	9. Obstruct	ion 12	2. Other imp	acts			/		09		
8. Cars Carrying	Cars Carrying 9. HAZMAT Cars					g	11. People	11. People			12. Divis	ivision				
HAZMAT 0 Damaged/Derailed			0	HAZMA	.1	0			0 Flor			e				
13 Nearest City/Town	1			14. Mile	epost		15. State		5 County							
15. Realest City/10wi	Laurens			(to n	nearest te	enth) K 554 Q	Abb	or Code			LAURENS					
17. Tomporoturo (E)			· · · · · · · · · · · · · · · · · · ·		A	KJJ4.9	N/A	sc		1	EAUKENS					
(specify if minus)	18. V1s1b1	ility ( Dawn	single entry) Code 19. V 3 Dusk			Veather (sing	le entry)	(y) Code			20. Type of Track			Code		
(specify if minus) 62 F	2. [	Dav	4.Dark	2	2	Cloudy 4 I	For 6 Snow	5.Sleet 1			an 3.8 ard 4 Iu	3. Siding 4. Industry		1		
21. Track Name/Number				22. FRA	Track	Code	23. Annual Tr	3. Annual Track Density			ne Table Direction			Code		
		•	Clas	s (1-9, X		(gross tor	is in		1. North 3. East				code			
	SI	ngie ma	1n			3	millions)	4	2. South 4. West 2							
					OPER	ATING TR	AIN #1			-						
25. Type of Equipment	1. Freight tra	in 4	. Work train 7.	. Yard/swi	itching	A. Spec. M	oW Equip. Cod	e 26. Was	Equip	ment C	Code 2	27. Train Nu	ımbeı	r/Symbol		
Consist (single entry)	2. Passenger	o(s).		1.0	Atte	ended?										
	3. Commuter	train 6	Cut of cars 9.	. Maint./in	ispect.ca	r	8	Yes	2. No F224-17							
28. Speed (recorded speed,	if available)	Code	30. Method(s)	of Operation	on (	enter code(s	) that apply)		30a. Remotely Controlled Locomotive?							
R - Recorded		D	b. Auto train	. Curren	t of traffic	n. Other than r		0 = Not a remotely controlled								
E - Estimated 20	MPH	К	c. Auto trair	i stop i.	. Time ta	ble/train order	ble/train orders o. Positive train control					2 = Remote control tower				
29. Trailing Tons (gross t	onnage,	Track w	arrant control	p. Other (Spe	cifv in narra	(ative) 3 = Remote control										
excluding power units)	k	. Direct	rect traffic control Code(s)				transmitter - more than one									
	N/A		f. Interlocking	g 1.	Yard lin	nits	k N/A	N/A N/A	N/A	remote	control tra	ansmitter		0		
31. Principal Car/Unit	a. Initial a	nd Num	ber b. Positio	on in Trair	n c. I	Loaded(ves/no	32. If railroa	d employee(	s) teste	ed for drug	z/alcohol	use,				
(1) First involved							enter the	e number tha	t were	positive i	n	Alcoho		Drugs		
(derailed, struck, etc)	ſ	N/A		1		no	the appr	opriate box.				0		N/A		
(2) Causing (if mechanic	al	0		0		N/A	N/A 33. Was this			ing passen	gers? (Y/	Y/N)		N/A		
34. Locomotive Units	М	fid Train	Re	ar End	35. Ca	rs		Lo	aded	E	Empty					
	End b. Ma		al c. Remote	d. Manua	1 c. Rer	note		a. F	reight	b. Pass.	c. Freig	ht d. Pass.	e. (	Caboose		
(1) Total in Train	1	0	0	0	0	(1) Tota	(1) Total in Equipment Co		0	0	0	0	_	0		
(2) Total Derailed	0	0	0	0	0	(2) Tota	l Derailed		0	0	0	0		0		
50. Equipment Damage	¢700.00	37.	. Track, Signal, V	Way,	¢0.00	38. Prin	nary Cause			39. Cont	ributing (	Cause	_			
This Consist	\$500.00	8	& Structure Dam	age	\$0.00	Code	H404 Code									
	Number	of Crew	/ Members	nbers			Len				gth of Time on Duty					
40. Engineer/ 41. F Operators	42	42. Conductors 43. Brakemen			44. Engineer/Operator				45. Conductor				25			
1		1 0				Mi	MI 35									
Casualties to: 46. Ra	ilroad Employ	yees 47.	7. Train Passengers 48. Other			49. EO	Γ Device?		50. Was EOT Device Properly Armed?							
Fatal	0 0				0	1. Yes 2. No			1. Yes 2. No N/A							
Nonfatal N/A			0 0			51. Caboose Occupied by Crew? 1. Yes 2.				Jo   2						
OPERATING TRAIN #2																
OPERATING I KAIN #2																
Consist (single entry)	o(s).	A. Spec. Mo	w Equip. Cod	Atter	nded?	1? Code 54. Train Number/Sy				symbol						
Consist (single entry)	3. Commuter	train 6.	. Cut of cars 9. Maint./inspect.car			r	9 1. Y				2. No 2 N/A					
55. Speed (recorded speed,	if available)	Code	57. Method(s)	of Operation	on (	enter code(s	) that apply)		-	57a. Rem	otely Cor	ntrolled Loc	comot	tive?		
R - Recorded	. Autom	atic block	0 = Not a remotely controlled													
E - Estimated 0 MPH R b. Auto train control h. Current of traffic n. Other than main track 1 = Remote control										ol portable						

DEPARTME FEDERAL RA	NT OF T AILROAI	'RAN D AD	ISPORT MINIST	FATI FRAT	ON TION	FRA F	ACTUA	AL RAILI	ROAD AC	CIE	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>6-14</u>		
56. Trailing Tons (gross tonnage, excluding power units)   N/A					c. d. e.	c. Auto train stop i. Time table/tr d. Cab j.Track warran e. Traffic k. Direct traffic f. Interlocking I. Yard limits				in orders o. Positive train control control p. Other (Specify in narrative) Code(s) k N/A N/A N/A N/A N/A					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter				
58 Principal Car/Unit a Initial and Nu						mber b. Position in Train c. Loa				50. If railroad amployee(s) tostad for drug/slocksl use									
(1) First involved					201			aca(yes/no)	enter the number that were positive in <u>Alcoho</u>							Drugs			
(derailed, struck, etc) OTE7528					281				no	the appropriate box. N/A									
(2) Causing (if mechanical cause reported) 0						0			N/A 60. Was this consist transporting passengers? (Y/						gers? (Y/N	[)	N/A		
61. Locomotive U	Units	a. Head End b. Mar			Mid Ianual <sub>I</sub>	Mid Train nual c. Remote d.		ear End al   c. Remote	62. Cars	Cars Loaded Empty a. Freight b. Pass. c. Freight d. Pas						npty   d. Pass.	e. Caboose		
(1) Total in Train			0	0		0	0	0	(1) Total in	1 Equipment Consist 0			0	0	0	0	0		
(2) Total De	) Total Derailed 0		0	0 0		0	(2) Total E	2) Total Derailed (			0	0	0	0	0				
63. Equipment Da This Consis	ent Damage \$0.00					ack, Signal, Structure D	Way, amage	\$0.00	65. Primar Code	65. Primary Cause Code N/A Code 66. Contributing Cause						iuse	N/A		
	Numbe	r of C	rew Me	embers					Length of	Time on D	uty								
67. Engineer/	68.	. Firer	nen		69. Co	nductors	70. Bi	rakemen	71. Engin	71. Engineer/Operator 72. Conductor							NC -		
Operators (	0 0					0		0		Hrs 0 Mi 0					Hrs 0				
Casualties to:	73. I	Railro	ad Emplo	oyees	74. Tra	in Passenge	rs 75. Ot	ther	76. EOT E	evice	?			77. Was	Armed?				
Fatal			0			0		0	1. Y	1. Yes 2. No N/A 1. Yes 2. No							N/A		
Nonfatal			0			0	_	0	78. Caboo	ose Oc	cupied b	y Crew	v?		N/A				
								0		1. Yes 2. No Poil Equipment Involved									
79. Type	ay U	ser mv	olved		C - 1-	83. Equip	Kall Equipment Involved 83. Equipment												
C. Tru	Motor Vel	nicle	3.Train (standing) 6.Light Loco(s) (moving)									Code							
B. Truck E. Va	estrian er (spec. in	narrative)	N/A	N/A 2.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative)															
80. Vehicle Spe	geograph	ical)	Code	84. Positio	84. Position of Car Unit in Train														
(est. MPH	orth 2.S	outh 3.East	4.West	N/A		N/A													
82. Position	C			а ·	Code	85. Circun	istanc	ent Struc	k High	way User				Code					
4. Trapped	ing 3.N	loving Ove	r Crossing	N/A	2. Rail Ed	quipm	ent Struc	k by H	lighway Use	er			N/A						
86a. Was the highway user and/or rail equipment involved								Code	86b. Was t	here a	a hazardo	ous mat	erials releas	e by			Code		
in the impa	act transpo	orting	hazardou	ıs ma	terials?			• N/A	1 High	way I	lear 2	Dail F	auinment	3 Both	1 Neithe	r	N/A		
1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A 1. Highway User 2. Rail Equipment 3. Both 4. Neither														IN/A					
oue. State here un		iu qua	unity of t	ine na	zaruous	materials i	cicascu, ii	N/A											
87. Type of 1	.Gates		4.Wig	g Wag	<u>zs</u>	7.Cros	sbucks 1	0.Flagged by	r crew	88. S	ignaled (	Crossin	g Warning	Code	89. Whis	tle Ban	Code		
Crossing 2 Worping	ffic sign	als 8.Stop	signs 1	1.Other (spe	c. in narr.)	(5	See instru	ctions	for codes)		1. Ye	s							
Warning 3	$\begin{array}{c c} \hline \\ \hline $						nman I	2.INONE	NT/A					N/A	3. Un	, iknown	N/A		
Code(s)	IN/A		A	IN/	A	N/A Codo	91 Cross	ing Warning	2 Interconnected Code 92 Crossing Illuminated by Street							Code			
1. Both Sides								n Highway Si	gnals		Coue		Lights or Special Lights						
2. Side of Vehicle Approach							1	1. Yes 2 No		I			1. Yes 2 No						
3. Opposite Side of Vehicle Approach						N/A	3	3. Unknown	N/A 2. NO 3. Unk					own	N/A				
93. Driver's 94. Driver's Gender Code 95. Driver Drove Behind								or in Front of Train Code 96. Driver						on Crossin	Code				
Age 1. Male 2. Female N/A						and Struck or was Struck by Second T1. Yes2. No3. Unknown				2. Stopped and then Proceeded 5. Other (specify in narrative)							g N/A		
97. Driver Passed Standing Code 98. View of Track Obscured by (									(primary obstruction)										
Highway Vehicle 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)   1. Veg 2 No. 2. Unknown N/A 2. Standing Beilaged Equipment 4. Turnworknown 6. With the other state													NT/A						
1. Yes 2. No 3. Unknown 10/A 2. Standing Railroad Equ   101. Casulties to Highwav-Rail 00 Dreven								quipment 4. Topography b. Highway Vehicle 8. Not obstructed   Driver Was Code 100 Was Driver in the Vabiala?							Code				
Crossing Users Killed					d	Injured 99. Driver Was 1. Killed 2.Injure			Uninjured   N/A				100. was L 1. Ye	N/A					
N/A N/A 10							102. High	Highway Vehicle Property Damage 103					103. Total 1	otal Number of Highway-Rail Crossing Users					
IVA     IVA     (est. dollar damage)     N/A     (include driver)     N/A       104     Locomotive Auxiliary Lights?     Code     105     Locomotive Auxiliary Lights?     N/A													Code						
1. Yes	s rusinal y	Ligit	2. No	)				N/A	105. Locol	Yes	c Auxilla	iy Ligi	2. No	1141 /			N/A		
106. Locomotive Headlight Illuminated?								Code	107. Locomotive Audible Warning Sounded?						Code				
1. Yes 2. No								N/A	1.	1. Yes 2. No							N/A		

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. HQ-14-2006 sketch.jpg



#### 109. SYNOPSIS OF THE ACCIDENT

On March 17, 2006, at 2:35 p.m. EST, CSX Train No. F224-17, operating as a light locomotive in a southward direction on the CSX Spartanburg Subdivision, struck a CSX Maintenance-of-Way (MofW) hi-rail vehicle and pushed it into a second MofW vehicle at milepost (MP) AK554.9. The accident ocurred in Laurens, South Carolina (SC) on a single Main Track on the approach to a thru girder deck plate bridge. The accident included one locomotive and two MofW vehicles. None of the equipment derailed. One MofW vehicle was completely destroyed, and the second vehicle sustained moderate damage. The locomotive sustained minor damage.

There were no injuries and no evacuation ordered. Equipment damages totaled \$100,500. The weather at the time of the accident was daylight, clear and 62°F.

The cause of the accident is the failure of the engineer and conductor of CSX Train F224-17 to stop at the Irby Block Sign. In addition, the train crew failed to stop at the Form W Limits conditional stop sign placed at MP AK555.07 by the CSX MofW foreman.

#### 110. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

CSX TRAIN F224-17

The crew of CSX F224-17 included a locomotive engineer and a conductor. They went on duty at 6:00 a.m. March 17, 2006, at the CSX Spartanburg Yard in Spartanburg, SC. This is the home terminal for both crew members and both received more than the required statutory off duty time. They were assigned to operate CSX Locomotive # 528, which would be used as helper locomotive power for trains operating between Spartanburg and Hunter Junction. Following a job briefing and locomotive inspection, Locomotive # 528 coupled to the rear of CSX Train N130-14, a loaded coal train. CSX Train N130-14 completed a terminal train air brake test and received authority from the train dispatcher to occupy the Arkwright and Roebuck Blocks, and departed CSX Spartanburg Yard at 8:45 a.m.

The train stopped at the south Roebuck Block Sign, six miles south of Spartanburg to meet and pass opposing rail traffic. At 11:52 a.m., the crew received permission to occupy the Tyger Block and proceded southward toward Hunter Junction. At 12:50 p.m., CSX Train N130-14 stopped at Hunter Junction to allow Locomotive # 528 to uncouple and receive authority to operate as CSX Train F224-17 in the Hunter Block, jointly with CSX Train N130-14. CSX Train N130-14 continued southward on the Spartanburg Subdivision to the CN&L Subdivision. At 2:18 p.m., CSX Train F224-17 received an authority for the Hunter and Laurens Blocks to proceed south to MP AK552.2, where the Irby Block begins. Both crew members stated in the "Report of Interview" that they were aware and familiar with the 707 in effect ahead of them. This was the last conversation between the dispatcher and CSX Train F224-17 prior to the collision.

As CSX Train F224-17 traveled south, the locomotive engineer was seated at the controls on the east side of the locomotive and the conductor was seated on the west side. The locomotive was being operated with the long nose end facing southward.

Approaching the accident site from MP AK555.4 there is tangent track for 1,000 ft., leading into a 6-degree, 22minute left hand curve. This is followed by 240 ft. of tangent track at the north end of a thru girder deck plate bridge and continues over the bridge. The grade between MP AK555.4 and AK554.9 is a 1.65-percent descending grade. The Irby Block Sign is located at MP AK555.2 on the east side of the track, 105 ft. south of the Flemming Street public road crossing. The sight distance around the curve is obscured by large trees and vegetation growing on both sides of the track; however train crew members acknowledged that excess vegetation was not an issue and did not obscure their vision in observing the advance 707 warning signs placed by the MofW employees. A second public road crossing, Riverside Street, crosses the track at MP AK555.07 and is in the curve.

# MAINTENANCE OF WAY CREWS:

The MofW crew at Laurens included a foreman, a machine operator, and two trackmen. The welding crew consisted of a welder and a welder helper. They went on duty at 7:00 a.m., March 17, 2006, at the CSX MofW headquarters in Laurens. The planned work for both crews was to repair internal rail defects identified by the Sperry Rail Service Test Truck No. 952 on the previous day.

At 7:42 a.m. the foreman of the section crew verified with the dispatcher that their on-track protection, CSX Rule 707, Form W-Conditional Stop was in effect. The Form W limits were within the Irby Block, between MP AK547.6 and AK555.0. Following a job briefing, the two crews went to MP AK 549.8 to begin repair operations of the first rail. At 11:47 a.m., the MofW foreman gave permission to CSX Locomotive # 420, CSX Train N337-09, to enter the south limits of his Form W Authority, with the understanding that they would not move beyond the north switch of Irby Yard at MP AK 553.9.

At approximately 2:15 p.m., the MofW foreman held a briefing with both crews prior to occupying the Main Track at MP AK554.6. After the briefing, the welding truck (OTE 75281) was placed on the Main Track facing northward and hi-railed to MP AK554.9, which is beyond the north end of the bridge. The section truck (OTE 74145) was placed on the Main Track facing the south and hi-railed in a backing direction toward the bridge, the section foreman overheard a train crew member announce over the radio that they were entering the Laurens Block in a southward direction.

The welding crew was standing behind their truck, and the section crew was standing behind their truck. The section crew was getting tools from their vehicle in preparation for rail repair. One section crew member remained in the truck.

The CSX timetable direction of travel was south. Geographic direction at the accident site was west. Timetable directions are used throughout this report.

# THE ACCIDENT

CSX Train F224-17 was being operated at 26 miles per hour (mph) approaching the accident site; maximum authorized speed for light locomotives is 30 mph. The engineer said he was standing up to operate the radio, using channel # 58 as he attempted to call the dispatcher requesting authority to enter the Irby Block. He sounded the locomotive whistle for the Flemming Street crossing at MP AK555.25, and proceeded southward over the crossing into the Irby Block. The conductor and engineer stated that they did not see the Irby Block Sign as a result of operating the train locomotive with the long nose forward thereby lessoning the window of view as the train operated in the curve. As the train crossed Riverside Street, MP AK555.07, the engineer turned to sit down and observed two MofW vehicles on the track ahead of him. He then placed the locomotive into an emergency train air brake application. The train passed the red conditional stop sign placed on the west side of the track at MP AK555.07 and impacted the welding truck at MP AK554.9. As a result of the impact, the train pushed the welding truck 182 ft. which in turn impacted the section truck, pushing both vehicles an additional 32 ft. south before stopping on the bridge.

Moments before CSX Train F224-17 entered the Irby Block, the section foreman and machine operator heard the train whistle. The foreman said he had not been contacted by any train crew members requesting authority to enter his Form W. territory. He returned to the section truck and by use of the company radio on channel 32 attempted to contact the train operating in the Laurens Block. At this same moment he observed CSX Train F224-17 in his rear view mirror. Simultaniously, the machine operator told the welders to clear the Main Track and retreat to a safe location. The foreman and trackman exited the truck and began running on the bridge walkway toward the south end of the bridge. The machine operator and second trackman ran off the north end

of the bridge to the west side. The welder and welder helper, who were already off the bridge, ran in a westerly direction. The track foreman and trackman were still on the bridge at the time of impact.

When the train came to a stop, the conductor exited the locomotive cab to check on the MofW people. The engineer made an emergency call on the radio to the dispatcher informing him of the collision and the location of the accident.

There were no injuries resulting from the collision. The locomotive and hi-rail vehicles remained upright and on the rail. The welding truck released an estimated 30 gallons of hydraulic fluid as a hydraulic hose was severed upon impact. The fluid dropped to a grass-covered area below the bridge. CSX notified Heapaco Environmental Services of the spill.

The bridge is a thru girder deck plate bridge, 385 feet in length, 35 feet high, with a walkway and hand rails on the west side, and spans Gordan Street and the Little River Creek. A public walking trail passes under the south end of the bridge.

Drug and alcohol testing of CSX Train F224-17 crew was conducted by CSX. The test results were negative.

#### ANALYSIS:

CSX Train F224-17 usually operates between the Spartanburg Yard and the Ora Block. The crew had operated in this location 7 or 8 trips; however pushing trains to Hunter Junction and continuing south to the Irby Block was beyond their normal job assignment. Operating the locomotive with the long nose forward was another unusual circumstance. The conductor and engineer expressed some frustration from the inability to contact the dispatcher throughout the day and both stated that this frustration added to distraction of operating the train.

The Federal Railroad Administration (FRA) determined that all permanent and temporary track side signs, as viewed from a locomotive cab, were unobstructed.

FRA obtained fatigue related information, including a 10-day work history, for all the employees involved in this incident. FRA concluded fatigue was not probable for any of these employees.

CSX Florence Division Timetable No. 4, effective January 1, 2005, designates Direct Traffic Control (DTC) as the type of authority for movement on the main track on the Spartanburg Subdivision. DTC divides the Main Track into sections called blocks. At 2:18 p.m., CSX Train F224-17 was issued DTC authority No. 54078 for southward movement in the Hunter and Laurens Blocks, but not the Irby Block.

On March 17, 2006, a CSX Rule 707 with working limits between MP AK547.6 and MP AK555.0 during the hours of 8:30 a.m. and 5:30 p.m., authority No. 16086 was issued to the CSX MofW foreman at 7:42 a.m. All temporary track signs that are required by CSX Rule 707 were in place.

# CONCLUSION:

The CSX MofW employees were in full compliance with CSX Operating Rules and FRA Regulations for Roadway Workers.

# PROBABLE CAUSE:

The cause of this accident, as determined by the FRA, was the failure of the crew of CSX Train F224-17 to stop at the Irby Block Sign. In addition, the train crew failed to stop at the Form W conditional stop sign placed at MP AK555.07 by the CSX MofW track foreman.