



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-34***

***Norfolk Southern (NS)  
Loudon, Tennessee  
May 22, 2006***


***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS ]			1a. Alphabetic Code NS			1b. Railroad Accident/Incident No. D025253		
2. Name of Railroad Operating Train #2 Norfolk Southern Corp. [NS ]			2a. Alphabetic Code NS			2b. Railroad Accident/Incident D025253		
3. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS ]			3a. Alphabetic Code NS			3b. Railroad Accident/Incident No. D025253		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 05 22 2006			6. Time of Accident/Incident 02:07: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision		
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
			13. Other (describe in narrative)			02		
8. Cars Carrying HAZMAT 2		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Central
13. Nearest City/Town Loudon			14. Milepost (to nearest tenth) 160		15. State Abbr Code N/A TN		16. County LOUDON	
17. Temperature (F) (specify if minus) 66 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2		
21. Track Name/Number Blair Bend Lead			22. FRA Track Code Class (1-9, X) 1		23. Annual Track Density (gross tons in millions) 0		24. Time Table Direction Code 1. North 3. East 1	
<b>OPERATING TRAIN #1</b>								
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 7		26. Was Equipment Attended? 1. Yes 2. No 1
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 11 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		
29. Trailing Tons (gross tonnage, excluding power units) 3050			30. Method(s) of Operation (enter code(s) that apply) m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0		
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A	1	no	Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0	0	N/A	N/A		N/A	
33. Was this consist transporting passengers? (Y/N)		N/A						
34. Locomotive Units		a. Head End	b. Mid Train		c. Rear End		35. Cars	
			b. Manual	c. Remote	d. Manual	c. Remote		
(1) Total in Train		1	0	0	0	0	(1) Total in Equipment Consist	
(2) Total Derailed		1	0	0	0	0	(2) Total Derailed	
		2	0	15	0	0		
36. Equipment Damage This Consist		120200		37. Track, Signal, Way, & Structure Damage		875		38. Primary Cause Code H607
								39. Contributing Cause Code H404
Number of Crew Members				Length of Time on Duty				
40. Engineer/Operators N/A	41. Firemen 0	42. Conductors 1	43. Brakemen 1	44. Engineer/Operator Hrs 6 Mi 7			45. Conductor Hrs 6 Mi 7	
Casualties to:	46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No 2			50. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
Fatal	0	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No			N/A	
Nonfatal	N/A	0	0					
<b>OPERATING TRAIN #2</b>								
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		53. Was Equipment Attended? 1. Yes 2. No 1
54. Train Number/Symbol 44ET52			0					
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 5 MPH R			57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic m. Special instructions n. Other than main track		
						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons (gross tonnage, excluding power units)		9021		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol N/A		Drugs N/A			
(1) First involved (derailed, struck, etc)		NS9203		1		no											
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A					
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose			
(1) Total in Train		4		0 0		0 0		(1) Total in Equipment Consist		70 0		0 0		0 0			
(2) Total Derailed		1		0 0		0 0		(2) Total Derailed		0 0		0 0		0 0			
63. Equipment Damage This Consist		80000		64. Track, Signal, Way, & Structure Damage		875		65. Primary Cause Code		H607		66. Contributing Cause Code		H399			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
1		0		1		0		Hrs 3 Mi 17		Hrs 3 Mi 17							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No   1		1. Yes 2. No   1							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		N/A							
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A							
				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance		Code									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code									
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		1. Yes		2. No		3. Unknown	
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A		N/A		N/A	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes		N/A		1. Yes		N/A							
2. Side of Vehicle Approach				2. No				2. No									
3. Opposite Side of Vehicle Approach		N/A		3. Unknown				3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)					
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code											
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A											
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed													
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
						102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A					
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-34-  
2006  
sketch.jpg



#### 109. SYNOPSIS OF THE ACCIDENT

On May 22, 2006, about 2:07 p.m. Eastern Standard Time (EST) NS Train 44ET520 was operating westbound from Knoxville to Loudon, Tennessee (TN) with four locomotives and 70 loaded grain cars, 9,109 tons. It collided head-on with NS Train T72T522, operating with one locomotive and 35 railcars, 3,050 tons, on the Blair Bend Lead near Loudon.

The accident resulted in the derailment of the locomotive of Train T72T522 along with the railcar next to the locomotive and the lead wheels of the second car from the locomotive. The head-end of the lead locomotive on Train 44ET520 was also derailed.

Current damage estimates are \$200,200 for equipment and \$1,750 for track. It was a cloudy day with a temperature of 66 &#778;F. The only hazardous material released was approximately 250 gallons of diesel fuel from one of the locomotives. No injuries are reported.

The probable cause of the accident was the failure of both trains to comply with the provisions of restricted speed.

A contributing cause of the accident was the failure of the crew members of Train 44ET520 to comply with the dispatcher's bulletin and special timetable instructions.

#### 110. NARRATIVE

##### CIRCUMSTANCES PRIOR TO THE ACCIDENT

###### Train 44ET520

The crew of Train 44ET520 was called to go on duty at Knoxville, TN on May 22, 2006, at 10:50 a.m. The crew consisted of a conductor and engineer. Prior to reporting for duty, the conductor had received a rest period of 16 hours and 50 minutes and the engineer had a rest period of 12 hours and 50 minutes. The train consisted of four locomotives and 70 loads of grain for a total of 9,109 tons. The crew was to operate the train on the Knoxville District West End Subdivision to the Blair Bend Lead and deliver the grain to the A.E. Staley Corporation.

The crew performed the normal initial terminal duties, departed Knoxville Yard, mile post (MP) 123.0A, via a crew bus and proceeded to Train 44ET520 located at MP 130.0A. The crew members performed the required inspections and other duties prior to moving the train. They received a track warrant authority to proceed westbound onto the Knoxville District West End Subdivision toward the Blair Bend Lead. The first track warrant authorized movement of the train to MP 149.0A. A second track warrant was issued authorizing movement to the Blair Bend Lead switch. At Blair Bend Lead, the signal was displaying a proceed indication and the crew members proceeded west toward the Blair Bend Lead.

Dispatcher's Bulletin and Timetable Special Instructions require that trains entering the Blair Bend Lead must contact the Loudon Yard Road Switcher prior to occupying the lead. If contact with the switcher cannot be established, the dispatcher must be contacted for instructions. The crew stopped at the Blair Bend Lead switch, aligned the switch for their movement, and operated their train onto the lead without complying with these special instructions. The engineer was alone in the operating compartment of the locomotive as the conductor had remained at the main line switch to return it to normal position after the train had cleared the main track.

###### Train T72T522

On May 22, the crew of Train T72T522 reported for duty at the Loudon Yard Office at 8 a.m. The crew consisted of three employees; an engineer, conductor and brakeman. They are responsible for performing switching duties at the industries located in the Loudon Yard. All crew members had received a rest period of 40:55 minutes prior to reporting for duty.

They had performed normal switching duties during the morning and returned to the yard office for lunch around 11:30 am. After lunch they called Staley manufacturing to determine what was needed in the way of switching. They then notified the Staley plant industrial switcher and Staley security they were entering the plant facility to perform switching.

After switching the Staley plant, they departed with 30 loads and 4 empties, 3,050 tons, for delivery to the Loudon Yard. The crew stopped at the west end yard office to discuss the situation and perform a job briefing. During their job briefing, the crew was concerned that their locomotive power would not be enough to clear the east end switches and make the steep grade located at the east end of the yard. They decided that the conductor and brakeman would use their personal vehicle (POV) and proceed to the east end of the yard and align the switches for a straight move up the lead. The train crew was not aware of any other movement entering their territory. The engineer was alone in the operating compartment as he traversed the main lead through the yard. He was attempting to gain enough momentum to ascend the severe incline on the lead. He looked at the speed indicator when he passed the east end lead switches and said he was operating between 12 and 14 miles per hour (mph).

NS timetable and geographic direction is north and south. Timetable direction is used throughout this report.

THE ACCIDENT

Train 44ET520

The engineer of Train 44ET520 was operating from a wide-body locomotive, which gave him a panoramic view of the territory ahead of his movement as he entered a 9.35-degree left hand curve. According to the event recorder, the engineer was proceeding at a speed of five mph, with a 20 lbs automatic brake application, in throttle notch no. 8, with amperage on the lead locomotive of 680 amps. He intended to stop the train after it cleared the main track and allow the conductor to walk back to the locomotive.

Train T72T522

The engineer of Road Switcher T72T522 was operating from the right side of the locomotive giving him a complete view of the track in the front of his movement as he entered a 9.35-degree right-hand curve. He was not expecting any other movements in this section of the yard. The engineer said he initiated a whistle signal for a highway-rail grade crossing and turned back to see if his train would clear the east end switches. As he looked back toward the track he was operating over, he saw Train 44ET520 directly in front of him. The engineer said he zeroed the throttle, applied a full service independent brake, initiated an emergency brake application, and abandoned the locomotive. He was off the locomotive about two or three seconds prior to impact.

ANALYSIS AND CONCLUSION

Analysis

Dispatcher's Bulletin and Timetable Special Instructions require that trains entering the Blair Bend Lead must contact the Loudon Yard Road Switcher prior to occupying the lead. If contact with the switcher cannot be established, the dispatcher must be contacted for instructions. The crew stopped at the Blair Bend Lead switch, aligned the switch for their movement, and operated their train onto the lead without complying with these special instructions. The engineer was alone in the operating compartment of the locomotive as the conductor had remained at the main line switch to return it to normal position after the train had cleared the main track.

After switching the Staley plant, they departed with 30 loads and 4 empties, 3,050 tons, for delivery to the Loudon Yard. The crew stopped at the west end yard office to discuss the situation and perform a job briefing. During their job briefing, the crew was concerned that their locomotive power would not be enough to clear the east end switches and make the steep grade located at the east end of the yard. They decided that the conductor and brakeman would use their POV and proceed to the east end of the yard and align the switches for a straight move up the lead. The train crew was not aware of any other movement entering their territory. The engineer was alone in the operating compartment as he traversed the main lead through the yard. He was attempting to gain enough momentum to ascend the severe incline on the lead.

The engineer of Train 44ET520 was operating from a wide-body locomotive, which gave him a panoramic view of the territory ahead of his movement as he entered a 9.35 degree left hand curve. According to the event recorder, the engineer was proceeding at a speed of 5 mph, with a 20 lbs automatic brake application, in throttle notch no. 8, with amperage on the lead locomotive of 680 amps.

The engineer of Road Switcher T72T522 was operating from the right side of the locomotive giving him a complete view of the track in the front of his movement as he entered a 9.35-degree right-hand curve. He was not expecting any other movements in this section of the yard. The engineer said he initiated a whistle signal for a highway-rail grade crossing and turned back to see if his train would clear the east end switches. As he looked back toward the track he was operating over, he saw Train 44ET520 directly in front of him. The engineer said he zeroed the throttle, applied a full service independent brake, initiated an emergency brake application, and abandoned the locomotive.

There were no injuries reported. The only hazardous material spilled is about 250 gallons of diesel fuel from Locomotive NS 7071.

FRA Post-Accident Drug and Alcohol Testing was conducted with negative results.

At the time of the collision, the temperature was 66 &#778;F with cloudy visibility.

PROBABLE CAUSE AND CONTRIBUTING FACTORS

The probable cause of the accident was the failure of both trains to comply with the provisions of restricted speed.

A contributing cause of the accident was the failure of the crew members of Train 44ET520 to comply with the dispatcher's bulletin and special timetable instructions.

#