



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-44***

***Burlington Northern Santa Fe
Lockwood, Missouri
June 8, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF			1b. Railroad Accident/Incident No. SF0606102			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF			3b. Railroad Accident/Incident No. SF0606102			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month: 06 Day: 08 Year: 2006			6. Time of Accident/Incident 04:00: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
			13. Other (describe in narrative)			01			
8. Cars Carrying HAZMAT 4		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Springfield	
13. Nearest City/Town Lockwood			14. Milepost (to nearest tenth) 159.7		15. State Abbr Code N/A MO		16. County DADE		
17. Temperature (F) (specify if minus) 70 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
21. Track Name/Number Main Track			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 54.64		24. Time Table Direction Code 1. North 3. East 2		
OPERATING TRAIN #1									
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 44 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits			
29. Trailing Tons (gross tonnage, excluding power units) 10373			30. Method(s) of Operation (enter code(s) that apply) m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				
(1) First involved (derailed, struck, etc)		N/A	21	yes	Alcohol		Drugs		
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0		
33. Was this consist transporting passengers? (Y/N)					N				
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.	
		d. Manual	e. Remote				c. Freight	d. Pass.	
(1) Total in Train		4	0	0	(1) Total in Equipment Consist		76	0	
(2) Total Derailed		0	0	0	(2) Total Derailed		36	0	
		0	0	0			6	0	
		0	0	0			0	0	
36. Equipment Damage This Consist		963723		37. Track, Signal, Way, & Structure Damage 250000		38. Primary Cause Code T207		39. Contributing Cause Code N/A	
Number of Crew Members					Length of Time on Duty				
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 2 Mi 0	
								45. Conductor Hrs 2 Mi 0	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 1	
Fatal		0		0		0		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Nonfatal		N/A		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2									
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
54. Train Number/Symbol N/A									
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic m. Special instructions n. Other than main track			
						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A						N/A		N/A			
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A					
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.	
(1) Total in Train		N/A		N/A		N/A		N/A		(1) Total in Equipment Consist		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A		N/A		(2) Total Derailed		N/A		N/A		N/A	
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage		N/A		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A							
Nonfatal		N/A		N/A		N/A		78. Caboose Occupied by Crew?		N/A							
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A							
				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance		Code									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code									
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		N/A		1. Yes		Code	
		3. Standard FLS		6. Audible		9. Watchman		12. None						2. No		Code	
Code(s)		N/A		N/A		N/A		N/A						3. Unknown		N/A	
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code					
1. Both Sides						1. Yes		N/A		1. Yes		N/A					
2. Side of Vehicle Approach						2. No				2. No		N/A					
3. Opposite Side of Vehicle Approach				N/A		3. Unknown				3. Unknown		N/A					
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)					
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code											
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A											
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed													
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
						102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A					
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code									
1. Yes 2. No				N/A		1. Yes 2. No		N/A									
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code									
1. Yes 2. No				N/A		1. Yes 2. No		N/A									

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-44Sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

At approximately 4 a.m. CDT, June 8, 2006, a BNSF southbound mixed freight Train Symbol H KCKMEM1 07 derailed at milepost (MP) 159.7 in the vicinity of Lockwood, Missouri. This derailment occurred on the BNSF's Springfield Division, Ft. Scott Subdivision. There were no injuries or any hazardous materials involved. Forty-two cars were derailed, resulting in equipment damages of \$963,723; track damages of \$250,000; and no signal damage. The temperature was 70 °F and the weather was clear. The cause of this derailment has been determined to be a broken rail that had an internal defect (T207 - Detailed Fracture).

110. NARRATIVE

Circumstances Prior to the Accident

BNSF Railway Company (BNSF) Train Symbol H KCKMEM1 07, a mixed freight train, originated in Kansas City, Kansas, where it received an initial terminal air test on June 6, 2006, at 6:15 p.m. The two-member crew consisting of an engineer and a conductor went on duty at Ft. Scott, Kansas, MP 98, at 2 a.m., June 8, 2006. Ft. Scott is the away-from-home terminal for both crew members. They had received 12 hours 15 minutes off-duty time prior to reporting for duty. Ft. Scott is a crew change point, and they took control of this train upon its arrival. They departed Ft. Scott at 2:20 a.m., June 8, 2006, and made no pick-ups or set outs en route, and operated to MP 159.7 without incident. The engineer was operating lead Locomotive No. BNSF 4113 with the short hood forward, and was sitting behind the control stand on the west side. The conductor was sitting on the east side of the lead locomotive. They had just passed a track-side warning detector (TWD) at MP 154.7 and had received a radio message with no defects found. They were proceeding geographically and timetable direction south, on clear signals, at 45 mph. Starting at MP 158.6, there is a 1-percent descending grade southbound that ends at the bridge at MP 159.9. There are two curves in this area, a right-hand 3-degree 15-minute curve, and a left-hand 3-degree 41-minute curve. The initial derailment occurred at MP 159.7, which is at the extreme south end of the spiral of the curve within a very few feet of tangent track.

The Accident

Train Symbol H KCKMEM1 07 consisted of 4 locomotives, 76 loads, 37 empties, 10,373 tons, and was 7,310 feet long. As the train approached MP 159.7, it was traveling at a recorded speed of 44 mph. Approximately 1-minute 18-seconds prior to the derailment, the engineer had set the train up in dynamic braking in preparation of slowing the train for a 25 mph speed restriction starting at MP 160.8. Speed tapes from lead Locomotive No. BNSF 4143 indicate the traction motor current was 600 amps. Since this was a heavy tonnage train, the engineer felt he should supplement the dynamic braking, so just seconds prior to the derailment, he made a 10-pound brake pipe reduction. Another 4-pound reduction was being initiated when the train had an emergency brake application. The maximum authorized speed for this train was 45 mph, as designated in the current BNSF Springfield Division Timetable No. 5. The crew states they neither saw nor felt anything unusual. When the train stopped, the conductor got off the locomotive and started walking the train at which time he found that the 17th through 38th cars and the 49th through 68th cars from the head end were derailed.

Analysis and Conclusions

After the derailment occurred, both train crew members were transported to the Barton County Memorial Hospital at Lamar, Missouri, for post-accident toxicological testing. Drug and alcohol tests were performed on both crew members, and test results were negative.

The last inspection on this trackage was performed on Monday, June 5, 2006. The BNSF geometry car had operated over this territory on May 9, 2006, with no defects noted. Internal rail testing was done by Sperry Rail Services (Car SRS 829) on May 22, 2006, with no indication of a defect in this area.

The derailment was caused by a broken rail as determined by the test results from BNSF's Technical Research & Development Physical Test Laboratory in Topeka, Kansas. It is thought that, account shelling found on the gage side of the rail, it masked the detection of the 10 percent detail fracture that was present in this rail. Also, rail wear measurements revealed the vertical head loss was at the condemnable limit according to BNSF Standards.

Probable Cause and Contributing Factors

The Federal Railroad Administration found the probable cause of HQ-2006-44 to be a detailed fracture from shelling or head check. This accident occurred due to the fact that a 1949 Tennessee Brand 132.25-pound rail had developed a 10 percent internal defect, determined to be a detailed fracture, and broke under the train.