



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-45***


***Burlington Northern Santa Fe
Grants, NM
June 9, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF			1b. Railroad Accident/Incident No. SW0606102					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A					
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF			3b. Railroad Accident/Incident No. SW0606102					
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 06 09 2006			6. Time of Accident/Incident 06:52: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM					
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision					
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts					
			13. Other (describe in narrative)			01					
8. Cars Carrying HAZMAT 5		9. HAZMAT Cars Damaged/Derailed 1		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Southwest			
13. Nearest City/Town Anzac			14. Milepost (to nearest tenth) 87.7		15. State Abbr Code N/A NM		16. County CIBOLA				
17. Temperature (F) (specify if minus) 59 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/Number Main Track/Main T-2			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 92.0		24. Time Table Direction Code 1. North 3. East 3				
OPERATING TRAIN #1											
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		
			A. Spec. MoW Equip. Code 1			26. Was Equipment Attended? 1. Yes 2. No 1			27. Train Number/Symbol ZLACK CK108		
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 56 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits						30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		
29. Trailing Tons (gross tonnage, excluding power units) 4859			c		e		N/A		N/A		
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A		5		yes		Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0		0		N/A		0		0	
			33. Was this consist transporting passengers? (Y/N)			N					
34. Locomotive Units		a. Head End		Mid Train		Rear End		35. Cars		Loade	
		b. Manual		c. Remote		d. Manual		c. Remote		a. Freight	
(1) Total in Train		4		0		0		0		66	
(2) Total Derailed		0		0		0		0		8	
		0		0		0		0		0	
		0		0		0		0		0	
36. Equipment Damage This Consist			998599			37. Track, Signal, Way, & Structure Damage 550000			38. Primary Cause Code T213		
									39. Contributing Cause Code N/A		
Number of Crew Members					Length of Time on Duty						
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 7 Mi 12		45. Conductor Hrs 7 Mi 12	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal		0		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No		2	
Nonfatal		N/A		0		0					
OPERATING TRAIN #2											
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		
			A. Spec. MoW Equip. Code N/A			53. Was Equipment Attended? 1. Yes 2. No N/A			54. Train Number/Symbol N/A		
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A									
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs									
(1) First involved (derailed, struck, etc)		0		N/A		N/A				N/A		N/A									
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A									
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass.		Empty e. Caboose									
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		0 0		0 0									
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		0 0		0 0									
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A							
Number of Crew Members						Length of Time on Duty															
67. Engineer/Operators		N/A		68. Firemen		N/A		69. Conductors		N/A		70. Brakemen		N/A							
71. Engineer/Operator		Hrs 0 Mi 0		72. Conductor		Hrs 0 Mi 0		76. EOT Device?		1. Yes 2. No		N/A		77. Was EOT Device Properly Armed?		1. Yes 2. No		N/A			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		1. Yes 2. No		N/A		77. Was EOT Device Properly Armed?		1. Yes 2. No		N/A			
Fatal		0		0		0		78. Caboose Occupied by Crew?		1. Yes 2. No		N/A									
Nonfatal		0		0		0															
Highway User Involved						Rail Equipment Involved															
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing) 6. Light Loco(s) (moving)		Code		1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing)		Code		2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative)		N/A			
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian		B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		N/A		84. Position of Car Unit in Train		N/A													
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		85. Circumstance		Code		1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing		Code		1. Rail Equipment Struck Highway User		Code			
82. Position		1. North 2. South 3. East 4. West		N/A		86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		Code		4. Trapped		N/A		2. Rail Equipment Struck by Highway User		Code			
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A		86b. Was there a hazardous materials release by		Code		Code						1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A			
86c. State here the name and quantity of the hazardous materials released, if any.														N/A							
87. Type of Crossing		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		Code		88. Signaled Crossing Warning		Code		Code		89. Whistle Ban		Code		2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)		Code			
Warning		3. Standard FLS 6. Audible		N/A		9. Watchman 12. None		(See instructions for codes)		N/A		1. Yes 2. No 3. Unknown		N/A							
Code(s)		N/A		N/A		N/A		N/A		N/A											
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code		1. Both Sides		Code		2. Side of Vehicle Approach		Code			
3. Opposite Side of Vehicle Approach		N/A		1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A											
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code		1. Drove around or thru the Gate 4. Stopped on Crossing		Code		2. Stopped and then Proceeded 5. Other (specify in narrative)		Code	
0		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		3. Did not Stop		N/A									
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code		Code		Code		1. Yes 2. No 3. Unknown		N/A		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		Code		7. Other (specify in narrative)	
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A															
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code		0		103. Total Number of Highway-Rail Crossing Users (include driver)		Code		0	
		0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A									
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code		Code		Code		1. Yes 2. No		Code		1. Yes 2. No		Code		1. Yes 2. No	
1. Yes 2. No		N/A		1. Yes 2. No		N/A															
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code		Code		Code		1. Yes 2. No		Code		1. Yes 2. No		Code		1. Yes 2. No	
1. Yes 2. No		N/A		1. Yes 2. No		N/A															

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-45-
2006.jpg



109. SYNOPSIS OF THE ACCIDENT

On June 9, 2006, at 6:52 a.m. (MDT), an eastbound Intermodal BNSF freight train, Z-LACKCK1-08A, derailed at mile post 87.7, on Main Track No. 2, at a location referred to as Anzac. This location is approximately 13.4 miles east of Grants, NM, and on the Gallup Sub-division of the Southwest Division. The derailment occurred on the Acoma Indian Reservation.

The first thru eighth freight cars behind the four locomotives at the head end of the train derailed. The eight freight cars were Articulated Cars and consisted of 26 articulated segments. There were no casualties, no release of hazardous materials, nor were there any evacuations in the sparsely populated area. Monetary damages are estimated to be \$1,548,599. Monetary cost of lading and for clearing the derailment totaled \$1,560,000. Total costs amounted to \$3,108,599.

The temperature, visibility, and weather at 6:52 a.m., on June 9, 2006, was 59 degrees Fahrenheit, daylight, with partly cloudy skies.

Observations of rail batter on the west end rail revealed evidence that rail wheel flanges had been contacting the tops of the compromise joint bars. This condition indicates that the compromised joint broke as a previous opposing west bound train passed this location 40 minutes prior to the derailment of Train Z-LACKCK1-08A. The derailment occurred in an area with solid concrete tie and ballast structure.

110. NARRATIVE

Circumstances Prior to the Accident

The train crew of train Z-LACKCK1-08A, was a two person train crew and consisted of a locomotive engineer and conductor. The train crew went on duty at 11:40 p.m. (MDT), on June 8, 2006, at the BNSF yard, in Winslow, AZ. This was the home terminal for the train crew. Both train crew members had received more than the statutory off duty period prior to reporting for duty and also reported the trip as uneventful prior to the derailment.

The Z-LACKCK1-08A, an intermodal train originating in Hobart Yard, Los Angeles, CA, and terminating in Kansas City, KS, consisted of four locomotives, 66 loaded, and no empty freight cars. The train was 6,687 feet in length and was pulling 4,859 trailing tons. The train was equipped with an armed and functioning Quantum manufactured two-way end-of-train device. The two-way end-of-train device was numbered BNQ 40380, and was previously calibrated on 5-15-2006, at the Kansas City Central Repair Facility, according to the affixed tag on said device.

The train, Z-LACKCK1-08A, was given a Class I Brake Test-Initial Terminal Brake Test at Hobart Yard, Los Angeles, CA. The initial train crew boarded and began operation of train symbol Z-LACKCK1-08A, at Hobart Yard, Los Angeles, CA, with subsequent crew change locations at Barstow, CA, Needles, CA, and Winslow, AZ. The Winslow, AZ, train crew, was the train crew involved in the derailment.

As the train approached the derailment area from the west, the train was traveling 56 mph (recorded) and in dynamic braking mode. The locomotive engineer was seated on the seat provided near the control stand on the south side of the lead and controlling locomotive. The conductor of the train was seated on the seat provided on the north side and directly across from the locomotive engineer. The distance traveled from the time of the train induced emergency and when the train came to a complete stop, was approximately 1,086 feet.

In this area of the railroad, the track is of 136 lb. CWR (Continuous Welded Rail) and was installed in 1974. The track is tangent for about 600 feet from the west on the parent rail* to the location of the severed compromised joint bar, followed by approximately 100 feet prior to the beginning of spiral into a two degree 56 minute curve to the left. The grade at this location is .43 percent descending.

* The "Parent Rail" is defined as the initially installed rail prior to any replacement of subsequent rail sections.

The railroad timetable direction of train symbol Z-LACKCK1-08A, was east. The geographic direction was southeast. Timetable directions are used throughout this report.

The Accident

The Z-LACKCK1-08A, was being operated at a recorded speed of 56 mph approaching the derailment area and was in dynamic braking according to the event recorder. The train crew's view is obstructed to the left in the direction of travel, by hills and mountains and to the east, by a succession of curves. The crew's view to the right, in the direction of travel, is fairly unobstructed and parallels Interstate 40 East.

The engineer stated that he first became aware of the derailment after the train went into a train induced emergency application of the air brakes. Shortly after notifying the conductor of the emergency air brake application, the engineer stated that he moved the automatic brake valve handle to the "Emergency/Handle Off" position on the automatic brake valve quadrant. The engineer stated that shortly thereafter, he released the locomotive air brakes, by depressing the independent air brake handle, so as to attempt a controlled stop of the remaining portion of the train.*

* The actions taken, as stated by the locomotive engineer, correspond with actions indicated on the event recorder.

The conductor stated that at 6:55* a.m. (MDT), after having felt and having been notified that the Z-LACKCK1-08A, was in a train induced emergency application of the air brakes, he looked to the rear of the train and could see the first car on the ground. The conductor stated that he immediately called the number nine button(emergency number) and notified the number eight train dispatcher(Gallup East).**

* The conductor states that shortly after the derailment he looked at his watch. The time was, according to him, 6:55 a.m. All other documents indicate the time of derailment 6:52 a.m.

** During the conductors interview, he referred to the number eight dispatcher as the Belen dispatcher. The no. eight dispatcher, is actually the Gallup East dispatcher, that handles the territory east from Gallup, NM to Belen, NM.

Both the engineer and conductor, stated they felt no abnormalities on the track or track structure, as the lead locomotive went over the defective compromise joint bar immediately preceding the derailment.

On June 9, 2006, at approximately 6:52 a.m. (MDT), train symbol Z-LACKCK1-08A, derailed on Main Track No. 2, in the vicinity of Anzac at m.p. 87.7, Gallup Sub-division, Southwest Division. The accident occurred on the Acoma Indian Reservation.

The first thru eighth Articulated Cars (26 articulated segments), derailed resulting in the destruction of all but the first Articulated Car (three articulated segments). One of the Articulated Cars, BNSF 253128, was hauling container TRLU 701158. This container was carrying a load of hazardous material (sparkler fireworks), hazard class 1.4, and derailed. The container of sparklers, was never compromised nor was there an evacuation of the sparsely populated area.

The derailment resulted in no injuries to the general public, emergency response personnel, nor railroad employees. The New Mexico State Police, was notified at 7:08 a.m. The Acoma Indian Tribal entities were immediately notified and responded at approximately 7:00 a.m. with fire engines, a hazmat trailer, and ambulance. The Grants, NM, Fire Department was notified at about 7:30 a.m., and shortly thereafter responded with a fire engine, pick-up truck, and equipment trailer. Standby assistance was requested by the Acoma Fire Chief from Cubero, NM, and Laguna, NM, Fire Departments.

The Cibola County Sheriffs Department was notified at 6:55 a.m., via 911, by the use of a cellular phone, by an unknown person(s), and responded shortly thereafter.

Analysis and Conclusions

Immediately following the accident, the determination was made that the FRA's monetary threshold had been met and arrangements were made to conduct toxicological testing under FRA Mandatory Sub-Part C. The urine and blood toxicological results for the locomotive engineer and conductor proved negative.

The event recorder on the lead and controlling locomotive BNSF 5037, a General Electric C44-9W locomotive built in 2004, was unable to be down-loaded after the derailment. A BNSF, Superintendent of Operating Practices, was present to perform the event recorder down load and stated during the process, the event recorder cable on the BNSF 5037, had not been properly connected. The unconnected cable on BNSF 5037, resulted in the down-loading of the event recorder on BNSF 4575, the third of four locomotives being used for the motive power on train symbol Z-LACKCK1-08A. There was no indication the event recorder and/or cable had been altered or tampered with.

On the afternoon of June 10, 2006, I traveled to Grants, NM, to conduct an inspection of the remaining portion of train symbol Z-LACKCK1-08A (See FRA F6180.96 RCG-70). There were 22 remaining Articulated Cars consisting of 78 articulated segments. There were no defects noted on the inspection report other than a comment made indicating the air brakes had bled off of two articulated segments. There were no FRA exceptions noted.

On May 15, 2006, a Herzog rail detector car identified a detail fracture in the North Rail at mile post 87.664, on Main Track No. 2. The identified defect was removed and BNSF welders, were present to insert and weld a section of similar rail, also referred to as a "plug." During the thermal welding process, a failure occurred and the two rail ends never fused or welded. Shortly after, a second plug rail was added at the location. This resulted in two plug rails and three rail joints at that location.

The parent rail, according to a BNSF report, was vertically head worn up to 3/4", 1/16" more than the current relay limits of 11/16". In order to meet joint miss-match requirements, new BNSF approved Chinese* manufactured compromise joints were installed at the three joint locations. The presence of compromise joint bars at this location was the result of a "failed weld." This condition may have been the result of a defective rail mold, improper sealing or packing of the rail ends to be thermally fused, or possibly error on the part of the welders.

* The Chinese manufactured compromise joints in use at the time of derailment met AREMA (American Railway Engineering and Maintenance of Way Association) Standards joint bar chemistry.

In a report provided by the Southwest Region titled 3P Analysis: Root Cause & Corrective Action mentions that the suspect first car that derailed, BNSF 240462, a five-unit segment Articulated, had a WILD (Wheel Impact Load Detector) reading of 79.3 kips (kilo pounds). A wheel impact load detector, measures the wheel impact of the rail wheels against the rail. One kip is equal to 1,000 pounds. Rule 41- Wheels and Axles of the AAR (Association of American Railroads) calls for renewal of a single WILD reading at 90,000 pounds (90 kips) at any time. The BNSF renews impacted wheels at readings at 90 kips at Repair Facilities and will set out suspect wheels in a train following wayside detectors at scans above 120 kips.

While a 79.3 kip reading on L10 wheel of Articulated Car, BNSF 240462, was above the normal reading of 30-50, the reading did not exceed the parameters used by AAR nor BNSF.

Although a forthcoming containment plan identifying changes will be provided by the BNSF Railway, the Southwest Division Engineering Department, has issued instructions concerning head loss, rail mis-match, inspection of rail joint bars, compromise or otherwise, for wheel flange contact, identification of Chinese manufactured compromise joint bars, and the development of "head free" compromise joint bars.

The Federal Railroad Administration's investigation found that the probable cause of the derailment was a severed 132/136 compromise joint bars on the North Rail of Main Track No. 2, in the vicinity of mile post 87.7, due to fatigue cracks in the bottom flanges of compromise joint bar. The fatigue cracks grew to approximately 10 to 20 percent of the total joint bar cross sectional area before rapid failure of the remainder of the bars, which occurred in a single cycle event.