

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2006-56

Burlington Northern Santa Fe Houston, TX June 27, 2006

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # <u>HQ-2006-56</u>																			
1.Name of Railroad O	1a. Alphabetic Code 1b					1b.	b. Railroad Accident/Incident No.												
BNSF Rwy Co. [BN	BNSF					25.1	GC0606111												
N/A	∠a.	<i>i</i> siphabeth	20. F	b. Raiiroad Accident/Incident															
3.Name of Railroad Ro	3a. Alphabetic Code						3b. Railroad Accident/Incident No.												
BNSF Rwy Co. [BN	BNSF							N/A											
4. U.S. DOT_AAR Gr	5. I	Date of Acc	6. 1	Time of Accident/Incident															
									Month 06		27	2006	5	12:27: AM 🖌 PM					
7. Type of Accident/In	ndicent	1. Derail	ment		4. Side collision				Hwy-rail	crossin	ng 10.	. Explos	ion-detor	detonation 13. Other					
(single entry in cod	le box)	2. Head of	on coll	ision	5. Raking	g collisior	1 	8.	8. RR grade crossing 11. Fire/violent rupture (describe in narrative)										
		3. Rear e	nd col	lision	6. Brokei	n Train co	D 1	9.	Obstructio	on	12.	. Other 1	mpacts					01	
8. Cars Carrying HAZMAT 10	Cars Carrying 9. HAZMAT Cars AZMAT 10 Damaged/Derailed					HAZMAT				Ev	. People			0	12. Division Houston				
19					1	14 Mil	most		1					0	Houston				
13. Nearest City/Town	n				(to nearest t					15. St	5. State Abbr Code			6. County		HADDIC			
17 Teners (E)		Hous	ston			<u> </u>			353		N/A TX			1	HARRIS				
(specify if minus)		18. Visit	oility Dawn	(sing 3.D	gle entry) Jusk	Code	19. W	Veath	er (single ar 3. Ri	e entry ain) 5.Sleet	Co	ode	20. Typ	20. Type of Track			Code	
95 F 2. Day				4.I	Dark ²				udy 4. Fo	og	6.Snow			2. Ya	ard 4. Industry			1	
21. Track Name/Number						22. FRA	Track	2	Code	23. A	3. Annual Track Density			24. Tin		ne Table Direction		Code	
	er 1 M	ain	Class $(1-9, X)$ 4					gross tons nillions)	s 1n	20	1. North 3. East				3				
OPERATING TRAIN #1																			
25. Type of Equipment	nt 1	. Freight tra	ain	4. W	ork train 7.	Yard/sw	itching	A	. Spec. Mo	W Equ	ip. Code	26. W	/as Equip	oment (Code	27. 1	Frain Nu	nber/Symbol	
Consist (single en				11	A	ttended?	vnded?												
28 Speed (recorded a	s need if	. Commute	r train	6. Cu	t of cars 9. Method(s) (Maint./ir	ispect.ca	r ente	r code(s)	that a	(nnly)		1. 1 es	2. NO	otely C	ontro	761	26 26 26	
R - Recorded R - Re												Wienled							
E - Estimated	23	MPH	R	b	. Auto train c	control h	. Curren	t of t	raffic	c	1 = Remote control portable								
29. Trailing Tons (gross tonnage. d. Cab i Track									rain orders nt control	s o. Po p. Oti	sitive trair	i control	rrativa)	2 = Remote control tower 3 = Remote control					
excluding power	k	. Direct	traffi	ic control		Code	transmitter - more than one												
14935 f. Interlocking 1. Yard limits e N/A N/A N/A N/A remote control transmitter 0														0					
31. Principal Car/Unit		a. Initial	and N	umber	b. Positic	on in Train	n c. l	Load	ed(yes/no)	32.	If railroad	employ	ee(s) test	ed for drug	g/alcoho	l use,			
(1) First involved		82				yes enter the appro			number	that were	e positive i	n	F	Alcohol	Drugs				
(defailed, struck, et (2) Causing (if mec	hanica	1								33	Was this	consist	transport	ing passen	aers? (N/A	N/A	
cause reported)		N/A			1	N/A	55	. was uns	consist	uansport	ing passen	igers: (1	1/11)		N				
34. Locomotive Units a. Head		Mid 7	Frain a Romoto	Re d Manua	ar End	moto	35. Car	s			Lo Freight	b Pass	c Frei	Emp obt L	ty d Pass	e Caboose			
(1) Total in Train		2	0. M		c. Kelliote	0	1 C. Kei	mote	(1) Total	l in Ea	uinment C	onsist	113	0.1435.	15	igni (0	0	
(1) 10001 11 11000				0	0	0	-		(1) 1000	- 111 Eq.	anpinioni e	onoist	115	0	1.	, 	0	0	
(2) Total Derailed	1	0		0	0	0	0		(2) Total	l Derail	led		9	0	4		0	0	
36. Equipment Damage 379939				37. Tra	ick, Signal, V	00	38. Prim Code	00	39. Contributing Cause Code N/Δ										
This Consist		Langth of Time on Duty																	
40. Engineer/ 41. Firemen 4				42. Co	42. Conductors 43. Brakemen				44. Engineer/Operator					45. Conductor					
Operators N/A	Operators N/A N/A				1		N/A		Hrs 5			Mi	27		Н	rs	5	Mi 27	
Casualties to:	46. Rail	road Emplo	oyees .	47. Tra	. Train Passengers 48. Other				49. EOT Device?					50. Was EOT Device Properly An					
Fatal		0			0		1. Yes 2. No 1						1. Yes 2. No 1						
					-	_			51. Cabo	Occupied by Crew?									
Nonfatal	tal N/A				0 0				1. Yes 2. I					o 2					
						0	PERAT	ΓING	G TRAIN	N #2									
52. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 53. Was Equipment Code 54. Train Number/Symbol																			
Consist (single ent	5. Sin	5. Single car 8. Light loco(s).				Atte					['] 2 No N/A N/A				A				
55. Speed (recorded s	55. Speed (recorded speed, if available) Code 57. Method(s) of Operation (enter code(s) that apply) 57a. Remotely Controlled Locomotive?																		
R - Recorded a. ATCS g. At								natic l	block	m.Sp	ecial instru	uctions		0 = Not a	a remote	ly co	ntrolled		
E - Estimated MPH N/A $a. ATCS$ $g. Automate block$ $m. operation and the set of the set of$																			

DEPARTMENT FEDERAL RAILF	OF TRA ROAD AI	NSPORT DMINIST	TATI RAT	ON ION	FRA FA	ACTUAI	LRAILR	OAD AC	CIE	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>6-56</u>		
56. Trailing Tons (gross tonnage, excluding power units)				с. d. e.	c. Auto train stop d. Cab e. Traffic k. Direct traffic				ain orders o. Positive train control t control p. Other (Specify in narrative) c control Code(s)					2 = Remote control tower 3 = Remote control transmitter - more than one				
N/A				f.	f. Interlocking 1. Yard limits				N/A	N/A 1	N/A N	J/A N/A	remote c	N/A				
58. Principal Car/Unit a. Initial and Nu				Jumber	b. Posit	led(yes/no)	59. I	lf railroad	l emplo	oyee(s) teste	ed for drug	g/alcohol us	se,					
(1) First involved 0					N/A		N/A	enter the number that were positive in Alcohol							Drugs			
(2) Causing (if mechanical							-		N/A							N/A		
cause reported) 0					N/A]	N/A	60. was this consist transporting passengers? (1/N)							N/A			
61. Locomotive Units	5	a. Head End b. Ma			Mid Train [anual c. Remote d		r End c. Remote	62. Cars			Lo a. Freight	ade b. Pass.	pty d. Pass.	e. Caboose				
(1) Total in Trai	(1) Total in Train 0		0	0	0	0	(1) Total in	(1) Total in Equipment Consist			0	0	0	0	0			
(2) Total Deraile	(2) Total Derailed 0			0 0		0	0	(2) Total Derailed				0	0	0	0	0		
63. Equipment Damage 6 This Consist 0					ack, Signal, Structure Da	Way, amage	0	65. Primar Code	65. Primary Cause 66. Contributing Cause Code N/A Code						use	N/A		
		Numbe	r of Ċ	rew Me	embers				Length of Time on Duty									
67. Engineer/ Operators N/	68. Fire	emen N/A		69. Co	nductors N/A	70. Bra	kemen N/A	71. Engineer/Operator 72. Conductor Hrs 0 Hrs 0						0	Mi 0			
Casualties to:	73. Railr	oad Emplo	oyees	74. Tra	in Passenge	rs 75. Othe	75. Other		76. EOT Device? 77.					77. Was EOT Device Properly Ar				
Fatal		0			0		0		es ise Oc	2. No	V Crew	N/A '?	1.	Yes	2. No	N/A		
Nonfatal		0			0			1. Yes 2. No										
		Rail Equipment Involved																
79. Type C. Truck-	Frailer. F	F. Bus		J. Other	Motor Veh	icle	Code	83. Equipment 3.Train (standing) 6.Light Loco(s) (moving) Co										
A. Auto D. Pick-U B. Truck E. Van	p Truck C	K. Pede M. Othe	strian er (spec. in i	narrative)	N/A	1.Train(units pulling) 4.Car(s) (moving) 7.Light(s) (standing) 2.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative)												
80. Vehicle Speed		84. Position of Car Unit in Train																
(est. MPH at in	outh 3.East	4.west	Code	85. Circum	85. Circumstance							Code						
1.Stalled on Cros	r Crossing		1. Rail Equipment Struck Highway User															
4. Trapped 86a. Was the highway user and/or rail equipment involved							Code	2. Rail Ed 86b. Was t	luipm here a	ent Struc	k by H us mat	erials releas	e by			N/A		
in the impact tr		N/A	1 High	1. Highway User 2. Rail Equipment 3. Both 4 Neither														
1. Highway User	2. Rail E	Equipment	3. he ha	Both zardous	4. Neither	leased if a		1. High	way c	2.	Kall L	quipinent	5. Doui	4. Neture		IN/A		
obe. State here the ha	ine and qu	annity of t	ne na	zaruous	materials it	licased, ii ai	N/A											
87. Type of 1.Ga Crossing 2.Car Warning 2.G	bucks 10. signs 11.	Flagged by Other (spec	crew . in narr.)	88. S (S	ignaled C ee instru	Crossin ctions t	g Warning for codes)	Code	89. Whis 1. Ye 2. No	tle Ban s	Code							
Code(s) N/A	N/A N/A N/A			A	N/A	N/A	N/A	N/A					N/A	3. Un	known	N/A		
90. Location of Warn 1. Both Sides	ing	Code 91. Crossing Warning with Highway S							Interconnected Code 92. Crossing Illuminated by Street Interconnected Code Lights or Special Lights									
2. Side of Vehicl	1. 2.	Yes No					1. Yes 2. No	Yes No										
					N/A	3.		in Code 96 Driver						N/A				
95. Driver's 94. Driver's Gender Code 95. Age 1. Male 2 Female					d Struck or Yes 2	rain Code Frain	rain 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in											
0	· · ·		N/A		3. Did not Stop narrative) N													
97. Driver Passed Standing Highway Vehicle Code 98. View of Track Obscured by 1. Permanent Structure (primary obstruction) 3. Passing Train 5. Vegetation 7. Other (specify in narrative)														Code				
1. Yes 2. No 3. Unknown N/A 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed														N/A				
101. Casulties to Highway-Rail Crossing Users Killed					Injured	99. Driver	Was 2.Injured 3.	Uninjured	Jinijured N/A 1. Yes 2. No							Code N/A		
0					0	102. Highw	vay Vehicle	Property Damage 0 103. Total Number of Highway-Rail Cross (include driver) 0							ing Users			
104. Locomotive Aux		(csi. u	Code	105. Locoi	notive	e Auxilia	ry Ligh	ts Operatio	nal?		U	Code						
1. Yes		2. No)				N/A	1. Yes 2. No						N/A				
106. Locomotive Headlight Illuminated?							Code	107. Locomotive Audible Warning Sounded?						Code				
1. Yes			IN/A	1.	1. Yes 2. No							N/A						

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. HQ-56-2006.jpg



109. SYNOPSIS OF THE ACCIDENT

Synopses of the Accident

An eastbound BNSF freight train derailed on June 27, 2006. The accident occurred near Dawes, Texas at UP Milepost 353.2, on the UP Lafayette Subdivision.

There were no injuries to the crew. A total of thirteen cars was derailed with one car landing in a bayou. There was a total of seven hazardous cars in the thirteen derailed cars. One of the derailed hazardous cars had a release of its contents. There was no mandatory public evacuation. The equipment cost was \$390,015 track was \$243,700 the signal was \$97,990 and bridge structure was \$90,000 making this derailment a FRA reportable accident.

At the time of the accident it was daylight and clear, with no measurable wind. The temperature was 95 °F.

The accident was caused by irregular cross level from a tank car warp.

110. NARRATIVE

Circumstances Prior to the Accident

The crew of train BNSF 4344 East included a locomotive engineer and a conductor. They first went on duty at 7:00 a.m., CST, June 27, 2006 at BNSF's New South Yard located in Houston, Texas. This was the home terminal for both crew members, and all received more than the statutory off duty period, prior to reporting for duty.

Their assigned freight train consisted of two locomotives, 113 loaded and 15 empty cars of several varieties. It was 8,274 feet long and weighed 14,935 tons. The train was scheduled to travel to Dayton, Texas, with cars to be added and removed at several locations en route. The crew was taken to the train from BNSF's New South Yard by local cab service to UP's Englewood Yard in Houston, Texas. The train was on main number one of the UP Terminal Subdivision.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the south side of leading locomotive. The conductor was seated on the north side of the leading locomotive.

In this area of the railroad there is a subdivision change from UP's Terminal Subdivision double main to UP's Lafayette Subdivision single main with a number 16 turnout to complete the transition from the two. The speed through this turnout from Terminal Subdivision main 1 to Lafayette Subdivision main track is twenty-five (25) mph. There was a .5 mile long temporary speed restriction of twenty-five mph on the Terminal Subdivision's main 1 for a surface and line condition on the track. There are no curves around this area. The grade is practically level.

The railroad timetable direction of the train is east. The geographic direction was east. Timetable directions are used throughout this report.

The Accident Train BNSF 4344 East

The train was being operated at a recorded speed of 23 mph approaching the accident area. The train crew's view of the eastbound control signal was not obstructed by any vegetation. The engineer approached the east switch at Dawes with a clear signal and proceeded to enter the Lafayette Subdivision's main track. After traveling about .2 miles on the Lafayette Subdivision, the train had an undesirable emergency brake application. After the train came to a stop, the engineer stayed on the locomotive to establish radio communications with UP's train dispatchers. The conductor walked back toward the end of train to investigate why the train went into an emergency. While walking back to the end of the train the conductor noticed an UP signal maintainer and got in his truck to be transported to the end of the train. On the way to the end of the train, a Houston Fire truck and other emergence equipment came into the scene and the conductor decided to go back to the head of the train to get the train documents with the maintainer. After collecting the train documents, the conductor traveled back to the scene of the incident. After being sure the scene was safe, the conductor made an evaluation of the derailment. It was noticed that a loaded hopper car a PSPX 9097 fell off the Greens Bayou bridge and landed in the middle of the bayou.

Analysis and Conclusions Train BNSF 4344 East

The primary cause of the derailment is the tank car warp located at UP's Milepost 353.048 Main one on the Terminal Subdivision as identified in UP's Defects for the Track TDMS report dated June 28, 2006. The lead trucks on the PSPX 6508 line 80 on the trains consist had a wheel lift at the tank car warp causing the car to

FRA FACTUAL RAILROAD ACCIDENT REPORT

derail and being dragged to the power switch at control point LF353 where the Terminal double track ends and the Lafayette single main begins in an eastward direction. After the PSPX 6508 came to the frog, it pulled the car ahead of it off the track which was dragged over the switch and onto the Greens Bayou bridge's walkway where it then was too heavy for the walkway and fell into the bayou and on impact released some of its product into the bayou.

The eleven (11) cars following the PSPX 6508 crashed into the derailed car and came to rest as indicated in the drawing in this report. The rest of the train, 35 cars, came to a rest without derailing on Main 1 on the Terminal Subdivision.

In conclusion the derailment was not cause by a broken rail as of first thought. UP initiated a rail analysis of a rail that was first thought to be the primary cause of the derailment by FRA. The conclusion of the analysis was the rail was not the primary cause.

Probable Cause & Contributing Factors Train BNSF 4344 East

The accident occurred because of a tank car warp measuring 3.53 inches in the switch area in the transition from main 1 of the Terminal Subdivision to single main of the Lafayette Subdivision at UP's Milepost 353.04.