



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-68***

***Central Oregon & Pacific Railroad, Inc.
Roseburg, OR
July 27, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Central Oregon & Pacific RR, Inc. [CORP]		1a. Alphabetic Code CORP		1b. Railroad Accident/Incident No. ID06450		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A		
3. Name of Railroad Responsible for Track Maintenance: Central Oregon & Pacific RR, Inc. [CORP]		3a. Alphabetic Code CORP		3b. Railroad Accident/Incident No. ID06450		
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 07 Day: 27 Year: 2006		6. Time of Accident/Incident 02:45: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box) 1. Derailment 4. Side collision 7. Hwy-rail crossing 10. Explosion-detonation 13. Other (describe in narrative) 2. Head on collision 5. Raking collision 8. RR grade crossing 11. Fire/violent rupture 3. Rear end collision 6. Broken Train collision 9. Obstruction 12. Other impacts 01						
8. Cars Carrying HAZMAT 1	9. HAZMAT Cars Damaged/Derailed 1	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division System		
13. Nearest City/Town Roseburg		14. Milepost (to nearest tenth) 571.8	15. State Abbr Code N/A OR	16. County DOUGLAS		
17. Temperature (F) (specify if minus) 92 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2			
21. Track Name/Number T6101		22. FRA Track Class (1-9, X) Code 1	23. Annual Track Density (gross tons in millions) 0	24. Time Table Direction Code 1. North 3. East 2		
OPERATING TRAIN #1						
25. Type of Equipment Consist (single entry) 3. Commuter train	1. Freight train 2. Passenger train	4. Work train 5. Single car	7. Yard/switching 8. Light loco(s).	A. Spec. MoW Equip. Code 1	26. Was Equipment Attended? 1. Yes 2. No 1	
27. Train Number/Symbol 501						
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 7 MPH R	29. Trailing Tons (gross tonnage, excluding power units) 6367	30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
31. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A	a. Initial and Number 22	b. Position in Train 22	c. Loaded (yes/no) yes	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A		
(2) Causing (if mechanical cause reported) N/A	N/A	N/A	N/A	33. Was this consist transporting passengers? (Y/N) N		
34. Locomotive Units (1) Total in Train 5	a. Head End 0	b. Mid Train 0	c. Remote 0	d. Manual 0	e. Caboose 0	
(2) Total Derailed 0	0	0	0	0	0	
35. Cars (1) Total in Equipment Consist 35	a. Freight 6	b. Pass. 0	c. Freight 19	d. Pass. 0	e. Caboose 0	
(2) Total Derailed 0	0	0	0	0	0	
36. Equipment Damage This Consist 132000	37. Track, Signal, Way, & Structure Damage 20000	38. Primary Cause Code T110	39. Contributing Cause Code N/A			
Number of Crew Members			Length of Time on Duty			
40. Engineer/Operators N/A	41. Firemen 0	42. Conductors 2	43. Brakemen 0	44. Engineer/Operator Hrs: 2 Mi: 45	45. Conductor Hrs: 6 Mi: 45	
Casualties to:	46. Railroad Employees 0	47. Train Passengers 0	48. Other 0	49. EOT Device? 1. Yes 2. No 1	50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal	0	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No 2		
Nonfatal	N/A	0	0			
OPERATING TRAIN #2						
52. Type of Equipment Consist (single entry) 3. Commuter train	1. Freight train 2. Passenger train	4. Work train 5. Single car	7. Yard/switching 8. Light loco(s).	A. Spec. MoW Equip. Code N/A	53. Was Equipment Attended? 1. Yes 2. No N/A	
54. Train Number/Symbol N/A						
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A	57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs	
(1) First involved (derailed, struck, etc)		0		N/A		N/A				N/A		N/A	
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A	
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty	
				b. Manual c. Remote		d. Manual c. Remote				a. Freight b. Pass.		c. Freight d. Pass.	
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		0 0		0 0	
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		0 0		0 0	
63. Equipment Damage		This Consist		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code	
0												N/A	
Number of Crew Members						Length of Time on Duty							
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor			
N/A		N/A		N/A		N/A		Hrs 0 Mi 0		Hrs 0 Mi 0			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?			
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		N/A			
								1. Yes 2. No					
Highway User Involved						Rail Equipment Involved							
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing) 6. Light Loco(s) (moving)		Code			
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling) 4. Car(s)(moving)		7. Light(s) (standing)		N/A			
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing) 5. Car(s)(standing)		8. Other (specify in narrative)		N/A			
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A			
				1. North 2. South 3. East 4. West		N/A							
82. Position				Code		85. Circumstance		Code					
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A					
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code					
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A					
86c. State here the name and quantity of the hazardous materials released, if any.													
N/A													
87. Type of Crossing		1. Gates 4. Wig Wags		7. Crossbucks 10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS 5. Hwy. traffic signals		8. Stop signs 11. Other (spec. in narr.)		(See instructions for codes)				1. Yes 2. No 3. Unknown		N/A	
Code(s)		N/A N/A		N/A N/A		N/A N/A		N/A					
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code			
1. Both Sides				1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A			
2. Side of Vehicle Approach													
3. Opposite Side of Vehicle Approach		N/A											
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code	
N/A		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate 4. Stopped on Crossing		N/A	
										2. Stopped and then Proceeded 5. Other (specify in narrative)		N/A	
										3. Did not Stop			
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code							
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A							
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed									
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code	
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A	
						102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A	
104. Locomotive Auxiliary Lights?													
1. Yes 2. No													
105. Locomotive Auxiliary Lights Operational?													
1. Yes 2. No													
106. Locomotive Headlight Illuminated?													
1. Yes 2. No													
107. Locomotive Audible Warning Sounded?													
1. Yes 2. No													

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-68-
2006-
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On July 27, 2006, at 2:45 p.m. (PDT), a Central Oregon & Pacific Railroad Inc.(CORP) freight train (501) derailed on the Roseburg Subdivision, Roseburg, Oregon, at milepost 571.8. The train was traveling south on yard track No.6101 at a recorded speed of 7 mph. The maximum authorized timetable track speed in the area of the accident is 10 mph.

The train consisted of five locomotives, 100 rail cars of mixed freight, 6,367 trailing tons and was 6,645 feet in length. A total of 25 cars (17 th through the 41st) derailed. There were no injuries and no release of hazardous materials. Damages reported was \$152,000 (\$132,000 equipment and \$20,000 track).

At the time of the derailment it was daylight ,clear, and the temperature was 92° F.

The probable cause of the accident was wide gage (due to defective or missing crossies) T110.

110. NARRATIVE

Circumstances Prior to the Accident

A Central Oregon & Pacific Railroad Inc. (CORP) crew consisting of an engineer, a conductor, and a helper conductor went on duty at their home terminals on July 27, 2006. The conductor reported at Medford, Oregon, at 8:00 a.m., and operated his private vehicle to Roseburg, arriving at 11:30 a.m (PDT). The helper conductor (helper) went on duty at Roseburg at 11:15 a.m. and the engineer went on duty at 12 noon. All three had received more than the statutory off duty time prior to reporting for duty. The crew was assigned to operate CORP train symbol 501, from Oakland to Roseburg, Oregon, a distance of 19 miles. After arriving at Roseburg they were to place the train in the Roseburg yard on tracks T6101, T6102, T6103 and T6104.

The train consisted of five locomotives, 100 railcars (35 loads and 65 empties), 6,367 trailing tons, and was 6,645 feet in length. The train originated at Eugene, Oregon, and was operated to Oakland by a previous train crew. According to the engineer, the train had received a Class 1 air brake inspection by the previous train crew prior to departing Eugene. The conductor transported the engineer by company vehicle to Oakland milepost 589.1. The engineer boarded the train and departed Oakland at 12:50 p.m. The conductor returned to Roseburg via the company vehicle. The helper remained in Roseburg awaiting the arrival of the train.

The train approached the derailment area traveling geographically and timetable south. Timetable directions will be used throughout the report. The engineer was seated at the controls on the right (west) side of the leading locomotive. The conductor was sitting in a company vehicle at the north switch to yard track T6101, milepost 572.4. The helper was standing at the south switch to track T6104 at milepost 571.9. Both were located on the west side of the train. Upon arrival at Roseburg, the engineer operated the train onto yard track T6101.

On the trackage of the accident, trains operate on yard tracks under Yard Limit authority. The maximum authorized speed for freight trains is 10 mph as designated in the current CORP Timetable No. 10.

Approaching the accident site from the north on yard track T6101 at milepost 572.4, there is in session tangent track 795 feet in length, a curve 5-degree 58-minute to the left 208 feet to point of derailment and 1,583 feet beyond to the south turnout of 6101 onto the main track. The grade at the accident area is 0.11 percent ascending.

According to the crew, as the train approached the accident area, the trip was uneventful and the weather was daylight, clear and hot.

The Accident

As the train approached the accident site and at the time the accident occurred, the train was being operated at 7 mph. The speed was recorded by the event recorder of the second locomotive UP 5007. The engineer stated as the train was pulling through yard track 6101 and onto the main track, he suddenly felt the train pulling hard. He applied a full air brake application and the train came to a stop in about seven car lengths. When stopped, the locomotive and 18 cars were on the main track at the south end of the yard. The engineer told the conductor and the helper via radio to walk the train. The helper on the south end of the yard discovered the derailed cars in the train and advised the engineer by radio of the derailment. The engineer immediately contacted the dispatcher, and advised that the train was stopped and derailed. The crew discovered a total of 25 cars (17 th through the 41st) had derailed. The train had traveled approximately 1,583 feet after derailling before coming to a stop.

Analysis and Conclusions

This accident did not meet the criteria for 49 CFR Part 219 Subpart C Post Accident Toxicological testing and the crew was not tested.

The railroad reported damages of \$152,000 (\$132,000 equipment and \$20,000 track).

Car JTTX 90110 was identified as the first car to derail.

Wheel flange marks on the inside base of the east rail at milepost 571.8 indicates the point of derailment.

The L-3 wheel on both the JTTX 90110 and JTTX 90047 had derailed and re-railed at the heel of the guard rail at the south turnout switch of T6101.

Lateral rail/tie plate abrasion (Tie plate movement laterally) on the crossties indicates a wide gauge rail condition.

Missing fasteners (spikes) in the area of the derailment allowed for lateral movement of tie plates.

Crosstie condition in the derailment area were impaired to the extent the crossties would not hold spikes or rail fasteners and were so deteriorated that the tie plate or base of rail could move laterally more than ½ inch relative to the crossties.

On June 30, 2006 (accident occurred on July 27), a CORP track inspector conducted a walking track inspection between milepost 569.5 to milepost 575.0. Four switch non-compliance defects were documented in the accident area. No exceptions were taken for missing fasteners, tie plate abrasion condition, or crosstie deterioration.

Geometry car and rail detector car surveys had not been conducted on the Roseburg yard tracks.

Conclusions

A CORP track inspector walked this track on June 30, 2006, but did not see or document defective crossties, missing rail fasteners or lateral rail/tie plate abrasion on track 6101 at milepost 571.8. The railroad assessed discipline to the inspector, and also sent him to training as part of their remedial action.

Missing fasteners along with lateral Rail/tie plate abrasion due to defective crossties indicate the wheel of car JTTX 90110 dropped into the inside of the rail due to wide gauge.

Probable Cause

FRA determined the probable cause to be a wide gage due to defective or missing crossties (T110).