



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-70***

***CSX Transportation
Grovetown, GA
August 4, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 CSX Transportation [CSX]		1a. Alphabetic Code CSX		1b. Railroad Accident/Incident No. R000024601	
2. Name of Railroad Operating Train #2 CSX Transportation [CSX]		2a. Alphabetic Code CSX		2b. Railroad Accident/Incident R000024601	
3. Name of Railroad Responsible for Track Maintenance: CSX Transportation [CSX]		3a. Alphabetic Code CSX		3b. Railroad Accident/Incident No. R000024601	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 08 Day: 04 Year: 2006		6. Time of Accident/Incident 06:15: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
				13. Other (describe in narrative) 02	
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0	
				11. People Evacuated 0	
				12. Division Atlanta	
13. Nearest City/Town Grovetown		14. Milepost (to nearest tenth) YYG15.2		15. State Abbr Code N/A GA	
				16. County COLUMBIA	
17. Temperature (F) (specify if minus) 80 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
				20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number main track		22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 19.4	
				24. Time Table Direction Code 1. North 3. East 1	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s).		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code 1	
				26. Was Equipment Attended? 1. Yes 2. No 1	
				27. Train Number/Symbol A74303	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 4 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
29. Trailing Tons (gross tonnage, excluding power units) 2067				m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) g k N/A N/A N/A	
				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
31. Principal Car/Unit		a. Initial and Number		b. Position in Train	
(1) First involved (derailed, struck, etc)		N/A		6	
(2) Causing (if mechanical cause reported)		N/A		N/A	
				c. Loaded (yes/no) no	
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A	
				33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		b. Mid Train	
		b. Manual		c. Remote	
		d. Manual		e. Remote	
(1) Total in Train		2		0	
(2) Total Derailed		0		0	
				35. Cars	
				a. Freight	
				b. Pass.	
				c. Freight	
				d. Pass.	
				e. Caboose	
				(1) Total in Equipment Consist	
				(2) Total Derailed	
36. Equipment Damage This Consist		37. Track, Signal, Way, & Structure Damage 7550		38. Primary Cause Code H605	
				39. Contributing Cause Code N/A	
Number of Crew Members			Length of Time on Duty		
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1	
				43. Brakemen 1	
				44. Engineer/Operator Hrs 10 Mi 15	
				45. Conductor Hrs 11 Mi 15	
Casualties to:		46. Railroad Employees		47. Train Passengers	
Fatal		0		0	
Nonfatal		N/A		0	
				48. Other 0	
				49. EOT Device? 1. Yes 2. No 1	
				50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				51. Caboose Occupied by Crew? 1. Yes 2. No 2	
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s).		9. Maint./inspect.car	
				A. Spec. MoW Equip. Code 1	
				53. Was Equipment Attended? 1. Yes 2. No N/A	
				54. Train Number/Symbol U49202	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control		g. Automatic block h. Current of traffic m. Special instructions n. Other than main track	
				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units) 12230		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) g k N/A N/A N/A			2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
58. Principal Car/Unit (1) First involved (derailed, struck, etc) CSXT4 48		a. Initial and Number 1		b. Position in Train no		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A			Drugs N/A			
(2) Causing (if mechanical cause reported) 0		N/A		N/A		60. Was this consist transporting passengers? (Y/N) N/A						
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars			Loade a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
(1) Total in Train 2		0		0		0		(1) Total in Equipment Consist 94			0	
(2) Total Derailed 0		0		0		0		(2) Total Derailed 0			0	
63. Equipment Damage This Consist 1400		64. Track, Signal, Way, & Structure Damage 0		65. Primary Cause Code H605			66. Contributing Cause Code H104					
Number of Crew Members						Length of Time on Duty						
67. Engineer/Operators 1		68. Firemen 0		69. Conductors 1		70. Brakemen 0		71. Engineer/Operator Hrs 8 Mi 45			72. Conductor Hrs 8 Mi 45	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device? 1. Yes 2. No 1			77. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal 0		0		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No			2	
Nonfatal 0		0		0		0						
Highway User Involved						Rail Equipment Involved						
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		Code N/A		83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train (units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train (units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)			Code N/A					
80. Vehicle Speed (est. MPH at impact) N/A		81. Direction geographical 1. North 2. South 3. East 4. West		Code N/A			84. Position of Car Unit in Train N/A					
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User			Code N/A					
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A		86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither			Code N/A					
86c. State here the name and quantity of the hazardous materials released, if any. N/A												
87. Type of Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None		Code N/A		88. Signaled Crossing Warning (See instructions for codes) Code N/A			89. Whistle Ban 1. Yes 2. No 3. Unknown Code N/A					
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code N/A			92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code N/A					
93. Driver's Age N/A		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A			96. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative) Code N/A					
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) Code N/A								
101. Casualties to Highway-Rail Crossing Users		Killed N/A		Injured N/A		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A			100. Was Driver in the Vehicle? 1. Yes 2. No Code N/A			
				102. Highway Vehicle Property Damage (est. dollar damage) N/A			103. Total Number of Highway-Rail Crossing Users (include driver) N/A					
104. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No Code N/A								
106. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No Code N/A								

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-70
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

Synopsis

On August 4, 2006, at 6:15 a.m. Eastern Standard Time (EST), CSX Train A74303 operating on the Atlanta Division, Georgia Subdivision in a northward direction struck CSX Train U49202 at milepost (MP) YYG15.2. The accident occurred in Grovetown, Georgia (GA) on single main track that parallels the Grovetown siding. Four empty rock cars from Train A74303 were derailed during the collision and the locomotives from both trains were damaged.

The total damages to rail equipment was \$39,025. The total damages to track, signals, and structures was \$7,550.

Two reportable injuries resulted from the collision. The engineer and the conductor of Train A74303 were given prescription medication. No hazardous materials were involved and no evacuation ordered.

The weather at the time of the accident was clear and 85 °F.

The probable cause of the accident is failure of Train A74303 to comply with restricted speed in connection with a restrictive indication of a block signal.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident
Train A74303

The crew of CSX Train A74303 included a locomotive engineer, a conductor, and a conductor trainee. On August 3, 2006, at 5 p.m., the conductor trainee was called by crew management to deadhead to Camak, GA and serve as the conductor on CSX Train A74303. At 7 p.m. the conductor went on duty at Augusta, GA and deadheaded to Camak. The locomotive engineer and the conductor trainee went on duty at Camak at 8 p.m. All crew members met or exceeded the required prior time off duty period prior to going on duty.

The crew received permission to occupy the North Siding at Camak from the BE dispatcher. At 8:10 p.m. they spoke with the trainmaster for a job briefing. They were taking two cuts of cars in Martin Marietta (MMA) quarry, putting them together. The crew confirmed their instructions and departed by van to the MMA depot to board the locomotives. They put their train together and performed a class 1 brake test on 78 cars. At 9:57 p.m. the crew obtained the Warren DTC block and proceeded south. They released the Warren block at 11:38 p.m.

At 11:53 p.m. the crew received authority No. 55149 to occupy the Warren, Thomson, Dearing, Grovetown, and Harrisonville DTC blocks. Train A74303 proceeded south towards Augusta, GA with 78 loaded cars and two locomotives. They arrived in Augusta on August 4, 2006, at 2:40 a.m. At 2:42 a.m. they released the Warren, Thomson, Dearing, Grovetown, and Harrisonville DTC blocks and the North siding at Camak to the BE train dispatcher.

At 5:30 a.m. Train A74303 departed Augusta Yard with 70 empty cars and two locomotives bound for MMA at Camak. At 5:41 a.m. the crew received authority No. 55485 and proceeded north on the Harrisonville block. At 6:10 a.m. Train A74303 passed an approach signal at MP YYG12.5 at 38 miles per hour (mph). At 6:13 a.m. the train was still 5,240 feet from the point of impact and operating in No. 5 throttle position. The engineer was seated at the controls on the east side of the locomotive cab, the conductor was seated on the west side of the cab, and the conductor trainee was positioned in the middle seat.

The line segment both trains were operating is located on the Atlanta Division, Georgia Subdivision. The territory is governed by ABS-DTC authority. Approaching the accident site from the south the approach signal is located at MP YYG 12.5. The south end of Grovetown siding is located at milepost YYG15.1 and also serves as the dividing point between the Harrison DTC block and the Grovetown DTC block. There is a 0.7 per cent ascending grade in the northbound direction and the mainline track speed is 50 mph.

Train U49202

The crew of CSX Train U49202 included a locomotive engineer and a conductor. They went on duty at 9:30 p.m. on August 3, 2006, at Tilford Yard in Atlanta, GA. This is the away from home terminal for both crew members that are assigned to extra board in Augusta, GA. Train U49202 consisted of two locomotives, lead locomotive No. CSXT 448, and 94 loaded freight cars. They departed Tilford Yard at 10:59 p.m. and received their first signal at Howell at 11:36 p.m. The crew operated southbound toward Augusta under normal operating conditions obtaining and releasing the following DTC blocks: Stone Mountain, Redan, Lithonia, Conyers, Almon, Covington, Social Circle, Rutledge, Madison, Buckhead, Greensboro, Union Point, Crawfordville, Barnett, Camak, Warren, Thomson, and Dearing.

On August 4, 2006, at 4:22 a.m. the crew obtained the Grovetown DTC block from the BE train dispatcher and proceeded south. At 4:49 a.m. the train crew released the Thomas and Dearing DTC blocks and stopped on the main track at the south end of Grovetown. The engineer was seated at the controls on the west side of the locomotive cab and the conductor was seated on the east side of the cab.

The direction of movement in this report is based on timetable direction of North and South.

The Accident

Train A74303 was operating at 38 mph as it passed the approach signal MP YYG12.5. The engineer acknowledged the signal and reduced locomotive throttle to No. 5 position. The train slowed to 27 mph as it approached the accident site. The conductor trainee noticed they were not slowing down to take the Grovetown siding as required. He started calling the engineer's name and shook him to get his attention. During this time the train passed the stop signal indication at 27 mph.

Train U49202 was stopped on the mainline at Grovetown waiting for Train A74303 to take the siding. Moments before impact the crew noticed the headlight of Train A74303 and determined it was on the mainline. The engineer grabbed the handset to call Train A74303, but realized it was too late and braced for the impact.

After the collision, the engineer of Train A74303 went out the locomotive cab door to the lead locomotive of Train U49202 and saw the crew members were not hurt. He then contacted the CSX dispatcher about the accident. Both the engineer and conductor of Train A74303 had reportable injuries.

CSX, Grovetown Police Department, Fire Department, and Rescue Department responded to the accident.

Analysis & Conclusion

The engineer and conductor of Train A74303, through their own admission, did not recall the elapsed time from approach signal MP YYG12.5 to when they observed Train U46202.

At 6:14 a.m. Train A74303 event recorder indicated they passed the stop signal and the siding switch with the throttle in the No. 5 position and the train operating at 27 mph. At 6:15 a.m. the locomotive throttle was in idle position, the train was placed in emergency, and the independent brake applied. The impact speed is four mph. It was also evident on the event recorder the horn blew once for five seconds and the bell was on for 19 seconds.

The crew of Train A74303 was tested under Federal Railroad Administration regulations and the results were negative.

The Fatigue Avoidance Scheduling Tool (FAST) is a software product which uses employee's sleep and work schedules to predict individual work performance, effectiveness, and alertness over a period of time. Effectiveness can be defined as a measure of speed of making correct and accurate decisions and is highly correlated with reaction time, cognitive output, and overall operator performance.

Based on information furnished by crew members and the hours of service documents completed by the train crew, the circadian rhythms software program calculated that the engineer, conductor, and conductor trainee of Train A74303 were each found to be at 68% effective at the time of the accident.

Train A74303 came to rest 941 feet from the south end of the Grovetown siding switch, derailing the four empty rock cars.

Probable Cause

The Federal Railroad Administration found the probable cause of the accident to be the failure of Train A74303 to comply with restricted speed in connection with a restrictive indication of a block signal.

#