



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-74***

***Florida East Coast Railway Company
Ft. Lauderdale, FL
August 22, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Florida East Coast Rwy Co. [FEC]		1a. Alphabetic Code FEC		1b. Railroad Accident/Incident No. D116082206	
2. Name of Railroad Operating Train #2 Florida East Coast Rwy Co. [FEC]		2a. Alphabetic Code FEC		2b. Railroad Accident/Incident D116082206	
3. Name of Railroad Responsible for Track Maintenance: Florida East Coast Rwy Co. [FEC]		3a. Alphabetic Code FEC		3b. Railroad Accident/Incident No. N/A	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 08 Day: 22 Year: 2006		6. Time of Accident/Incident 12:01: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
				13. Other (describe in narrative) 05	
8. Cars Carrying HAZMAT 4	9. HAZMAT Cars Damaged/Derailed 1	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division System	
13. Nearest City/Town Ft. Lauderdale		14. Milepost (to nearest tenth) 344.7	15. State Abbr Code N/A FL	16. County BROWARD	
17. Temperature (F) (specify if minus) 89 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 3		
21. Track Name/Number airport siding		22. FRA Track Code Class (1-9, X) 3	23. Annual Track Density (gross tons in millions) 50	24. Time Table Direction Code 1. North 3. East 1	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
				26. Was Equipment Attended? 1. Yes 2. No 1	
				27. Train Number/Symbol FEC208 22	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 37 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
29. Trailing Tons (gross tonnage, excluding power units) 16567		a. N/A	b. N/A	c. N/A	d. N/A
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.
(1) First involved (derailed, struck, etc)		N/A	81	yes	Alcohol N/A
(2) Causing (if mechanical cause reported)		N/A	N/A	N/A	Drugs N/A
				33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars
		b. Manual	c. Remote	d. Manual	e. Remote
(1) Total in Train		3	0	0	0
(2) Total Derailed		0	0	0	0
		0	0	0	0
36. Equipment Damage This Consist		801883	37. Track, Signal, Way, & Structure Damage	172960	38. Primary Cause Code T111
					39. Contributing Cause Code N/A
40. Engineer/Operators N/A			41. Firemen N/A		
42. Conductors 1			43. Brakemen N/A		
44. Engineer/Operator Hrs 2 Mi 31			45. Conductor Hrs 2 Mi 31		
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No 1
Fatal		0	0	0	50. Was EOT Device Properly Armed? 1. Yes 2. No 1
Nonfatal		N/A	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No 2
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
				53. Was Equipment Attended? 1. Yes 2. No 1	
				54. Train Number/Symbol FEC141 21	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable

56. Trailing Tons (gross tonnage, excluding power units)		3878		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved (derailed, struck, etc)		TTAX5 53600		10		yes						N/A		N/A			
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)						N			
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.	
(1) Total in Train		3		0		0		(1) Total in Equipment Consist		7		0		85		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		3		0		0		0	
63. Equipment Damage This Consist		190723		64. Track, Signal, Way, & Structure Damage		18400		65. Primary Cause Code		T111		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
1		N/A		1		N/A		Hrs 6 Mi 1		Hrs 6 Mi 1							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No 1		1. Yes 2. No 1							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?								N/A	
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A							
				1. North 2. South 3. East 4. West		N/A											
82. Position		1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code		85. Circumstance		1. Rail Equipment Struck Highway User		Code							
				N/A		2. Rail Equipment Struck by Highway User				N/A							
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		86b. Was there a hazardous materials release by		Code		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A							
1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A															
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		Code		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code					
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)		Warning 3. Standard FLS 6. Audible 9. Watchman 12. None				(See instructions for codes)		N/A		1. Yes 2. No 3. Unknown		N/A					
Code(s)		N/A		N/A		N/A		N/A									
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A							
2. Side of Vehicle Approach																	
3. Opposite Side of Vehicle Approach		N/A															
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop		4. Stopped on Crossing 5. Other (specify in narrative)		N/A			
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		Code							
1. Yes 2. No 3. Unknown		N/A		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		N/A											
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-74 Sketch
rev.jpg



109. SYNOPSIS OF THE ACCIDENT

On August 22, 2006, a Florida East Coast (FEC) Train FEC 20822 was traveling northbound on the main track from Hialeah, Florida (FL) to Jacksonville, FL. This train received a diverging signal at the airport siding, milepost (MP) 345.1, to pass southbound Train FEC 14121 that was stopped on the main track. At 12:01 p.m. Eastern Standard Time (EST), Train FEC 20822, operating on the Airport Side Track, derailed 31 freight cars at MP 344.7. As a result of the derailment, several cars collided into the Train FEC 14121 consist derailing an additional three cars. The impact from this collision struck another cut of standing cars on the No. 1 Storage Track located east and adjacent to the main track. All the derailed cars were in a general pileup.

There were no injuries to any of the crew members. There was no hazardous material spilled and no evacuation necessary. As a result of the derailment and collision, damage to the equipment was \$992,606 and \$191,360 to the track.

At the time of the derailment, it was daylight and clear with a recorded temperature of 89°F.

The cause of the accident is wide gage due to missing or broken fasteners.

110. NARRATIVE

Circumstances prior to the Accident
Train FEC 20822

On August 22, 2006, at 9:30 a.m., a two-man crew reported to their home terminal at Medley, FL. The crew consisted of an engineer and conductor and was assigned to operate Train FEC 20822. They were to operate Train FEC 20822 from Medley to Jacksonville, a distance of 351 miles. Both crew members had a rest period of 12 hours. Train FEC 20822 consisted of three locomotives, 131 loads, five empties, 16,567 tons and a length of 6,130 ft. The crew received documentation for their brake test, a dispatcher's bulletin, and was cleared to depart from Medley in a northward direction by the dispatcher.

Train FEC 20822 was signaled by the dispatcher for a main track route from North Ojus, MP 251.1, a diverging move onto Airport Siding, MP 345.1, then back to the main track at Wilton Manors, MP 338.8. The engineer was seated at the controls on the east side of the lead locomotive and the conductor seated on the west side of the cab observing signals. At 11:47 a.m., they had a clear indication at North Ojus and at 11:59 a.m., received a diverging clear signal indication at Control Point (CP) Airport. At 12:01, Train FEC 20822 was traversing the siding and clear of Airport switch.

Train FEC 14121

On August 21, 2006, a two man crew reported to their home team in Jacksonville at 11:45 p.m. The crew consisted of an engineer with eight hours rest and a conductor with 12 hours rest. They operated Train FEC 14121 southbound from Jacksonville to Hialeah, a distance of 357 miles. Their train consisted of three locomotives, seven loads, 85 empties, 3,906 tons and was 3,200 ft in length. The crew received their operating bulletins, orders, and an air brake test departing Jacksonville at 12:30 a.m.

Train FEC 14121 was operating southbound on the main track near the city of Fort Lauderdale and was instructed to stop at CP Airport, MP 345.1, to meet northbound Train FEC 20822 for a crew change. The relieving crew consisted of an engineer and trainmaster/conductor who went on duty at Hialeah on August 22, at 6 a.m. The crew change took place before the arrival of Train FEC 20822.

In the Fort Lauderdale area, MP 346.9, the timetable speed for the main track is 45 miles per hour (mph) and the track is tangent. Approaching the CP Airport there is a 1,690 ft, 2-degree, 12 minute right-hand curve, followed by 1.7 mile of tangent. At Airport switch, MP 345.3, there is a No. 20 left-hand turnout. After traversing the turn out there is a 2-degree, 1 minute right-hand curve that is 2,555 ft. The speed through the turnout and siding is 40 mph.

The railroad timetable direction of the train was north. The geographic direction was also north. Timetable directions are used throughout this report.

The Accident

Train FEC 20822 was operating at 37 mph in a No. 5 throttle position with a brake pipe pressure of 91 lbs operating on Airport Siding. The speed was recorded by the event recorder on the controlling locomotive. Both the engineer and conductor said they felt a dip in the track when the locomotive passed MP 344.7. They continued north for another 81 car lengths and felt the train jerk forward and an emergency brake application occurred. The engineer released the locomotive independent brake, which prevents a run in from the rear-end of the train to the head-end of the train, and brought the train to a controlled stop. He radioed the conductor of Train FEC 14121 that his train was in emergency. The conductor replied that Train FEC 14121 was also in emergency and departed the locomotive to see what the problem was. About 12:05 p.m., he radioed the engineer of Train FEC 20822 informing him of the derailment. He discovered that Train FEC 20822 had derailed into the side of Train FEC 14121, and two derailed cars from Train FEC 14121 struck a standing cut of cars located on the No. 1 storage track.

The conductor of Train FEC 20822 was instructed to install an end of train device (EOT) on the rear of the remaining portion of the train and proceed on to Jacksonville.

Analysis and Conclusion

Analysis - Mechanical

On October 5, 2006, a post accident inspection was conducted by the Federal Railroad Administration (FRA) Motor Power and Equipment (MP&E) and FEC mechanical inspectors on Train FEC 20822. The 77th and 78th cars in the train consist were taken to FEC's Madden Car Shop in Jacksonville. The 77th car, FEC 13034, was the last car in the head section of the train that did not derail. The 78th car, FEC 15667, was the first car in the train's consist that was derailed. These two cars were suspect as a contributing causal factor to the derailment.

FEC 13034 is a hopper car of special construction used for hauling stone. The car was built 10/72 and rebuilt 05/04. This car was in the train with the A-end of the car facing the direction of movement. An inspection of the side bearings, ride control, wheels, roller bearing adapters, truck side frames, truck bolsters, center plates, and truck springs was made with no FRA defects noted.

FEC 15667 is a hopper car of special construction used for hauling stone. The car was built 12/87 and rebuilt 06/99. This car was in the train with the B-end of the car facing the direction of movement. An inspection of the side bearings, ride control, wheels, roller bearing adapters, truck side frames, truck bolsters, center plates, and truck springs was made with no FRA defects noted. After completing the mechanical inspection it was determined that neither FEC 13034 nor FEC 15667 hopper cars contributed to the accident.

Analysis - Track

On August 23, FRA conducted a hi-rail and track walking inspection between MP 347.5 and MP 342.5 with two defects noted at MP 345.1. The point of derailment (POD) was located between MP 344.4 and MP 344.7. This section of track was destroyed and no geometry measurements could be taken.

FRA conducted a track records inspection on FEC main track and sidings. The inspection revealed that on August 11, 2006 through August 16, 2006, the main track and siding had been inspected by a Herzog Rail Detector Car with no defects found between MP 344.3 and MP 344.7 on Airport Siding. On August 2, 2006, the main track and siding between MP 245.0 and MP 370.0 were inspected by a Norfolk Southern (NS) 33 geometry car. The NS car listed two locations on Airport Siding indicating gage widening at MP 344 + 3102 ft showed 1.08 inches, 14 ft. long and MP 344 + 4694 ft showed 0.91 inches gage widening for 20 ft. These defects were shown as a priority defect on their inspection report, but were still within FRA standards for Class 3 track.

On August 8, 11, 15, and 18, 2006, an FEC track inspector conducted a hi-rail inspection between MP 344.5 and MP 344.3 and listed no defects.

The Freight Train FEC 20822 had the event recorder downloaded by FEC road foreman of engines and the analysis disclosed that the train was traveling at 37 mph and in the 5th throttle position, 91 lbs of brake pipe pressure. The download indicated no unusual operating errors or train handling irregularities.

Conclusion

The Airport passing siding is comprised of 132 lbs RE continuous welded rail re-laid in the year 2000. The rail is attached to concrete ties with bolted compression clips and is supported by limestone ballast. The gage widening noted by the NS Geometry Car NS-33 at MP 344 + 3102 ft of 1.08 inches for 14 ft and MP 344 + 4694 ft with 0.91 inches for 20 ft was never repaired by FEC maintenance of way. Although this condition is still within FRA for compliance, at the time of the test the fastener system had begun to fail. The length of 14 ft and 20 ft are significant. The lateral force exerted on the rail by constant train traffic causes the existing compression clips to break. As the clips break, the length of detached rail increases and the gage continues to widen resulting in a derailment. The statements of the engineer and conductor that they "felt an unusual dip in the track at MP 344.7" supports this event's occurrence.

An investigation by the Federal Railroad Administration found that the probable cause was a wide gage due to defective or missing or broken rail fasteners.