



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-80***


***Burlington Northern Santa Fe
Abbott, NE
October 18, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF			1b. Railroad Accident/Incident No. NE1006108			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF			3b. Railroad Accident/Incident No. NE1006108			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 10 18 2006			6. Time of Accident/Incident 05:57: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
			13. Other (describe in narrative)			01			
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Nebraska	
13. Nearest City/Town Cario			14. Milepost (to nearest tenth) 105.7		15. State Abbr Code N/A NE		16. County HALL		
17. Temperature (F) (specify if minus) 33 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 6		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
21. Track Name/Number Main Track #2			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 113.5		24. Time Table Direction Code 1. North 3. East 3		
OPERATING TRAIN #1									
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1	
								27. Train Number/Symbol CBTM CNR01	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 45 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits			
29. Trailing Tons (gross tonnage, excluding power units) 18999						m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)			
						e N/A N/A N/A N/A			
31. Principal Car/Unit			a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)			N/A	76	yes	Alcohol Drugs 0 0			
(2) Causing (if mechanical cause reported)			0	0	N/A	33. Was this consist transporting passengers? (Y/N) N/A			
34. Locomotive Units		a. Head End	b. Mid Train		c. Remote	d. Manual	e. Remote	35. Cars	
(1) Total in Train		0	0		0	1	0	(1) Total in Equipment Consist	
(2) Total Derailed		0	0		0	0	0	(2) Total Derailed	
36. Equipment Damage This Consist			1278235			37. Track, Signal, Way, & Structure Damage 432500			
						38. Primary Cause Code T204			
						39. Contributing Cause Code N/A			
Number of Crew Members				Length of Time on Duty					
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 0 Mi 57	
								45. Conductor Hrs 0 Mi 57	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 1	
Fatal		0		0		0		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Nonfatal		N/A		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2									
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
								54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic m. Special instructions n. Other than main track			
						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

56. Trailing Tons (gross tonnage, excluding power units)		0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved (derailed, struck, etc)		0		0		N/A						N/A		N/A			
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A					
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight			
(1) Total in Train		0		0		0		(1) Total in Equipment Consist		0		0		0			
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0		0			
63. Equipment Damage		This Consist		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
0		0		0		0		Hrs 0 Mi 0		Hrs 0 Mi 0							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?						N/A			
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		0		81. Direction geographical		Code		84. Position of Car Unit in Train		0							
				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance		Code									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing				N/A		1. Rail Equipment Struck Highway User		N/A									
4. Trapped						2. Rail Equipment Struck by Highway User		N/A									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code									
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes			
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A		2. No		N/A	
														3. Unknown		N/A	
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code					
1. Both Sides						1. Yes				1. Yes							
2. Side of Vehicle Approach						2. No		N/A		2. No							
3. Opposite Side of Vehicle Approach				N/A		3. Unknown				3. Unknown							
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
0		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)		N/A			
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code											
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A											
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed													
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
						102. Highway Vehicle Property Damage (est. dollar damage)		0		103. Total Number of Highway-Rail Crossing Users (include driver)		0					
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code									
1. Yes 2. No				N/A		1. Yes 2. No		N/A									
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code									
1. Yes 2. No				N/A		1. Yes 2. No		N/A									

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

An eastbound BNSF Railway Company (BNSF) coal train derailed 31 cars on October 18, 2006, at 5:57 a.m. (CDT). The accident occurred 6.1 miles east of Cairo, Nebraska, at milepost (MP) 105.7, on the BNSF Ravenna Subdivision.

There were no injuries or hazardous material spills as a result of the derailment. Total damages reported for the derailment were \$1,710,735.

At the time of the accident, it was dark with light snow and a temperature of 33 degrees Fahrenheit.

The probable cause of the derailment is being ruled as T204 - Broken weld (field).

110. NARRATIVE

Circumstances Prior to the Accident

The train crew of Train Symbol CBTMCNR0-16 consisted of an engineer and conductor. They first went on duty at 5 a.m., CDT, October 18, 2006, at Ravenna, Nebraska. This was their away terminal, and both had received more than the statutory off-duty period prior to reporting for duty.

Their assigned train consisted of one locomotive on the head-end, 134 loaded coal cars, and a remote unit on the rear-end. The train was 7,113 feet long with 18,999 trailing tons. This crew was scheduled to take the train to Lincoln, Nebraska.

The train had received a Class 1 air brake test 8 days prior to the derailment. This test was performed by BNSF mechanical personnel in Alliance, Nebraska, on October 10, 2006, when this cycle train was an empty heading to Wyoming to be loaded. According to BNSF mechanical officials, this train sat at Ardmore, South Dakota, for 5 days after receiving their Class 1 air brake test. This was for train spacing purposes before continuing to the plant October 15, to be loaded. The train kept its same power and remained on air continuously.

There was no work performed en route after departing, and the trip was uneventful for the 22 miles leading up to the derailment.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the south side of the lead locomotive. The conductor was seated on the north side of the same locomotive.

The track at and leading up to the point of derailment (POD) is tangent and on a level grade. It is constructed of 132-pound continuous-welded rail (CWR) on concrete ties, except for the area across a ballast deck bridge, which is 136-pound conventional jointed rail on wood crossties. This jointed rail was because of panels laid across the bridge during a recent construction project. The joints had been staggered and were scheduled to be welded in the near future. There are no other switches, turnouts, bridges, or culverts in the immediate area.

The railroad timetable direction and geographical direction of the train is east.

The Accident

The train was being operated at 45 mph approaching the derailment area. According to the train crew, they did not observe or feel anything unusual prior to this area. The speed at the time of the derailment was also 45 mph. Both speeds (approaching and at the time of derailment) were recorded by the event recorder of the controlling locomotive. Maximum authorized speed for this track is 60 mph. Maximum authorized speed for this train was 50 mph because it exceeded the 100-ton threshold per operative brake, as designated in current BNSF Nebraska Division Timetable.

Just after traversing a bridge, the train experienced an undesired emergency application of the air brake system, where upon it was discovered the 75th through 105th head cars had derailed.

Immediately following the accident, the train crew immediately contacted a westbound train coming at them on main Track No. 1 and told them they were in emergency. The westbound quickly brought their train down to restricted speed and were able to stop well short of the derailed cars that were fouling main Track No. 1. The conductor of the derailing train then walked back and found the derailed cars.

As a result of the derailment, there was damage to both ballast deck bridges located on Main Track Nos. 1 and 2. After the derailed cars were cleared, the bridge was found to be structurally sound and not the cause of the derailment. The damage was limited to the walkways and ballast retainers.

Analysis and Conclusions

Analysis

The two crew members of Train Symbol CBTMCNR0-16 were FRA mandatory post-accident toxicologically tested because this accident exceeded the \$1 million major accident threshold. The test results obtained from the FRA Alcohol and Drug Control Program Manager were negative.

The event recorders for both locomotives revealed nothing inconsistent with normal train handling at or prior to the time of the derailment.

The last ultrasonic rail detection test through this area was on August 29, 2006, and the last geometry car survey with the railroad's Car No. 80 was on September 6, 2006, with no defects noted in the immediate area. The track was inspected by hi-rail vehicle on October 16, 2006, with no exceptions taken in the area. Track inspection records revealed that this track was inspected well within the required frequency the month prior to the accident, with no exceptions noted in the immediate area.

A suspect piece of rail (at a Orogo-thermit field weld) was recovered from the accident and sent to the BNSF's Technical Research and Development Lab in Topeka, Kansas, for analysis. The weld was 132/136 compromise weld and had leaving head batter on the rail consistent with this type of derailment cause.

The suspect piece had small "hot tears," 1-1/8 in length and extending approximately 1/8 inch into the rail. These tears were located along the base of the rail at the edge of the weld in the heat affected zone. Hot tears are caused by non-uniform cooling or movement of the weld during the cooling process. The mate to this fracture was not recovered from the derailment sight to determine receiving head batter.

This weld was made on October 3, 2006, and according to the BNSF welding report, there was no rail added or subtracted. The welder who made this particular weld said there was nothing he recalled as being unusual during the process and felt he had sufficient time to make it.

No suspicious mechanical equipment was found in the wreck or during clean-up activities.

Conclusion

The railroad was in compliance with their own and all applicable FRA standards. There were no witnesses to the accident.

The data reviewed from the event recorder ruled out train handling as a cause. There were no marks found on the rail or ties prior to the pile-up. There were also no track components, i.e. bridges, turnouts, grade crossings in the point of derailment (POD) area that could have contributed to the cause. There was no grade and curvature in the area that would have contributed to the cause. No marks were found on the flange or tread of the wheels of the one locomotive and 75 cars that made it over this area to suggest they encountered anything prior to the derailment. The last hotbox/dragging equipment detector at MP 107.3 had no exceptions taken

Probable Cause and Contributing Factors

The Federal Railroad Administration found that the catastrophic nature of this derailment substantiates the evidence found in the broken field weld. The probable cause of this derailment is determined as T204 - Broken weld (field).