



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-86***

***Burlington Northern Santa Fe  
Miltonvale, KS  
October 27, 2006***

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. KS100611	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		3a. Alphabetic Code BNSF		3b. Railroad Accident/Incident No. KS100611	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 10 Day: 27 Year: 2006		6. Time of Accident/Incident 05:15: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	

7. Type of Accident/Incident (single entry in code box)						01						
1. Derailment	2. Head on collision	3. Rear end collision	4. Side collision	5. Raking collision	6. Broken Train collision	7. Hwy-rail crossing	8. RR grade crossing	9. Obstruction	10. Explosion-detonation	11. Fire/violent rupture	12. Other impacts	13. Other (describe in narrative)

8. Cars Carrying HAZMAT	9. HAZMAT Cars Damaged/Derailed	10. Cars Releasing HAZMAT	11. People Evacuated	12. Division
0	0	0	0	Kansas

13. Nearest City/Town Miltonvale		14. Milepost (to nearest tenth) 97.4		15. State Abbr Code N/A KS		16. County CLOUD	
-------------------------------------	--	---	--	-------------------------------	--	---------------------	--

17. Temperature (F) (specify if minus) 42 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
--	--	--	--	---	--	---	--

21. Track Name/Number Single Main Track		22. FRA Track Code Class (1-9, X) 3		23. Annual Track Density (gross tons in millions) 3.82		24. Time Table Direction Code 1. North 3. East 3	
--	--	--	--	---	--	--	--

**OPERATING TRAIN #1**

25. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		26. Was Equipment Attended?		27. Train Number/Symbol	
		2. Passenger train		5. Single car		8. Light loco(s).		1		1. Yes 2. No		1 GCCD GAT92	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car							

28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 32 MPH R		30. Method(s) of Operation (enter code(s) that apply)						30a. Remotely Controlled Locomotive?			
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits						0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter			
29. Trailing Tons (gross tonnage, excluding power units) 15099		j		N/A		N/A		N/A		0	

31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A		11		yes		Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0		0		N/A		0		0	
								33. Was this consist transporting passengers? (Y/N) N			

34. Locomotive Units		a. Head End		Mid Train		Rear End		35. Cars		a. Freight		b. Pass.		c. Freight		d. Pass.		e. Caboose	
(1) Total in Train		3		0		0		(1) Total in Equipment Consist		111		0		0		0		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		25		0		0		0		0	

36. Equipment Damage This Consist		1111546		37. Track, Signal, Way, & Structure Damage		70500		38. Primary Cause Code		T207		39. Contributing Cause Code		N/A	
-----------------------------------	--	---------	--	--	--	-------	--	------------------------	--	------	--	-----------------------------	--	-----	--

40. Engineer/Operators				41. Firemen				42. Conductors				43. Brakemen				44. Engineer/Operator				45. Conductor			
N/A				0				1				1				Hrs 6 Mi 30				Hrs 6 Mi 30			

Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device?				50. Was EOT Device Properly Armed?			
Fatal		0		0		0		1. Yes 2. No   1				1. Yes 2. No   1			
Nonfatal		N/A		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No				N/A			

**OPERATING TRAIN #2**


52. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		53. Was Equipment Attended?		54. Train Number/Symbol	
		2. Passenger train		5. Single car		8. Light loco(s).		N/A		1. Yes 2. No		N/A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car							

55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply)						57a. Remotely Controlled Locomotive?	
		a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track						0 = Not a remotely controlled 1 = Remote control portable	



108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-  
86\_Sketch.  
jpg



#### 109. SYNOPSIS OF THE ACCIDENT

Eastbound BNSF Railway Company's (BNSF) Train Symbol GCCDGAT9-25 derailed on October 27, 2006 at 5:15 a.m. CDT, near Miltonvale, Kansas, on single main track, at BNSF Milepost (MP) 97.4, on Kansas Division, Strong City Subdivision. Miltonvale is located in Cloud County, about 30 miles north of Salina, Kansas. Timetable directions used for this report are east and west.

The train consisted of 3 locomotives, 111 covered hoppers loaded with grain and no empties.

Twenty-five rail cars derailed, beginning with the 8th head rail car through the 32nd head rail car. Twenty-three of the derailed cars spilled their load and 19 were destroyed. There were no injuries. There was no evacuation. Damages were \$1.1 million for equipment and \$70,500 for track and structures.

It was dark at the time of derailment and the weather was reported as 42 °F and cloudy.

The cause of the derailment was determined to be a track-related cause, due to a detail fracture from shelling or head check.

#### 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

##### Circumstances Prior to the Accident

The BNSF train crew consisting of an engineer, conductor, and brakeman went on duty 10:45 p.m. (c.d.t.), on October 26, 2006, at their home terminal in Newton, Kansas. All crew members received at least the minimum time off for rest before reporting for duty. They were provided deadhead transportation via a company provided van service from Newton to Concordia, Kansas. Upon arriving at Concordia, the crew proceeded to couple their train together and completed a Class I brake test - initial inspection as required.

The crew received their track bulletins and train consist at Concordia. After receiving the required track warrants from the dispatcher to occupy the main track between Concordia and Newton, the conductor performed a job safety briefing with the crew members.

The train departed Concordia with Locomotive No. BNSF 5495 in the lead position and Locomotive Nos. BNSF 5699 and BNSF 5388 in the trailing positions; coupled with 111 loaded, covered hoppers and no empties. The train consisted of 15,099 trailing tons and was 6,816 feet in length. The train was operated entirely on the BNSF Strong City Subdivision.

The engineer was seated at the controls of the lead locomotive on the south side of the locomotive. The conductor was sitting behind the brakeman on the north side of the locomotive.

The track had a left-hand curve of 5-degrees 14-minutes on a level grade, while approaching MP 97.4.

##### The Accident

Train Symbol GCCDGAT9-25 departed Concordia, from a grain elevator at MP 113.5. The train was traveling at a recorded speed of 32 miles per hour (mph). The maximum authorized speed is 40 mph as designated in BNSF Timetable No. 7, dated April 28, 2004.

The train received an undesired emergency train air brake application at MP 97.4. After the train came to a stop, the conductor and brakeman proceeded to inspect the train. They found 25 rail cars derailed, beginning with the 8th head rail car through the 32nd head rail car. All derailed rail cars were loaded with grain. Twenty-three of the cars spilled their load and 19 were destroyed. The conductor reported to the dispatcher there was no hazardous material involved and there were no injuries.

##### Analysis and Conclusion

###### Analysis

The last date of an internal rail inspection was September 14, 2006, by Herzog, patrolling in vehicle HRZ 108. The inspection frequency for the area is 110 days.

The last recorded inspections are as follows: rail detector inspection on 9/14/06; track geometry car inspection on 9/11/06; routine track inspection on 10/23/06 (which is performed twice weekly).

Review of report and site observations determined that the rail was manufactured by US Steel in Illinois in June 1988.

The crew members were transported to a medical facility for FRA post-accident toxicology tests. All test results were negative.

Conclusion

The rail profile showed a head loss of 3/8 inch. The annual million gross tonnage is 5.5. The specific rail failure description is a detail fracture, with the length/size of the defect at 25 percent. The derailment occurred in the spiral of a curve because of this rail failure.

Probable Cause

The FRA determined that the cause of the derailment was a broken rail - detail fracture from shelling or head crack.