



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-87***

***Union Pacific
Kismet, KS
November 8, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 1106KC006					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A					
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 1106KC006					
4. U.S. DOT_AAR Grade Crossing Identification Number 605539A			5. Date of Accident/Incident Month Day Year 11 08 2006			6. Time of Accident/Incident 02:04: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM					
7. Type of Accident/Incident (single entry in code box)			1. Derailment			2. Head on collision					
			3. Rear end collision			4. Side collision					
			5. Raking collision			6. Broken Train collision					
			7. Hwy-rail crossing			8. RR grade crossing					
			9. Obstruction			10. Explosion-detonation					
			11. Fire/violent rupture			12. Other impacts					
			13. Other (describe in narrative)			07					
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Kansas City			
13. Nearest City/Town Kismet			14. Milepost (to nearest tenth) 422.22		15. State Abbr Code N/A KS		16. County SEWARD				
17. Temperature (F) (specify if minus) 88 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/Number Single Main			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 33		24. Time Table Direction Code 1. North 3. East 4				
OPERATING TRAIN #1											
25. Type of Equipment Consist (single entry)		1. Freight train		2. Passenger train		3. Commuter train		4. Work train			
		5. Single car		6. Cut of cars		7. Yard/switching		8. Light loco(s).			
		9. Maint./inspect.car		A. Spec. MoW Equip. Code		26. Was Equipment Attended?		27. Train Number/Symbol			
		8		1. Yes 2. No		1		IDUAL-7			
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 68 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remotely controlled transmitter				
29. Trailing Tons (gross tonnage, excluding power units) 0			e		N/A N/A N/A N/A		0				
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A		1		N/A		Alcohol		Drugs	
		N/A		N/A		N/A		N/A		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A		33. Was this consist transporting passengers? (Y/N) N/A			
34. Locomotive Units		a. Head End		b. Mid Train		c. Rear End		35. Cars		Load	
		b. Manual		c. Remote		d. Manual		e. Remote		a. Freight	
		b. Pass.		c. Freight		d. Pass.		e. Caboose			
(1) Total in Train		1		0		0		0		(1) Total in Equipment Consist	
		0		0		0		0		0	
(2) Total Derailed		0		0		0		0		(2) Total Derailed	
		0		0		0		0		0	
36. Equipment Damage This Consist 300			37. Track, Signal, Way, & Structure Damage 0			38. Primary Cause Code M302			39. Contributing Cause Code N/A		
Number of Crew Members					Length of Time on Duty						
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 1		44. Engineer/Operator Hrs 5 Mi 7		45. Conductor Hrs 5 Mi 7	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 2		50. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
Fatal		0		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
Nonfatal		N/A		0		0					
OPERATING TRAIN #2											
52. Type of Equipment Consist (single entry)		1. Freight train		2. Passenger train		3. Commuter train		4. Work train		5. Single car	
		6. Cut of cars		7. Yard/switching		8. Light loco(s).		9. Maint./inspect.car		A. Spec. MoW Equip. Code	
		N/A		N/A		N/A		N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
		N/A		N/A		N/A		N/A		54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable				

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT					FRA File # HQ-2006-87																			
56. Trailing Tons (gross tonnage, excluding power units) 0			c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A																	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.																		
(1) First involved (derailed, struck, etc)		0		0		N/A		Alcohol		Drugs																
(2) Causing (if mechanical cause reported)		0		0		N/A		N/A		N/A																
60. Was this consist transporting passengers? (Y/N)		N/A																								
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars			Loade		Empty		e. Caboose											
				b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass.		c. Freight		d. Pass.								
(1) Total in Train		0		0		0		0		0		(1) Total in Equipment Consist		0		0		0		0						
(2) Total Derailed		0		0		0		0		0		(2) Total Derailed		0		0		0		0						
63. Equipment Damage This Consist			64. Track, Signal, Way, & Structure Damage			65. Primary Cause Code			66. Contributing Cause Code			N/A			N/A											
Number of Crew Members						Length of Time on Duty																				
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor		Hrs		0		Mi		0								
0		0		0		0		Hrs		0		Mi		0		0		0								
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?		1. Yes		2. No		N/A		1. Yes		2. No		N/A				
Fatal		0		0		0		1. Yes		2. No		N/A		1. Yes		2. No		N/A								
Nonfatal		0		0		0		78. Caboose Occupied by Crew?				1. Yes		2. No						N/A						
								1. Yes		2. No																
Highway User Involved						Rail Equipment Involved																				
79. Type		C. Truck-Trailer.		F. Bus		J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code										
A. Auto		D. Pick-Up Truck		G. School Bus		K. Pedestrian		A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)												
B. Truck		E. Van		H. Motorcycle		M. Other (spec. in narrative)				2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		6										
80. Vehicle Speed (est. MPH at impact)		15		81. Direction geographical		Code		84. Position of Car Unit in Train		1																
				1. North		2. South		3. East		4. West																
82. Position		Code		1. Stalled on Crossing		2. Stopped on Crossing		3. Moving Over Crossing		4. Trapped		3		85. Circumstance		Code										
												1. Rail Equipment Struck Highway User		2. Rail Equipment Struck by Highway User		1										
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		1. Highway User		2. Rail Equipment		3. Both		4. Neither		4		86b. Was there a hazardous materials release by		Code										
												1. Highway User		2. Rail Equipment		3. Both		4. Neither		4						
86c. State here the name and quantity of the hazardous materials released, if any.		N/A																								
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code										
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		1. Yes		2. No		3. Unknown		2								
Code(s)		07		08		N/A		N/A		N/A		N/A														
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code		1. Both Sides		2. Side of Vehicle Approach		3. Opposite Side of Vehicle Approach		1		1. Yes		2. No		3. Unknown		2
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code		1. Drove around or thru the Gate		4. Stopped on Crossing		5. Other (specify in narrative)		3						
37		1. Male		2		1. Yes		2. No		3. Unknown		2		2. Stopped and then Proceeded		3. Did not Stop										
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code		1. Permanent Structure		3. Passing Train		5. Vegetation		7. Other (specify in narrative)		8										
1. Yes		2. No		3. Unknown		2		2. Standing Railroad Equipment		4. Topography		6. Highway Vehicle		8. Not obstructed												
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code		1. Killed		2. Injured		3. Uninjured		1		103. Total Number of Highway-Rail Crossing Users (include driver)		3		
		3		0		102. Highway Vehicle Property Damage (est. dollar damage)		6000		1. Yes		2. No														
104. Locomotive Auxiliary Lights?		Code		1. Yes		2. No		1		105. Locomotive Auxiliary Lights Operational?		Code		1. Yes		2. No		1								
106. Locomotive Headlight Illuminated?		Code		1. Yes		2. No		1		107. Locomotive Audible Warning Sounded?		Code		1. Yes		2. No		1								

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-87
Sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On November 8, 2006, at approximately 2:04 p.m., westbound Union Pacific Railroad Company (UP) freight Train Symbol IDUAL-7, consisting of a single locomotive operating at a recorded speed of 68 mph, collided with a southbound 2002 Dodge Intrepid motor vehicle. The motor vehicle was operating at an estimated speed of 15 mph. The collision occurred at a passive highway-rail grade crossing (HGC) intersection, equipped with crossbucks for both directions of motor vehicle traffic and a stop sign for southbound motor vehicle traffic. The collision occurred approximately 124.22 miles west of Pratt, Kansas, near railroad location, Kismet, Kansas, at UP Milepost (MP) 422.22 on the Kansas City Service Unit, Pratt Subdivision.

The motor vehicle contained three occupants. The driver and passengers were fatally injured. The motor vehicle damages were estimated to be \$6,000.

The train crew of Train Symbol IDUAL-7 was not injured and the locomotive did not derail. The estimated monetary damages to the locomotive was \$300.

The weather at the time of the collision was daylight, clear, with a temperature of 88 degrees Fahrenheit and 14 mph winds.

The collision was caused by the failure of the motor vehicle operator to stop at the stop sign located at the HGC intersection and failure to yield the right-of-way to a train in the hazardous proximity of the HGC intersection.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

UP Train Symbol IDUAL-7 West included a locomotive engineer, conductor, and brakeman. They went on duty at 9 a.m. central standard time (c.d.t.), November 8, 2006, at their home terminal in Pratt, Kansas. All crew members received more than their required statutory off-duty period prior to reporting for duty.

The train consisted of one locomotive only and is considered the West Local by local UP personnel. The locomotive was destined for Liberal, Kansas, the train crew's away-from-home terminal. The train departed Pratt, Kansas, at 10:30 a.m., after the train crew conducted required equipment tests. There was no work conducted en route.

The locomotive engineer was seated in the engineer's seat (the north side of the cab) and operated Train Symbol IDUAL-7 from Pratt, without incident prior to the point of the collision, utilizing the locomotive's dynamic braking as needed throughout the trip. The conductor was seated left of the engineer (the south side of the cab), with the brakeman seated directly behind the conductor.

The 2002 Dodge Intrepid had three occupants, the 37-year-old female driver, a 54-year-old female in the right front seat, and a 4-year-old female in the back seat. The motor vehicle was traveling southbound on County Road "P", also identified as Rolling Hills Road, approaching the highway-rail grade crossing (HGC) intersection at approximately 15 mph. Information on the driver's alertness and activities prior to the collision are not available.

The railroad through this area is a single main track tangent in both directions from the subject HGC intersection for at least 5 miles, with a .26-percent westward ascending grade. Timetable directions are east and west through the subject area. These directions are used throughout this report.

The railroad timetable direction is east to west, with the geographical direction northeast to southwest. The geographical direction of County Road "P"/ Rolling Hills Road is north to south.

County Road "P"/Rolling Hills Road, roadway prior to and at the HGC intersection, is a 2-lane, sand and native soil surface, tangent from the north to the south. Traveling north to south on this county road, the grade is practically level. The dirt/sand road intersects the single main track at approximately 80-degree angle. The crossing is 24-foot full timber constructed surface. The surrounding terrain north of the HGC intersection is predominantly level, non-tilled agriculture property.

The Accident

Train IDUAL-7 West

The train was operating at a recorded speed of 70 mph while approaching the subject HGC intersection. The train crew's sight quadrants of the intersection were not obstructed, with the exception of the slightly raised agriculture and vegetational ridge area in the northeast quadrant of the HGC intersection.

Just prior to the collision, the brakeman observed a dark colored motor vehicle traveling southbound on County Road "P"/Rolling Hills Road. The brakeman alerted the locomotive engineer and conductor. The engineer utilized the locomotive's air horn and bell prior to the whistle board that was installed 1,600 feet prior to the intersection and did not apply the train's air brakes. The engineer thought the motor vehicle would stop at the stop sign located at the HGC intersection. The motor vehicle disappeared from the sight of the train crew due to the slightly raised dirt and vegetational ridge area in the northeast quadrant of the HGC intersection.

Approximately 15 to 20 feet from the HGC intersection, the train crew observed the motor vehicle emerge from behind the slightly raised dirt and vegetational ridge area. The motor vehicle did not stop at the stop sign north of the HGC intersection, so the engineer placed the train's air brakes into a service application. The train had slowed to 68 mph when the locomotive collided with the motor vehicle. The engineer placed the train's air brakes into an emergency application and waited for the locomotive to stop. The train crew was not injured.

Witnesses traveling westbound on U.S. Highway 54, which parallels the UP trackage through the subject area, indicated they observed the southbound motor vehicle on County Road "P"/Rolling Hills Road enter the HGC intersection without stopping at the stop sign, and then observed the resultant car/train collision. The Kansas Highway Patrol estimated the motor vehicle was traveling at approximately 10 to 15 mph at the time of the impact. There is no posted speed limit sign on the roadway in the area of the HGC intersection.

The locomotive struck the left side of the motor vehicle in the area of the driver's door, ejecting the right front occupant. The right front seat belt for the ejected occupant was still buckled in place and had stretch and blood evidence on the belt indicating the belt was applied during the collision. The other occupants remained in the motor vehicle. The motor vehicle was thrown into the southwest quadrant of the HGC intersection, resting on its top approximately 100 feet from the point of impact. There was no evidence of the motor vehicle braking prior to the collision.

The locomotive stopped 3,426 feet west of the point of impact. The conductor utilized the onboard radio communications to contact the train dispatcher and corridor manager, indicating the car/train collision. The conductor and brakeman detrained and walked back to the point of impact. Emergency response was at the scene when they arrived at the HGC intersection.

Emergency responders assessed the collision area and found one motor vehicle occupant ejected and two occupants seat belted into the motor vehicle, all fatally injured. The Kansas District 26 Coroner pronounced the three motor vehicle occupants deceased.

The locomotive sustained approximately \$300.00 monetary damages. The motor vehicle sustained approximately \$6,000.00 damages. There was no damage to the track structure or passive warning devices.

Analysis and Conclusions

Analysis:

The HGC intersection north of the UP main track was equipped with two individual signs on two separate posts, a stop sign, and a crossbuck sign. The south portion of the HGC intersection approaching the UP main track is equipped with a crossbuck sign only. The northeast quadrant of the HGC intersection has a raised sand/dirt area with dead and dormant vegetation paralleling the UP main track to the east.

The locomotive was equipped with two headlights, two ditch lights, and audible warning device required by Federal regulations. The locomotive engineer post incident tested these devices at the accident site in the presence of the Kansas Highway Patrol and UP Manager of Operating Practices. The devices functioned as intended.

The locomotive was also equipped with a speed indicator and an event recorder. The relevant event recorder data was downloaded by a UP official. Analysis disclosed the locomotive engineer was in compliance with all applicable railroad operating and train handling requirements. The Federal Railroad Administration (FRA) reviewed the analysis and concurred with the conclusions.

Conclusion:

The railroad was in full compliance with their own standards and all applicable Federal Regulatory Standards. The train crew and eye witnesses indicated that the southbound motor vehicle did not stop at the stop sign when a train was in the hazardous proximity of the HGC intersection and was struck by the westbound locomotive.

Probable Cause and Contributing Factors:

The FRA determined that the probable cause of the collision was the motor vehicle driver's failure to stop at the stop sign located at the HGC intersection, as