



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-91***

***Union Pacific/Burlington Northern Santa Fe  
Memphis, TN  
November 22, 2006***


***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 1106LK046		
2. Name of Railroad Operating Train #2 BNSF Rwy Co. [BNSF]		2a. Alphabetic Code BNSF		2b. Railroad Accident/Incident SF11206117		
3. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS ]		3a. Alphabetic Code NS		3b. Railroad Accident/Incident No. 027240		
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month   Day   Year 11   22   2006		6. Time of Accident/Incident 02:19: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box) 1. Derailment      4. Side collision      7. Hwy-rail crossing      10. Explosion-detonation      13. Other (describe in narrative) 2. Head on collision      5. Raking collision      8. RR grade crossing      11. Fire/violent rupture 3. Rear end collision      6. Broken Train collision      9. Obstruction      12. Other impacts						
8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed 0	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division N/A		
13. Nearest City/Town N/A		14. Milepost (to nearest tenth) 547.0	15. State Abbr Code N/A   N/A	16. County N/A		
17. Temperature (F) (specify if minus) 0 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark N/A	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow N/A	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry N/A			
21. Track Name/Number N/A		22. FRA Track Code Class (1-9, X) N/A	23. Annual Track Density (gross tons in millions) 0	24. Time Table Direction Code 1. North 3. East N/A		
<b>OPERATING TRAIN #1</b>						
25. Type of Equipment Consist (single entry) 1. Freight train      4. Work train      7. Yard/switching 2. Passenger train      5. Single car      8. Light loco(s). 3. Commuter train      6. Cut of cars      9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No   1		
27. Train Number/Symbol QNLSE21						
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated      16      MPH      R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS      g. Automatic block      m. Special instructions b. Auto train control      h. Current of traffic      n. Other than main track c. Auto train stop      i. Time table/train orders      o. Positive train control d. Cab      j. Track warrant control      p. Other (Specify in narrative) Code(s) e. Traffic      k. Direct traffic control f. Interlocking      l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 6619						
31. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A		a. Initial and Number 6	b. Position in Train 6	c. Loaded (yes/no) yes	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol   Drugs N/A   N/A	
(2) Causing (if mechanical cause reported) 0		0	0	N/A	33. Was this consist transporting passengers? (Y/N) N/A	
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars	
		b. Manual	c. Remote	d. Manual   c. Remote	a. Freight   b. Pass.   c. Freight   d. Pass.   e. Caboose	
(1) Total in Train		2	0	0	(1) Total in Equipment Consist 49   0   24   0   0	
(2) Total Derailed		0	0	0	(2) Total Derailed 3   0   2   0   0	
36. Equipment Damage This Consist      26984		37. Track, Signal, Way, & Structure Damage 12417		38. Primary Cause Code H605		
				39. Contributing Cause Code H603		
40. Engineer/Operators N/A			41. Firemen 0			
42. Conductors 1		43. Brakemen 0				
44. Engineer/Operator Hrs 5 Mi 49		45. Conductor Hrs 5 Mi 49				
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other		
Fatal		0	0	0		
Nonfatal		N/A	0	0		
		49. EOT Device? 1. Yes 2. No   1		50. Was EOT Device Properly Armed? 1. Yes 2. No   1		
		51. Caboose Occupied by Crew? 1. Yes 2. No   N/A				
<b>OPERATING TRAIN #2</b>						
52. Type of Equipment Consist (single entry) 1. Freight train      4. Work train      7. Yard/switching 2. Passenger train      5. Single car      8. Light loco(s). 3. Commuter train      6. Cut of cars      9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		53. Was Equipment Attended? 1. Yes 2. No   1		
54. Train Number/Symbol EMHSNAM223						
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated      0      MPH      R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS      g. Automatic block      m. Special instructions b. Auto train control      h. Current of traffic      n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units)  3087		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) 1 N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter  0									
58. Principal Car/Unit (1) First involved (derailed, struck, etc) BNSF 6062		a. Initial and Number 1		b. Position in Train N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol N/A		Drugs N/A							
(2) Causing (if mechanical cause reported) 0		0		N/A		60. Was this consist transporting passengers? (Y/N) N/A											
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loaded a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose			
(1) Total in Train 2		0		0		0		(1) Total in Equipment Consist 0		0		123		0			
(2) Total Derailed 0		0		0		0		(2) Total Derailed 0		0		0		0			
63. Equipment Damage This Consist 15000		64. Track, Signal, Way, & Structure Damage 1500		65. Primary Cause Code H605		66. Contributing Cause Code N/A		Number of Crew Members				Length of Time on Duty					
67. Engineer/Operators 1		68. Firemen 0		69. Conductors 1		70. Brakemen 1		71. Engineer/Operator Hrs 8 Mi 19		72. Conductor Hrs 8 Mi 19							
Casualties to:		73. Railroad Employees 0		74. Train Passengers 0		75. Other 0		76. EOT Device? 1. Yes 2. No   1		77. Was EOT Device Properly Armed? 1. Yes 2. No   1							
Nonfatal 0		0		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No				N/A					
Highway User Involved						Rail Equipment Involved											
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)   N/A		Code N/A		83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train (units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train (units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)   N/A		Code N/A		84. Position of Car Unit in Train 0		Code N/A							
80. Vehicle Speed (est. MPH at impact) 0		81. Direction geographical 1. North 2. South 3. East 4. West   N/A		Code N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User   N/A		Code N/A									
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped   N/A		Code N/A		86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither   N/A		Code N/A		86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither   N/A		Code N/A							
86c. State here the name and quantity of the hazardous materials released, if any. N/A																	
87. Type of Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) Warning 3. Standard FLS 6. Audible 9. Watchman 12. None		Code N/A		88. Signaled Crossing Warning (See instructions for codes) Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown   N/A		Code N/A									
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach   N/A		Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown   N/A		Code N/A		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown   N/A		Code N/A							
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female   N/A		Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown   N/A		Code N/A		96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative)   N/A		Code N/A					
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown   N/A		Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed   N/A		Code N/A		Code N/A									
101. Casualties to Highway-Rail Crossing Users Killed Injured 0 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured   N/A		Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No   N/A		Code N/A									
104. Locomotive Auxiliary Lights? 1. Yes 2. No   N/A		Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No   N/A		Code N/A											
106. Locomotive Headlight Illuminated? 1. Yes 2. No   N/A		Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No   N/A		Code N/A											

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
HQ-2006-91.jpg

U.S. Department of Transportation  
Federal Railroad Administration  
**FRA FACTUAL RAILROAD ACCIDENT REPORT**  
108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



About 2:05 a.m. UP train QNLSF21 called the NS yardmaster requesting a track. The NS yardmaster instructed UP QNLSF21 to use the East Main from Tower 17 to Neptune Street (MP 550.4) en route to the UP's Sargent Yard. The UP crew on QNLSF21 called the train dispatcher via radio advising him of the designated track. The request given by QNLSF21 over the radio was unclear. The train dispatcher repeated the instructions, but thought the crew requested the West Main at the Southern instead of East Main. The crew of QNLSF21 confirmed the instructions repeated by the train dispatcher by ending the conversation with, "UP 9164 out." The repeat by the train dispatcher clearly stated West Main. After QNLSF21 ended the radio transmission the train dispatcher lined the switches from the UP No. 1 Main Track to the NS West Main. The UP train dispatcher did not have prior knowledge that NS had interchanged an empty coal train to the BNSF on the NS West Main at Tower 17.

Eastbound UP trains arriving Memphis, TN must operate across the CNIC (Canadian Central/Illinois Central) railroad crossing at grade, MP 376.3. Union Pacific operating rules designate that Yard Limit Rules govern movement between Kentucky Street (MP 378.1 and Sargent Yard (MP 380.7). Authority to occupy the main track is Centralized Traffic Control. The maximum authorized speed between these limits is 10 mph. UP QNLSF21 was operating on a restricted signal when it impacted head-on with BNSF EMTSNAM2-23. The recorded speed as determined by the event recorder on lead locomotive UP 9164, indicated that QNLSF21 was operating at 22 mph when the engineer initiated an emergency brake application. Impact was recorded at 16 mph.

HQ-91-2006  
UP/BNSF Head-On Collision  
November 22, 2006  
UP Memphis NS West Main  
UP Memphis, TN  
MP 378.49

## 109. SYNOPSIS OF THE ACCIDENT

On November 22, 2006, about 2:19 a.m. Central Standard Time (CST), an eastbound Union Pacific Railroad (UP) freight Train QNLSF21 collided head-on with a westbound Burlington Northern/Santa Fe (BNSF) Train EMHSNAM2-23 that was stopped on the Norfolk Southern (NS) Westbound Main Track at milepost (MP) 547.0 in Memphis, Tennessee (TN). UP trains operating over NS at this location must receive permission from the NS yardmaster located at Forrest Yard to enter the Westbound or Eastbound main track. However, the switches at this location are remotely controlled by the UP train dispatcher located in Omaha, Nebraska (NE).

The NS yardmaster instructed Train QNLSF21 to operate eastward on the Eastbound Main Track. The crew operating Train QNLSF21 repeated these instructions to the UP train dispatcher. The train dispatcher repeated the instructions back to the train crew, but incorrectly said Westbound Main instead of Eastbound Main. Radio recordings indicate the UP train crew confirmed the dispatcher's repeat of Westbound Main. The train dispatcher lined Train QNLSF21 into the NS Westbound Main Track, where BNSF Train EMHSNAM2-23 was stopped, causing the head-on collision. The collision resulted in the derailment of five cars on Train QNLSF21.

UP reported equipment damage to Train QNLSF21 to be \$26,984 (\$10,001 to the locomotive and \$16,983 to the cars) and track damage at \$12,417. BNSF reported equipment damage to be \$15,000 to locomotive BNSF 6062. NS estimates track damage at \$1,500. The engineer on Train QNLSF21 reported injuries to his right hand and neck and was given a prescription after receiving medical treatment. The conductor of Train QNLSF21 reported injuries to his neck, shoulder, right knee, and left thumb.

At the time of the accident, the sky was dark, but clear and the temperature was reported to be 35°F.

The probable cause of the accident was the failure of Train QNLSF21 to comply with restricted speed. NS Time Table Division Special Instructions require all trains to operate at this location at a maximum authorized speed of 10 miles per hour (mph).

Contributing to the accident was a Federal Railroad Administration (FRA) speed violation. UP Train QNLSF21 was operating at a recorded speed of 21 mph prior to the collision.

## 110. NARRATIVE

## Circumstances Prior To The Accident

## Train QNLSF21

The crew of Train QNLSF21 reported for duty at 8:35 p.m. on November 21, 2006, in Little Rock, Arkansas (AR) MP 289. The crew consisted of an engineer and conductor. The train consisted of two locomotives, 49 loads, 24 empties, weighed 6,619 tons, and was 4,313 feet in length. Prior to reporting for duty each crew member received more than the statutory off duty period.

UP Train QNLSF21 was assigned locomotives UP 9164 and UP 9250 located in the locomotive shop at North Little Rock Terminal. The engineer and conductor operated the locomotives from the shop to their train, which was on Track No. 1 in the departure yard. They received a Class 1 terminal brake inspection, conducted a job briefing with the UP train dispatcher, and reviewed their train bulletins prior to departing Little Rock. The crew did not have any work (pickup/set offs) en route to Memphis. The method of operation on the Memphis subdivision is Centralized Train Control (CTC). The maximum authorized speed for freight trains is 60 mph. Train movement on this subdivision is controlled by desk 51 at the UP Harriman Dispatch Center located in Omaha, NE.

About 1:30 a.m. the UP train dispatcher called the NS yardmaster in Memphis that there were two eastbound UP trains en route. Train QNLSF21 would be the first inbound and was operating on Main Track No. 1. The yardmaster replied to let both eastbound trains come ahead. About 2:05 a.m. Train QNLSF21 called the NS yardmaster requesting a yard track. The NS yardmaster instructed them to use the East Main Track from Tower 17 to Neptune Street (MP 550.4) en route to the UP's Sargent Yard. The crew called the dispatcher via radio advising him of the designated track. According to the dispatcher, the request given by Train QNLSF21 over the radio was unclear. The dispatcher repeated the instructions, but thought the crew requested the West Main Track at the Southern instead of East Main Track. The crew confirmed the instructions by the dispatcher ending the conversation with, "UP 9164 out". The train dispatcher lined the switches from the UP Main Track No. 1 to the NS West Main Track. The engineer was operating from the south side of the locomotive cab and the conductor was seated on the north side in the conductor's seat.

At the Memphis Terminal, UP, BNSF, and NS conduct interchanges at Tower 17, MP 547.0. The UP dispatcher controls the switches at this location and NS owns two yard tracks on either side of the UP main track. The NS tracks are called the NS (Southern) East Main and the NS (Southern) West Main. All trains using the NS tracks at this location must get permission from the NS yardmaster located at Forrest Yard in Memphis. The NS yardmaster advises the UP train dispatcher or provides instructions directly to the train crew on which track they will be using. Once the UP train dispatcher is notified, he will align the switches for the specified track.

## Train EMHSNAM2-23

At 12:15 a.m. on November 22, NS Train Q33 arrived on the NS Westbound Main Track with two locomotives and 124 empty coal hoppers, weighing 3,087 tons, and 4,313 ft in length. This train was interchanged to the BNSF as Train EMHSNAM2-23.

On November 21, the crew for BNSF Train EMHSNAM2-23 reported for duty at 6 p.m. in Marion, AR. The BNSF crew consisted of an engineer, conductor, and brakeman. The crew was taxied from Marion to Memphis to operate Train EMHSNAM2-23 and boarded the train about 2:10 a.m. The crew was advised by the NS yardmaster they would be allowed to operate in a westward direction after the UP Train QNLSF21 cleared the NS West Main switch. All three crew members were located on the lead locomotive.

The timetable direction for this movement is west to east and the geographical direction is the same.

## The Accident

Train QNLSF21 was operating eastbound on a restricted signal from UP Main Track No. 1 to NS West Main Track when it impacted Train EMHSNAM2-23, which was stopped on the NS West Main Track. Train QNLSF21 was operating at 22 mph when the engineer initiated an emergency brake application prior to impact. The speed was determined by the event recorder on lead Locomotive UP 9164. They impacted Train EMHSNAM2-23 at a recorded speed of 16 mph. The three man crew of Train EMHSNAM2-23 that was situated on the locomotive did not have time to dismount and braced themselves for impact. The locomotive of their train was lifted into the air upon impact, but did not derail. The collision resulted in the derailment of five cars (6th, 7th, 8th, 9th and 31st) on Train QNLSF21.

The engineer on UP Train QNLSF21 reported injuries to his right hand and neck and was given a prescription after receiving medical treatment. The conductor of UP Train QNLSF21 reported injuries to his neck, shoulder, right knee, and left thumb. There were no injuries to the crew of Train EMHSNAM2-23.

Analysis and Conclusion  
Analysis

Eastbound UP trains arriving to Memphis from Little Rock must operate across the Canadian Central/Illinois Central (CNIC) railroad crossing at grade, MP 378.3. UP operating rules designate that Yard Limit Rules govern movement between Kentucky Street (MP 378.1) and Sargent Yard (MP 380.7). Authority to occupy the main track is Centralized Traffic Control. The maximum authorized speed between these limits is 10 mph.

UP crew members operating Train QNLSF21 declined to be interviewed by the FRA. The NS yardmaster on duty did provide FRA with an interview and written documentation outlining the instructions given to Train QNLSF21. There was also a recorded conversation from the UP train dispatcher's office. The recording revealed that the train dispatcher lined the track for the NS West Main according to instructions received from the crew of Train QNLSF21.

The information repeated by the UP train dispatcher to occupy the West Main at the Southern was confirmed by the crew of Train QNLSF21, although the crew was advised by the NS yardmaster to operate via the East Main Track. The UP train dispatcher lined the switches from the UP No. 1 Main Track to the NS West Main. With this line-up, Train QNLSF21 was operating on a Restricted Signal.

BNSF Train EMHSNAM2-23 was occupying an NS yard track at the time of the collision. There are no signal circuits that would alert the UP dispatcher that there was a train occupying either NS East or West Main Tracks. The UP train dispatcher had not been advised that the NS West Main was occupied (this is currently not required by railroad operating rules). UP operating rules require that eastbound UP trains that operate via the NS East or West Main tracks must call the NS yardmaster at Forrest Yard when they arrive in the vicinity of the Mississippi River Bridge (MP 379.0).

Trains will obtain routing instructions from the NS yardmaster and the crew will relay this information to the UP train dispatcher. The UP train dispatcher on duty on November 22, 2006, said that when Train QNLSF21 requested the route given to them by the NS yardmaster the request was unclear. The dispatcher thought the crew requested the West Main Track at the Southern and repeated this to the crew. The train dispatcher said the crew responded, "Okay", when posed the question regarding the West Main at the Southern. When the crew confirmed West Main at the Southern, the UP train dispatcher proceeded to line the route.

The investigation of the track, signal, and equipment disclosed no defective conditions contributing to the cause of this accident.

## Conclusion

The FRA investigation revealed that the maximum authorized speed at this location is 10 mph, as documented in UP timetable No. 3, effective 0001 hours Sunday, November 09, 2003. Information obtained from the event recorder located on UP lead Locomotive 9164 revealed that Train QNLSF21 was operating on a Restricted Signal and obtained a speed of 22 mph. The maximum authorized speed at this location was exceeded by more than 10 mph.

In an effort to increase safety awareness and prevent future accidents of this type, UP officials at Memphis and Little Rock developed a Critical Incident Alert (CIA). The CIA highlighted rules that are in place to prevent the type of accident that occurred involving Train QNLSF21. Officers reviewed General Code of Operating Rules 1.47 Duties of Crew Members, 2.3 Repetition, 6.1 Repeat Instructions, and 6.27 Movement at Restricted Speed. All train and engine service employees were contacted on the Memphis subdivision.

## Fatigue Analysis

FRA obtained fatigue related information, including a 10-day work history, for all of the employees involved in this incident. FRA reviewed the work history of the crew members involved and noted that the employees may have been working at a diminished level of effectiveness due to fatigue, which may have contributed to the cause of the accident.

FRA concluded fatigue was a probable cause for the following employees, the engineer and conductor and dispatcher of UP Train QNLSF21.

## Probable Cause

The probable cause of the accident was the failure of Train QNLSF21 to comply with restricted speed. NS Time Table Division Special Instructions require all trains to operate at this location at a maximum authorized speed of 10 mph.

Contributing to the accident was an FRA speed violation. UP Train QNLSF21 was operating at a recorded speed of 21 mph prior to the collision.