



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-92***

***Burlington Northern Santa Fe
Sadler, Missouri
November 29, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF			1b. Railroad Accident/Incident No. NE110612					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A					
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF			3b. Railroad Accident/Incident No. NE110612					
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 11 29 2006			6. Time of Accident/Incident 10:10: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM					
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision					
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts					
			13. Other (describe in narrative)			01					
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Nebraska			
13. Nearest City/Town Iatan			14. Milepost (to nearest tenth) 40.3		15. State Abbr Code N/A MO		16. County PLATTE				
17. Temperature (F) (specify if minus) 29 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/Number Single Main			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 166.4		24. Time Table Direction Code 1. North 3. East 3				
OPERATING TRAIN #1											
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars					
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1			
								27. Train Number/Symbol CBTMS FB044			
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 50 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
29. Trailing Tons (gross tonnage, excluding power units) 17329			e		I		N/A N/A N/A				
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.						
(1) First involved (derailed, struck, etc)		N/A	60	yes	Alcohol		Drugs				
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0				
					33. Was this consist transporting passengers? (Y/N) N						
34. Locomotive Units		a. Head End	b. Mid Train Manual	c. Rear End Remote	35. Cars		a. Freight	b. Pass.	c. Empty Freight	d. Empty Pass.	e. Caboose
(1) Total in Train		2	0	0	(1) Total in Equipment Consist		122	0	0	0	0
(2) Total Derailed		0	0	0	(2) Total Derailed		40	0	0	0	0
36. Equipment Damage This Consist		20204602		37. Track, Signal, Way, & Structure Damage 69000		38. Primary Cause Code T099		39. Contributing Cause Code N/A			
Number of Crew Members						Length of Time on Duty					
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 8 Mi 00		45. Conductor Hrs 8 Mi 00	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No N/A		50. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
Fatal		0		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
Nonfatal		N/A		0		0					
OPERATING TRAIN #2											
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		
						A. Spec. MoW Equip. Code N/A			53. Was Equipment Attended? 1. Yes 2. No N/A		54. Train Number/Symbol N/A
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable					

56. Trailing Tons (gross tonnage, excluding power units) N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A					
58. Principal Car/Unit (1) First involved (derailed, struck, etc) N/A		a. Initial and Number N/A		b. Position in Train N/A		c. Loaded(yes/no) N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A					
(2) Causing (if mechanical cause reported) N/A		N/A		N/A		N/A		60. Was this consist transporting passengers? (Y/N) N/A					
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass. e. Caboose			
(1) Total in Train N/A		N/A		N/A		N/A		(1) Total in Equipment Consist N/A		N/A			
(2) Total Derailed N/A		N/A		N/A		N/A		(2) Total Derailed N/A		N/A			
63. Equipment Damage This Consist N/A		64. Track, Signal, Way, & Structure Damage N/A		65. Primary Cause Code N/A		66. Contributing Cause Code N/A		Number of Crew Members		Length of Time on Duty			
67. Engineer/Operators N/A		68. Firemen N/A		69. Conductors N/A		70. Brakemen N/A		71. Engineer/Operator Hrs N/A Mi N/A		72. Conductor Hrs N/A Mi N/A			
Casualties to: Fatal N/A		73. Railroad Employees N/A		74. Train Passengers N/A		75. Other N/A		76. EOT Device? 1. Yes 2. No N/A		77. Was EOT Device Properly Armed? 1. Yes 2. No N/A			
Nonfatal N/A		N/A		N/A		N/A		78. Caboose Occupied by Crew? 1. Yes 2. No		N/A			
Highway User Involved						Rail Equipment Involved							
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) Code N/A		80. Vehicle Speed (est. MPH at impact) N/A		81. Direction geographical 1. North 2. South 3. East 4. West Code N/A		82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped Code N/A		83. Equipment 1. Train(units pulling) 2. Train(units pushing) 3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing) 6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative) Code N/A		84. Position of Car Unit in Train N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User Code N/A	
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A						86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A							
86c. State here the name and quantity of the hazardous materials released, if any. N/A													
87. Type of Crossing Warning Code(s) N/A		1. Gates 2. Cantilever FLS 3. Standard FLS N/A		4. Wig Wags 5. Hwy. traffic signals 6. Audible N/A		7. Crossbucks 8. Stop signs 9. Watchman N/A		10. Flagged by crew 11. Other (spec. in narr.) N/A		88. Signaled Crossing Warning (See instructions for codes) Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown Code N/A	
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code N/A				91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code N/A				92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code N/A					
93. Driver's Age N/A		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop Code N/A		4. Stopped on Crossing 5. Other (specify in narrative) Code N/A					
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) Code N/A											
101. Casualties to Highway-Rail Crossing Users Killed N/A		Injured N/A		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No Code N/A		102. Highway Vehicle Property Damage (est. dollar damage) N/A		103. Total Number of Highway-Rail Crossing Users (include driver) N/A			
104. Locomotive Auxiliary Lights? 1. Yes 2. No Code N/A								105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No Code N/A					
106. Locomotive Headlight Illuminated? 1. Yes 2. No Code N/A										107. Locomotive Audible Warning Sounded? 1. Yes 2. No Code N/A			

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-
92
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On November 29, 2006, at approximately 10:10 a.m. (CST), BNSF Railway Company (BNSF) coal Train Symbol CBTMSFBO-44A derailed 40 cars (57th through 96th head cars) at milepost (MP) 40.35, on the single Main Track. The accident occurred about 75 feet east of the Woolston Road Crossing (DOT No. 095 196 J) in Platte County, Missouri, approximately 3 miles east of Iatan, Missouri.

Train Symbol CBTMSFBO-44A consisted of three diesel electric locomotives (BNSF 5878, lead locomotive; CEFX 1005, trailing locomotive; and BNSF 9829, a distributed power unit) and 122 cars with 17,360 trailing tons. The train length was 6,476 feet. At the time of the derailment, Train Symbol CBTMSFBO-44A was traveling eastward (timetable direction) at a recorded speed of 50 mph. The geographic direction was south. Timetable directions are used throughout this report. The weather was cloudy with 16 mph winds. The temperature was 29 degrees Fahrenheit.

There were 39 coal cars destroyed with damages estimated at \$2,204,602. Track damages were estimated at \$64,000. Signal damages were estimated at \$5,000, making the total estimated accident damages \$2,273,602. There were no injuries to the train crew.

The probable cause of the accident was vertical deflections (track dips) just west of the point of the derailment causing the trucks on Car No. CEFX 60382, the 60th head car, to bounce resulting in wheel unloading and derailment of the train.

110. NARRATIVE

Circumstances Prior to the Accident

Train Symbol CBTMSFBO-44A originated at the Black Thunder Mine in Colorado, with a destination of Brookline, Missouri. On the prior empty cycle, the train (Train Symbol SFBATM-43) received a Class 1 brake test - initial terminal inspection on November 26, 2006, at Alliance, Nebraska. On the subsequent loaded cycle, it received a Class 1A brake test - 1000-mile inspection at Lincoln, Nebraska, between 1 a.m. and 1:45 a.m., November 29, 2006. No exceptions were noted on either inspection.

The accident occurred on the BNSF Nebraska Division, St. Joseph Subdivision, on the single Main Track. The St. Joseph Subdivision extends from MP 0.5 to MP 207.5, a distance of 207 miles. The method of operation is Centralized Traffic Control (CTC), which is controlled from the BNSF Dispatching Center in Ft. Worth, Texas. BNSF Timetable No. 5, effective at 8:00 a.m. (CST), December 17, 2003, authorizes a 50 mph maximum speed for freight trains in the accident area.

The rail near the point of derailment is 132-pound continuously-welded rail (CWR). It was manufactured by CFI, rolled in the 2nd month of 1984. The rail is secured on concrete ties with spring clip fasteners in good condition. Approaching the accident area, the track is tangent from MP 41.9 to the point of derailment. The average grade is .14 percent descending for eastbound trains. The grade is .05 percent descending at the point of derailment.

The crew of Train Symbol CBTMSFBO-44A included a locomotive engineer and a conductor. They had gone on duty at Lincoln, at 2:10 a.m., November 29, 2006. They had received the required statutory off duty period prior to being called for the train.

Prior to the accident, the locomotive engineer was seated at the controls on the south side of the leading locomotive. The conductor was seated on the north side in the front seat.

The last signal indication prior to the accident was a flashing yellow. Due to the signal indication and the descending grade, the engineer operated the train gradually reducing the throttle to idle approaching the accident area.

The Accident

The train speed was traveling at a recorded speed of 50 mph. Shortly after crossing Woolston Road, Train Symbol CBTMSFBO-44A experienced a train line induced emergency brake application. The conductor walked back to the 17th head car finding a broken knuckle. While the crew was replacing the knuckle, a motorist called the BNSF Police reporting derailed cars. The crew was unaware of the derailment prior to this report. After being contacted by the BNSF dispatcher, the conductor walked toward the rear of train and discovered 40 cars derailed (57th through 96th head cars).

Analysis and Conclusion

Analysis

The BNSF Technical Research and Development Department (TRD) collected and examined evidence secured from the accident site. Evidence included, but was not limited to, event recorder data, broken wheels, broken truck side frames, broken rails, and track geometry car data. Through analysis of evidence, TRD ruled out train make-up, train handling, and train dynamics as possible accident causes. TRD also ruled out failure of truck components as possible accident causes.

Analysis showed the truck components were broken as a result of the accident. Early in the investigation, TRD considered the probable cause of the accident was a

broken rail. There were 5 portions of rail secured near the point-of-derailment. One of those portions was missing the head of the rail. This piece was never found and analysis was inconclusive to determine a broken rail as a possible accident cause.

In the accident area, the last track geometry car inspection was November 3, 2006. No defects were found. The last ultra-sonic rail test was November 14, 2006. No defects were found. The last hi-rail vehicle inspection was November 28, 2006.

During the last BNSF track geometry test, a series of three track dips (approximately 1 inch of vertical deflection) were detected just west of Woolston Road. TRD conducted a New and Untried Car Analytic Regime Simulation (NUCARS) to determine if conditions were capable of producing truck bounce. The NUCARS revealed the track dips produced truck spring bottoming and nearly complete unloading on wheels of trailing trucks (lead, left hand wheels). Minimum wheel loads of 79 pounds were produced when the expected wheel loads should have been 37,500 pounds.

Post accident alcohol and drug tests of both crew members were negative.

Conclusion

Analysis of the event recorder download ruled out any operating issues as a cause. Inspections of all equipment ruled out all mechanical causes. The NUCARS revealed the track dips produced truck spring bottoming and nearly complete unloading on wheels of trailing trucks (lead, left hand wheels). Minimum wheel loads of 79 pounds were produced when the expected wheel loads should have been 37,500 pounds.

Probable Cause

The FRA found the probable cause of the accident to be vertical deflections (track dips) just west of the point of the derailment causing the trucks on Car No. CEFX 60382, the 60th head car, to bounce resulting in wheel unloading and derailment of the train.