



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-94***

***Saginaw Bay Southern Railroad
Saginaw, MI
December 2, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Lake State Rwy Co. [LSRC]		1a. Alphabetic Code LSRC		1b. Railroad Accident/Incident No. A061202	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: Lake State Rwy Co. [LSRC]		3a. Alphabetic Code LSRC		3b. Railroad Accident/Incident No. A061202	
4. U.S. DOT_AAR Grade Crossing Identification Number 232455W		5. Date of Accident/Incident Month: 12 Day: 02 Year: 2006		6. Time of Accident/Incident 04:12:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
				13. Other (describe in narrative) 07	
8. Cars Carrying HAZMAT 20		9. HAZMAT Cars Damaged/Derailed 00		10. Cars Releasing HAZMAT 00	
				11. People Evacuated 0	
				12. Division SAGINAW	
13. Nearest City/Town SAGINAW		14. Milepost (to nearest tenth) 1.4		15. State Abbr Code N/A MI	
				16. County SAGINAW	
17. Temperature (F) (specify if minus) 23 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2	
				20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2	
21. Track Name/Number INBOUND LEAD		22. FRA Track Code Class (1-9, X) 1		23. Annual Track Density (gross tons in millions) 5.6	
				24. Time Table Direction Code 1. North 3. East 1	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
				26. Was Equipment Attended? 1. Yes 2. No 1	
				27. Train Number/Symbol Z127	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH E		30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
				m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) i N/A N/A N/A N/A	
29. Trailing Tons (gross tonnage, excluding power units) 6967				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
31. Principal Car/Unit		a. Initial and Number		b. Position in Train	
(1) First involved (derailed, struck, etc)		N/A		99	
(2) Causing (if mechanical cause reported)		0		0	
				c. Loaded (yes/no) no N/A	
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A	
				33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		b. Mid Train	
		b. Manual		c. Remote	
		d. Manual		c. Remote	
(1) Total in Train		2		0	
(2) Total Derailed		0		0	
				35. Cars	
				a. Freight	
				b. Pass.	
				c. Freight	
				d. Pass.	
				e. Caboose	
				(1) Total in Equipment Consist 33	
				(2) Total Derailed 0	
				0	
				0	
				0	
36. Equipment Damage This Consist		37. Track, Signal, Way, & Structure Damage		38. Primary Cause Code M302	
0		0		39. Contributing Cause Code N/A	
Number of Crew Members			Length of Time on Duty		
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1	
				43. Brakemen 1	
				44. Engineer/Operator Hrs 11 Mi 30	
				45. Conductor Hrs 11 Mi 30	
Casualties to:		46. Railroad Employees		47. Train Passengers	
Fatal		0		0	
Nonfatal		N/A		0	
				48. Other 0	
				49. EOT Device? 1. Yes 2. No 1	
				50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
				51. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
				53. Was Equipment Attended? 1. Yes 2. No N/A	
				54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control		g. Automatic block h. Current of traffic m. Special instructions n. Other than main track	
				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s)					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A								
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.					Alcohol	Drugs							
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A							N/A	N/A							
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		60. Was this consist transporting passengers? (Y/N)					N/A								
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose							
				b. Manual		c. Remote		d. Manual		c. Remote		a. Freight		b. Pass.	c. Freight	d. Pass.					
(1) Total in Train		N/A		N/A		N/A		N/A		N/A		N/A		N/A	N/A	N/A					
(2) Total Derailed		N/A		N/A		N/A		N/A		N/A		N/A		N/A	N/A	N/A					
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage		N/A		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A							
Number of Crew Members								Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor											
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A											
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?											
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A											
Nonfatal		N/A		N/A		N/A		78. Caboose Occupied by Crew?						N/A							
								1. Yes 2. No													
Highway User Involved								Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code									
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian						1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)											
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		A				2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		3									
80. Vehicle Speed (est. MPH at impact)		30		81. Direction geographical		Code		84. Position of Car Unit in Train		99											
				1. North 2. South 3. East 4. West		4															
82. Position				Code		85. Circumstance		Code													
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				3		1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User		2													
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code													
1. Highway User 2. Rail Equipment 3. Both 4. Neither				4		1. Highway User 2. Rail Equipment 3. Both 4. Neither		4													
86c. State here the name and quantity of the hazardous materials released, if any.																					
N/A																					
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code					
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes		Code					
3. Standard FLS		6. Audible		9. Watchman		12. None								2. No							
Code(s)		01		03		06		07		N/A		N/A		N/A		01		3. Unknown		2	
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code									
1. Both Sides						1. Yes				1. Yes											
2. Side of Vehicle Approach						2. No		2		2. No											
3. Opposite Side of Vehicle Approach				1		3. Unknown				3. Unknown						1					
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code									
36		1. Male				1. Yes				1. Drove around or thru the Gate		4. Stopped on Crossing									
		2. Female		2		2. No		2		2. Stopped and then Proceeded		5. Other (specify in narrative)									
						3. Unknown				3. Did not Stop											
97. Driver Passed Standing Highway Vehicle				Code		98. View of Track Obscured by (primary obstruction)		Code													
1. Yes 2. No 3. Unknown				2		1. Permanent Structure				7. Other (specify in narrative)											
						2. Standing Railroad Equipment		4. Topography		6. Highway Vehicle		8. Not obstructed				8					
101. Casualties to Highway-Rail Crossing Users				Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code							
				0		1		1. Killed 2. Injured 3. Uninjured		2		1. Yes		2. No		1					
								102. Highway Vehicle Property Damage (est. dollar damage)		8500		103. Total Number of Highway-Rail Crossing Users (include driver)		1							
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code													
1. Yes 2. No				1		1. Yes 2. No		1													
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code													
1. Yes 2. No				1		1. Yes 2. No		1													

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-94-
2006 -
Accident
Sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

An automobile collided with the 99th car of Saginaw Bay Southern Railway Company (SBS) freight train Z127 which was stopped and blocking the highway-rail grade crossing at Janes Avenue. The accident occurred on December 2, 2006, at approximately 4:12 a.m. E.S.T. The accident occurred in Saginaw, Michigan, at SBS milepost 1.41, on the SBS Saginaw Division.

The driver of the motor vehicle was transported to St. Mary's Hospital in Saginaw. The motor vehicle sustained extensive damage. There were no injuries to the train crew. The rail car sustained minor damage, and there was no derailment caused by the motor vehicle striking the train.

At the time of the accident it was dark and cloudy. The temperature was 23 F.

According to the Saginaw Police Department Michigan Traffic Crash Report, the driver bent down to get her cell phone and when she looked up, she was not able to stop in time and struck the train. The driver was not issued a citation.

The accident was caused by highway user inattentiveness.

110. NARRATIVE

Circumstances Prior to the Accident

Lake State Railway Company (LSRC) and the SBS are owned and operated by the same management team. SBS was acquired from the CSX Transportation Company in 2005.

The crew of SBS Train No. Z127 included a locomotive engineer, conductor, and a brakeman. They first went on duty at 4:30 p.m. E.S.T., on December 1, 2006, at Saginaw Yard in Saginaw, Michigan. This was the home terminal for all crew members, and all received more than the statutory off duty period prior to reporting for duty.

Their assigned freight train consisted of two locomotives, 33 loaded, and 98 empty cars of several varieties. It was 7,208 feet long, and weighed 7,487 tons. The train was scheduled to travel north from Flint, Michigan, to Saginaw Yard. The train crew had a job briefing with the train coordinator and performed an initial air brake test prior to departure.

Train Z127 passed over Janes Avenue on SBS trackage without incident as they entered Saginaw Yard. At 3:20 a.m. they reported to the third Shift Coordinator that R40 yard switch was broken. Train Z127 attempted to cut the blocked highway-rail grade crossings. At 3:50 a.m. Train Z127 reported they had derailed two cars on R50 track and the crossings were still blocked. The derailed cars were the first two cars behind the locomotives. The third shift coordinator contacted 911 and notified them that the crossings at Janes Avenue and Lapeer Street were blocked by Train Z127. The crew of Train Z127 left the train and walked to crew headquarters at Saginaw Yard.

The area of the railroad where the accident occurred is tangent for one half mile. There is a 0.24 percent ascending grade approaching the Janes Avenue crossing from the south.

The railroad timetable and geographic direction of the train was north.
The Accident

Train LSRC Z127

Train Z127 was stopped and the crew had left the locomotive due to derailling two cars of the train. Janes Avenue and Lapeer Street highway-rail grade crossings were blocked because of the derailment.

At approximately 4:12 a.m. an automobile traveling in an westward direction struck the 99th car of Train Z127 at Janes Avenue.

Highway Vehicle

The automobile was traveling east to west on Janes Avenue with one occupant at an unknown speed. The posted highway speed limit is 30 mph. Speed of the automobile at impact is unknown.

The driver of the automobile was reported to have been bending down to get her cell phone just prior to the collision. The automobile struck the 99th car of Train Z127 and ended up partially under the rail car. The driver of the automobile was pinned in the driver's seat.

A Saginaw police officer arrived at the scene at 4:12 a.m. The police officer reported the accident occurred on the east side of the crossing and when he arrived at the scene the railroad's flashing lights were flashing and the audible bells were working but the gate on the east side of Janes Avenue was in the upright position.

The Saginaw Fire Rescue Squad and paramedics arrived a few minutes later and removed the driver from the vehicle.

The driver of the automobile was taken by ambulance to St. Mary's Hospital in Saginaw. There were no other reported injuries.

A National Signal Corporation (NSC) signal maintainer who is contracted by SBS to test and maintain the highway-rail grade crossing warning equipment was dispatched to the accident site and arrived at approximately 5:30 a.m. The signal maintainer performed testing and determined that the highway-rail grade crossing warning system was operating and the northeast gate was in the up or vertical position with the train stopped and blocking the highway-rail grade crossing at Janes Avenue.

There was no track damage reported.

Analysis and Conclusions

Analysis

The driver of the automobile was a 36 year old female.

The highway-rail grade crossing is equipped with 12 inch flashing light units, two gate mechanisms, two bells, stop on red signal signs, and cross bucks for each direction of highway traffic. There are advanced warning signs posted approximately 300 feet from the crossing. Pavement marking were in place.

The highway-rail grade crossing warning system was again tested by a LSRC-SBS signal supervisor and a NSC signal maintainer at 10:00 a.m. the day of the accident. The signal maintainer indicated the cover of the northeast quadrant gate mechanism had been stolen. Absence of the gate mechanism cover allowed ice to form in the gate mechanism causing it to malfunction. Photographs supplied by NSC show the ice deposits in the gate mechanism. The highway-rail crossing warning devices worked as intend during the post accident testing. The LSRC-SBS signal supervisor decided to remove the warning system gates from service. The LSRC-SBS signal supervisor notified the train coordinator to apply a stop and flag order for all train movements over the crossing until proper repairs could be made.

The highway-rail grade crossing warning system tests were performed again on December 12, 2006, by a NSC signal maintainer, this time in the presence of an FRA signal and train control inspector. The warning devices functioned as intended when they were tested during the inspection.

It is not known when, where, or how the gate mechanism cover was removed from the gate mechanism.

Conclusions

The railroad was in compliance with their operating and safety rules. The railroad was issued a defect for non-compliance with CFR 234.273, for not having the required monthly test and inspection reports on file within the required time frame, by one day.

The Saginaw Police Department State of Michigan Traffic Crash Report states the driver of the automobile was bending down to get her cell phone just prior to the collision and was unable to stop in time to avoid the collision.

Probable Cause and Contributing Factors

Probable Cause

The accident was caused by highway user inattentiveness.

#