



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-99***

***CSX Transportation  
Woodstock, MD  
December 15, 2006***


***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 CSX Transportation [CSX]			1a. Alphabetic Code CSX			1b. Railroad Accident/Incident No. 00027596					
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A					
3. Name of Railroad Responsible for Track Maintenance: CSX Transportation [CSX]			3a. Alphabetic Code CSX			3b. Railroad Accident/Incident No. 00027596					
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month   Day   Year 12   15   2006			6. Time of Accident/Incident 02:15:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM					
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision					
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts					
			13. Other (describe in narrative)			01					
8. Cars Carrying HAZMAT 24		9. HAZMAT Cars Damaged/Derailed 4		10. Cars Releasing HAZMAT 0		11. People Evacuated 100		12. Division Baltimore			
13. Nearest City/Town Marriottsville, Md/Woodstock			14. Milepost (to nearest tenth) 26.1		15. State Abbr Code N/A   MD		16. County BALTIMORE				
17. Temperature (F) (specify if minus) 40 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 4		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/Number Old Main Line Single			22. FRA Track Code Class (1-9, X) 2		23. Annual Track Density (gross tons in millions) 46.4		24. Time Table Direction Code 1. North 3. East 3				
<b>OPERATING TRAIN #1</b>											
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars					
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1			
								27. Train Number/Symbol Q370-14			
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 23 MPH   R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
29. Trailing Tons (gross tonnage, excluding power units) 8839			j   N/A   N/A   N/A   N/A				0				
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.						
(1) First involved (derailed, struck, etc)		N/A	28	yes	Alcohol		Drugs				
(2) Causing (if mechanical cause reported)		CMHX711117	27	yes	N/A		N/A				
					33. Was this consist transporting passengers? (Y/N) N						
34. Locomotive Units		a. Head End	b. Mid Train Manual	c. Rear End Remote	35. Cars		a. Freight	b. Pass.	c. Empty Freight	d. Empty Pass.	e. Caboose
(1) Total in Train		3	0	0	(1) Total in Equipment Consist		80	0	11	0	0
(2) Total Derailed		0	0	0	(2) Total Derailed		16	0	4	0	0
36. Equipment Damage This Consist		37. Track, Signal, Way, & Structure Damage		38. Primary Cause Code		39. Contributing Cause Code					
357387		69000		E07C		N/A					
Number of Crew Members						Length of Time on Duty					
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 10 Mi 45		45. Conductor Hrs 10 Mi 45	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal		0		0		0					
Nonfatal		N/A		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
<b>OPERATING TRAIN #2</b>											
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		
						A. Spec. MoW Equip. Code N/A			53. Was Equipment Attended? 1. Yes 2. No N/A		54. Train Number/Symbol N/A
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH   N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable					

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs	
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A				N/A		N/A	
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A	
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty	
				b. Manual c. Remote		d. Manual c. Remote				a. Freight b. Pass.		c. Freight d. Pass.	
(1) Total in Train		N/A		N/A		N/A		(1) Total in Equipment Consist		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A		(2) Total Derailed		N/A		N/A	
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage		N/A		65. Primary Cause Code		N/A		66. Contributing Cause Code	
												N/A	
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor			
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?			
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		N/A		N/A		N/A		78. Caboose Occupied by Crew?				N/A	
								1. Yes 2. No					
Highway User Involved						Rail Equipment Involved							
79. Type						83. Equipment							
C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code						3. Train (standing) 6. Light Loco(s) (moving) Code							
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian						1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing)							
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A						2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative) N/A							
80. Vehicle Speed (est. MPH at impact) N/A						84. Position of Car Unit in Train							
81. Direction geographical) Code						N/A							
1. North 2. South 3. East 4. West N/A													
82. Position Code						85. Circumstance Code							
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing						1. Rail Equipment Struck Highway User							
4. Trapped N/A						2. Rail Equipment Struck by Highway User N/A							
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? Code						86b. Was there a hazardous materials release by Code							
1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A						1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A							
86c. State here the name and quantity of the hazardous materials released, if any.													
N/A													
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning Code		89. Whistle Ban Code	
		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		1. Yes	
		3. Standard FLS		6. Audible		9. Watchman		12. None				2. No	
Code(s)		N/A		N/A		N/A		N/A		N/A		3. Unknown N/A	
90. Location of Warning Code				91. Crossing Warning Interconnected with Highway Signals Code				92. Crossing Illuminated by Street Lights or Special Lights Code					
1. Both Sides				1. Yes				1. Yes					
2. Side of Vehicle Approach				2. No				2. No					
3. Opposite Side of Vehicle Approach N/A				3. Unknown				3. Unknown					
93. Driver's Age		94. Driver's Gender Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train Code		96. Driver Code		97. Driver Passed Standing Highway Vehicle Code		98. View of Track Obscured by (primary obstruction) Code			
N/A		1. Male N/A		1. Yes 2. No 3. Unknown N/A		1. Drove around or thru the Gate 4. Stopped on Crossing		1. Yes 2. No 3. Unknown N/A		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		5. Other (specify in narrative) N/A	
		2. Female				2. Stopped and then Proceeded							
		N/A				3. Did not Stop							
97. Driver Passed Standing Highway Vehicle Code		98. View of Track Obscured by (primary obstruction) Code		99. Driver Was Code		100. Was Driver in the Vehicle? Code		101. Casualties to Highway-Rail Crossing Users		102. Highway Vehicle Property Damage (est. dollar damage) Code		103. Total Number of Highway-Rail Crossing Users (include driver) Code	
1. Yes 2. No 3. Unknown N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) N/A		1. Killed 2. Injured 3. Uninjured N/A		1. Yes 2. No N/A		N/A		N/A		N/A	
		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed											
104. Locomotive Auxiliary Lights?		105. Locomotive Auxiliary Lights Operational?		106. Locomotive Headlight Illuminated?		107. Locomotive Audible Warning Sounded?							
1. Yes 2. No		1. Yes 2. No		1. Yes 2. No		1. Yes 2. No							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

SKETCH  
HQ-2006-  
99.jpg



## 109. SYNOPSIS OF THE ACCIDENT

DATE: 12-15-2006

TIME: 02:15 am

VISIBILITY: Foggy and dark

TEMPERATURE: 40°

An eastbound CSX mixed freight derailed 20 cars on 12-15-2006 at 2:15 am. The derailment occurred near Marriottsville Maryland, Carroll County at CSX milepost 26.1 on the Old Main Line subdivision. Of the 20 cars derailed, 4 were tank cars. There was major concern with the PLMX 135248, a tank car loaded with Anhydrous Ammonia. This car came to rest in an inverted position, therefore a determination could not be made as to possible leakage and extent of damage until the car was righted by the salvage crew. The Carroll County Emergency Management team on scene commanders then initiated a precautionary evacuation for a one mile radius.

The estimated damages for track and equipment was set at \$426,387 - not to include labor.

The probable cause of the derailment was determined to be dragging brake rigging equipment from the A-end truck of the 28th car in the consist.

## 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

## Circumstances Prior to the Accident:

The crew of the CSX 0370-14 east, engineer and conductor, went on duty at 3:30 pm (est) on Dec. 14, 2006 at Cumberland Terminal Maryland. Both engineer and conductor had received more than the statutory off duty period prior to reporting for duty. Their assigned mixed freight train, the Q370-1 4 consisted of 3 locomotives, 80 loads, and 11 emptys, comprising a total of 8839 trailing tons. The Class I Brake Test was done at Cumberland Terminal Maryland.

At 11:59 pm, this train notified the dispatcher of their undesired emergency brake application at milepost 43.8. The locomotive HLCX 6319 was not loading, and their train stalled on grade. The conductor then proceeded to walk the train and inspect for separation of the consist, kinked EOT hose, or any other non-conformity. Once confirmation was made that the train was intact, the dispatcher directed the 0787-14 to cut their power away from their train and help the 0370-14 over the grade to East Hood. (01.10 am). Once over the grade, the D787-14 cut away its power, and the 0370-14 was able to continue eastward. The train was being operated at 25 mph as they approached the derailment area. The engineer was seated at the controls on the south side of the lead locomotive and the conductor was seated on the north side of that same locomotive. At 2:15 am the Q370-14 experienced another undesired emergency brake application. After inspection of the train, the conductor notified the dispatcher of derailment at milepost 26.1. The speed at the time of the derailment was 23 mph as indicated by the lead locomotive event recorder. The maximum authorized speed in this territory is 25 mph.

On the approach to the point of derailment (POD), from the west on single track mainline, there are a succession of curves and tangents. From milepost 27, heading east, there is a long tangent of 390 feet, then a 10 degree 12 minute right hand curve 560 feet long. Next an 11 degree 27 minute left curve 752 feet long, a 10 degree 00 minute right curve 380 feet long, a 4 degree 47 minute left curve that's 780 feet, a tangent of 210 feet, a 4 degree 35 minute right curve of 565 feet, a tangent of 560 feet and a 5 degree 12 minute right curve -of which the POD is 102 feet into the west spiral of that curve. The track grade approaching the POD is a .28% descending eastward grade. There are no highway crossings, track switches, or wayside signals in this stretch of track.

## The Accident:

Of the 20 derailed cars, 4 were tank cars. The PLMX 135248, a loaded tank car of particular importance, had come to rest in an inverted position 30-40 feet from the rail. Its contents were that of "Anhydrous Ammonia," a very dangerous inhalant hazard if released into the

atmosphere. The particular spot where this tank came to rest was the soft ground substrate of the adjacent Patapsco River bed, which served as cushioning for its top protective cover. Before efforts were made to move this car, the Carroll County Emergency Management Team initiated a precautionary evacuation of a one mile radius. The approximate number evacuated of personnel was 100, for a period of 4.5 hours. The salvage crew "Cranemasters" had set the tank upright by 7:30 pm. A CSX Hazmat manager and team crew member got on top of the PLMX 135248 and confirmed that the integrity of the valves were intact and there was no chance of leakage.

Analysis and Conclusions:

The CSX was found to be in full compliance with all applicable federal standards. The lead locomotive was equipped with a speed recorder and event recorder as required. This event recorder was downloaded by the Road Foreman of Engines, and it shows the engineer employed good train handling throughout the course of the trip. The train crew members were the only witnesses to the incident.

The total damage was placed at \$69,000.00 for track and car damage was placed at \$426,387. These figures are excluding labor costs.

Probable Cause:

The FRA determined that the derailment occurred because the CSXT 138295 had downed and dragging brake rigging from the A-end truck. Physical evidence indicates that this did eventually cause the derailment.